Appendix 10
Hazards and Hazardous Materials

SITE HISTORY REPORT

APRIL 2014

Seawall Lot 337/Pier 48
Mixed-Use Project
San Francisco, California

For:

ICF International
San Francisco, California

13208-00.02125

BASELINE ENVIRONMENTAL CONSULTING

5900 Hollis Street, Suite D, Emeryville, CA 94608 | P: (510) 420-8686 | F: (510) 420-1707 | www.baseline-env.com

SITE HISTORY REPORT

APRIL 2014

Seawall Lot 337/Pier 48
Mixed-Use Project

San Francisco, California

For:

ICF International
San Francisco, California

13208-00.02125

BASELINE Environmental Consulting
5900 Hollis Street, Suite D, Emeryville, California 94608
(510) 420-8686

TABLE OF CONTENTS

page

ARTICLE 22A CERTIFICATION v

1. INTRODUCTION 1
   - 1.1. Purpose of the Site History 1
   - 1.2. Scope of Services 2
2. PHYSICAL SETTING 2
3. CURRENT LAND USES 2
4. HISTORICAL LAND USES 2
5. REGULATORY AGENCY RECORDS 4
   - 5.1. Hazardous Substances Use, Storage, Handling, and Disposal 5
   - 5.2. Known Hazardous Substances Releases 5
   - 5.3. Previous Environmental Investigations and Regulatory Actions 7
6. CONCLUSIONS 10
7. RECOMMENDATIONS 11
8. LIMITATIONS 12
9. REFERENCES 13

APPENDICES
(PDF on CD-ROM)

A: Historical Land Use Resources
B: Environmental Database Report
C: Land Use Restrictions
D: Qualifications of Preparers

FIGURES

1: Regional Location
2: Maher Zone Map
3: Historical Land Uses
4: Hazardous Substances Use, Storage, Handling, and/or Disposal Sites
5: Hazardous Substances Release Sites within One Mile of the Project
6: Hazardous Substances Release Sites within the Potential Area of Concern

TABLES

1: Potential Impacts to Soil and Groundwater Quality from Historical Land Uses
2: Hazardous Substances Use, Storage, Handling, and/or Disposal Sites
3: Hazardous Substances Release Sites within the Potential Area of Concern

LIST OF ABBREVIATIONS

AST	aboveground storage tank
ASTM	American Society of Testing and Materials
ATSF	Atchison, Topeka, and Santa Fe
BASELINE	BASELINE Environmental Consulting
bgs	below ground surface
CSA	Container Storage Area
DEQ	Oregon Department of Environmental Quality
DTSC	Department of Toxic Substance Control
EDR	Environmental Data Resources, Inc.
GIS	Geographic Information Systems
H&H	H&H Ship Services Company
PAH	polynuclear aromatic hydrocarbons
PCBs	polychlorinated biphenyls
Project Site	Seawall Lot 337/Pier 48 Mixed-Use Project
RCRA	Resource Conservation and Recovery Act
SFDPH	San Francisco Department of Public Health
SU	Solidification Unit
SVOC	semi-volatile organic compound
SWRCB	State Water Resource Control Board
TCA	Tank Cleaning Area
TPHd	total petroleum hydrocarbons as diesel
TPHg	total petroleum hydrocarbons as gasoline
TPHmo	total petroleum hydrocarbons as motor oil
TTA	Treatment Transfer Area
UST	underground storage tank
VOC	volatile organic compound

ARTICLE 22A CERTIFICATION

In our judgment, this site history report is accurate and complete, and fulfills the requirements of Section 22A.6 *Site History* in Article 22A of the San Francisco Public Health Code.

Yane Nordhav
Principal
Prof. Geologist No. 4009

Patrick Sutton
Environmental Engineer

SITE HISTORY REPORT

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

1. INTRODUCTION

BASELINE Environmental Consulting ("BASELINE") prepared this report to describe the activities and present the findings, conclusions, and recommendations of a site history for the Seawall Lot 337/Pier 48 Mixed-Use Project ("Project Site") located at Seawall Lot 337 and Pier 48 in San Francisco, California. The Project Site encompasses approximately 27 acres and includes: Seawall Lot 337, Pier 48, China Basin Park, Block P20, and adjacent streets and access areas (Figure 1). The proposed Project would include multi-phased construction of residential and commercial uses, open spaces, public access areas, an internal grid of new streets and utilities, and a bicycle/pedestrian network.

1.1. Purpose of the Site History

BASELINE prepared this site history at the request of ICF International in support of environmental review of the Project. The Project Site is located within the jurisdiction of Article 22A of the San Francisco Public Health Code, which is administered by the San Francisco Department of Public Health ("SFDPH") (also referred to as the Maher Ordinance). The Maher Ordinance applies to any project that could potentially encounter hazardous substances[1] in the subsurface. This includes any sites that would excavate more than 50 cubic yards of soil and are currently mapped within a Maher zone or are suspected to contain hazardous substances in the subsurface.[2] The Project is subject to the Maher Ordinance because proposed soil excavation would exceed 50 cubic yards and Seawall Lot 337, China Basin Park, Block P20, and adjacent streets and access areas are mapped within a Maher zone (Figure 2). Pier 48 is also mapped within a Maher zone, but since the pier is located over the San Francisco Bay and no soil excavation would occur, subsurface investigation and mitigation activities would not be required for this portion of the Project Site.

Under the Maher Ordinance, the Project is required to assess, sample, analyze, and remediate (if necessary) subsurface contamination prior to the issuance of building permits. The purpose of this site history report is to assess potential and/or known sources of subsurface contamination at the Project Site and provide recommendations for a subsurface investigation. Prior to the issuance of building permits for the Project, SFDPH must review and approve this

[1] "Hazardous substance" means any hazardous substance as defined in the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), 42 U.S.C. §9601(14) and petroleum products and byproducts.

[2] Projects that would excavate less than 50 cubic yards of soil where subsurface contamination is suspected should refer to the SFDPH to determine if enrollment in the Maher program is necessary.

site history report, as well as any subsequent subsurface investigation and mitigation activities (if necessary).

1.2. Scope of Services

The scope of services for this report included: review of physical setting sources, historical land use information, previous environmental investigations, and regulatory agency environmental records; site reconnaissance of current land use conditions; and preparation of this report to document our findings, conclusions, and recommendations for a subsurface investigation workplan. The review of environmental records was performed in accordance with guidance in the American Society of Testing and Materials ("ASTM") Method E1527-13, *Standard Practice for Environmental Site Assessments: Phase I Environmental Assessment Process*.

2. PHYSICAL SETTING

The Project Site is generally flat with a site-wide elevation of about 8 feet above mean sea level (United State Geological Survey, 1995). The Project Site is generally underlain by artificial fill (Graymer, R.W, et al., 2006). The groundwater depth on the Project Site ranges from about 7 to 9 feet below ground surface ("bgs") (Treadwell & Rollo, 2011). Based on the Project's proximity to the Bay, groundwater flow is likely tidally influenced with a predominant flow direction to the northeast towards the Bay.

3. CURRENT LAND USES

On 14 January 2014, BASELINE performed a site reconnaissance to determine current land uses at and adjacent to the Project Site. The site reconnaissance was also conducted to identify evidence of past or current use, storage, handling, disposal, or releases of hazardous substances within and/or adjacent to the Project Site. Evidence of hazardous substances releases could include apparent odors, stained or discolored surfaces, and stressed or damaged vegetation. All observations were made from public rights-of-way. Most of the Project Site is paved. Seawall Lot 337 is a surface parking lot, Pier 48 is occupied by storage warehouses with indoor parking, and China Basin Park is a developed open space area. Evidence of a hazardous substances release was not observed on or adjacent to the Project Site.

4. HISTORICAL LAND USES

Historical land uses at and adjacent to the Project Site were determined by reviewing Sanborn fire insurance maps, aerial photographs, building permits records, and previous environmental investigations. The review of building permit records associated with the Project Site, which ranged from 1977 and 2013, did not reveal any historical uses of hazardous substances. The Sanborn fire insurance maps, aerial photographs, and building permits reviewed for this report are included in Appendix A. The approximate locations of historical land uses potentially associated with hazardous substances are shown on Figure 3.

Prior to 1906, the Project Site was part of the San Francisco Bay. In 1906, the Project Site was created by filling in the marshlands and shallow tidal flats at the San Francisco Bay margin with serpentine rock and soils from the nearby Potrero Hill (Ver Planck Historic Preservation Consulting, 2014). Serpentine is a type of ultramific rock that commonly contains naturally-occurring asbestos. The fill material likely included construction debris and rubble from the 1906 earthquake and fire as well. The fill materials may potentially contain contaminants such as metals, polynuclear aromatic hydrocarbons ("PAHs"), petroleum hydrocarbons, and asbestos. Potential impacts to soil quality from contaminated fill materials are summarized in Table 1. Historical land use developments on and adjacent to the Project Site that were potentially associated with hazardous substances are summarized below and illustrated in Figure 3.

Railway Yards and Warehouses

The Project Site was predominantly occupied by Atchison, Topeka, and Santa Fe ("ATSF") railway yards from about 1913 to 1956. Storage warehouses associated with railroad operations were located on and adjacent to the western portion of the Project Site. A railroad supply depot was located on the southern portion of the Project Site and a roundhouse with oil storage was located south of the Project Site (Figure 3).

The primary contaminants of concern associated with the former railway yards and associated structures on the Project Site include total petroleum hydrocarbons as diesel and motor oil ("TPHd" and "TPHmo", respectively) from fueling operations, leaking engines, and rail cars, polychlorinated biphenyls ("PCBs") from leaking engines and electrical equipment, chlorinated solvents from maintenance and painting operations, and metals from miscellaneous maintenance and operational activities. In addition, soils beneath the former railway yards could be contaminated with herbicides used for weed abatement (Environmental Protection Agency, 2013 and Oregon Department of Environmental Quality ["DEQ"], 2001). Potential releases of TPHd and/or chlorinated solvents from warehouses west of the Project Site and the roundhouse south of the Project Site may have impacted groundwater that could have migrated beneath the Project Site. Potential impacts to soil and groundwater quality from the former railway yards and associated structures are summarized in Table 1.

After the ATSF railway yards closed in the 1950s, the warehouses remained on and adjacent to the Project Site as late as 1999. Releases of hazardous substances at warehouses located on and adjacent to the Project Site were likely less common as overall transport and maintenance activities were reduced to only truck-related operations. The Pier 48 was also serviced by railroad operations while the ATSF yard was active (Figure 3); however, historical uses of hazardous materials at Pier 48 would not have impacted land-based soil and/or groundwater, because the structures are located on piers over the San Francisco Bay.

Metal Fabrication and Machine Shops

Metal fabrication and machine shops with oil storage were located on the northern portion of the Project Site from about 1949 to 1993 (Figure 3). The primary contaminants of concern

associated with former metal fabrication and machine shops on the Project Site include chlorinated solvents, metals, TPHd, TPHmo, cyanide, and acids (Oregon DEQ, 2001). Potential impacts to soil and groundwater quality from the former metal/machine shops are summarized in Table 1.

Truck Repair Shops

Two truck repair shops were located in the northern portion of the Project Site in the 1960s and 1970s (Figure 3). The primary contaminants of concern associated with former truck repair shops located on the Project Site include TPHd, TPHmo, chlorinated solvents, and acids (Oregon DEQ, 2001). Potential impacts to soil and groundwater quality from the former truck repair shops are summarized in Table 1.

H&H Ship Services Company

H&H Ship Services Company ("H&H") operated a hazardous waste treatment facility on the northern portion of the Project Site from 1950 to 1996. The facility included a service yard with a Treatment Transfer Area ("TTA"), Tank Cleaning Area ("TCA"), Container Storage Area ("CSA"), and Solidification Unit ("SU"). The TTA was located along the edge of the Bay and the TCA, CSA, and SU were located within a service yard further inland (Figure 3). The waste streams managed at the H&H facility included bilge water from ships (containing mostly water and some petroleum hydrocarbons), empty fuel underground storage tanks ("USTs"), and rinse water from the USTs. The primary contaminants of concern associated with the former hazardous waste treatment facility located on the Project Site likely includes metals, total petroleum hydrocarbons as gasoline ("TPHg"), TPHd, TPHmo, PAHs, and chlorinated solvents. Potential impacts to soil and groundwater quality from operations at the former TTA and service yard are summarized in Table 1.

In 1978, several of the wastes were determined to be hazardous by the Department of Toxic Substance Control ("DTSC") and from 1978 to 1996 H&H operated under a Resource Conservation and Recovery Act ("RCRA") interim status. A RCRA operating permit was never issued for the Site because required facility upgrades were never completed. Between 1994 and 1999, H&H implemented Site closure activities in response to a cease and desist order from the DTSC. Site closure activities included dismantling, testing, and disposal of equipment, removal of waste inventory, and soil and groundwater quality sampling (Harding Lawson Associates, 1999a). The results of the subsurface investigation activities are described further under Section 5.3, below.

5. REGULATORY AGENCY RECORDS

BASELINE contracted with Environmental Data Resources, Inc. ("EDR"), an environmental resource service, to conduct a preliminary search of federal, state, and local regulatory agency records pertaining to past and present hazardous substances use, storage, handling, disposal, and releases on properties at or near the Project Site. On 8 November 2013, an environmental records search was conducted by EDR that identified 382 records of Sites that have used,

stored, handled, disposed, or released hazardous substances within 1 mile of the Project Site (EDR, 2013a). The records from the EDR report were filtered to select only the standard environmental record sources presented in ASTM E1527-13. The standard environmental records were then imported into Geographic Information Systems ("GIS") to spatially select records within the minimum search distances presented in ASTM E1527-13 to evaluate potential sites of concern. The findings of the environmental record review process are presented below and the complete EDR environmental records report is included in Appendix B.

5.1. Hazardous Substances Use, Storage, Handling, and Disposal

After reviewing the EDR report, four sites were identified that have used, stored, handled, and/or disposed of hazardous substances on or adjacent to the Project Site (Table 2 and Figure 4). Hazardous substances releases have been reported at two of the sites: H&H on the Project Site and Pier 50 adjacent to the Project Site (Figure 4). Since Pier 50 is located over the San Francisco Bay, hazardous substances release would not likely impact soil and/or groundwater beneath the Project Site. A detailed discussion of the environmental conditions at the H&H site is provided under Section 5.3, below. Hazardous substances releases have not been reported at the other two sites located adjacent to the Project: Waterloo Beverages and Pier 50 Gear (Figure 4). Evidence of an existing hazardous substance release or a material threat of a release was not observed at the Waterloo Beverages or Pier 50 Gear sites during the Project Site reconnaissance on 14 January 2014 (see Section 3, above).

5.2. Known Hazardous Substances Releases

After reviewing the EDR report, 183 records of sites that have released hazardous substances within up to 1 mile of the Project Site were identified (Figure 5). Many of the sites are represented by more than 1 record under different names and/or addresses, which means that the total number of actual sites is likely less than the total number of records. Hazardous substances releases on or hydraulically upgradient of the Project Site could impact soil and/or groundwater quality beneath the Project Site. With the exception of Pier 48, the Project Site and a conservative estimate of areas potentially hydraulic upgradient of the Project Site are collectively shown on Figure 5 as the "Potential Area of Concern".

There are 25 known sites with hazardous substances releases located within the Potential Area of Concern (Table 3 and Figure 6). Groundwater contamination from sites located outside the Potential Area of Concern does not likely pose a risk of migrating beneath the Project Site. The current regulatory status of the 25 known release sites within the Area of Concern was reviewed and summarized in Table 3.

Regulatory oversight at 22 of the 25 release sites has been closed, indicating that regulatory requirements for response actions, such as site assessment and remediation, have either been completed or were not necessary. Any residual soil and/or contamination of potential concern associated with a closed release site would not be expected to extend from the release site onto other properties. As shown in Figure 6, 2 of the 22 closed release sites were formerly located on the northern portion of the Project Site: an unnamed site at the former 405 China

Basin Street (Site C11 in Table 3 and Figure 6) and the CCSF-Port of San Francisco site at the former 145 China Basin Street (Site C13 in Table 3 and Figure 6). Potential residual soil and/or groundwater contamination associated with these two sites is discussed further under Section 5.3, below. Residual groundwater contamination from the other 20 closed release sites located potentially upgradient of the Project Site does not likely pose a risk of migrating beneath the Project Site (Table 3 and Figure 6).

Three of the 25 known hazardous substance release sites have not been closed. One of the release sites (H&H) is located on the Project Site and the other two release sites (Esprit Outlet Store and Pier 64/Mission Bay) are located potentially upgradient of the Project Site. The regulatory status and environmental conditions associated with these three release sites are summarized below.

H&H Ship Services Company

As previously discussed under Section 4, above, the H&H site was a hazardous waste treatment facility formerly located on the north eastern portion of the Project Site from 1950 to 1996 (Site A8 in Table 3 and Figure 6). According to the DTSC EnviroStor Database (DTSC, 2013), there are two land use restrictions associated with residual soil contamination from H&H. A detailed discussion of the environmental conditions and land use restrictions at the H&H site is provided under Section 5.3, below.

Esprit Outlet Store

The former Esprit Outlet Store site is a hazardous waste site located about 0.5 miles south of the Project Site at 499 Illinois Street (Site 207 in Table 3 and Figure 6). The site was identified on the Historical Cortese list, which includes hazardous waste sites formerly designated by the State Water Resource Control Board ("SWRCB"), the Integrated Waste Management Board, and the DTSC. This listing is no longer updated by the California Environmental Protection Agency. Additional information regarding the regulatory status of the site could not be found on the SWRCB Geotracker Database (SWRCB, 2013) or the DTSC EnviroStor Database (DTSC, 2013). According to the SWRCB's Hazardous Substance Storage Container Database, diesel and waste oil USTs were formerly located on the site (EDR, 2013a). Since the petroleum hydrocarbons in the diesel and waste oil carbon range have relatively low solubility, a potential release of diesel or waste oil from a UST (if any) at the Esprit Outlet Store site would not likely migrate far from the source area (i.e., would not migrate 0.5 miles to the Project Site).

Pier 64/Mission Bay

The Pier 64/Mission Bay is an active hazardous waste site located about 0.4 miles south of the Project Site (Site 183 in Table 3 and Figure 6). The site was formerly occupied by various bulk fuel storage facilities. Historical operations at the site resulted in contamination of the underlying groundwater with petroleum hydrocarbons. The dissolved petroleum hydrocarbon plumes are migrating northeast from the site toward the San Francisco Bay (Arcadis, 2012). As

a result, groundwater contamination from the Pier 64/Mission Bay site does not pose a threat of migrating beneath the Project Site.

5.3. Previous Environmental Investigations and Regulatory Actions

Available environmental documents of previous environmental investigations were reviewed to evaluate potential subsurface contamination from the three known hazardous substances release sites identified on the Project Site (see Figure 6 and Section 5.2, above). In addition, environmental investigations performed at the Project Site in the late 1990s were also reviewed to evaluate potential sources of subsurface contamination. The previous investigations at the Project Site were conducted to satisfy the requirements of the Maher Ordinance prior to redevelopment of Seawall Lot 337 into the current parking lot (Figure 1) and to achieve a conditional site closure for hazardous substances released from the former H&H site (Figure 3).

Since all of the environmental investigations were performed over 13 years ago, the SFDPH has determined that the analytical results cannot be used to properly characterize the current soil and groundwater quality at the Project Site because new releases may have occurred (Cushing, 2013). However, the findings can be used to inform the design of a future subsurface sampling and analysis workplan. The findings of the previous environmental investigations at the Project Site are summarized below.

405 China Basin Street

In 1991, an emergency spill response was reported at the former 405 China Basin Street (Site C11 in Table 3 and Figure 6) due to a 300 yard sheen observed in the China Basin (EDR, 2013a).[3] No additional regulatory response actions were reported, which indicates that the case was closed. A potential release of petroleum hydrocarbons into the China Basin would not likely affect soil and/or groundwater beneath the Project Site.

CCSF – Port of San Francisco

In 1987, a 1,000-gallon gasoline UST was removed from the CCSF – Port of San Francisco site at the former 145 China Basin Street (Site C13 in Table 3 and Figure 6). Concentrations of TPHg, TPHd, benzene, ethylbenzene, toluene, and total xylenes were reported in a groundwater sample collected from the excavation pit, but were not reported above laboratory reporting limits in a groundwater sample collected from a well located about 20 feet downgradient from the pit. As a result, SFDPH issued a *Remedial Action Completion Certification* in 2008 (SFDPH, 2008). A map of the former UST location was not available for review. Residual soil and/or groundwater contamination may be present in the immediate vicinity of the former excavation pit.

[3] China Basin Street was formerly located on the Project Site adjacent to China Basin.

H&H Ship Services Company

In February 1999, a *RCRA Closure Certification Report* was prepared for the former H&H site at 220 China Basin Street (Site A8 in Table 3 and Figure 6) on the Project Site to document the closure of the following four hazardous waste management units: TTA, TCA, CSA, and SU (Harding Lawson Associates, 1999a). The TTA was located along the edge of the San Francisco Bay and the TCA, CSA, and SU were located within a service yard further inland (Figure 3). The report included a baseline health risk assessment to evaluate the potential cancer risks and non-cancer hazards associated with potential future on-site exposures to hazardous substances in soil. Groundwater quality was also evaluated for potential impacts to aquatic species in the San Francisco Bay. Soil and groundwater quality data were previously collected in the TTA (Harding Lawson Associates, 1995) and new soil and groundwater samples were collected and analyzed in the TCA, CSA, and SU. Soil and groundwater analytical results for the four hazardous waste management units are summarized below.

Treatment Transfer Area Investigation

The TTA included a tank farm and pier, where 11 aboveground storage tanks ("ASTs") of various sizes were installed in an unpaved area in the late 1960s (Figure 3). A concrete and asphalt pad for the ASTs was constructed at a later date. Ships discharged contaminated bilge water into the ASTs. Settling and treatment tanks were used to remove petroleum products from the wastewater, and the recovered petroleum product was transported to oil recycling facilities. Based on the sampling and analysis of the treated wastewater for hazardous constituents, the wastewater was transported to the Publicly Owned Treatment Works. In 1995, a total of 66 soil samples were collected from 20 borings at depths ranging from 2 to 8 feet bgs. Three grab groundwater samples were collected from borings. All soil and groundwater samples were analyzed for total metals, volatile organic compounds ("VOCs"), semi-volatile organic compounds ("SVOCs"), PAHS, pesticides, and PCBs. Elevated concentrations of arsenic, total chromium, lead, and PAHs were reported in soil samples and elevated concentrations of various total metals were reported in groundwater samples (Harding Lawson Associates, 1995). The findings are consistent with the expected contaminants of concern summarized in Table 1.

Service Yard Investigation

The TCA was a bermed concrete pad, where former fuel USTs were rinsed. The rinse water was pumped into 55-gallon storage drums and stored in the CSA. The CSA, which was a partially bermed concrete pad, was also used to store petroleum products and waste oil in 55-gallon drums. Materials stored in the CSA were shipped off-site for recycling or disposal. Sludge from USTs was solidified in the SU using absorbent materials and mixing equipment (Figure 3).

A total of 17 soil samples were collected from 12 borings.[4] Five grab groundwater samples were collected from borings. All soil and groundwater samples were analyzed for total metals, VOCs, TPHg, TPHd, oil and grease, PAHS, and PCBs. Elevated concentrations of arsenic, total chromium, TPHg, TPHd, and oil and grease were reported in soil samples and elevated

[4] Soil sample depths not reported.

concentrations of TPHd and PAHs were reported in groundwater samples (Harding Lawson Associates, 1999a). The findings are consistent with the expected contaminants of concern summarized in Table 1.

Baseline Risk Assessment

Contaminants of potential concern that were evaluated for the baseline risk assessment included arsenic and PAHs in soil. For the baseline risk assessment, potential human receptors included construction workers and commercial/industrial workers, and potential ecological receptors included fish and aquatic invertebrates in the adjacent open water habitat. Human health risks from exposure to groundwater contaminants were not evaluated because the groundwater at the site was not considered a potential source of drinking water. The baseline risk assessment indicated that the calculated non-cancer hazards and cancer risk levels at the site do not likely pose a threat to future commercial/industrial workers, construction workers, or aquatic organisms (Harding Lawson Associates, 1999a).

In July 1999, an additional risk evaluation was conducted for the TTA to evaluate potential health risks to recreational receptors as related to the development of China Basin Park. The contaminants of potential concern included antimony, arsenic, total chromium, lead, molybdenum, PAHs, and Aroclor 1260. The additional risk assessment indicated that the calculated non-cancer hazards and cancer risk levels in the TTA do not likely pose a threat to future adult and children recreational users (Harding Lawson Associates, 1999b).

Land Use Restrictions

Two land use restrictions have been placed on the former H&H site through a *Covenant and Agreement* made by and between the City of San Francisco and the Department of Toxic Substances Control (DTSC). One deed restriction limits the use of the service yard at the former H&H site to commercial/industrial land uses, as analyzed in the 1999 closure certification report (Harding Lawson Associates, 1999a). The perimeter of the H&H service yard is defined in the deed restriction included in Appendix C. Since the health risk assessment for the service yard did not evaluate an unrestricted land-use scenario, the DTSC concluded that use of the property as a residence, hospital, school for persons under 21, day care center for children, or recreational use involving direct contact with soil would entail an unacceptable potential human health risk. The deed restriction requires excavated soils to be evaluated and managed in accordance with the Maher Ordinance, and prohibits the raising of food or extraction of groundwater for purposes other than site remediation and construction dewatering without prior approval from the DTSC.

The deed restriction for the TTA allows commercial/industrial or recreational land uses, as analyzed in the 1999 closure certification report (Harding Lawson Associates, 1999a) and subsequent response to closure comments (Harding Lawson Associates, 1999b). The perimeter of the TTA is defined in the deed restriction included in Appendix C. At the time the deed restriction was established, the TTA was being considered for redevelopment and incorporation into the current China Basin Park. The deed restriction requires the existing asphalt-concrete pad, that covers the soil contamination to remain in–place, be covered by 18 inches of

imported top soil and sod as long as the TTA is used as a recreational park. Since the health risk assessment for the TTA did not evaluate an unrestricted land-use scenario, the DTSC concluded that use of the property as a residence, hospital, school for persons under 21, or day care center for children would entail an unacceptable potential human health risk. The deed restriction requires excavated soils to be evaluated and managed in accordance with the Maher Ordinance, a Soil Management Plan, and a Health and Safety Plan. The deed restriction also prohibits the raising of food, extraction of groundwater for purposes other than site remediation and construction dewatering, or disturbance/alteration/degradation of the cap without prior approval from the DTSC.

Burlington Northern Santa Fe Railway Company

Between 1994 and 1996, an environmental site assessment and soil quality investigation was performed for the Burlington Northern Santa Fe Railway Company on the western half of the Project Site (formerly ATSF). One soil boring was located in the southwest portion of the Project Site and soil samples were collected at depths of 0.5, 5, and 8 feet bgs and analyzed for TPHg, TPHmo, and total metals. Analytical results reported elevated concentrations of several metals in the soil (Geomatrix, 1999). The findings are consistent with expected contaminants of concern in fill materials, railway yards, and associated railway structures summarized in Table 1.

Seawall Lot 337

In June 1999, a soil and groundwater quality investigation was performed for the entire Seawall Lot 337 site (Figure 1) in accordance with requirements from the Maher Ordinance. Eight soils borings were located at 200-foot intervals across the Project Site and soil samples were collected at about 1 and 5 feet bgs from each boring. Soil samples were analyzed for VOCs, PAHs, pesticides, PCBs, total metals, pH, asbestos, cyanide, total sulfide, and fluoride. The potential presence of flammable gases, such as methane, was monitored using a flame-ionization detector while drilling each boring. Two grab groundwater samples were collected from borings and analyzed for VOCs, PAHs, and total metals. Analytical results reported elevated concentrations of metals in the soil (Geomatrix, 1999). The findings are consistent with expected contaminants of concern in fill materials, railway yards, and associated railway structures summarized in Table 1.

6. CONCLUSIONS

A site reconnaissance of current land use conditions at and adjacent to the Project Site did not reveal any evidence of hazardous substances releases, such as apparent odors, stained or discolored surfaces, and stressed or damaged vegetation. Review of historical land use resources indicated that hazardous substances have likely been present on and adjacent to the Project Site as early 1913, when the Project Site was first developed by placing fill materials along the San Francisco Bay shoreline. Historical land use developments on the Project Site are shown in Figure 3 and include the following:

- Former railway yards and associated structures;

- Former metal/machine shops;
- Former truck repair shops; and
- A former hazardous waste treatment facility (H&H service yard and TTA).

The primary contaminants of concern associated with each historical land use that could potentially impact soil and/or groundwater quality on the Project Site are summarized in Table 1.

Based on review of the regulatory agency records, groundwater contamination from adjacent or potentially upgradient hazardous substances release sites does not pose a threat of migrating beneath the Project Site. Review of regulatory agency records and previous environmental investigations indicated that residual soil and/or groundwater contamination is likely present from the CCSF-Port of San Francisco (Site C13) and H&H (Site A8) sites formerly located on the Project Site (Table 3 and Figure 6). A third hazardous substances release site was reported at the former 405 China Basin Street site (Site C11 in Table 3 and Figure 6) located on the Project Site, but residual contamination would not likely be encountered in the soil or groundwater. Information about the exact location and extent of impacts from the release of petroleum hydrocarbons at the CCSF-Port of San Francisco site (Site C13) was not available for review. Two land use restrictions have been established for the former H&H site associated with residual soil and groundwater contamination (Appendix C).

Review of previous environmental investigations confirmed that some of the primary contaminants of concern associated with historical land uses (Table 1) on the Project Site have been reported in soil and groundwater samples. Since the subsurface sampling for previous environmental investigations on the Project Site was conducted more than 13 years ago, the analytical results cannot be reused to properly characterize the current soil and groundwater quality on the Project Site.

7. RECOMMENDATIONS

Based on the findings of the site history review, hazardous substances released from historical land uses may be present in soil and groundwater beneath the Project Site. Depending on the nature and concentration of hazardous substances present in the subsurface, special soil and groundwater management procedures and health and safety measures for the protection of construction workers and the public may be required during construction. Therefore, prior to construction and earthwork activities, subsurface sampling and analysis should be performed to characterize the quality of soil and groundwater that would be disturbed during construction of the land portion of the Project Site (i.e., not sediments submerged in the Bay beneath Pier 48). The purposes of the subsurface investigation would be to:

1) Identify potentially undocumented releases of hazardous substances from historical land uses (if any) that may require response actions under regulatory oversight;

2) Pre-characterize soil quality to evaluate reuse and disposal options at permitted facilities;

3) Pre-characterize groundwater quality to evaluate proper storage and disposal options during construction dewatering activities; and

4) Evaluate construction worker health and safety considerations.

A workplan for subsurface sampling and analysis of the primary contaminants of concern, summarized in Table 1, should be submitted to the SFDPH for review. The sampling frequency and distribution should be guided by the location of historical land uses shown in Figure 3 and the analytical results from previous environmental investigations.

After completing the subsurface investigation, a Subsurface Analysis Report should be prepared to evaluate the potential presence of hazardous substances in soil and groundwater at the Project Site and determine whether hazardous substances are causing or are likely to cause significant health and safety risks given the intended land use.

The findings of the Subsurface Analysis Report should be incorporated into a Site Mitigation Plan to delineate specific soil and groundwater management and disposal procedures, construction worker health and safety requirements, and contingency measures in case unknown contamination is encountered during construction (e.g., residual contamination from the CCSF-Port of San Francisco site). The Site Mitigation Plan should also include measures to comply with the land use restrictions established for residual soil and groundwater contamination at the H&H service yard and TTA (Figure 3). Any proposed deviations from the land use restrictions should be approved by the DTSC.

8. LIMITATIONS

This site history report was performed to provide an understanding of the current environmental conditions at the Project Site. BASELINE's interpretations and conclusions regarding this information and presented in this report are based on the expertise and experience of BASELINE in conducting similar assessments and current local, state, and federal regulations and standards. The qualifications of the preparers are included in Appendix D.

BASELINE's objective is to perform our work with care, exercising the customary thoroughness and competence of earth science, environmental, and engineering consulting professionals, in accordance with the standard for professional services for a consulting firm at the time these services were provided. It is important to recognize that even the most comprehensive scope of services may fail to detect environmental conditions and potential liability at a particular site. Therefore, BASELINE cannot act as insurers and cannot "certify or underwrite" that a site is free of environmental contamination, and no expressed or implied representation or warranty is included or intended in this report except that the work was performed within the limits prescribed with the customary thoroughness and competence of our profession.

The passage of time, manifestation of latent conditions, or occurrence of future events may require further exploration at the Project Site, analysis of the data, and re-evaluation of the findings, observations, conclusions, and recommendations expressed in this report.

The findings, observations, conclusions, and recommendations expressed by BASELINE in this report are limited by the scope of services and should not be considered an opinion concerning the compliance of any past or current owner or operator of the Project Site with any federal, state, or local law or regulation. No warranty or guarantee, whether expressed or implied, is made with respect to the data reported or findings, observations, conclusions, and recommendations expressed in this report.

9. REFERENCES

Arcadis, 2012. *Groundwater Monitoring Report; Former Petroleum Terminals and Related Pipelines Located at Pier 64 and the Vicinity.* October.

City and County of San Francisco Planning Department, 2013. *Expanded Maher Area, October 2013*.

Cushing, Stephanie, 2013. Personal Communication between Stephania Cushing from the San Francisco Department of Public Health and Bruce Abelli-Amen, Principal at BASELINE Environmental, regarding the use of historical subsurface investigation data to satisfy the requirements of the Maher Ordinance. November.

DTSC, 2013. EnviroStor Database. http://www.envirostor.dtsc.ca.gov/public/. Accessed on 26 November.

EDR, 2013a. *The EDR Radius Map™ Report with GeoCheck®*. 8 November.

EDR, 2013b. *Certified Sanborn® Map Report*. 11 November.

EDR, 2013c. *The EDR Aerial Photo Decade Package*. 13 November.

Environmental Protection Agency, 2013. *Mid-Atlantic Brownfields & Land Revitalization; Rail Yards*. Last updated 25 September.

Geomatrix, 1999. *Site Use History and Proposed Article 20 Sampling Program; Proposed Imperial Weitz Parking Lots, South of China Basin Channel, San Francisco, California*. March.

Graymer, R.W, et al., 2006. *Geologic Map of the San Francisco Bay Region*. USGS, Scientific Investigations Map 2918.

Harding Lawson Associates, 1999a. *RCRA Closure Certification Report, Former H&H Ship Service Facility, San Francisco, California*. 4 February.

Harding Lawson Associates, 1999b. *Response to Comments, RCRA Closure Certification Report, Former H&H Ship Service Facility, 220 Terry Francois/China Basin Street, San Francisco, California. Attachment 1, Additional Risk Evaluation – Hypothetical Recreational Exposure Scenario*. 15 July.

Harding Lawson Associates, 1995. *Preliminary Screening Evaluation, H&H Ship Service Company, San Francisco, California*. 14 September.

Oregon DEQ, 2001. *Typical Contaminants from Land Uses/Sources*. June.

SFDPH, 2008. *Remedial Action Completion Certification; Underground Storage Tanks (UST) Case, Commercial Property, 145 China Basin Street, San Francisco, LOP Case Number: 10318*. 15 April.

SWRCB, 2013. GeoTracker Database. http://geotracker.swrcb.ca.gov/. Accessed on 26 November.

Treadwell & Rollo, 2011. *Preliminary Geotechnical Investigation, Seawall Lot 337 – Mission Bay San Francisco, California*. 8 September.

United State Geological Survey, 1995. *San Francisco North Quadrangle, California, 7.5-Minute Series (Topographic)*.

Ver Planck Historic Preservation Consulting, 2014. *Draft Historic Resource Evaluation; Seawall Lot 337 & Pier 48 Mixed-Use Development Project, San Francisco, California*. March.

FIGURES

REGIONAL LOCATION

Figure 1

Base: Google Maps

Legend

Project Site Boundary

N

0 350 Feet

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

MAHER ZONE MAP

Figure 2



Legend

Project Site Boundary

Mapped Maher Zone (October 2013)

Base: City and County of San Francisco Planning Department, 2013

N

0 0.65 Mile

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

HISTORICAL LAND USES

Figure 3



Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

HAZARDOUS SUBSTANCES USE, STORAGE, HANDLING, AND/OR DISPOSAL SITES

Figure 4

Legend

Project Site Boundary

Hazardous Substances Use, Storage, Handling and/or Disposal Site

Base: Google Maps
Source: Site locations (EDR, 2013a)

N

0 300 Feet

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

HAZARDOUS SUBSTANCES RELEASE SITES WITHIN ONE MILE OF THE PROJECT

Figure 5



Legend

- Project Site Boundary
- Potential Area of Concern
- Hazardous Substances Release Site

Base: Google Maps
Source: Site locations (EDR, 2013a)

Note: "Potential Area of Concern" includes portions of the Project site and potential hydraulically upgradient areas where hazardous substances release sites could impact soil and/or groundwater beneath the Project site.

N

0 1,900 Feet

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

HAZARDOUS SUBSTANCES RELEASE SITES WITHIN THE POTENTIAL AREA OF CONCERN

Figure 6

Legend

Project Site Boundary

Regulatory Status of Release Sites:

- Active
- Closed
- Unknown
- Land Use Restriction

Base: Google Maps
Source: Site ID and locations (EDR, 2013a)

N

0 600 Feet

Seawall Lot 337/Pier 48 Mixed-Use Project
San Francisco, California

BASELINE ENVIRONMENTAL CONSULTING

TABLES

TABLE 1: Potential Impacts to Soil and Groundwater Quality from Historical Land Uses

Historical Land Uses	Primary Contaminants of Concern										
	Title 22 Metals	TPHg	TPHd	TPHmo	Chlorinated Solvents	PAHs	PCBs	Pesticides	Cyanide	Acids	Asbestos
Fill Materials	X	X	X	X		X					X
Former Railway Yards and Structures	X		X	X	X		X	X			
Former Metal/Machine Shops	X		X	X	X				X	X	
Former Truck Repair Shops			X	X	X					X	
Former H&H Treatment Transfer Area	X	X	X	X	X	X					
Former H&H Service Yard	X	X	X	X	X	X					

Notes:

Fill materials are present across the entire Project site.

Former land uses are shown in Figure 3.

X = Potential impact to soil

= Potential impact to groundwater

TABLE 2: Hazardous Substances Use, Storage, Handling, and/or Disposal Sites

Site Name	Address	Environmental Records					
		HAZNET	RCRA-SQG	UST	CA FID UST	HIST UST	SWEEPS UST
H&H Ship Service	220 China Basin St, San Francisco	X	X		X	X	X
Waterloo Beverages LLC	295 Terry Francois St, San Francisco	X					
Pier 50	Pier 50, San Francisco	X	X				
Pier 50 Gear	300 China Basin St, San Francisco			X	X		X

Notes:

Site names and environmental records derived from the *EDR Radius Map Report (2013a)* in Appendix C.
Site locations are shown on Figure 4.

TABLE 3: Hazardous Substances Release Sites within the Potential Area of Concern

Site ID	Site Name	Address	Standard Environmental Records								Regulatory Status
			Land Use Restriction	Emergency Spill Response	Hazardous Waste Site	Leaking Storage Tank	Brownfields	RCRA Non-CORRACTS TSD	CERCLIS NFRAP	RCRA CORRACTS	
		Environmental Record Search Distance (miles)	**0.0**	**0.0**	**0.5**	**0.5**	**0.5**	**0.5**	**0.5**	**1.0**	
Sites Located on the Project Site											
C13	CCSF - Port Of San Francisco	145 China Basin St, San Francisco			X	X					Closed[1]
C11	---	405 China Basin St, San Francisco		X							Closed[2]
A8	H & H Ship Service	220 China Basin St, San Francisco	X	X	X			X	X	X	Land Use Restriction[2]
Sites Located Potentially Upgradient of the Project Site											
206	Chevron Station #9-0294	1200 7th St, San Francisco				X					Closed[1]
146	Santa Fe Pacific Realty C	1201 6th St, San Francisco			X	X					Closed[1]
O64	Santa Fe Pacific Realty C	1301 6th St, San Francisco			X	X					Closed[1]
168	Southern Pacific Motor Trucking	1355 6th St, San Francisco			X	X					Closed[1]
148	Pearson Equipment Company	1400 6th St, San Francisco			X	X					Closed[1]
54	Ares Commercial Properties	1501 3rd St, San Francisco			X	X					Closed[1]
166	Mission Bay Parcel 24	1600 6th St, San Francisco			X	X					Closed[1]
184	Mission Bay P10	1600 Owens St, San Francisco					X				Closed[3]
AH175	Carraro Property	1800 3rd St, San Francisco			X	X					Closed[1]
K56	Santa Fe Pacific Realty Corp	195 Channel St, San Francisco			X	X					Closed[1]
AE156	Santa Fe Pacific Realty C	205 Channel St, San Francisco			X	X					Closed[1]
N63	"Golden Brands Bottling Co., In"	255 Channel St, San Francisco			X	X					Closed[1]
AH173	Kaiser Sand & Gravel	300 16th St, San Francisco			X	X					Closed[1]
K52	Southern Pacific Transportatio	415 Channel St, San Francisco			X	X					Closed[1]

TABLE 3: Hazardous Substances Release Sites within the Potential Area of Concern

Site ID	Site Name	Address	Standard Environmental Records								Regulatory Status
			Land Use Restriction	Emergency Spill Response	Hazardous Waste Site	Leaking Storage Tank	Brownfields	RCRA Non-CORRACTS TSD	CERCLIS NFRAP	RCRA CORRACTS	
		Environmental Record Search Distance (miles)	**0.0**	**0.0**	**0.5**	**0.5**	**0.5**	**0.5**	**0.5**	**1.0**	
Y144	CCSF - Port Of San Francisco	333 Illinois St, San Francisco			X	X					Closed[1]
207	Esprit Outlet Store	499 Illinois St, San Francisco			X						Unknown[2]
AH169	3rd Street Light Rail Project Seg.B	3rd & 16th St, San Francisco				X					Closed[1]
Y133	SFFD Pumping Station	698 2nd St, San Francisco				X					Closed[1]
197	Super Shuttle	700 16th St, San Francisco			X	X					Closed[1]
28	Commercial	1250 4th St, San Francisco				X					Closed[1]
H50	"Mission Bay, Park P16 Mitigation Project"	Mission Bay Blvd & Terry Francois Blvd, San Francisco					X				Closed[3]
183	Pier 64/Mission Bay	Vicinity of Pier 64, San Francisco			X						Open[1]

Notes:

"---" = Site name not reported

Site ID, site names, and environmental records are derived from the *EDR Radius Map Report (2013a)* in Appendix C.

"Potential Area of Concern" is shown in Figure 5.

Site locations are shown in Figure 6.

[1] SWRCB, 2013. GeoTracker Database. http://geotracker.swrcb.ca.gov/. Accessed on 26 November.

[2] EDR, 2013a. *The EDR Radius Map Report with GeoCheck* . 8 November.

[3] EPA, 2012. *EPA Region 9 Brownfields Program RLF Success Stories; California DTSC Subgrants* . July.

APENDIX A

HISTORICAL LAND USE RESOURCES

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3781208.5
November 13, 2013

The EDR Aerial Photo Decade Package

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography November 13, 2013

Target Property:

Pier 48

San Francisco, CA 94158

Year	***Scale***	***Details***	***Source***
1938	Aerial Photograph. Scale: 1"=300'	Flight Year: 1938 Best Copy Available from original source	Ryker
1946	Aerial Photograph. Scale: 1"=500'	Flight Year: 1946	Jack Ammann
1956	Aerial Photograph. Scale: 1"=500'	Flight Year: 1956	USGS
1968	Aerial Photograph. Scale: 1"=500'	Flight Year: 1968	USGS
1974	Aerial Photograph. Scale: 1"=500'	Flight Year: 1974	USGS
1982	Aerial Photograph. Scale: 1"=500'	Flight Year: 1982	USGS
1993	Aerial Photograph. Scale: 1"=500'	/DOQQ - acquisition dates: 1993	EDR
1998	Aerial Photograph. Scale: 1"=500'	Flight Year: 1998	USGS
2005	Aerial Photograph. Scale: 1"=500'	Flight Year: 2005	EDR
2009	Aerial Photograph. Scale: 1"=500'	Flight Year: 2009	EDR
2010	Aerial Photograph. Scale: 1"=500'	Flight Year: 2010	EDR
2012	Aerial Photograph. Scale: 1"=500'	Flight Year: 2012	EDR

INQUIRY #: 3781208.5

YEAR: 1938

= 300'

N

EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 1946
= 500'
N

INQUIRY #: 3781208.5
YEAR: 1956
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 1968
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 1974
= 500'
N

INQUIRY #: 3781208.5
YEAR: 1982
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 1993
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 1998
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 2005
= 500'
N

INQUIRY #: 3781208.5
YEAR: 2009
= 500'
N
EDR Environmental Data Resources Inc


INQUIRY #: 3781208.5
YEAR: 2010
= 500'
N
EDR Environmental Data Resources Inc

INQUIRY #: 3781208.5
YEAR: 2012
= 500'
N
EDR Environmental Data Resources Inc

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3791748.2
November 21, 2013

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

ASTM and EPA Requirements

ASTM E 1527-05 lists building department records as a "standard historical source," as detailed in § 8.3.4.7: "Building Department Records – The term building department records means those records of the local government in which the property is located indicating permission of the local government to construct, alter, or demolish improvements on the property." ASTM also states that "Uses in the area surrounding the property shall be identified in the report, but this task is required only to the extent that this information is revealed in the course of researching the property itself."

EPA's Standards and Practices for All Appropriate Inquires (AAI) states: "§312.24: Reviews of historical sources of information. (a) Historical documents and records must be reviewed for the purposes of achieving the objectives and performance factors of §312.20(e) and (f). Historical documents and records may include, but are not limited to, aerial photographs, fire insurance maps, building department records, chain of title documents, and land use records."

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILDFAX® PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of Baseline Environmental Cons. on Nov 21, 2013.

TARGET PROPERTY

Pier 48
San Francisco, CA 94158

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **YES**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

San Francisco

Year	*Source*	*TP*	*Adjoining*
2013	City and County of San Francisco, Communications Di		
2012	City and County of San Francisco, Communications Di		
2011	City and County of San Francisco, Communications Di	X	
2010	City and County of San Francisco, Communications Di	X	
2009	City and County of San Francisco, Communications Di		
2008	City and County of San Francisco, Communications Di		
2007	City and County of San Francisco, Communications Di		
2006	City and County of San Francisco, Communications Di		
2005	City and County of San Francisco, Communications Di		
2004	City and County of San Francisco, Communications Di		
2003	City and County of San Francisco, Communications Di		
2002	City and County of San Francisco, Communications Di		
2001	City and County of San Francisco, Communications Di		
2000	City and County of San Francisco, Communications Di		
1999	City and County of San Francisco, Communications Di		
1998	City and County of San Francisco, Communications Di		
1997	City and County of San Francisco, Communications Di		
1996	City and County of San Francisco, Communications Di		
1995	City and County of San Francisco, Communications Di		
1994	City and County of San Francisco, Communications Di		
1993	City and County of San Francisco, Communications Di		
1992	City and County of San Francisco, Communications Di	X	
1991	City and County of San Francisco, Communications Di		
1990	City and County of San Francisco, Communications Di		
1989	City and County of San Francisco, Communications Di		
1988	City and County of San Francisco, Communications Di		
1987	City and County of San Francisco, Communications Di		
1986	City and County of San Francisco, Communications Di		

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

Year	Source	TP	Adjoining
1985	City and County of San Francisco, Communications Di		
1984	City and County of San Francisco, Communications Di		
1983	City and County of San Francisco, Communications Di		
1982	City and County of San Francisco, Communications Di		
1981	City and County of San Francisco, Communications Di		
1980	City and County of San Francisco, Communications Di		
1979	City and County of San Francisco, Communications Di		
1978	City and County of San Francisco, Communications Di		
1977	City and County of San Francisco, Communications Di		

BUILDING DEPARTMENT RECORDS SEARCHED

Name: San Francisco
Years: 1977-2013
Source: City and County of San Francisco, Communications Division, San Francisco, CA
Phone: (415) 558-6088

Name: Alameda
Years: 2001-2012
Source: City of Alameda, Planning and Building Department, Alameda, CA
Phone: (510) 747-6800

Name: Berkeley
Years: 1992-2012
Source: City of Berkeley, Planning and Development, Berkeley, CA
Phone: (510) 981-7400

Name: Daly City
Years: 1990-2009
Source: Daly City, Building Division, Daly City, CA
Phone: (650) 991-8061

Name: Richmond
Years: 2007-2012
Source: City of Richmond, Building Regulations, Richmond, CA
Phone: (510) 620-6868

Name: San Bernardino County
Years: 2002-2012
Source: San Bernardino County, Land Use Services Department, San Bernardino, CA
Phone: (909) 256-4750

Name: San Leandro
Years: 1993-2012
Source: City of San Leandro, Building and Safety, San Leandro, CA
Phone: (510) 577-3405

Name: San Mateo County Unincorporated Area
Years: 1999-2010
Source: San Mateo County, Planning and Building Department, Redwood City, CA
Phone: (650) 363-4161

Name: South San Francisco
Years: 2000-2012
Source: City of South San Francisco, Building Division, South San Francisco, CA
Phone: (650) 829-6670

Name: Vacaville
Years: 2000-2009
Source: City of Vacaville, Building Permits , Vacaville , CA
Phone: (707) 449-5152

Name: Oakland
Years: 1968-2012
Source: City of Oakland,Building Services Division, Oakland, CA
Phone: (510) 238-3891

Name: Santa Barbara County Unincorporated Area
Years: 2002-2011
Source: Santa Barbara County, Licenses, Registrations and Permits, Santa Barbara, CA
Phone: (805) 568-2000

Name: San Bruno
Years: 1997-2011
Source: San Bruno, Building Permits and Inspections, San Bruno, CA
Phone: (650) 616-7076

Name: San Pablo
Years: 1999-2011
Source: San Pablo, Building Permit and Inspection, San Pablo, CA
Phone: (510) -215--3060

Name: Huntington Beach
Years: 1999-2011
Source: Huntington Beach, Dept. of Building and Safety, Huntington Beach, CA
Phone: (714) 536-5241

Name: Pacifica
Years: 1993-2012
Source: City of Pacifica, Planning Department, pacifica, CA
Phone: 650-738-7341

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

Pier 48
San Francisco, CA 94158

Pier 48

Date:	**7/15/2011**
Permit Type:	**PM**
Description:	**(2) KITCHEN HOODS, DRYER VENT (X2) (4) BATHROOM FANS, (1) A/V VENTILATION**
Permit Description:	**MECHANICAL PERMIT**
Work Class:	
Proposed Use:	
Permit Number:	PM20100719504
Status:	EXPIRED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	FORCED AIR SYSTEMS

Date:	**4/8/2010**
Permit Type:	**E**
Description:	**ROOF: 14 ROOF-MOUNTED SOLAR PV MODULES; 225 WATTS MODULE; 14 INTERACTIVE INVERTER; 210 WATTS POWER RATING (EACH); TOTAL NO. OF RATING: 2.73 KW; ADDITONAL COMMENTS: INSTALL 2.73KW UTILITY INTERACTIVE ROOF MOUNTED PV SYSTEM.**
Permit Description:	**ELECTRICAL PERMIT**
Work Class:	
Proposed Use:	
Permit Number:	E201004086603
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	OCCIDENTAL POWER

TARGET PROPERTY FINDINGS

Date:	**3/23/1992**
Permit Type:	
Description:	**REMOVE AND REPLACE TWELVE WINDOWS.**
Permit Description:	
Work Class:	ADDITIONS, ALTERATIONS OR REPAIRS-"I"OCCUPANCY WIT
Proposed Use:	2 FAMILY DWELLING
Permit Number:	9120080
Status:	EXPIRED
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Permits Found

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use(s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3781208.3
November 11, 2013

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

11/11/13

Site Name:
Mission Rock
Pier 48
San Francisco, CA 94158

Client Name:
Baseline Environmental Cons.
5900 Hollis Street
Emeryville, CA 94608

EDR Inquiry # 3781208.3

Contact: Patrick Sutton

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Baseline Environmental Cons. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: Mission Rock
Address: Pier 48
City, State, Zip: San Francisco, CA 94158
Cross Street:
P.O. # NA
Project: Mission Rock
Certification # C30B-4858-8E1F

Maps Provided:

1999	1950
1990	1949
1988	1913
1984	1899
1974	1887
1970	

Sanborn® Library search results
Certification # C30B-4858-8E1F

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Baseline Environmental Cons. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1999 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1990 Source Sheets



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1988 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1984 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1974 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1970 Source Sheets



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1950 Source Sheets

Volume 1, Sheet xxxx



Volume 2, Sheet 212



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1949 Source Sheets



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

1913 Source Sheets



Volume 2, Sheet 217



Volume 2, Sheet 221



Volume 2, Sheet 222

Volume 1, Sheet xxxx

1899 Source Sheets



Volume 2, Sheet 232

1887 Source Sheets



Volume 1, Sheet 27

Volume 1, Sheet 27

1999 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1999

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

1990 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1990

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

1988 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification #: C30B-4858-8E1F
Copyright: 1988

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

1984 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1984

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

N

1974 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

N

1970 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1970



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1950 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1950

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet xxxx
Volume 2, Sheet 212
Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1949 Certified Sanborn Map



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1913 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1913

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

C30B-4858-8E1F

Certification #

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 2, Sheet 217
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 1, Sheet xxxx

N

1899 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1899



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 232

0 Feet 165 330 660

N

1887 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48

City, ST, ZIP: San Francisco CA 94158

Client: Baseline Environmental Cons.

EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F

Copyright: 1887



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 27
Volume 1, Sheet 27

0 Feet 165 330 660

N

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3781208.3
November 11, 2013

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

11/11/13

Site Name:
Mission Rock
Pier 48
San Francisco, CA 94158

Client Name:
Baseline Environmental Cons.
5900 Hollis Street
Emeryville, CA 94608

EDR Inquiry # 3781208.3

Contact: Patrick Sutton

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Baseline Environmental Cons. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: Mission Rock
Address: Pier 48
City, State, Zip: San Francisco, CA 94158
Cross Street:
P.O. # NA
Project: Mission Rock
Certification # C30B-4858-8E1F

Maps Provided:

1999	1950
1990	1949
1988	1913
1984	
1974	
1970	

Sanborn® Library search results
Certification # C30B-4858-8E1F

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Baseline Environmental Cons. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1999 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 221

1990 Source Sheets



Volume 2, Sheet 221

1988 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 221

1984 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 221



Volume 2, Sheet 222

1974 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 221

1970 Source Sheets



Volume 2, Sheet 221

1950 Source Sheets

Volume 1, Sheet xxxx

Volume 2, Sheet 212



Volume 2, Sheet 221

1949 Source Sheets



Volume 2, Sheet 221

1913 Source Sheets



Volume 2, Sheet 221



Volume 2, Sheet 222

Volume 1, Sheet xxxx

1999 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1999

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 221

N

1990 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1990



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 2, Sheet 221

0 Feet 165 330 660

N

1988 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1988

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 221

N

1984 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1984

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 212
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1974 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1974

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.



Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 212
Volume 2, Sheet 221

0 Feet 165 330 660

N

1970 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1970



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 221

0 Feet 165 330 660

N

1950 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1950

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F



This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet xxxx
Volume 2, Sheet 212
Volume 2, Sheet 221

0 Feet 165 330 660

N

1949 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1949



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660





Volume 2, Sheet 221

N

1913 Certified Sanborn Map

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1913



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 1, Sheet xxxx

0 Feet 165 330 660

N

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3781208.3
November 11, 2013

Certified Sanborn® Map Report

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

11/11/13

Site Name:
Mission Rock
Pier 48
San Francisco, CA 94158

Client Name:
Baseline Environmental Cons.
5900 Hollis Street
Emeryville, CA 94608

EDR Inquiry # 3781208.3

Contact: Patrick Sutton

EDR® Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Baseline Environmental Cons. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

Certified Sanborn Results:

Site Name: Mission Rock
Address: Pier 48
City, State, Zip: San Francisco, CA 94158
Cross Street:
P.O. # NA
Project: Mission Rock
Certification # C30B-4858-8E1F

Maps Provided:

1999	1950
1990	1949
1988	1913
1984	1899
1974	1887
1970	

Sanborn® Library search results
Certification # C30B-4858-8E1F

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Baseline Environmental Cons. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1999 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222



Volume 2, Sheet 223

1990 Source Sheets



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222



Volume 2, Sheet 223

1988 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222



Volume 2, Sheet 223

1984 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222



Volume 2, Sheet 223

1974 Source Sheets



Volume 2, Sheet 212



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221

Volume 2, Sheet 222



Volume 2, Sheet 223

1970 Source Sheets



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222

1950 Source Sheets

Volume 1, Sheet xxxx



Volume 2, Sheet 212

Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220

Volume 2, Sheet 221



Volume 2, Sheet 222



Volume 2, Sheet 223

1949 Source Sheets



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222

1913 Source Sheets



Volume 2, Sheet 216



Volume 2, Sheet 217



Volume 2, Sheet 220



Volume 2, Sheet 221



Volume 2, Sheet 222

Volume 1, Sheet xxxx

1899 Source Sheets



Volume 2, Sheet 228



Volume 2, Sheet 230



Volume 2, Sheet 232

1887 Source Sheets



Volume 1, Sheet 27

Volume 1, Sheet 27

1999 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1999

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

1990 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

N

1988 Certified Sanborn Map

The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1988

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

N

1984 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1984

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

N

1974 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1974

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 212
Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

N

1970 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1970

This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection.

Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1950 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 1, Sheet xxxx
Volume 2, Sheet 212
Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222
Volume 2, Sheet 223

N

1949 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1949

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222

0 Feet 165 330 660

N

1913 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1913

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 2, Sheet 216
Volume 2, Sheet 217
Volume 2, Sheet 220
Volume 2, Sheet 221
Volume 2, Sheet 222

Volume 1, Sheet xxxx

1899 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name:	Mission Rock
Address:	Pier 48
City, ST, ZIP:	San Francisco CA 94158
Client:	Baseline Environmental Cons.
EDR Inquiry:	3781208.3
Order Date:	11/11/2013 4:18:00 PM
Certification #	C30B-4858-8E1F
Copyright:	1899

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 2, Sheet 228
Volume 2, Sheet 230
Volume 2, Sheet 232

0 Feet 165 330 660

N

1887 Certified Sanborn Map



The certified Sanborn Library search results in this report can be authenticated by visiting www.ednet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # C30B-4858-8E1F

Site Name: Mission Rock
Address: Pier 48
City, ST, ZIP: San Francisco CA 94158
Client: Baseline Environmental Cons.
EDR Inquiry: 3781208.3
Order Date: 11/11/2013 4:18:00 PM
Certification # C30B-4858-8E1F
Copyright: 1887

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 165 330 660



Volume 1, Sheet 27
Volume 1, Sheet 27

N

APENDIX B

ENVIRONMENTAL DATABASE REPORT

Mission Rock
Pier 48
San Francisco, CA 94158

Inquiry Number: 3781208.2s
November 08, 2013

The EDR Radius Map™ Report with GeoCheck®

EDR® Environmental Data Resources Inc

440 Wheelers Farms Road
Milford, CT 06461
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	492
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-7
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	A-23

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

PIER 48
SAN FRANCISCO, CA 94158

COORDINATES

Latitude (North):	37.7748000 - 37° 46' 29.28''
Longitude (West):	122.3883000 - 122° 23' 17.88''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	553871.1
UTM Y (Meters):	4180800.0
Elevation:	5 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	37122-G4 SAN FRANCISCO NORTH, CA
Most Recent Revision:	1999
East Map:	37122-G3 OAKLAND WEST, CA
Most Recent Revision:	1980

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year:	2012
Source:	USDA

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
PIER 48 PIER 48 SAN FRANCISCO, CA	ERNS	N/A
PIER 48 PIER 48 SAN FRANCISCO, CA	ERNS	N/A
PIER 48 PIER 48 SAN FRANCISCO, CA	ERNS	N/A

EXECUTIVE SUMMARY

PIER 48
PIER 48
SAN FRANCISCO, CA 94107

ERNS

N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

CERCLIS ---------- Comprehensive Environmental Response, Compensation, and Liability Information System
FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal RCRA generators list

RCRA-LQG ---------- RCRA - Large Quantity Generators
RCRA-CESQG ---------- RCRA - Conditionally Exempt Small Quantity Generator

Federal institutional controls / engineering controls registries

US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls
LUCIS ---------- Land Use Control Information System

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Solid Waste Information System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

INDIAN UST ---------- Underground Storage Tanks on Indian Land

FEMA UST ---- Underground Storage Tank Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
HAULERS ---- Registered Waste Tire Haulers Listing
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL ---- Clandestine Drug Labs
SCH ---- School Property Evaluation Program
Toxic Pits ---- Toxic Pits Cleanup Act Sites
CDL ---- Clandestine Drug Labs
US HIST CDL ---- National Clandestine Laboratory Register

Local Land Records

LIENS 2 ---- CERCLA Lien Information
LIENS ---- Environmental Liens Listing

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
CHMIRS ---- California Hazardous Material Incident Report System
LDS ---- Land Disposal Sites Listing
MCS ---- Military Cleanup Sites Listing
SPILLS 90 ---- SPILLS 90 data from FirstSearch

Other Ascertainable Records

DOT OPS ---- Incident and Accident Data
DOD ---- Department of Defense Sites
FUDS ---- Formerly Used Defense Sites
CONSENT ---- Superfund (CERCLA) Consent Decrees
ROD ---- Records Of Decision
UMTRA ---- Uranium Mill Tailings Sites
US MINES ---- Mines Master Index File
TRIS ---- Toxic Chemical Release Inventory System
TSCA ---- Toxic Substances Control Act
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
SSTS ---- Section 7 Tracking Systems
ICIS ---- Integrated Compliance Information System
PADS ---- PCB Activity Database System
MLTS ---- Material Licensing Tracking System

RADINFO	Radiation Information Database
RMP	Risk Management Plans
CA BOND EXP. PLAN	Bond Expenditure Plan
UIC	UIC Listing
NPDES	NPDES Permits Listing
Cortese	"Cortese" Hazardous Waste & Substances Sites List
CUPA Listings	CUPA Resources List
DRYCLEANERS	Cleaner Facilities
WIP	Well Investigation Program Case List
ENF	Enforcement Action Listing
INDIAN RESERV	Indian Reservations
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
HWT	Registered Hazardous Waste Transporter Database
Financial Assurance	Financial Assurance Information Listing
LEAD SMELTERS	Lead Smelter Sites
2020 COR ACTION	2020 Corrective Action Program List
US AIRS	Aerometric Information Retrieval System Facility Subsystem
PRP	Potentially Responsible Parties
WDS	Waste Discharge System
EPA WATCH LIST	EPA WATCH LIST
US FIN ASSUR	Financial Assurance Information
PCB TRANSFORMER	PCB Transformer Registration Database
PROC	Certified Processors Database
MWMP	Medical Waste Management Program Listing

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 04/26/2013 has revealed that there are

2 CERC-NFRAP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
PG&E GAS PLANT SAN FRANCISCO 5	KING & 2ND STS	N 1/8 - 1/4 (0.224 mi.)	L91	165

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 07/11/2013 has revealed that there are 2 CORRACTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
C & M PLATING WORKS	***598 SIXTH ST***	***W 1/2 - 1 (0.615 mi.)***	***AO213***	***403***

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-TSDF list, as provided by EDR, and dated 07/11/2013 has revealed that there is 1 RCRA-TSDF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 07/11/2013 has revealed that there are 6 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
SERVICE ENGINEERING CO	***PIER 50***	***SE 0 - 1/8 (0.024 mi.)***	***B16***	***46***
MV CAPE HUDSON	PIER 50	SE 0 - 1/8 (0.024 mi.)	B17	58

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MAJOR LEGAL SERVICES	***185 BERRY ST***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F31***	***73***
UCSF AT CHINA BASIN LANDING	***185 BERRY ST STE 350***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F36***	***88***
NOW AUTO CENTER AND BODY SHOP	***180 TOWNSEND ST***	***NW 1/8 - 1/4 (0.220 mi.)***	***P84***	***156***

Federal ERNS list

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/2012 has revealed that there are 3 ERNS sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	220 CHINA BASIN ST.	0 - 1/8 (0.000 mi.)	A9	39
Not reported	405 CHINA BASIN	0 - 1/8 (0.000 mi.)	C11	41
Not reported	220 CHINA BASIN ST.	0 - 1/8 (0.000 mi.)	A12	41

State- and tribal - equivalent NPL

RESPONSE: Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

A review of the RESPONSE list, as provided by EDR, and dated 09/05/2013 has revealed that there are 2 RESPONSE sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SITE K (SEAWALL LOT 333)	***1-59&1/2 TOWNSEND STREE***	***N 1/4 - 1/2 (0.341 mi.)***	***137***	***224***
PORT OF SAN FRANCISCO	***PIER 70***	***SSE 1/2 - 1 (0.999 mi.)***	***AR240***	***485***

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 09/05/2013 has revealed that there are 31 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
Status: Active				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUN CHEMICAL CORPORATION #1 Status: No Further Action	252 TOWNSEND ST	NW 1/8 - 1/4 (0.235 mi.)	Q106	177
SAN FRANCISCO IRON FOUNDRY Status: No Further Action	260 TOWNSEND	WNW 1/8 - 1/4 (0.241 mi.)	Q110	182
725 2ND STREET Status: Refer: 1248 Local Agency	725 2ND STREET	NNW 1/4 - 1/2 (0.264 mi.)	R114	185
MARINA VISTA PROJECT Status: Certified / Operation & Maintenance	***725 2ND STREET (75 & 99***	***NNW 1/4 - 1/2 (0.265 mi.)***	***R116***	***186***
SITE K (SEAWALL LOT 333) Status: Certified O&M - Land Use Restrictions Only	***1-59&1/2 TOWNSEND STREE***	***N 1/4 - 1/2 (0.341 mi.)***	***137***	***224***
415 BRYANT STREET Status: Refer: 1248 Local Agency	415 BRYANT STREET	NNW 1/4 - 1/2 (0.475 mi.)	AL196	362
355 BRYANT STREET SITE Status: Refer: Other Agency	***355 BRYANT STREET***	***NNW 1/2 - 1 (0.518 mi.)***	***208***	***393***
NORTH HALF OF MISSISSIPPI STRE Status: Refer: Other Agency	17TH AND MISSISSIPPI ST	SSW 1/2 - 1 (0.595 mi.)	210	396
C & M PLATING WORKS Status: No Further Action Status: Refer: 1248 Local Agency	***598 6TH STREET***	***W 1/2 - 1 (0.615 mi.)***	***AO212***	***399***
FILIPINO EDUCATION CENTER Status: Inactive - Action Required	***824 HARRISON STREET***	***WNW 1/2 - 1 (0.615 mi.)***	***214***	***416***
RUBER, E. G. & SONS Status: Refer: Other Agency	725 18TH	S 1/2 - 1 (0.692 mi.)	217	421
CONSOLIDATED IRON WORKS Status: Certified	***634 TOWNSEND STREET***	***WSW 1/2 - 1 (0.696 mi.)***	***218***	***422***
MCDONALD'S RESTAURANT SITE Status: Certified O&M - Land Use Restrictions Only	***820 BRYANT ST***	***W 1/2 - 1 (0.729 mi.)***	***AP220***	***427***
ROTOMETALS INC Status: No Further Action	980-82 HARRISON	WNW 1/2 - 1 (0.746 mi.)	221	435
858-860 FOLSOM STREET Status: Refer: 1248 Local Agency	***858-860 FOLSOM STREET***	***WNW 1/2 - 1 (0.747 mi.)***	***222***	***436***
ELECTRICAL SHOP Status: Refer: Other Agency	528 FOLSOM	NNW 1/2 - 1 (0.750 mi.)	223	438
COLOR III LAB, INC. Status: Inactive - Needs Evaluation	560 19TH STREET	S 1/2 - 1 (0.773 mi.)	224	439
1717 17TH ST. Status: Refer: 1248 Local Agency	1717 17TH ST.	SW 1/2 - 1 (0.832 mi.)	225	440
1601 MARIPOSA STREET Status: Active	***1601 MARIPOSA STREET***	***SW 1/2 - 1 (0.845 mi.)***	***226***	***441***
436-438 CLEMENTINA STREET Status: Refer: 1248 Local Agency	436-438 CLEMENTINA STRE	WNW 1/2 - 1 (0.850 mi.)	227	444
SKS INVESTMENTS Status: Refer: 1248 Local Agency	***350 RHODE ISLAND STREET***	***SW 1/2 - 1 (0.887 mi.)***	***AQ230***	***446***
DEHARO/RHODE ISLAND LIVE/WORK Status: Certified O&M - Land Use Restrictions Only	***BETWEEN 17TH/DEHARO & 1***	***SW 1/2 - 1 (0.904 mi.)***	***AQ231***	***450***
199 FREMONT PROPERTY Status: Refer: Other Agency	***199 FREMONT STREET***	***NNW 1/2 - 1 (0.914 mi.)***	***232***	***456***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
241 SIXTH STREET	***241 6TH STREET***	***WNW 1/2 - 1 (0.927 mi.)***	***233***	***459***
Status: Certified / Operation & Maintenance				
PIONEER SOAP CO. INC.	470 CAROLINA ST.	SW 1/2 - 1 (0.927 mi.)	234	468
Status: Refer: Other Agency				
BESSIE CARMICHAEL ELEMENTARY S	***355/375 7TH STREET***	***W 1/2 - 1 (0.930 mi.)***	***235***	***469***
Status: No Further Action				
FORMER S & C FORD	***450 RHODE ISLAND STREET***	***SW 1/2 - 1 (0.938 mi.)***	***237***	***474***
Status: Refer: Other Agency				
CALIFORNIA HIGHWAY PATROL, SAN	***455 EIGHT STREET***	***W 1/2 - 1 (0.960 mi.)***	***238***	***476***
Status: Certified / Operation & Maintenance				
1028 HOWARD STREET	***1028 HOWARD***	***WNW 1/2 - 1 (0.993 mi.)***	***239***	***483***
Status: Refer: Other Agency				
PORT OF SAN FRANCISCO	***PIER 70***	***SSE 1/2 - 1 (0.999 mi.)***	***AR240***	***485***
Status: Certified				

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 09/16/2013 has revealed that there are 95 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMMERCIAL	CENTRAL SUBWAY SFMTA PR	SW 0 - 1/8 (0.112 mi.)	28	69
Status: Completed - Case Closed				
LEVEL 3 COMMUNICATIONS	***185 BERRY STREET***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F35***	***82***
CHINA BASIN PROPERTIES	***185 BERRY STREET***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F39***	***93***
Status: Completed - Case Closed				
CONSTRUCTION DEVELOPMENT	160 KING ST.	NNW 1/8 - 1/4 (0.166 mi.)	G43	97
Status: Completed - Case Closed				
CONSTRUCTION	160 KING ST.	NNW 1/8 - 1/4 (0.166 mi.)	G46	100
ARES COMMERCIAL PROPERTIES	1501 03RD ST	S 1/8 - 1/4 (0.190 mi.)	54	112
Status: Completed - Case Closed				
UNKNOWN	***1289 2ND ST***	***N 1/8 - 1/4 (0.192 mi.)***	***L58***	***118***
Status: Completed - Case Closed				
GOLDEN BRANDS BOTTLING CO., IN	***255 CHANNEL ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***N63***	***123***
Status: Completed - Case Closed				
SANTA FE PACIFIC REALTY C	***1301 6TH***	***SW 1/8 - 1/4 (0.202 mi.)***	***O64***	***128***
Status: Completed - Case Closed				
MC DONALD'S CORP	701 03RD ST	NW 1/8 - 1/4 (0.209 mi.)	P67	132
Status: Completed - Case Closed				
WESTWIND AUTOMOTIVE	***178 TOWNSEND***	***NW 1/8 - 1/4 (0.220 mi.)***	***P80***	***148***
Status: Completed - Case Closed				
RESIDENTIAL	360 RITCH	NW 1/8 - 1/4 (0.222 mi.)	P87	160

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RESIDENTIAL APARTMENT Status: Completed - Case Closed	360 RITCH	NW 1/8 - 1/4 (0.222 mi.)	P89	163
WEST COAST SHIP CHANDLERS Status: Completed - Case Closed	***164 TOWNSEND***	***NNW 1/8 - 1/4 (0.227 mi.)***	***S100***	***171***
COMMERCIAL DEVELOPMENT PROPERT Status: Completed - Case Closed	235 BERRY STREET	W 1/8 - 1/4 (0.239 mi.)	M107	178
COMMERCIAL ***COMMERCIAL*** Status: Completed - Case Closed	101 TOWNSEND STREET ***101 TOWNSEND***	NNW 1/4 - 1/2 (0.275 mi.) ***NNW 1/4 - 1/2 (0.275 mi.)***	T117 ***T118***	193 ***195***
COMMERCIAL Status: Completed - Case Closed	630 3RD ST	NW 1/4 - 1/2 (0.288 mi.)	U120	197
COMMERCIAL PROPERTY ZELLERBACH FAMILY FUND Status: Completed - Case Closed	630 3RD ST 630 03RD ST	NW 1/4 - 1/2 (0.288 mi.) NW 1/4 - 1/2 (0.288 mi.)	U121 U122	199 200
COMMERCIAL PROPERTY Status: Completed - Case Closed	322-326 RITCH ST	NW 1/4 - 1/2 (0.290 mi.)	U123	203
SOUTHERN PACIFIC TRANSPOR Status: Completed - Case Closed	***329 TOWNSEND***	***WNW 1/4 - 1/2 (0.309 mi.)***	***V125***	***206***
MISSION BAY PARCEL 24 Status: Completed - Case Closed	***1600 6TH***	***SW 1/4 - 1/2 (0.318 mi.)***	***W126***	***209***
COMMERCIAL COMMERCIAL BUILDING Status: Completed - Case Closed	35 STANFORD ST. 35 STANFORD ST.	NNW 1/4 - 1/2 (0.321 mi.) NNW 1/4 - 1/2 (0.321 mi.)	X127 X128	211 212
COMMERCIAL COMMERCIAL Status: Completed - Case Closed	64-72 TOWNSEND STREET 64-72 TOWNSEND STREET	NNW 1/4 - 1/2 (0.322 mi.) NNW 1/4 - 1/2 (0.322 mi.)	T131 T132	214 216
SFFD PUMPING STATION Status: Completed - Case Closed	698 02ND ST.	S 1/4 - 1/2 (0.333 mi.)	Y133	217
COMMERCIAL PROPERTY Status: Completed - Case Closed	330 TOWNSEND ST	WNW 1/4 - 1/2 (0.334 mi.)	V134	221
ROSENMAYER PROPERTY ***ROSENMAYER PROPERTY*** Status: Completed - Case Closed	350 BRANNAN STREET ***350 BRANNAN STREET***	NNW 1/4 - 1/2 (0.346 mi.) ***NNW 1/4 - 1/2 (0.346 mi.)***	Z138 ***Z139***	233 ***235***
COMMERCIAL PROPERTY Status: Completed - Case Closed	680 02ND ST	NNW 1/4 - 1/2 (0.353 mi.)	X140	236
PACIFIC MOTOR TURCKING CO ***JACKSON H E & CO#*** Status: Completed - Case Closed	***1355 6TH STREET*** ***334 BRANNAN ST***	***SW 1/4 - 1/2 (0.354 mi.)*** ***NNW 1/4 - 1/2 (0.354 mi.)***	***W141*** ***X142***	***239*** ***243***
H.E. JACKSON CO. CCSF - PORT OF SAN FRANCISCO ***CCSF - PORT OF SAN FRANCISCO*** Status: Completed - Case Closed	334 BRANNAN STREET 333 ILLINOIS STREET ***333 ILLINOIS STREET***	NNW 1/4 - 1/2 (0.354 mi.) S 1/4 - 1/2 (0.363 mi.) ***S 1/4 - 1/2 (0.363 mi.)***	X143 Y144 ***Y145***	246 247 ***249***
SANTA FE PACIFIC REALTY C Status: Completed - Case Closed	***1201 6TH***	***SW 1/4 - 1/2 (0.365 mi.)***	***146***	***251***
WELLS FARGO BANK PROPERTY Status: Completed - Case Closed	***490 BRANNAN***	***WNW 1/4 - 1/2 (0.370 mi.)***	***AA147***	***253***
PEARSON EQUIPMENT CO (FORMER) Status: Completed - Case Closed	1400 06TH ST	SSW 1/4 - 1/2 (0.372 mi.)	148	256

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COMMERCIAL	***444 NATOMA ST***	***W 1/4 - 1/2 (0.373 mi.)***	***AB149***	***258***
Status: Completed - Case Closed				
COMMERCIAL	370 TOWNSEND ST	W 1/4 - 1/2 (0.374 mi.)	AB150	262
PARKING LOT	599 03RD ST.	NW 1/4 - 1/2 (0.375 mi.)	AC151	264
Status: Completed - Case Closed				
HEUBLEIN, INC.	601 04TH ST.	WNW 1/4 - 1/2 (0.376 mi.)	AA153	267
Status: Open - Eligible for Closure				
SHELL BRANDED GASOLINE STATION	551 03RD STREET	NW 1/4 - 1/2 (0.383 mi.)	AC154	271
Status: Open - Site Assessment				
GEORGE LITHOGRAPH	650 02ND ST	NNW 1/4 - 1/2 (0.385 mi.)	AD155	272
Status: Completed - Case Closed				
BRANNAN STREET AUTO REPAIR	518 BRANNAN STREET	WNW 1/4 - 1/2 (0.394 mi.)	AA158	277
Status: Completed - Case Closed				
THIRD STREET SHELL	***551 03RD ST***	***NW 1/4 - 1/2 (0.395 mi.)***	***AC159***	***279***
Status: Completed - Case Closed				
CHARLES O. JONES, INC.	49 ZOE STREET	NW 1/4 - 1/2 (0.399 mi.)	AF161	290
CHARLES O JONES INC	***49 ZOE***	***NW 1/4 - 1/2 (0.399 mi.)***	***AF162***	***292***
Status: Completed - Case Closed				
COMMERCIAL PROPERTY	33-35 SOUTH PARK	NNW 1/4 - 1/2 (0.403 mi.)	163	294
Status: Completed - Case Closed				
RINGROSE CORPORATION	***275 BRANNAN ST***	***NNW 1/4 - 1/2 (0.405 mi.)***	***AG164***	***295***
Status: Completed - Case Closed				
TAYLOR PROPERTY	***150 PARK***	***NW 1/4 - 1/2 (0.405 mi.)***	***AC165***	***299***
Status: Completed - Case Closed				
CATELLUS DEVELOPMENT CORP.	1600 06TH ST	SSW 1/4 - 1/2 (0.407 mi.)	166	302
Status: Completed - Case Closed				
COMMERCIAL PROPERTY	77 BLUXOME ST	WNW 1/4 - 1/2 (0.408 mi.)	AB167	305
Status: Completed - Case Closed				
3RD STREET LIGHT RAIL PROJECT	3RD STREET & 16TH STREE	S 1/4 - 1/2 (0.410 mi.)	AH169	308
Status: Completed - Case Closed				
COMMERCIAL BUILDING	542 BRANNAN STREET	WNW 1/4 - 1/2 (0.413 mi.)	AI170	310
SAN PACIFIC IMPORTS, INC.	***530 BRANNAN ST***	***WNW 1/4 - 1/2 (0.413 mi.)***	***AI171***	***311***
Status: Completed - Case Closed				
AUTO REPAIR & AUTO PARK	***529 3RD***	***NW 1/4 - 1/2 (0.414 mi.)***	***AC172***	***316***
Status: Completed - Case Closed				
KAISER SAND & GRAVEL	***300 16TH***	***S 1/4 - 1/2 (0.415 mi.)***	***AH173***	***319***
Status: Completed - Case Closed				
CARRARO PROPERTY	***1800 03RD ST***	***S 1/4 - 1/2 (0.419 mi.)***	***AH175***	***323***
Status: Completed - Case Closed				
3RD STREET LIGHT RAIL PROJECT	3RD STREET & 16TH STREE	S 1/4 - 1/2 (0.419 mi.)	AH176	326
Status: Completed - Case Closed				
COMMERCIAL PROPERTY	557 04TH ST.	WNW 1/4 - 1/2 (0.427 mi.)	177	327
Status: Completed - Case Closed				
WASHINGTON SPORTSWEAR, INC.	ONE SOUTH PARK AVE	NNW 1/4 - 1/2 (0.429 mi.)	AD178	331
Status: Completed - Case Closed				
WASHINGTON	1 SOUTH PARK AVE	NNW 1/4 - 1/2 (0.429 mi.)	AD179	332
SF RDVLOPMNT AGNCY #K	***1 59.5 TOWNSEND ST***	***N 1/4 - 1/2 (0.432 mi.)***	***180***	***334***
Status: Completed - Case Closed				

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LNR-LANNAR BRANNAN, LLC	***250 BRANNAN ST***	***NNW 1/4 - 1/2 (0.435 mi.)***	***AG181***	***335***
Status: Completed - Case Closed				
GALLO SALAME	***250 BRANNAN ST***	***NNW 1/4 - 1/2 (0.435 mi.)***	***AG182***	***338***
COMMERCIAL PROPERTY	501 3RD ST	NW 1/4 - 1/2 (0.455 mi.)	AJ185	345
Status: Completed - Case Closed				
COMMERCIAL	500 3RD STREET	NW 1/4 - 1/2 (0.455 mi.)	AJ186	346
Status: Completed - Case Closed				
PAUL SHEEL METAL WORK	***474 BRYANT***	***NW 1/4 - 1/2 (0.455 mi.)***	***AJ187***	***348***
Status: Completed - Case Closed				
PAUL SHEET METAL WORK	474 BRYANT STREET	NW 1/4 - 1/2 (0.455 mi.)	AJ188	350
MERLE HORN ET AL., PROPERTY	***510 BRYANT STREET***	***NW 1/4 - 1/2 (0.457 mi.)***	***AJ189***	***351***
Status: Completed - Case Closed				
MERLE HORN ET AL., PROPERTY	510 BRYANT STREET	NW 1/4 - 1/2 (0.457 mi.)	AJ190	353
COMMERCIAL PROPERTY	***542 BRANNAN***	***NW 1/4 - 1/2 (0.461 mi.)***	***AK191***	***354***
Status: Completed - Case Closed				
COMMERCIAL PROPERTY	535 BRYANT STREET	NW 1/4 - 1/2 (0.461 mi.)	AK192	356
COMMERCIAL PROPERTY	***535 BRYANT STREET***	***NW 1/4 - 1/2 (0.461 mi.)***	***AK193***	***358***
Status: Completed - Case Closed				
CHROME WORKS	425 BRYANT STREET	NNW 1/4 - 1/2 (0.470 mi.)	AL194	359
CHROME WORKS	***425 BRYANT STREET***	***NNW 1/4 - 1/2 (0.470 mi.)***	***AL195***	***361***
Status: Completed - Case Closed				
SUPER SHUTTLE	***700 16TH ST***	***SSW 1/4 - 1/2 (0.479 mi.)***	***197***	***363***
Status: Completed - Case Closed				
FERRO & VERNAZZA PROPERTY	***601 BRANNAN STREET***	***WNW 1/4 - 1/2 (0.480 mi.)***	***AM198***	***368***
FERRO & VERNAZZA PROPERTY	601 BRANNAN STREET	WNW 1/4 - 1/2 (0.480 mi.)	AM199	370
Status: Completed - Case Closed				
SAN FRANCISCO NEWSPAPER AGENCY	***590 BRANNAN ST***	***WNW 1/4 - 1/2 (0.483 mi.)***	***AM200***	***371***
Status: Open - Remediation				
CHAVO'S RESTAURANT	595 BRYANT ST	WNW 1/4 - 1/2 (0.483 mi.)	AN201	378
Status: Completed - Case Closed				
BANK OF AMERICA AUTO REPAIR	420 04TH ST.	WNW 1/4 - 1/2 (0.484 mi.)	AN202	381
Status: Completed - Case Closed				
SHELL STATION #8202	598 BRYANT STREET	WNW 1/4 - 1/2 (0.488 mi.)	AN203	384
RETAIL SHELL SERVICE STATION	***598 BRYANT***	***WNW 1/4 - 1/2 (0.488 mi.)***	***AN205***	***387***
Status: Completed - Case Closed				
CHEVRON STATION #9-0294	1200 07TH AVE	SW 1/4 - 1/2 (0.490 mi.)	206	388
Status: Completed - Case Closed				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SAN FRANCISCO PORT OF	***145 CHINA BASIN***	***0 - 1/8 (0.000 mi.)***	***C6***	***9***
Status: Completed - Case Closed				
CCSF - PORT OF SAN FRANCISCO	145 CHINA BASIN STREET	0 - 1/8 (0.000 mi.)	C13	41
SOUTHERN PACIFIC TRANSPORTATIO	***415 CHANNEL ST***	***WSW 1/8 - 1/4 (0.182 mi.)***	***K52***	***107***
Status: Completed - Case Closed				
SANTA FE PACIFIC REALTY CORP	195 CHANNEL ST	WSW 1/8 - 1/4 (0.191 mi.)	K56	115
Status: Completed - Case Closed				
SANTA FE PACIFIC REALTY CORP	195 CHANNEL ST	WSW 1/8 - 1/4 (0.219 mi.)	K75	140
SANTA FE PACIFIC REALTY C	***205 CHANNEL***	***WSW 1/4 - 1/2 (0.385 mi.)***	***AE156***	***275***
Status: Completed - Case Closed				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC MOTOR TRUCKIN	***1355 6TH ST***	***WSW 1/4 - 1/2 (0.408 mi.)***	***168***	***307***
Status: Completed - Case Closed				

SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, and dated 09/16/2013 has revealed that there are 5 SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PAC BELL PARK	CROSS TOWNSEND AND 2ND	NNW 0 - 1/8 (0.123 mi.)	29	71
Facility Status: Completed - Case Closed				
PG & E	UNKNOWN KING & 2ND ST	NNW 1/8 - 1/4 (0.226 mi.)	R95	166
Facility Status: Open - Inactive				
RINCON POINT SOUTH BEACH	UNKNOWN UNKNOWN	N 1/4 - 1/2 (0.339 mi.)	136	223
Facility Status: Open - Inactive				
PIER 64/MISSION BAY	VICINITY OF PIER 64	SSE 1/4 - 1/2 (0.441 mi.)	183	342
Facility Status: Open - Remediation				

Lower Elevation	Address	Direction / Distance	Map ID	Page
MISSION BAY REDEVELOPMENT AREA	MISSION BAY DEVELOPMENT	W 1/8 - 1/4 (0.199 mi.)	M60	120
Facility Status: Open - Site Assessment				

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, and dated 09/16/2013 has revealed that there are 20 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
PIER 50 GEAR	300 CHINA BASIN ST	SSE 0 - 1/8 (0.010 mi.)	B15	44
SPRINT, CHINA	185 BERRY ST	WNW 1/8 - 1/4 (0.126 mi.)	F33	75
GTE SPRINT, CHINA BASIN	185 BERRY ST FL 6	WNW 1/8 - 1/4 (0.126 mi.)	F34	81
ROSENBERG HOOD	160 KING ST	NNW 1/8 - 1/4 (0.166 mi.)	G44	99
GOLDEN BRANDS	255 CHANNEL ST	WSW 1/8 - 1/4 (0.200 mi.)	N61	120
SITE DEVELOPMENT	200 TOWNSEND ST	NW 1/8 - 1/4 (0.216 mi.)	P71	136
PEER LIGHT CO.	179 TOWNSEND ST	NW 1/8 - 1/4 (0.219 mi.)	P73	137
NGOW AUTO CENTER &	177 TOWNSEND ST	NW 1/8 - 1/4 (0.220 mi.)	P77	142
178 TOWNSEND ST	178 TOWNSEND ST	NW 1/8 - 1/4 (0.220 mi.)	P78	143
WEST WINDS	178 TOWNSEND ST	NW 1/8 - 1/4 (0.220 mi.)	P81	152
NOW AUTO CENTER &	180 TOWNSEND ST	NW 1/8 - 1/4 (0.220 mi.)	P83	154
360 RITCH ST	360 RITCH ST	NW 1/8 - 1/4 (0.222 mi.)	P88	161
CCSF/PURCHASING/CENTRAL SHOPS	100 KING ST	NNW 1/8 - 1/4 (0.226 mi.)	R96	167
WEST COAST SHIP	164 TOWNSEND ST	NNW 1/8 - 1/4 (0.227 mi.)	S98	168
LINCOLN PROPERTY	155 TOWNSEND ST	NNW 1/8 - 1/4 (0.228 mi.)	S102	175

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DEVCON (CONST	235 BERRY ST	W 1/8 - 1/4 (0.239 mi.)	M108	180
CIRCLE PLAZA	260 TOWNSEND ST	WNW 1/8 - 1/4 (0.241 mi.)	Q112	183

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC	415 CHANNEL ST	WSW 1/8 - 1/4 (0.182 mi.)	K51	105
CATELLUS	195 CHANNEL ST	WSW 1/8 - 1/4 (0.191 mi.)	K57	116

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, and dated 08/01/2009 has revealed that there is 1 AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN FRANCISCO AIRPORT JUNCTION	***NORTH ACCESS RD.***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F30***	***71***

State and tribal voluntary cleanup sites

VCP: Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

A review of the VCP list, as provided by EDR, and dated 09/05/2013 has revealed that there is 1 VCP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARINA VISTA PROJECT	***725 2ND STREET (75 & 99***	***NNW 1/4 - 1/2 (0.265 mi.)***	***R116***	***186***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 06/24/2013 has revealed that there are 3 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MISSION BAY, PARK P16 MITIGATI	MISSION BAY BLVD./TERRY	SSE 1/8 - 1/4 (0.181 mi.)	H50	104
TOWNSEND	***178 TOWNSEND STREET***	***NW 1/8 - 1/4 (0.220 mi.)***	***P79***	***145***
MISSION BAY P10	1600 OWENS ST	SW 1/4 - 1/2 (0.452 mi.)	184	343

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: The Waste Management Unit Database System is used for program tracking and inventory of waste management units. The source is the State Water Resources Control Board.

A review of the WMUDS/SWAT list, as provided by EDR, and dated 04/01/2000 has revealed that there are 2 WMUDS/SWAT sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SAN FRANCISCO AIRPORT JUNCTION	***NORTH ACCESS RD.***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F30***	***71***
COMMERCIAL	***444 NATOMA ST***	***W 1/4 - 1/2 (0.373 mi.)***	***AB149***	***258***

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 09/16/2013 has revealed that there is 1 SWRCY site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEXCYCLE	298 KING ST	WNW 1/8 - 1/4 (0.225 mi.)	93	166

Local Lists of Hazardous waste / Contaminated Sites

HIST Cal-Sites: Formerly known as ASPIS, this database contains both known and potential hazardous substance sites. The source is the California Department of Toxic Substance Control. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

A review of the HIST Cal-Sites list, as provided by EDR, and dated 08/08/2005 has revealed that there are 3 HIST Cal-Sites sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SITE K (SEAWALL LOT 333)	***1-59&1/2 TOWNSEND STREE***	***N 1/4 - 1/2 (0.341 mi.)***	***137***	***224***
CONSOLIDATED IRON WORKS	***634 TOWNSEND STREET***	***WSW 1/2 - 1 (0.696 mi.)***	***218***	***422***
PORT OF SAN FRANCISCO	***PIER 70***	***SSE 1/2 - 1 (0.999 mi.)***	***AR240***	***485***

Local Lists of Registered Storage Tanks

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 15 CA FID UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
PIER 50 GEAR ROOM-STEVEDORING	***300 CHINA BASIN ST***	***SSE 0 - 1/8 (0.010 mi.)***	***B14***	***43***
SF AUTO CENTER INC.	***1420 4TH ST***	***SW 0 - 1/8 (0.038 mi.)***	***D18***	***62***
****SFFD/FIRE STATION #30***	***1300 4TH ST***	***WSW 0 - 1/8 (0.056 mi.)***	***D21***	***65***
VACANT	***1401 3RD ST***	***SSW 0 - 1/8 (0.090 mi.)***	***24***	***67***
GTE SPRINT, CHINA BASIN	***185 BERRY ST***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F32***	***74***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARES COMMERCIAL PROPERTIES	***1501 3RD ST***	***S 1/8 - 1/4 (0.174 mi.)***	***J49***	***102***
GOLDEN BRANDS BOTTLING CO. INC	***255 CHANNEL ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***N62***	***122***
SOUTHERN PACIFIC DEVELOPMENT	***1301 6TH ST***	***SW 1/8 - 1/4 (0.202 mi.)***	***O66***	***130***
NGOW AUTO CENTER & BODY	***177 TOWNSEND ST***	***NW 1/8 - 1/4 (0.220 mi.)***	***P76***	***141***
WEST COAST SHIP CHANDLERS INC.	***164 TOWNSEND ST***	***NNW 1/8 - 1/4 (0.227 mi.)***	***S99***	***169***
LINCOLN PROPERTY COMPANY	***155 TOWNSEND ST***	***NNW 1/8 - 1/4 (0.228 mi.)***	***S101***	***174***
A.R.A. SERVICES	***1400 6TH ST***	***SW 1/8 - 1/4 (0.241 mi.)***	***O109***	***181***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC TRANSPORT.	***415 CHANNEL ST***	***WSW 1/8 - 1/4 (0.182 mi.)***	***K53***	***111***
WESCAR FREIGHT, INC	***195 CHANNEL ST***	***WSW 1/8 - 1/4 (0.219 mi.)***	***K74***	***139***

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 10 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
ROBERTSON DRAYAGE CO., INC.	1420 4TH ST	SW 0 - 1/8 (0.038 mi.)	D19	63
FIRE STATION #30	1300 4TH ST	WSW 0 - 1/8 (0.056 mi.)	D20	64
SAN FRANCISCO AIRPORT JUNCTION	***NORTH ACCESS RD.***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F30***	***71***
CHINA BASIN TOC "SFS"	185 BERRY ST BLDG 4SUIT	WNW 1/8 - 1/4 (0.126 mi.)	F38	92
PIER 50 GEAR ROOM	300 CHINA BASIN	SSE 1/8 - 1/4 (0.157 mi.)	H42	97
GOLDEN BRANDS BOTTLING CO., IN	***255 CHANNEL ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***N63***	***123***
ROMEO DRAYAGE & WAREHOUSING CO	1301 6TH ST	SW 1/8 - 1/4 (0.202 mi.)	O65	130
WEST COAST SHIP CHANDLERS	164 TOWNSEND ST	NNW 1/8 - 1/4 (0.227 mi.)	S97	167

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC TRANSPORTATIO	***415 CHANNEL ST***	***WSW 1/8 - 1/4 (0.182 mi.)***	***K52***	***107***

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 16 SWEEPS UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
PIER 50 GEAR ROOM-STEVEDORING	***300 CHINA BASIN ST***	***SSE 0 - 1/8 (0.010 mi.)***	***B14***	***43***
SF AUTO CENTER INC.	***1420 4TH ST***	***SW 0 - 1/8 (0.038 mi.)***	***D18***	***62***
****SFFD/FIRE STATION #30***	***1300 4TH ST***	***WSW 0 - 1/8 (0.056 mi.)***	***D21***	***65***
VACANT	***1401 3RD ST***	***SSW 0 - 1/8 (0.090 mi.)***	***24***	***67***
GTE SPRINT, CHINA BASIN	***185 BERRY ST***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F32***	***74***
CHINA BASIN PROPERTIES	***185 BERRY STREET***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F39***	***93***
ARES COMMERCIAL PROPERTIES	***1501 3RD ST***	***S 1/8 - 1/4 (0.174 mi.)***	***J49***	***102***
GOLDEN BRANDS BOTTLING CO. INC	***255 CHANNEL ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***N62***	***122***
SOUTHERN PACIFIC DEVELOPMENT	***1301 6TH ST***	***SW 1/8 - 1/4 (0.202 mi.)***	***O66***	***130***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NGOW AUTO CENTER & BODY	*177 TOWNSEND ST*	*NW 1/8 - 1/4 (0.220 mi.)*	*P76*	*141*
WEST COAST SHIP CHANDLERS INC.	*164 TOWNSEND ST*	*NNW 1/8 - 1/4 (0.227 mi.)*	*S99*	*169*
LINCOLN PROPERTY COMPANY	*155 TOWNSEND ST*	*NNW 1/8 - 1/4 (0.228 mi.)*	*S101*	*174*
A.R.A. SERVICES	*1400 6TH ST*	*SW 1/8 - 1/4 (0.241 mi.)*	*O109*	*181*

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTHERN PACIFIC TRANSPORT.	*415 CHANNEL ST*	*WSW 1/8 - 1/4 (0.182 mi.)*	*K53*	*111*
WESCAR FREIGHT, INC	*195 CHANNEL ST*	*WSW 1/8 - 1/4 (0.219 mi.)*	*K74*	*139*

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 09/11/2013 has revealed that there are 3 DEED sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	*220 CHINA BASIN ST.*	*0 - 1/8 (0.000 mi.)*	*A8*	*11*
MARINA VISTA PROJECT	*725 2ND STREET (75 & 99*	*NNW 1/4 - 1/2 (0.265 mi.)*	*R116*	*186*
SITE K (SEAWALL LOT 333)	*1-59&1/2 TOWNSEND STREE*	*N 1/4 - 1/2 (0.341 mi.)*	*137*	*224*

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 07/11/2013 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MANHOLE 5276	INTERSECTION OF 3RD	NW 0 - 1/8 (0.087 mi.)	E23	66
D R EXCAVATING AND TRUCKING	*185 BERRY ST*	*WNW 1/8 - 1/4 (0.126 mi.)*	*F37*	*91*
AVALON BAY MISSION BAY PROJECT	*4TH ST AND BERRY ST*	*WNW 1/8 - 1/4 (0.190 mi.)*	*I55*	*114*

Lower Elevation	Address	Direction / Distance	Map ID	Page
C C S F PORT OF SF	PIER 46	NNE 1/8 - 1/4 (0.139 mi.)	40	95

EXECUTIVE SUMMARY

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 03/08/2013 has revealed that there is 1 FINDS site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE CO	220 CHINA BASIN ST	0 - 1/8 (0.000 mi.)	A7	11

RAATS: The RCRA Administration Action Tracking System contains records based on enforcement actions issued under RCRA and pertaining to major violators. It includes administrative and civil actions brought by the United States Environmental Protection Agency. The source of this database is the U.S. EPA.

A review of the RAATS list, as provided by EDR, and dated 04/17/1995 has revealed that there is 1 RAATS site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 51 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHINA BASIN PROPERTIES	***185 BERRY STREET***	***WNW 1/8 - 1/4 (0.126 mi.)***	***F39***	***93***
SCCSD EAST CLIFF PUMP STA	160 KING	NNW 1/8 - 1/4 (0.166 mi.)	G45	100
ARES COMMERCIAL	1501 3RD	S 1/8 - 1/4 (0.174 mi.)	J48	102
UNKNOWN	***1289 2ND ST***	***N 1/8 - 1/4 (0.192 mi.)***	***L58***	***118***
GOLDEN BRANDS BOTTLING CO., IN	***255 CHANNEL ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***N63***	***123***
SANTA FE PACIFIC REALTY C	***1301 6TH***	***SW 1/8 - 1/4 (0.202 mi.)***	***O64***	***128***
MCDONALDS CORPORATION	701 3RD	NW 1/8 - 1/4 (0.216 mi.)	P69	135
WEST COAST SHIP CHANDLERS	***164 TOWNSEND***	***NNW 1/8 - 1/4 (0.227 mi.)***	***S100***	***171***
SITE K (SEAWALL LOT 333)	159 & 1/2 TOWNSEND ST	NNW 1/8 - 1/4 (0.228 mi.)	S103	176
MARINA VISTA PROJECT (SIT	725 2ND 75 & 99 TOWNSEN	NNW 1/4 - 1/2 (0.265 mi.)	R115	186
COMMERCIAL	***101 TOWNSEND***	***NNW 1/4 - 1/2 (0.275 mi.)***	***T118***	***195***
SFFD PUMPING STATION	698 2ND	NNW 1/4 - 1/2 (0.277 mi.)	T119	196
COMMERCIAL PROPERTY	680 2ND	NNW 1/4 - 1/2 (0.294 mi.)	T124	206
SOUTHERN PACIFIC TRANSPOR	***329 TOWNSEND***	***WNW 1/4 - 1/2 (0.309 mi.)***	***V125***	***206***
MISSION BAY PARCEL 24	***1600 6TH***	***SW 1/4 - 1/2 (0.318 mi.)***	***W126***	***209***
GEORGE LITHOGRAPH	650 2ND	NNW 1/4 - 1/2 (0.322 mi.)	X129	214
COMMERCIAL	64 72 TOWNSEND	NNW 1/4 - 1/2 (0.322 mi.)	T130	214
PARKING LOT	599 3RD ST	NW 1/4 - 1/2 (0.336 mi.)	U135	223
ROSENMAYER PROPERTY	***350 BRANNAN STREET***	***NNW 1/4 - 1/2 (0.346 mi.)***	***Z139***	***235***
JACKSON H E & CO#	***334 BRANNAN ST***	***NNW 1/4 - 1/2 (0.354 mi.)***	***X142***	***243***
CCSF - PORT OF SAN FRANCISCO	***333 ILLINOIS STREET***	***S 1/4 - 1/2 (0.363 mi.)***	***Y145***	***249***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SANTA FE PACIFIC REALTY C	***1201 6TH***	***SW 1/4 - 1/2 (0.365 mi.)***	***146***	***251***
WELLS FARGO BANK PROPERTY	***490 BRANNAN***	***WNW 1/4 - 1/2 (0.370 mi.)***	***AA147***	***253***
COMMERCIAL	***444 NATOMA ST***	***W 1/4 - 1/2 (0.373 mi.)***	***AB149***	***258***
HEUBLEIN INC	601 4TH	WNW 1/4 - 1/2 (0.375 mi.)	AA152	267
BAYSIDE VILLAGE ASSOCIATES	***551 1ST ST***	***NW 1/4 - 1/2 (0.395 mi.)***	***AC160***	***287***
CHARLES O JONES INC	***49 ZOE***	***NW 1/4 - 1/2 (0.399 mi.)***	***AF162***	***292***
TAYLOR PROPERTY	***150 PARK***	***NW 1/4 - 1/2 (0.405 mi.)***	***AC165***	***299***
SAN PACIFIC IMPORTS, INC.	***530 BRANNAN ST***	***WNW 1/4 - 1/2 (0.413 mi.)***	***AI171***	***311***
AUTO REPAIR & AUTO PARK	***529 3RD***	***NW 1/4 - 1/2 (0.414 mi.)***	***AC172***	***316***
KAISER SAND & GRAVEL	***300 16TH***	***S 1/4 - 1/2 (0.415 mi.)***	***AH173***	***319***
COMMERCIAL PROPERTY	557 4TH	WNW 1/4 - 1/2 (0.415 mi.)	AA174	322
CARRARO PROPERTY	***1800 03RD ST***	***S 1/4 - 1/2 (0.419 mi.)***	***AH175***	***323***
SF RDVLOPMNT AGNCY #K	***1 59.5 TOWNSEND ST***	***N 1/4 - 1/2 (0.432 mi.)***	***180***	***334***
LNR-LANNAR BRANNAN, LLC	***250 BRANNAN ST***	***NNW 1/4 - 1/2 (0.435 mi.)***	***AG181***	***335***
PAUL SHEEL METAL WORK	***474 BRYANT***	***NW 1/4 - 1/2 (0.455 mi.)***	***AJ187***	***348***
MERLE HORN ET AL., PROPERTY	***510 BRYANT STREET***	***NW 1/4 - 1/2 (0.457 mi.)***	***AJ189***	***351***
COMMERCIAL PROPERTY	***542 BRANNAN***	***NW 1/4 - 1/2 (0.461 mi.)***	***AK191***	***354***
COMMERCIAL PROPERTY	***535 BRYANT STREET***	***NW 1/4 - 1/2 (0.461 mi.)***	***AK193***	***358***
CHROME WORKS	***425 BRYANT STREET***	***NNW 1/4 - 1/2 (0.470 mi.)***	***AL195***	***361***
SUPER SHUTTLE	***700 16TH ST***	***SSW 1/4 - 1/2 (0.479 mi.)***	***197***	***363***
FERRO & VERNAZZA PROPERTY	***601 BRANNAN STREET***	***WNW 1/4 - 1/2 (0.480 mi.)***	***AM198***	***368***
SAN FRANCISCO NEWSPAPER AGENCY	***590 BRANNAN ST***	***WNW 1/4 - 1/2 (0.483 mi.)***	***AM200***	***371***
SIA'S SUPER SHELL #4, SIA BAKH	***598 BRYANT ST***	***WNW 1/4 - 1/2 (0.488 mi.)***	***AN204***	***386***
ESPRIT OUTLET STORE	***499 ILLINOIS ST***	***S 1/4 - 1/2 (0.490 mi.)***	***207***	***391***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SAN FRANCISCO PORT OF	***145 CHINA BASIN***	***0 - 1/8 (0.000 mi.)***	***C6***	***9***
SOUTHERN PACIFIC TRANSPORTATIO	***415 CHANNEL ST***	***WSW 1/8 - 1/4 (0.182 mi.)***	***K52***	***107***
SANTA FE PACIFIC REALTY C	195 CHANNEL	WSW 1/8 - 1/4 (0.192 mi.)	K59	119
SANTA FE PACIFIC REALTY C	***205 CHANNEL***	***WSW 1/4 - 1/2 (0.385 mi.)***	***AE156***	***275***
PEARSON EQUIPMENT COMPANY	1400 6TH	WSW 1/4 - 1/2 (0.387 mi.)	AE157	277
SOUTHERN PACIFIC MOTOR TRUCKIN	***1355 6TH ST***	***WSW 1/4 - 1/2 (0.408 mi.)***	***168***	***307***

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 10/21/1993 has revealed that there are 7 Notify 65 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN	***1289 2ND ST***	***N 1/8 - 1/4 (0.192 mi.)***	***L58***	***118***
FLAIR ELECTRO SALES INC.	***516 TOWNSEND***	***W 1/2 - 1 (0.573 mi.)***	***209***	***395***
THE GLIDDEN COMPANY	***1000 16TH STREET***	***SW 1/2 - 1 (0.607 mi.)***	***211***	***397***
UNKOWN	1200 17TH STREET	SSW 1/2 - 1 (0.636 mi.)	215	419
AUTO SYMPHONY	***800 BRYAN ST.***	***W 1/2 - 1 (0.689 mi.)***	***AP216***	***420***
AUTO SYMPHONY	800 BRYAN ST.	W 1/2 - 1 (0.702 mi.)	AP219	427
PIER 70	20TH STREET	SSE 1/2 - 1 (0.999 mi.)	AR241	491

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency

A review of the HAZNET list, as provided by EDR, and dated 12/31/2012 has revealed that there are 2 HAZNET sites within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WATERLOO BEVERAGES LLC	295 TERRY FRANCOIS ST	0 - 1/8 (0.000 mi.)	B5	8
H & H SHIP SERVICE CO	220 CHINA BASIN ST	0 - 1/8 (0.000 mi.)	A10	40

EMI: Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies

A review of the EMI list, as provided by EDR, and dated 12/31/2010 has revealed that there is 1 EMI site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***

HWP: Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

A review of the HWP list, as provided by EDR, and dated 08/28/2013 has revealed that there are 2 HWP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H & H SHIP SERVICE	***220 CHINA BASIN ST.***	***0 - 1/8 (0.000 mi.)***	***A8***	***11***
C & M PLATING WORKS	***598 6TH STREET***	***W 1/2 - 1 (0.615 mi.)***	***AO212***	***399***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there are 5 EDR MGP sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG AND E GAS PLANT SAN FRANCIS	KING NR 3RD STREET	NW 1/8 - 1/4 (0.214 mi.)	P68	135
PG AND E GAS PLANT SAN FRANCIS	KING AND 2ND STREET	NNW 1/8 - 1/4 (0.245 mi.)	R113	185
SAN FRANCISCO GAS LIGHT CO	HOWARD, FIFITH AND TEHA	WNW 1/2 - 1 (0.861 mi.)	228	445
PACIFIC BELL	140 NEW MONTGOMERY STRE	NW 1/2 - 1 (0.878 mi.)	229	445
PG AND E GAS PLANT SAN FRANCIS	FIRST, HOWARD,FREMONT,	NNW 1/2 - 1 (0.930 mi.)	236	474

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 12 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A B C AUTOMOTIVE SERVICE	905 3RD ST	NW 0 - 1/8 (0.085 mi.)	E22	66
ARTESEROS JAMES CHEVRON SERVIC	865 3RD	NW 0 - 1/8 (0.103 mi.)	E25	68
ARTESEROS JAMES CHEVRON SERVIC	865 3RD ST	NW 0 - 1/8 (0.104 mi.)	E26	68
ARTESEROS JAS CHEVRON SERVICE	854 3D	NW 0 - 1/8 (0.109 mi.)	E27	69
ANCHOR ENGINE REBUILDERS INC	165 KING ST	NNW 1/8 - 1/4 (0.148 mi.)	G41	96
BOB S UNION SERVICE STATION	701 3RD	NW 1/8 - 1/4 (0.216 mi.)	P70	135
LEE & PAUL	701 3D	NW 1/8 - 1/4 (0.217 mi.)	P72	137
PETRUCELA & CO	180 TOWNSEND ST	NW 1/8 - 1/4 (0.220 mi.)	P82	153
LOHMANN WM & CO	181 TOWNSEND	NW 1/8 - 1/4 (0.221 mi.)	P85	159
Not reported	178 TOWNSEND ST	NW 1/8 - 1/4 (0.221 mi.)	P86	159
PETRUCELA & CO	180 TOWNSEND	NW 1/8 - 1/4 (0.223 mi.)	P90	164
Not reported	260 TOWNSEND ST	WNW 1/8 - 1/4 (0.241 mi.)	Q111	183

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 5 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	185 BERRY ST	WNW 1/8 - 1/4 (0.171 mi.)	I47	102
J & T CLEANERS	234 TOWNSEND	NW 1/8 - 1/4 (0.224 mi.)	Q92	165
DAVIS G R MRS	230 TOWNSEND ST	NW 1/8 - 1/4 (0.226 mi.)	Q94	166
Not reported	242 TOWNSEND ST	NW 1/8 - 1/4 (0.230 mi.)	Q104	176
DAVIS G R MRS	682 3D	NW 1/8 - 1/4 (0.231 mi.)	P105	177

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 35 records.

Site Name	Database(s)
MISSION BAY	UST
MISSION	UST
UCSF/MISSION BAY	UST
PACIFIC BELL (TD-043)	HIST UST
CALTRANS D-4/CONSTR/EA-163734	HAZNET
CALTRANS DIST 4/CONSTR/EA04-291004	HAZNET
CALTRANS	HAZNET
CCSF-MUNI 3RD ST LIGHT RAIL	HAZNET
CITY AND CO OF S F 3RD ST BRIDGE	HAZNET
B & J SEWING	HAZNET
STUART-DEAN INC	HAZNET
URBAN HOUSING MB III LLC	HAZNET
CALTRANS DISTRICT 4	HAZNET
CALTRANS D-4/RELOCATE EXISTING UTI	HAZNET
CALTRANS D-4/EA04-2A1404	HAZNET
CALTRANS WEST APPROACH TO THE SFOB	HAZNET
CALTRANS DIST 4/CONSTR	HAZNET
CALTRANS DIST 4/CONSTR/04-435V4	HAZNET
CALTRANS DIST 4/CONSTR	HAZNET
CALTRANS DIST 4/CONSTRUCTION	HAZNET
CITY & COUNTY OF SAN FRANCISCO/DPH	HAZNET
CITY & COUNTY OF SAN FRANCISCO	HAZNET
AUTO RETURN - PIER 70	HAZNET
CALTRANS	HAZNET
CALTRANS DISTRICT 4	HAZNET
MANHOLE 5276	HAZNET
CALTRANS/KING ST RAMPS	HAZNET
CCSF-DPW EMBARCADERO ROADWAY	HAZNET
INNOVA DYNAMICS	HAZNET
US INNOVATION CTR USIC, BAYER HEAL	HAZNET
CIRQUE DU SOLEIL - OVO	HAZNET
NEKTAR THERAPEUTICS	HAZNET
CIRQUE DU SOLEIL	HAZNET
CIRQUE DU SOLEIL	HAZNET
MISSION PLACE, LLC	EMI

OVERVIEW MAP - 3781208.2s



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Mission Rock	CLIENT:	Baseline Environmental Cons.
ADDRESS:	Pier 48	CONTACT:	Patrick Sutton
	San Francisco CA 94158	INQUIRY #:	3781208.2s
LAT/LONG:	37.7748 / 122.3883	DATE:	November 08, 2013 4:29 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

DETAIL MAP - 3781208.2s



Target Property
Sites at elevations higher than or equal to the target property
Sites at elevations lower than the target property
Manufactured Gas Plants
Sensitive Receptors
National Priority List Sites
Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA
County Boundary
Oil & Gas pipelines from USGS
National Wetland Inventory

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Mission Rock	CLIENT: Baseline Environmental Cons.
ADDRESS: Pier 48	CONTACT: Patrick Sutton
San Francisco CA 94158	INQUIRY #: 3781208.2s
LAT/LONG: 37.7748 / 122.3883	DATE: November 08, 2013 4:30 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	0.001		0	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS	0.500		0	0	0	NR	NR	0
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	0.500		1	1	0	NR	NR	2
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		1	0	0	1	NR	2
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		1	0	0	NR	NR	1
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		3	3	NR	NR	NR	6
RCRA-CESQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
LUCIS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001	4	3	NR	NR	NR	NR	7
State- and tribal - equivalent NPL								
RESPONSE	1.000		0	0	1	1	NR	2
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.000		1	2	4	24	NR	31
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST	0.500		3	17	75	NR	NR	95

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
SLIC	0.500		1	2	2	NR	NR	5
INDIAN LUST	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
UST	0.250		2	18	NR	NR	NR	20
AST	0.250		0	1	NR	NR	NR	1
INDIAN UST	0.250		0	0	NR	NR	NR	0
FEMA UST	0.250		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
VCP	0.500		0	0	1	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	2	1	NR	NR	3
Local Lists of Landfill / Solid Waste Disposal Sites								
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
WMUDS/SWAT	0.500		0	1	1	NR	NR	2
SWRCY	0.500		0	1	0	NR	NR	1
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	1	2	NR	3
SCH	0.250		0	0	NR	NR	NR	0
Toxic Pits	1.000		0	0	0	0	NR	0
CDL	0.001		0	NR	NR	NR	NR	0
US HIST CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
CA FID UST	0.250		5	10	NR	NR	NR	15
HIST UST	0.250		3	7	NR	NR	NR	10
SWEEPS UST	0.250		5	11	NR	NR	NR	16
Local Land Records								
LIENS 2	0.001		0	NR	NR	NR	NR	0
LIENS	0.001		0	NR	NR	NR	NR	0
DEED	0.500		1	0	2	NR	NR	3
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		1	3	NR	NR	NR	4
DOT OPS	0.001		0	NR	NR	NR	NR	0
DOD	1.000		0	0	0	0	NR	0
FUDS	1.000		0	0	0	0	NR	0
CONSENT	1.000		0	0	0	0	NR	0
ROD	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
FINDS	0.001		1	NR	NR	NR	NR	1
RAATS	0.001		1	NR	NR	NR	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
UIC	0.001		0	NR	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
Cortese	0.500		0	0	0	NR	NR	0
HIST CORTESE	0.500		1	11	39	NR	NR	51
CUPA Listings	0.250		0	0	NR	NR	NR	0
Notify 65	1.000		0	1	0	6	NR	7
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
ENF	0.001		0	NR	NR	NR	NR	0
HAZNET	0.001		2	NR	NR	NR	NR	2
EMI	0.001		1	NR	NR	NR	NR	1
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
HWT	0.250		0	0	NR	NR	NR	0
HWP	1.000		1	0	0	1	NR	2
Financial Assurance	0.001		0	NR	NR	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PROC	0.500		0	0	0	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	2	0	3	NR	5
EDR US Hist Auto Stat	0.250		4	8	NR	NR	NR	12
EDR US Hist Cleaners	0.250		0	5	NR	NR	NR	5

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **ERNS** **91237202**
Target Property **PIER 48** **N/A**
SAN FRANCISCO, CA

Site 1 of 9 in cluster A

Actual:
5 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

A2 **ERNS** **91203119**
Target Property **PIER 48** **N/A**
SAN FRANCISCO, CA

Site 2 of 9 in cluster A

Actual:
5 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

A3 **ERNS** **91240257**
Target Property **PIER 48** **N/A**
SAN FRANCISCO, CA

Site 3 of 9 in cluster A

Actual:
5 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

A4 **ERNS** **91205043**
Target Property **PIER 48** **N/A**
SAN FRANCISCO, CA 94107

Site 4 of 9 in cluster A

Actual:
5 ft.

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

B5 **WATERLOO BEVERAGES LLC** **HAZNET** **S113787217**
295 TERRY FRANCOIS ST **N/A**
< 1/8 **SAN FRANCISCO, CA 94158**
1 ft.

Site 1 of 5 in cluster B

Relative:
Higher

Actual:
5 ft.

HAZNET:

Year:	2012
Gepaid:	CAC002702977
Contact:	JOHN VANLOO
Telephone:	4153681782
Mailing Name:	Not reported
Mailing Address:	295 TERRY FRANCOIS ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941582105
Gen County:	San Francisco
TSD EPA ID:	NVT330010000
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.75

WATERLOO BEVERAGES LLC (Continued) **S113787217**

Facility County: San Francisco

Year: 2012
Gepaid: CAC002702977
Contact: JOHN VANLOO
Telephone: 4153681782
Mailing Name: Not reported
Mailing Address: 295 TERRY FRANCOIS ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941582105
Gen County: San Francisco
TSD EPA ID: CAT080012602
TSD County: Solano
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.5421
Facility County: San Francisco

C6 **SAN FRANCISCO PORT OF** **HIST CORTESE** **S102436737**
145 CHINA BASIN **LUST** **N/A**
< 1/8 **SAN FRANCISCO, CA**
1 ft.

Site 1 of 3 in cluster C

Relative:
Lower

Actual:
0 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0310

LUST:
Region: STATE
Global Id: T0607500273
Latitude: 37.776416
Longitude: -122.388481
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 04/15/2008
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0310
LOC Case Number: 10318
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500273
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov

SAN FRANCISCO PORT OF (Continued) **S102436737**

Phone Number: Not reported

Global Id: T0607500273
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500273
Status: Completed - Case Closed
Status Date: 04/15/2008

Global Id: T0607500273
Status: Open - Case Begin Date
Status Date: 09/09/1987

Global Id: T0607500273
Status: Open - Remediation
Status Date: 09/09/1987

Global Id: T0607500273
Status: Open - Verification Monitoring
Status Date: 03/18/2008

Regulatory Activities:
Global Id: T0607500273
Action Type: ENFORCEMENT
Date: 03/18/2008
Action: File review

Global Id: T0607500273
Action Type: ENFORCEMENT
Date: 03/18/2008
Action: LOP Case Closure Summary to RB

Global Id: T0607500273
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500273
Action Type: ENFORCEMENT
Date: 04/14/2008
Action: File review

Global Id: T0607500273
Action Type: ENFORCEMENT
Date: 04/15/2008
Action: Closure/No Further Action Letter

Global Id: T0607500273
Action Type: Other

SAN FRANCISCO PORT OF (Continued) **S102436737**

Date: 01/01/1950
Action: Leak Discovery

A7 **H & H SHIP SERVICE CO** **FINDS** **1016053005**
220 CHINA BASIN ST **N/A**
< 1/8 **SAN FRANCISCO, CA**
1 ft.

Site 5 of 9 in cluster A

Relative: Higher

FINDS:

Registry ID: 110000621104

Actual: 5 ft.

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A8 **H & H SHIP SERVICE** **RCRA-TSDF** **1000116649**
220 CHINA BASIN ST. **CERC-NFRAP** **CAD004771168**
< 1/8 **SAN FRANCISCO, CA 94107** **CORRACTS**
1 ft. **RCRA-SQG**
RAATS
Site 6 of 9 in cluster A **CA FID UST**
UST
Relative: Higher **HIST UST**
SWEEPS UST
Actual: 5 ft. **DEED**
EMI
ENVIROSTOR
HWP

RCRA-TSDF:

Date form received by agency: 09/01/1996
Facility name: H & H SHIP SERVICE CO INC
Facility address: 220 CHINA BASIN ST
SAN FRANCISCO, CA 94107
EPA ID: CAD004771168
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09

H & H SHIP SERVICE (Continued) **1000116649**

Land type: Municipal
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste

Owner/Operator Summary:
Owner/operator name: WILLIAM HARRIS SR
Owner/operator address: 220 CHINA BASIN ST
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 543-4835
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: H & H SHIP SERVICE CO
Owner/operator address: PO BOX 77303
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 543-4835
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: H & H SHIP SERVICE CO
Owner/operator address: PO BOX 77363
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 543-4835
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: H & H SHIP SERVICE CO INC

H & H SHIP SERVICE (Continued) **1000116649**

Classification: Small Quantity Generator

Date form received by agency: 03/25/1996
Facility name: H & H SHIP SERVICE CO INC
Site name: H H SHIP SERVICE CO
Classification: Large Quantity Generator

Date form received by agency: 03/30/1994
Facility name: H & H SHIP SERVICE CO INC
Site name: H&H SHIP SERVICE CO
Classification: Large Quantity Generator

Date form received by agency: 03/02/1992
Facility name: H & H SHIP SERVICE CO INC
Site name: H&H SHIP SERVICE CO., INC.
Classification: Large Quantity Generator

Date form received by agency: 02/21/1992
Facility name: H & H SHIP SERVICE CO INC
Classification: Large Quantity Generator

Corrective Action Summary:
Event date: 03/09/1992
Event: CA029ST

Event date: 03/09/1992
Event: RFA Completed, Assessment was a PA-Plus.

Event date: 03/09/1992
Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.

Event date: 03/09/1992
Event: RFA Completed

Event date: 04/29/1992
Event: Stabilization Measures Evaluation,This facility is not amenable to stabilization activity at the present time for reasons other than 1- it appears to be technically infeasible or inappropriate (NF) or 2- there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.

Event date: 04/29/1992
Event: CA Prioritization, Facility or area was assigned a medium corrective action priority.

Event date: 10/30/1992
Event: RFA Completed

Facility Has Received Notices of Violations:
Regulation violated: FR - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 09/16/1994
Date achieved compliance: 01/01/1995

H & H SHIP SERVICE (Continued) **1000116649**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 09/16/1994
Date achieved compliance: 09/16/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 09/16/1994
Date achieved compliance: 01/01/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 09/16/1994
Date achieved compliance: 09/16/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 268.7
Area of violation: LDR - General
Date violation determined: 09/16/1994
Date achieved compliance: 11/07/1994
Violation lead agency: State

H & H SHIP SERVICE (Continued) **1000116649**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/16/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.110-120.G
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/07/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/07/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A
Area of violation: Generators - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/07/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

H & H SHIP SERVICE (Continued) **1000116649**

Enforcement action date: 07/07/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A
Area of violation: Generators - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.110-120.G
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 270
Area of violation: TSD - General
Date violation determined: 06/30/1993
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 03/19/1993
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 03/19/1993
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/07/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/08/1993
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1993
Enf. disposition status: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 01/08/1993
Date achieved compliance: 07/07/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.10-18.B
Area of violation: TSD - General
Date violation determined: 01/08/1993
Date achieved compliance: 07/07/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.30-34.C
Area of violation: Generators - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.30-34.C
Area of violation: Generators - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/01/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.170-177.I
Area of violation: TSD - General
Date violation determined: 01/08/1993
Date achieved compliance: 03/19/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/08/1993
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.140-150.H
Area of violation: TSD - Financial Requirements
Date violation determined: 03/23/1992
Date achieved compliance: 01/13/1993
Violation lead agency: EPA
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 99800
Final penalty amount: 99800
Paid penalty amount: Not reported

Regulation violated: FR - 264.110-120.G
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 268.7
Area of violation: LDR - General
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 264.110-120.G
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 99800
Final penalty amount: 99800
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 268.7
Area of violation: LDR - General
Date violation determined: 01/10/1991
Date achieved compliance: 12/02/1994
Violation lead agency: EPA
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 12/01/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: 99800
Final penalty amount: 99800

H & H SHIP SERVICE (Continued) **1000116649**

Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/28/1987
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.20-23.B
Area of violation: Generators - General
Date violation determined: 01/28/1987
Date achieved compliance: 01/10/1991
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/28/1987
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.20-23.B
Area of violation: Generators - General
Date violation determined: 01/28/1987
Date achieved compliance: 01/10/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/28/1987
Date achieved compliance: 05/11/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/28/1987
Date achieved compliance: 05/11/1992
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/15/1987
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/15/1987
Date achieved compliance: 05/11/1992
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263

H & H SHIP SERVICE (Continued) **1000116649**

Area of violation: Transporters - General
Date violation determined: 01/15/1987
Date achieved compliance: 05/11/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.20-23.B
Area of violation: Generators - General
Date violation determined: 01/15/1987
Date achieved compliance: 01/10/1991
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General
Date violation determined: 01/15/1987
Date achieved compliance: 05/11/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.50-60
Area of violation: Generators - General
Date violation determined: 01/15/1987
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 263
Area of violation: Transporters - General

H & H SHIP SERVICE (Continued) **1000116649**

Date violation determined: 01/15/1987
Date achieved compliance: 05/11/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.20-23.B
Area of violation: Generators - General
Date violation determined: 01/15/1987
Date achieved compliance: 01/10/1991
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 262.10-12.A
Area of violation: Generators - General
Date violation determined: 09/30/1986
Date achieved compliance: 05/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/01/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 10/03/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/25/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 06/29/1995
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Evaluation lead agency: State

Evaluation date: 12/02/1994
Evaluation: NOT A SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 08/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/01/1995
Evaluation lead agency: State

Evaluation date: 08/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 09/16/1994
Evaluation lead agency: State

Evaluation date: 08/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 01/01/1995
Evaluation lead agency: State

Evaluation date: 08/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/16/1994
Evaluation lead agency: State

Evaluation date: 08/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 11/07/1994
Evaluation lead agency: State

Evaluation date: 09/30/1993
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 05/03/1993
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/19/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 03/19/1993

H & H SHIP SERVICE (Continued) **1000116649**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/03/1993
Evaluation lead agency: State

Evaluation date: 03/19/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 03/19/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 03/19/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 01/13/1993
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/03/1993
Evaluation lead agency: State

Evaluation date: 05/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 03/19/1993
Evaluation lead agency: State

Evaluation date: 05/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 07/07/1993
Evaluation lead agency: State

Evaluation date: 05/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 03/19/1993
Evaluation lead agency: State

Evaluation date: 05/11/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/19/1993

H & H SHIP SERVICE (Continued) **1000116649**

Evaluation lead agency: State

Evaluation date: 03/23/1992
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/13/1993
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 01/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 12/02/1994
Evaluation lead agency: EPA

Evaluation date: 01/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 12/02/1994
Evaluation lead agency: EPA

Evaluation date: 01/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 12/02/1994
Evaluation lead agency: EPA

Evaluation date: 01/10/1991
Evaluation: SIGNIFICANT NON-COMPLIER
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 01/10/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 12/02/1994
Evaluation lead agency: EPA

Evaluation date: 01/28/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 01/10/1991
Evaluation lead agency: State

Evaluation date: 01/28/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 05/03/1993
Evaluation lead agency: State

Evaluation date: 01/28/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Transporters - General
Date achieved compliance: 05/11/1992
Evaluation lead agency: State

Evaluation date: 01/15/1987

H & H SHIP SERVICE (Continued) **1000116649**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 01/10/1991
Evaluation lead agency: State

Evaluation date: 01/15/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 05/11/1992
Evaluation lead agency: State

Evaluation date: 01/15/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Transporters - General
Date achieved compliance: 05/11/1993
Evaluation lead agency: State

Evaluation date: 01/15/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/03/1993
Evaluation lead agency: State

Evaluation date: 09/30/1986
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 05/03/1993
Evaluation lead agency: State

CERC-NFRAP:
Site ID: 0904296
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 13054802.00000
Person ID: 9271184.00000

Contact Sequence ID: 13286104.00000
Person ID: 13003854.00000

Contact Sequence ID: 13291699.00000
Person ID: 13003858.00000

Contact Sequence ID: 13297557.00000
Person ID: 13004003.00000

Program Priority:
Description: RCRA Deferral Audit

Description: RCRA Deferral - New Decision

Description: RCRA Deferral - Further Superfund Assessment

CERCLIS-NFRAP Assessment History:

H & H SHIP SERVICE (Continued) **1000116649**

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 01/23/96
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 03/31/92
Priority Level: Deferred to RCRA (Subtitle C)

Action: DISCOVERY
Date Started: / /
Date Completed: 07/09/91
Priority Level: Not reported

CORRACTS:

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920309
Action: CA029ST
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920309
Action: CA050 - RFA Completed
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: 19920309
Schedule end date: Not reported

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920309
Action: CA050PA - RFA Completed, Assessment was a PA-Plus
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY

H & H SHIP SERVICE (Continued) **1000116649**

Actual Date: 19920309
Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19920429
Action: CA075ME - CA Prioritization, Facility or area was assigned a medium corrective action priority
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD004771168
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19921030
Action: CA050 - RFA Completed
NAICS Code(s): 32411 324191 48411 42193
Petroleum Refineries
Petroleum Lubricating Oil and Grease Manufacturing
General Freight Trucking, Local
Original schedule date: 19921030
Schedule end date: Not reported

CA FID UST:
Facility ID: 38000347
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4155434835
Mail To: Not reported
Mailing Address: 220 CHINA BASIN
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SAN FRANCISCO CO. UST:
Facility ID: 8089

H & H SHIP SERVICE (Continued) **1000116649**

Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	5/11/1987
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	3/28/1988
UST Close ID:	547
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	8/29/1996
UST Close ID:	2676
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

H & H SHIP SERVICE (Continued) **1000116649**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	2/19/1997
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

HIST UST:

Region:	STATE
Facility ID:	00000032738
Facility Type:	Other
Other Type:	SHIP MAINTENANCE
Total Tanks:	0002
Contact Name:	Not reported
Telephone:	4155434835
Owner Name:	H&H SHIP SERVICE CO.
Owner Address:	220 CHINA BASIN STREET
Owner City,St,Zip:	SAN FRANCISCO, CA 94107

Tank Num:	001
Container Num:	#1
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	12 gauge
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00010000
Tank Used for:	PRODUCT

H & H SHIP SERVICE (Continued) **1000116649**

Type of Fuel: DIESEL
Tank Construction: 12 gauge
Leak Detection: Stock Inventor

SWEEPS UST:
Status: Not reported
Comp Number: 8089
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008089-000002
Actv Date: Not reported
Capacity: 10000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 1

Status: Active
Comp Number: 8089
Number: 1
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: A
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008089-000001
Actv Date: 09-30-92
Capacity: 10000
Tank Use: UNKNOWN
Stg: P
Content: UNSPECIFIED
Number Of Tanks: 1

DEED:
Area: Not reported
Sub Area: Not reported
Site Type: UNDERGOING CLOSURE
Status: UNDERGOING CLOSURE
Deed Date(s): Not reported
EDR Link ID: CAD004771168

Area: Not reported
Sub Area: Not reported
Site Type: UNDERGOING CLOSURE
Status: UNDERGOING CLOSURE
Deed Date(s): Not reported
EDR Link ID: CAD004771168

EMI:
Year: 1990

H & H SHIP SERVICE (Continued) **1000116649**

County Code:	38
Air Basin:	SF
Facility ID:	3946
Air District Name:	BA
SIC Code:	2992
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	17
Reactive Organic Gases Tons/Yr:	15
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

Year:	1993
County Code:	38
Air Basin:	SF
Facility ID:	3946
Air District Name:	BA
SIC Code:	2992
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	13
Reactive Organic Gases Tons/Yr:	11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	38
Air Basin:	SF
Facility ID:	3946
Air District Name:	BA
SIC Code:	2992
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	12
Reactive Organic Gases Tons/Yr:	11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	38
Air Basin:	SF
Facility ID:	3946
Air District Name:	BA
SIC Code:	2992
Air District Name:	BAY AREA AQMD

H & H SHIP SERVICE (Continued) **1000116649**

Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 12
Reactive Organic Gases Tons/Yr: 11
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers & Smllr Tons/Yr: 0

ENVIROSTOR:
Site Type: Corrective Action
Site Type Detailed: Corrective Action
Acres: 6.6
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: WM
Program Manager: Charles (Chip) Gribble
Supervisor: Denise Tsuji
Division Branch: Cleanup Berkeley
Facility ID: 80001528
Site Code: 200172
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Active
Status Date: 02/07/2011
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 37.77647
Longitude: -122.3883
APN: NONE SPECIFIED
Past Use: HAZARDOUS WASTE TREATMENT
Potential COC: Arsenic, TPH-diesel, TPH-MOTOR OIL, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Arsenic, TPH-diesel, TPH-MOTOR OIL, Polynuclear aromatic hydrocarbons (PAHs, 30001-NO, 30024-NO, 30472-NO, 3002502-NO
Potential Description: SOIL
Alias Name: CAD004771168
Alias Type: EPA Identification Number
Alias Name: 200172
Alias Type: Project Code (Site Code)
Alias Name: 80001528
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RCRA Facility Assessment Report
Completed Date: 03/09/1992
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Order
Completed Date: 10/30/1992

H & H SHIP SERVICE (Continued) **1000116649**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RCRA Facility Assessment Report
Completed Date: 10/30/1992
Comments: RFA report dated 10/1992

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Interim Measures Questionnaire
Completed Date: 04/29/1992
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Phase 1
Future Due Date: 2014
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HWP:
EPA Id: CAD004771168
Cleanup Status: UNDERGOING CLOSURE
Latitude: 37.77647
Longitude: -122.3883
Facility Type: Historical - Non-Operating
Facility Size: Not reported
Team: Not reported
Supervisor: Not reported
Site Code: 200172
Assembly District: 17
Senate District: 11
Public Information Officer: Not reported

Activities:
EPA Id: CAD004771168
Facility Type: Historical - Non-Operating
Unit Names: TANKTRT1
Event Description: New Operating Permit - CALL-IN LETTER ISSUED
Actual Date: 06/01/1985

EPA Id: CAD004771168
Facility Type: Historical - Non-Operating
Unit Names: TANKTRT1
Event Description: New Operating Permit - APPLICATION PART B RECEIVED
Actual Date: 09/25/1986

EPA Id: CAD004771168
Facility Type: Historical - Non-Operating
Unit Names: TANKTRT1
Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Actual Date: 08/23/1990

H & H SHIP SERVICE (Continued) **1000116649**

Closure:

EPA Id:	CAD004771168
Facility Type:	Historical - Non-Operating
Unit Names:	OTHRTRT1, TANKTRT1
Event Description:	Closure - CLOSURE PLAN RECEIVED
Actual Date:	04/08/1993

EPA Id:	CAD004771168
Facility Type:	Historical - Non-Operating
Unit Names:	OTHRTRT1, TANKTRT1
Event Description:	Closure - CLOSURE PLAN APPROVED
Actual Date:	01/12/1995

EPA Id:	CAD004771168
Facility Type:	Historical - Non-Operating
Unit Names:	OTHRTRT1, TANKTRT1
Event Description:	Closure - ISSUE CLOSURE VERIFICATION
Actual Date:	07/30/2002

Alias:

EPA Id:	CAD004771168
Facility Type:	Historical - Non-Operating
Alias Type:	Project Code (Site Code)
Alias:	200172

Maintenance:

EPA Id:	CAD004771168
Title:	Ammended LUC for the H & H Ship Service facility dated 1/27/2000.
Document Type:	Deed Restriction / LUC Issued
Received Date:	07/25/2002

EPA Id:	CAD004771168
Title:	LUC for the H & H Ship Service facility dated 1/27/2000.
Document Type:	Deed Restriction / LUC Issued
Received Date:	01/27/2000

A9
< 1/8
1 ft.

Relative: Higher

Actual: 5 ft.

220 CHINA BASIN ST.
SAN FRANCISCO, CA 94107

Site 7 of 9 in cluster A

ERNS **90167552**
N/A

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

A10 **H & H SHIP SERVICE CO** **HAZNET** **S112998991**
220 CHINA BASIN ST **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
1 ft.

Site 8 of 9 in cluster A

Relative: HAZNET:
Higher

Year:	1999
Gepaid:	CAD004771168
Contact:	H&H SHIP SERVICE CO
Telephone:	4155434835
Mailing Name:	Not reported
Mailing Address:	220 CHINA BASIN ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941070000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.2642
Facility County:	San Francisco

Actual: **5 ft.**

Year:	1999
Gepaid:	CAD004771168
Contact:	H&H SHIP SERVICE CO
Telephone:	4155434835
Mailing Name:	Not reported
Mailing Address:	220 CHINA BASIN ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941070000
Gen County:	Not reported
TSD EPA ID:	CAT080022148
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Not reported
Tons:	3.2109
Facility County:	San Francisco

Year:	1999
Gepaid:	CAD004771168
Contact:	H&H SHIP SERVICE CO
Telephone:	4155434835
Mailing Name:	Not reported
Mailing Address:	220 CHINA BASIN ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941070000
Gen County:	Not reported
TSD EPA ID:	CAT080022148
TSD County:	Not reported
Waste Category:	Tank bottom waste
Disposal Method:	Not reported
Tons:	16.0000
Facility County:	San Francisco

Year:	1998
Gepaid:	CAD004771168
Contact:	H&H SHIP SERVICE CO
Telephone:	4155434835
Mailing Name:	Not reported
Mailing Address:	220 CHINA BASIN ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941070000

H & H SHIP SERVICE CO (Continued) **S112998991**

Gen County: Not reported
TSD EPA ID: CAL000161741
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Recycler
Tons: .5421
Facility County: San Francisco

Year: 1998
Gepaid: CAD004771168
Contact: H&H SHIP SERVICE CO
Telephone: 4155434835
Mailing Name: Not reported
Mailing Address: 220 CHINA BASIN ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941070000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 2.1892
Facility County: San Francisco

Click this hyperlink while viewing on your computer to access
88 additional CA_HAZNET: record(s) in the EDR Site Report.

C11 **ERNS** **91222021**
405 CHINA BASIN **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
1 ft.

Site 2 of 3 in cluster C

Relative: Higher

Click this hyperlink while viewing on your computer to access
additional ERNS detail in the EDR Site Report.

Actual: 5 ft.

A12 **ERNS** **90167548**
220 CHINA BASIN ST. **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
1 ft.

Site 9 of 9 in cluster A

Relative: Higher

Click this hyperlink while viewing on your computer to access
additional ERNS detail in the EDR Site Report.

Actual: 5 ft.

C13 **CCSF - PORT OF SAN FRANCISCO** **LUST** **S103472562**
145 CHINA BASIN STREET **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
1 ft.

Site 3 of 3 in cluster C

Relative: Lower

LUST REG 2:
Region: 2
Facility Id: 38-0310
Actual: 0 ft.
Facility Status: Remediation Plan
Case Number: 10318
How Discovered: Not reported

CCSF - PORT OF SAN FRANCISCO (Continued) **S103472562**

Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: 9/9/1987
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0310
Facility Status: Not reported
Case Number: 10318
Case Type: Other ground water affected
Release Date: 9/9/1987
Discovered Date: 9/9/1987
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 9/9/1987
Case Closed: Not reported
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: Not reported
Entered Date: 10/4/1994
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: MA
Cross Street: Not reported
NOR Date: 10/4/1994
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: ND
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: 4/27/1989
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal
Interim Remediation: No

CCSF - PORT OF SAN FRANCISCO (Continued) **S103472562**

Priority:	Moderate Priority Site
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	11/17/1987
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	3800
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

B14 **PIER 50 GEAR ROOM-STEVEDORING** **CA FID UST** **S101623233**
SSE **300 CHINA BASIN ST** **SWEEPS UST** **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
0.010 mi.
54 ft. **Site 2 of 5 in cluster B**

Relative:
Higher

Actual:
5 ft.

CA FID UST:

Facility ID:	38000524
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4152711853
Mail To:	Not reported
Mailing Address:	300 CHINA BASIN ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

PIER 50 GEAR ROOM-STEVEDORING (Continued) **S101623233**

SWEEPS UST:

Status:	Not reported
Comp Number:	6725
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-006725-000001
Actv Date:	Not reported
Capacity:	7400
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	6725
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

B15 **PIER 50 GEAR** **UST** **U003904252**
SSE **300 CHINA BASIN ST** **N/A**
< 1/8 **SAN FRANCISCO, CA**
0.010 mi.
54 ft. **Site 3 of 5 in cluster B**

Relative:
Higher

Actual:
5 ft.

SAN FRANCISCO CO. UST:

Facility ID:	6725
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	5/11/1987

PIER 50 GEAR (Continued) **U003904252**

Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	546
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported

PIER 50 GEAR (Continued) **U003904252**

Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

B16 **SERVICE ENGINEERING CO** **RCRA-SQG** **1000593931**
SE **PIER 50** **FINDS** **CAD983573973**
< 1/8 **SAN FRANCISCO, CA 94107** **CHMIRS**
0.024 mi. **HAZNET**
128 ft. **Site 4 of 5 in cluster B** **EMI**

Relative: Higher

Actual: 5 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	SERVICE ENGINEERING CO
Facility address:	PIER 50 SAN FRANCISCO, CA 94107
EPA ID:	CAD983573973
Mailing address:	P O BOX 7714 SAN FRANCISCO, CA 94120
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	SERVICE ENG INDUSTRIES INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner

SERVICE ENGINEERING CO (Continued) **1000593931**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: SERVICE ENGINEERING CO
Classification: Small Quantity Generator

Date form received by agency: 01/24/1992
Facility name: SERVICE ENGINEERING CO
Site name: SERVICE ENGINEERING CO.
Classification: Large Quantity Generator

Date form received by agency: 04/15/1991
Facility name: SERVICE ENGINEERING CO
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001195055

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CHMIRS:
OES Incident Number: 06-6504
OES notification: 11/02/2006
OES Date: Not reported
OES Time: Not reported
Incident Date: Not reported
Date Completed: **Not reported**

SERVICE ENGINEERING CO (Continued) **1000593931**

Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	South San Francisco Bay	
Spill Site:	Not reported	
Cleanup By:	Reporting Party	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2006	
Agency:	Cape Horn	
Incident Date:	11/2/2006 12:00:00 AM	
Admin Agency:	Not reported	
Amount:	Not reported	
Contained:	Yes	
Site Type:	Ship/Harbor/Port	
E Date:	Not reported	
Substance:	hydraulic oil	
Quantity Released:	Not reported	
BBLS:	0	
Cups:	0	
CUFT:	0	
Gallons:	5	
Grams:	0	
Pounds:	0	

SERVICE ENGINEERING CO (Continued) **1000593931**

Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Released from a piece of machinery. Released onto the dock, a small amount went over the side.
OES Incident Number:	02-3069
OES notification:	06/04/2002
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Francisco Bay
Spill Site:	Not reported
Cleanup By:	Foss
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported

SERVICE ENGINEERING CO (Continued) **1000593931**

Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	InterOcean Ugland Mgt. Corp.
Incident Date:	6/4/200212:00:00 AM
Admin Agency:	San Francisco County Health Department
Amount:	Not reported
Contained:	No
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Hydraulic Fluid
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	1
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	A hydraulic line ruptured, spraying the side of the ship, a small amount got into the water. Foss Env. will boom the ship and clean the ship. SS Mount Washington is the ship.
OES Incident Number:	06-6507
OES notification:	11/02/2006
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported

SERVICE ENGINEERING CO (Continued) **1000593931**

Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	San Francisco Bay
Spill Site:	Not reported
Cleanup By:	Responsible Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2006
Agency:	NRC
Incident Date:	11/2/2006 12:00:00 AM
Admin Agency:	San Francisco County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Hydraulic Oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	5
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Per NRC report: "Caller stated there was a release of materials from a ROS vessel. This spill of materials was due to hydraulic oil coming out of a wench that was being worked on, on the vessel". Remedial actions: "Caller stated they used kitty liitter, absorbent pads, and dust pans, barrels to put the oil in."
OES Incident Number:	06-7099
OES notification:	12/01/2006

SERVICE ENGINEERING CO (Continued) **1000593931**

OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	San Francisco Bay
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2006
Agency:	Weststar Marine Services
Incident Date:	12/1/2006 12:00:00 AM
Admin Agency:	San Francisco County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Diesel fuel
Quantity Released:	Not reported
BBLS:	0
Cups:	0

SERVICE ENGINEERING CO (Continued) **1000593931**

CUFT:	0
Gallons:	1
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	RP: While fueling vessel from tanker truck at pier the overflow occurred from the tank vent on the vessel. Vessel name "Orion"
OES Incident Number:	01-1571
OES notification:	03/15/2001
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Francisco Bay
Spill Site:	Not reported

SERVICE ENGINEERING CO (Continued) **1000593931**

Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2001
Agency:	NRC
Incident Date:	3/15/200112:00:00 AM
Admin Agency:	San Francisco County Health Department
Amount:	Not reported
Contained:	Unknown
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	Unknown Oil
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0.000000
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	The caller is reporting a sunken sailboat that is causing a small sheen to form in the water. The caller states that the release may still be ongoing.
OES Incident Number:	97-3492
OES notification:	09/07/1997
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported

SERVICE ENGINEERING CO (Continued) **1000593931**

More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1997
Agency:	KEYSTONE SHIPPING
Incident Date:	9/7/199712:00:00 AM
Admin Agency:	San Francisco County Health Department
Amount:	Not reported
Contained:	Yes
Site Type:	Ship/Harbor/Port
E Date:	Not reported
Substance:	MOTOR DIESEL
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	2
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	MOVING RAMP ON SHIP, VENT BURPED SUBSTANCE.

HAZNET:
Year: 1996

SERVICE ENGINEERING CO (Continued) **1000593931**

Gepaid: CAD983573973
Contact: SERVICE ENGINEERING IND 50
Telephone: 4159571777
Mailing Name: Not reported
Mailing Address: PO BOX 7714
Mailing City,St,Zip: SAN FRANCISCO, CA 941207714
Gen County: Not reported
TSD EPA ID: CAD000633164
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Disposal, Land Fill
Tons: 2.5000
Facility County: San Francisco

Year: 1995
Gepaid: CAD983573973
Contact: SERVICE ENGINEERING IND 50
Telephone: 4159571777
Mailing Name: Not reported
Mailing Address: PO BOX 7714
Mailing City,St,Zip: SAN FRANCISCO, CA 941207714
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Recycler
Tons: 3.4053
Facility County: San Francisco

Year: 1995
Gepaid: CAD983573973
Contact: SERVICE ENGINEERING IND 50
Telephone: 4159571777
Mailing Name: Not reported
Mailing Address: PO BOX 7714
Mailing City,St,Zip: SAN FRANCISCO, CA 941207714
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Transfer Station
Tons: .6880
Facility County: San Francisco

Year: 1995
Gepaid: CAD983573973
Contact: SERVICE ENGINEERING IND 50
Telephone: 4159571777
Mailing Name: Not reported
Mailing Address: PO BOX 7714
Mailing City,St,Zip: SAN FRANCISCO, CA 941207714
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Tons: .1500

SERVICE ENGINEERING CO (Continued) **1000593931**

Facility County: San Francisco

Year: 1995
Gepaid: CAD983573973
Contact: SERVICE ENGINEERING IND 50
Telephone: 4159571777
Mailing Name: Not reported
Mailing Address: PO BOX 7714
Mailing City,St,Zip: SAN FRANCISCO, CA 941207714
Gen County: Not reported
TSD EPA ID: CAT000646117
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Disposal, Land Fill
Tons: 15.1704
Facility County: San Francisco

Click this hyperlink while viewing on your computer to access
28 additional CA_HAZNET: record(s) in the EDR Site Report.

EMI:

Year: 1990
County Code: 38
Air Basin: SF
Facility ID: 3126
Air District Name: BA
SIC Code: 3731
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 5
Reactive Organic Gases Tons/Yr: 4
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 4
Part. Matter 10 Micrometers & Smllr Tons/Yr: 2

Year: 1995
County Code: 38
Air Basin: SF
Facility ID: 3126
Air District Name: BA
SIC Code: 3731
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2
Reactive Organic Gases Tons/Yr: 1
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 3
Part. Matter 10 Micrometers & Smllr Tons/Yr: 2

Year: 1996
County Code: 38

SERVICE ENGINEERING CO (Continued) **1000593931**

Air Basin:	SF
Facility ID:	3126
Air District Name:	BA
SIC Code:	3731
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	3
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2

B17 **MV CAPE HUDSON** **RCRA-SQG** **1001217376**
SE **PIER 50** **CAR000033159**
< 1/8 **SAN FRANCISCO, CA 94107**
0.024 mi.
128 ft. **Site 5 of 5 in cluster B**

Relative:
Higher

Actual:
5 ft.

RCRA-SQG:

Date form received by agency:	03/20/2006
Facility name:	MV CAPE HUDSON
Facility address:	PIER 50 SAN FRANCISCO, CA 94107
EPA ID:	CAR000033159
Mailing address:	1500 FERRY POINT, SUITE 101 C/O PACIFIC GULF MARINE ALAMEDA, CA 94501
Contact:	BRYAN S VOGEL
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	(415) 744-2840
Contact email:	BRYAN.VOGEL@DOT.GOV
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	U.S. MARITIME ADMINISTRATION
Owner/operator address:	201 MISSION ST., SUITE 1800 SAN FRANCISCO, CA 94105
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1986
Owner/Op end date:	Not reported
Owner/operator name:	US DOT MARITIME ADMIN
Owner/operator address:	201 MISSION ST STE 2200

MV CAPE HUDSON (Continued) **1001217376**

SAN FRANCISCO, CA 94105
Owner/operator country: Not reported
Owner/operator telephone: (415) 744-2577
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PACIFIC GULF MARINE
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/08/2005
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/20/2006
Facility name: MV CAPE HUDSON
Classification: Large Quantity Generator

Date form received by agency: 08/01/2004
Facility name: MV CAPE HUDSON
Site name: SHIP CAPE HUDSON NO 901127
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/10/1999
Facility name: MV CAPE HUDSON
Site name: SHIP CAPE HUDSON NO 901127
Classification: Small Quantity Generator

Hazardous Waste Summary:
Waste code: D000
Waste name: Not Defined

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

MV CAPE HUDSON (Continued) **1001217376**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003
Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: F001
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002
Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F004

MV CAPE HUDSON (Continued) **1001217376**

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F005
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: U002
Waste name: ACETONE (I)

Waste code: U225
Waste name: BROMOFORM

Waste code: U228
Waste name: ETHENE, TRICHLORO-

Waste code: U239
Waste name: BENZENE, DIMETHYL- (I,T)

Waste code: 134
Waste name: 134

Waste code: 141
Waste name: 141

Waste code: 331
Waste name: 331

Waste code: 791
Waste name: 791

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

MV CAPE HUDSON (Continued) **1001217376**

Waste code: D008
Waste name: LEAD

Waste code: D011
Waste name: SILVER

Violation Status: No violations found

D18 **SF AUTO CENTER INC.** **CA FID UST** **S101591982**
SW **1420 4TH ST** **SWEEPS UST** **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
0.038 mi.
203 ft. **Site 1 of 4 in cluster D**

Relative:
Higher

Actual:
6 ft.

CA FID UST:
Facility ID: 38000298
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4152271114
Mail To: Not reported
Mailing Address: 2300 16TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 4239
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-004239-000001
Actv Date: Not reported
Capacity: 10000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 3

Status: Not reported
Comp Number: 4239
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported

SF AUTO CENTER INC. (Continued) **S101591982**

Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-004239-000002
Actv Date:	Not reported
Capacity:	2000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	4239
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-004239-000003
Actv Date:	Not reported
Capacity:	10000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	4239
Number:	1
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

D19 **ROBERTSON DRAYAGE CO., INC.** **HIST UST** **U001595299**
SW **1420 4TH ST** **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
0.038 mi.
203 ft. **Site 2 of 4 in cluster D**

Relative:
Higher

Actual:
6 ft.

HIST UST:

Region:	STATE
Facility ID:	00000011411
Facility Type:	Other
Other Type:	Not reported
Total Tanks:	0003
Contact Name:	R.I. BEAULIEU, V.P.
Telephone:	4154319563

ROBERTSON DRAYAGE CO., INC. (Continued) **U001595299**

Owner Name: TRANSWAY INTERNATIONAL CORP
Owner Address: 747 THIRD AVENUE
Owner City,St,Zip: NEW YORK, NY 10017

Tank Num: 001
Container Num: 2
Year Installed: 1970
Tank Capacity: 00009980
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 002
Container Num: 1
Year Installed: 1970
Tank Capacity: 00009980
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: 1978
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Visual, Stock Inventor

D20 **FIRE STATION #30** **HIST UST** **U001595254**
WSW **1300 4TH ST** **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
0.056 mi.
294 ft. **Site 3 of 4 in cluster D**

Relative:
Higher

Actual:
6 ft.

HIST UST:
Region: STATE
Facility ID: 00000055032
Facility Type: Other
Other Type: FIREFIGHTING
Total Tanks: 0001
Contact Name: ANTHONY RODRIGUEZ
Telephone: 4158618000
Owner Name: CITY AND COUNTY OF SAN FRANCIS
Owner Address: 260 GOLDEN GATE AVENUE
Owner City,St,Zip: SAN FRANCISCO, CA 94102

Tank Num: 001
Container Num: #30
Year Installed: 1928
Tank Capacity: 00000550
Tank Used for: PRODUCT
Type of Fuel: 06
Tank Construction: 10 gauge
Leak Detection: Stock Inventor

D21 ***SFFD/FIRE STATION #30** **CA FID UST** **S101592113**
WSW **1300 4TH ST** **SWEEPS UST** **N/A**
< 1/8 **SAN FRANCISCO, CA 94107**
0.056 mi.
294 ft. **Site 4 of 4 in cluster D**

Relative:
Higher

Actual:
6 ft.

CA FID UST:

Facility ID:	38000522
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	1300 4TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	4291
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-004291-000001
Actv Date:	Not reported
Capacity:	550
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	4291
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

E22
NW
< 1/8
0.085 mi.
447 ft.

A B C AUTOMOTIVE SERVICE
905 3RD ST
SAN FRANCISCO, CA

Site 1 of 5 in cluster E

EDR US Hist Auto Stat **1008999837**
N/A

Relative:
Higher

Actual:
11 ft.

EDR Historical Auto Stations:

Name:	A B C AUTOMOTIVE SERVICE
Year:	1971
Type:	AUTOMOBILE REPAIRING
Name:	A B C AUTOMOTIVE SERVICE
Year:	1971
Type:	AUTOMOBILE REPAIRING

E23
NW
< 1/8
0.087 mi.
458 ft.

MANHOLE 5276
INTERSECTION OF 3RD
SAN FRANCISCO, CA 94107

Site 2 of 5 in cluster E

RCRA NonGen / NLR **1007370063**
CAP000152538

Relative:
Higher

Actual:
11 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/29/2004
Facility name:	MANHOLE 5276
Facility address:	INTERSECTION OF 3RD AND BERRY ST SAN FRANCISCO, CA 94107
EPA ID:	CAP000152538
Mailing address:	PG AND E SERVICE CTR 2270 FOLSOM ST SAN FRANCISCO, CA 94110
Contact:	SUE FANDEL
Contact address:	PG AND E SERVICE CTR 2270 FOLSOM ST SAN FRANCISCO, CA 94110
Contact country:	US
Contact telephone:	415-695-3511
Contact email:	SMF2@PGE.COM
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	PG AND E SF SERVICE CTR
Owner/operator address:	2270 FOLSOM ST SAN FRANCISCO, CA 94110
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1940
Owner/Op end date:	Not reported
Owner/operator name:	PG AND E SF SERVICE CTR
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator

MANHOLE 5276 (Continued) **1007370063**

Owner/Op start date: 01/01/1940
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Hazardous Waste Summary:
Waste code: D008
Waste name: LEAD

Violation Status: No violations found

24
SSW
< 1/8
0.090 mi.
475 ft.

VACANT **CA FID UST** **S101592212**
1401 3RD ST **SWEEPS UST** **N/A**
SAN FRANCISCO, CA 94107

Relative:
Higher

Actual:
7 ft.

CA FID UST:
Facility ID: 38001576
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 1401 3RD ST
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 9298
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92

VACANT (Continued) **S101592212**

Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	9298
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-009298-000001
Actv Date:	Not reported
Capacity:	1000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

E25 **ARTESEROS JAMES CHEVRON SERVICE** **EDR US Hist Auto Stat** **1009069516**
NW **865 3RD** **N/A**
< 1/8 **SAN FRANCISCO, CA**
0.103 mi.
546 ft. **Site 3 of 5 in cluster E**

Relative:
Higher

Actual:
13 ft.

EDR Historical Auto Stations:

Name:	ARTESEROS JAMES CHEVRON SERVICE
Year:	1962
Type:	GASOLINE STATIONS

Name:	ARTESEROS JAMES CHEVRON SERVICE
Year:	1966
Type:	GASOLINE STATIONS

E26 **ARTESEROS JAMES CHEVRON SERVICE** **EDR US Hist Auto Stat** **1009001563**
NW **865 3RD ST** **N/A**
< 1/8 **SAN FRANCISCO, CA**
0.104 mi.
549 ft. **Site 4 of 5 in cluster E**

Relative:
Higher

Actual:
13 ft.

EDR Historical Auto Stations:

Name:	ARTESEROS JAMES CHEVRON SERVICE
Year:	1971
Type:	GASOLINE STATIONS

Name:	ARTESEROS JAMES CHEVRON SERVICE

ARTESEROS JAMES CHEVRON SERVICE (Continued) **1009001563**

Year: 1971
Type: GASOLINE STATIONS

E27
NW
< 1/8
0.109 mi.
573 ft.

ARTESEROS JAS CHEVRON SERVICE **EDR US Hist Auto Stat** **1009069161**
854 3D **N/A**
SAN FRANCISCO, CA

Site 5 of 5 in cluster E

Relative: Higher

Actual: 13 ft.

EDR Historical Auto Stations:
Name: ARTESEROS JAS CHEVRON SERVICE
Year: 1958
Type: GASOLINE STATIONS

28
SW
< 1/8
0.112 mi.
591 ft.

COMMERCIAL **LUST** **S111012695**
CENTRAL SUBWAY SFMTA PROJECT 1250 (4TH ST.) **N/A**
SAN FRANCISCO, CA 94107

Relative: Higher

Actual: 6 ft.

LUST:
Region: STATE
Global Id: T10000003015
Latitude: 37.7723641
Longitude: -122.3914042
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 05/26/2011
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: AL
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 11933
File Location: Not reported
Potential Media Affect: Not reported
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000003015
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T10000003015
Status: Completed - Case Closed
Status Date: 05/26/2011

Global Id: T10000003015

COMMERCIAL (Continued) **S111012695**

Status: Open - Case Begin Date
Status Date: 09/30/2010

Global Id: T10000003015
Status: Open - Site Assessment
Status Date: 05/09/2011

Regulatory Activities:
Global Id: T10000003015
Action Type: Other
Date: 01/01/1950
Action: Leak Began

Global Id: T10000003015
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: Notice of Responsibility

Global Id: T10000003015
Action Type: ENFORCEMENT
Date: 05/17/2011
Action: File Review - Closure

Global Id: T10000003015
Action Type: ENFORCEMENT
Date: 05/26/2011
Action: LOP Case Closure Summary to RB

Global Id: T10000003015
Action Type: ENFORCEMENT
Date: 05/26/2011
Action: Closure/No Further Action Letter

Global Id: T10000003015
Action Type: ENFORCEMENT
Date: 05/25/2011
Action: Closure/No Further Action Letter - #11933

Global Id: T10000003015
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T10000003015
Action Type: RESPONSE
Date: 04/28/2011
Action: Tank Removal Report / UST Sampling Report

Global Id: T10000003015
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T10000003015
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

29
NNW
< 1/8
0.123 mi.
647 ft.

PAC BELL PARK
CROSS TOWNSEND AND 2ND
SAN FRANCISCO, CA

SLIC **S106235169**
N/A

Relative:
Higher

Actual:
9 ft.

SLIC:

Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	02/01/2000
Global Id:	SL18329749
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Lead Agency Case Number:	Not reported
Latitude:	37.7784488267835
Longitude:	-122.389433383942
Case Type:	Cleanup Program Site
Case Worker:	VP
Local Agency:	Not reported
RB Case Number:	SL18329749
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region:	2
Facility ID:	SL18329749
Facility Status:	Case Closed
Date Closed:	Not reported
Local Case #:	Not reported
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Confirmed:	Not reported
Date Prelim Site Assmnt Workplan Submitted:	Not reported
Date Preliminary Site Assessment Began:	Not reported
Date Pollution Characterization Began:	Not reported
Date Remediation Plan Submitted:	Not reported
Date Remedial Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

F30
WNW
1/8-1/4
0.126 mi.
664 ft.

SAN FRANCISCO AIRPORT JUNCTION
NORTH ACCESS RD.
SAN FRANCISCO, CA 94005

WMUDS/SWAT **U001593885**
HIST UST **N/A**
AST

Site 1 of 10 in cluster F

Relative:
Higher

Actual:
9 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	Not reported
NPID:	Not reported
Tonnage:	0

SAN FRANCISCO AIRPORT JUNCTION (Continued) **U001593885**

Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	Not reported
Agency Name:	Not reported
Agency Department:	Not reported
Agency Address:	Not reported
Agency City,St,Zip:	Not reported
Agency Contact:	Not reported
Agency Telephone:	Not reported
Land Owner Name:	Not reported
Land Owner Address:	Not reported
Land Owner City,St,Zip:	CA
Land Owner Contact:	Not reported
Land Owner Phone:	Not reported
Region:	2
Facility Type:	Not reported
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	Not reported
Primary SIC:	Not reported
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	False
Solid Waste Assessment Test Program:	True
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	Not reported
Threat to Water Quality:	Not reported
Sub Chapter 15:	False
Regional Board Project Officer:	UN1
Number of WMUDS at Facility:	1
Section Range:	Not reported
RCRA Facility:	Not reported
Waste Discharge Requirements:	Not reported
Self-Monitoring Rept. Frequency:	Not reported
Waste Discharge System ID:	2 000070330
Solid Waste Information ID:	Not reported

HIST UST:

Region:	STATE
Facility ID:	00000045659
Facility Type:	Other
Other Type:	COMMON CARRIER PIPEL
Total Tanks:	0001
Contact Name:	J.E.DEAN
Telephone:	4154678107
Owner Name:	SOUTHERN PACIFIC PIPE LINES, I
Owner Address:	610 SOUTH MAIN STREET
Owner City,St,Zip:	LOS ANGELES, CA 90014
Tank Num:	001
Container Num:	D-1

SAN FRANCISCO AIRPORT JUNCTION (Continued) **U001593885**

Year Installed: 1969
Tank Capacity: 00001800
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: Not reported
Leak Detection: Visual

AST:
Owner: Level 3 Communications LLC
Total Gallons: 6,400
Certified Unified Program Agencies: San Francisco

Owner: China Basin/ San Francisco LLC
Total Gallons: 2,550
Certified Unified Program Agencies: San Francisco

F31 **MAJOR LEGAL SERVICES** **RCRA-SQG** **1001115533**
WNW **185 BERRY ST** **FINDS** **CAR000014696**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 2 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

RCRA-SQG:
Date form received by agency: 08/22/1996
Facility name: MAJOR LEGAL SERVICES
Facility address: 185 BERRY ST
LOBBY 1 STE 3000
SAN FRANCISCO, CA 941071729
EPA ID: CAR000014696
Mailing address: BERRY ST
LOBBY FIRST STE 3000
SAN FRANCISCO, CA 941071729
Contact: GEORGE BOUBALOS
Contact address: 185 BERRY ST LOBBY FIRST STE 3000
SAN FRANCISCO, CA 941071729
Contact country: US
Contact telephone: (415) 873-9292
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: RICHARD KIPPER
Owner/operator address: 185 BERRY ST LOBBY 1 STE 3000
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 905-1200
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

MAJOR LEGAL SERVICES (Continued) **1001115533**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002913704

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

F32 **GTE SPRINT, CHINA BASIN** **CA FID UST** **S101591923**
WNW **185 BERRY ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 3 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

CA FID UST:
Facility ID: 38000150
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4157775608
Mail To: Not reported
Mailing Address: 2330 SHAWNEE MISSION
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported

GTE SPRINT, CHINA BASIN (Continued) **S101591923**

NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 5604
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-005604-000001
Actv Date: Not reported
Capacity: 10000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 1

Status: Active
Comp Number: 5604
Number: 3
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

F33 **SPRINT, CHINA** **UST** **U003995438**
WNW **185 BERRY ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.126 mi.
664 ft. **Site 4 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

SAN FRANCISCO CO. UST:
Facility ID: 5604
Facility Status: Not reported
Number Of Tanks: Not reported
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Sprint
Care Of Addr: Not reported
2nd Care Of Add: Not reported
Mailing Address: 6480 Sprint Pkwy
Mailing City,St,Zip: Overland Park, KS 66251

SPRINT, CHINA (Continued) **U003995438**

Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	Not reported
Application Name:	Not reported
Action Type:	1
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

Tank ID:	1002
Tank Test:	Not reported
Local Tank Id:	5604001002
Tank Manufacturer:	Owens-Corning
Compartmentalized Tank:	No
# Of Tank Compartments:	Not reported
Date Tank Installed:	5/1/1990
Tank Capacity:	4000
Additional Desc:	Not reported
Tank Use:	1
Petroleum Type:	Diesel
Common Name:	Not reported
Case Number:	68476-34-6
Type Of Tank:	Double wall
Primary Tank Material:	Fiberglass/plastic
Secondary Tank Material:	Not reported
Tank Interior Lining:	Unknown
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	drop tube, striker plate
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	No
Othr Tnk Corrosive Prtctn:	Unknown
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Continuous Interstitial Monitoring
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	0
Tank Filled With Inert Material:	0
Piping System Type (Underground):	Gravity
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Double Wall
Piping Manufacturer (Underground):	Smith
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Fiberglass
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported

SPRINT, CHINA (Continued) **U003995438**

Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	9/27/2005
2nd Containment Test:	4/19/2006
Spill Containment Present:	Yes
Drop Tube Present:	Yes
Striker Plate Present:	Yes
Alarm Present:	No
Ball Float Present:	No
Fill Tube Present:	Yes
Other Tank Leak Detection Present:	No

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported

SPRINT, CHINA (Continued) **U003995438**

Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	680
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported

SPRINT, CHINA (Continued) **U003995438**

Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	381
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported

SPRINT, CHINA (Continued) **U003995438**

Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	758
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported

SPRINT, CHINA (Continued) **U003995438**

Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional CA_UST_SF: record(s) in the EDR Site Report.

F34 **GTE SPRINT, CHINA BASIN** **UST** **U003879531**
WNW **185 BERRY ST FL 6** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 5 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

UST:

Facility ID:	5604
Latitude:	37.77611
Longitude:	-122.39301

F35 **LEVEL 3 COMMUNICATIONS** **LUST** **1000596329**
WNW **185 BERRY STREET** **EMI** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 6 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

LUST REG 2:

Region:	2
Facility Id:	38-0104
Facility Status:	Case Closed
Case Number:	10296
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0104
Facility Status:	Case Closed
Case Number:	10296
Case Type:	Other ground water affected
Release Date:	9/9/1988
Discovered Date:	9/16/1988
Substance:	Waste Oil
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	9/9/1988
Case Closed:	11/2/1994
Closed Date:	11/2/1994
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	9/13/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	4TH ST
NOR Date:	9/13/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported

LEVEL 3 COMMUNICATIONS (Continued) **1000596329**

MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	2A
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	9/22/1988
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Used oil (waste
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	17000
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

EMI:

Year:	2002
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

LEVEL 3 COMMUNICATIONS (Continued) **1000596329**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2003
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2004
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.004
Reactive Organic Gases Tons/Yr:	0.0033468
Carbon Monoxide Emissions Tons/Yr:	0.006
NOX - Oxides of Nitrogen Tons/Yr:	0.037
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.002
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0.001952
Year:	2005
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.004
Reactive Organic Gases Tons/Yr:	.0033468
Carbon Monoxide Emissions Tons/Yr:	.006
NOX - Oxides of Nitrogen Tons/Yr:	.037
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.001952
Year:	2006

LEVEL 3 COMMUNICATIONS (Continued) **1000596329**

County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.024
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.001
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.000976

Year:	2006
County Code:	38
Air Basin:	SF
Facility ID:	16851
Air District Name:	BA
SIC Code:	4812
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.004
Reactive Organic Gases Tons/Yr:	.0033468
Carbon Monoxide Emissions Tons/Yr:	.01
NOX - Oxides of Nitrogen Tons/Yr:	.045
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.003
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.002928

Year:	2007
County Code:	38
Air Basin:	SF
Facility ID:	16851
Air District Name:	BA
SIC Code:	4812
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.004
Reactive Organic Gases Tons/Yr:	.0033468
Carbon Monoxide Emissions Tons/Yr:	.01
NOX - Oxides of Nitrogen Tons/Yr:	.045
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.003
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.002928

Year:	2007
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD

LEVEL 3 COMMUNICATIONS (Continued) **1000596329**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.024
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.001
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.000976

Year:	2008
County Code:	38
Air Basin:	SF
Facility ID:	16851
Air District Name:	BA
SIC Code:	4812
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.017
Reactive Organic Gases Tons/Yr:	.0142239
Carbon Monoxide Emissions Tons/Yr:	.046
NOX - Oxides of Nitrogen Tons/Yr:	.213
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.015
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.01464

Year:	2008
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.033
Reactive Organic Gases Tons/Yr:	.0276111
Carbon Monoxide Emissions Tons/Yr:	.047
NOX - Oxides of Nitrogen Tons/Yr:	.303
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.014
Part. Matter 10 Micrometers & Smllr Tons/Yr:	.013664

Year:	2009
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.3000000000000002E-2
Reactive Organic Gases Tons/Yr:	0.0276111
Carbon Monoxide Emissions Tons/Yr:	0.047
NOX - Oxides of Nitrogen Tons/Yr:	0.30299999999999999

LEVEL 3 COMMUNICATIONS (Continued) **1000596329**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0143442622950819
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0.014
Year:	2009
County Code:	38
Air Basin:	SF
Facility ID:	16851
Air District Name:	BA
SIC Code:	4812
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.7000000000000001E-2
Reactive Organic Gases Tons/Yr:	1.4223899999999999E-2
Carbon Monoxide Emissions Tons/Yr:	4.5999999999999999E-2
NOX - Oxides of Nitrogen Tons/Yr:	0.21299999999999999
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1.5368852459016299E-2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1.4999999999999999E-2
Year:	2010
County Code:	38
Air Basin:	SF
Facility ID:	16851
Air District Name:	BA
SIC Code:	4812
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.019
Reactive Organic Gases Tons/Yr:	0.0158973
Carbon Monoxide Emissions Tons/Yr:	5.8000000000000003E-2
NOX - Oxides of Nitrogen Tons/Yr:	0.26500000000000001
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1.9467213114753999E-2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0.019
Year:	2010
County Code:	38
Air Basin:	SF
Facility ID:	14775
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.012
Reactive Organic Gases Tons/Yr:	0.0100404
Carbon Monoxide Emissions Tons/Yr:	1.7999999999999999E-2
NOX - Oxides of Nitrogen Tons/Yr:	0.12
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	5.1229508196721299E-3
Part. Matter 10 Micrometers & Smllr Tons/Yr:	5.0000000000000001E-3

F36 **UCSF AT CHINA BASIN LANDING** **RCRA-SQG** **1007117603**
WNW **185 BERRY ST STE 350** **HAZNET** **CAR000150078**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 7 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

RCRA-SQG:

Date form received by agency:	12/08/2003
Facility name:	UCSF AT CHINA BASIN LANDING
Facility address:	185 BERRY ST STE 350 SAN FRANCISCO, CA 94107
EPA ID:	CAR000150078
Mailing address:	50 MEDICAL CTR WAY SAN FRANCISCO, CA 94143-0942
Contact:	EUGENE LAU
Contact address:	50 MEDICAL CTR WAY SAN FRANCISCO, CA 94143-0942
Contact country:	US
Contact telephone:	415-476-1300
Contact email:	Not reported
EPA Region:	09
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MCCARTHY COOK CO
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	UCSF
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	03/06/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

UCSF AT CHINA BASIN LANDING (Continued) **1007117603**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Hazardous Waste Summary:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D009
Waste name: MERCURY

Waste code: D011
Waste name: SILVER

Waste code: F003
Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: U122
Waste name: FORMALDEHYDE

Waste code: U188
Waste name: PHENOL

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 11/23/2010

UCSF AT CHINA BASIN LANDING (Continued) **1007117603**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

HAZNET:
Year: 2012
Gepaid: CAR000150078
Contact: BERT LUISTRO
Telephone: 4154760964
Mailing Name: Not reported
Mailing Address: 50 MEDICAL CENTER WAY
Mailing City,St,Zip: SAN FRANCISCO, CA 941430942
Gen County: San Francisco
TSD EPA ID: CAD980884183
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0675
Facility County: San Francisco

Year: 2012
Gepaid: CAR000150078
Contact: BERT LUISTRO
Telephone: 4154760964
Mailing Name: Not reported
Mailing Address: 50 MEDICAL CENTER WAY
Mailing City,St,Zip: SAN FRANCISCO, CA 941430942
Gen County: San Francisco
TSD EPA ID: CAD980884183
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.201
Facility County: San Francisco

Year: 2012
Gepaid: CAR000150078
Contact: BERT LUISTRO
Telephone: 4154760964
Mailing Name: Not reported
Mailing Address: 50 MEDICAL CENTER WAY
Mailing City,St,Zip: SAN FRANCISCO, CA 941430942
Gen County: San Francisco
TSD EPA ID: CAD980884183
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.2835
Facility County: San Francisco

Year: 2012
Gepaid: CAR000150078
Contact: BERT LUISTRO
Telephone: 4154760964

UCSF AT CHINA BASIN LANDING (Continued) **1007117603**

Mailing Name: Not reported
Mailing Address: 50 MEDICAL CENTER WAY
Mailing City,St,Zip: SAN FRANCISCO, CA 941430942
Gen County: San Francisco
TSD EPA ID: CAD980884183
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.085
Facility County: San Francisco

Year: 2012
Gepaid: CAR000150078
Contact: BERT LUISTRO
Telephone: 4154760964
Mailing Name: Not reported
Mailing Address: 50 MEDICAL CENTER WAY
Mailing City,St,Zip: SAN FRANCISCO, CA 941430942
Gen County: San Francisco
TSD EPA ID: CAD980884183
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.73
Facility County: San Francisco

Click this hyperlink while viewing on your computer to access
141 additional CA_HAZNET: record(s) in the EDR Site Report.

F37 **D R EXCAVATING AND TRUCKING** **RCRA NonGen / NLR** **1004678101**
WNW **185 BERRY ST** **FINDS** **CAR000105080**
1/8-1/4 **SAN FRANCISCO, CA**
0.126 mi.
664 ft. **Site 8 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/12/2001
Facility name: D R EXCAVATING AND TRUCKING
Facility address: 185 BERRY ST
SAN FRANCISCO, CA 94124
EPA ID: CAR000105080
Mailing address: P O BOX 281073
SAN FRANCISCO, CA 941281073
Contact: DAVID RAMIREZ
Contact address: P O BOX 281073
SAN FRANCISCO, CA 941281073
Contact country: US
Contact telephone: (415) 519-3060
Contact email: Not reported
EPA Region: 09
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: KATELLUS URBAN DEV CORP

D R EXCAVATING AND TRUCKING (Continued) **1004678101**

Owner/operator address: 255 CHANNEL ST
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 355-6600
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110012231931

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

F38 **CHINA BASIN TOC "SFS"** **HIST UST** **U001595243**
WNW **185 BERRY ST BLDG 4SUIT** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.126 mi.
664 ft. **Site 9 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

HIST UST:
Region: STATE
Facility ID: 00000059609
Facility Type: Other
Other Type: TELCOMMUNICATIONS
Total Tanks: 0001
Contact Name: ALVIN E. JOHNSON
Telephone: 4155438510
Owner Name: GTE SPRINT
Owner Address: ONE ADRIAN COURT
Owner City,St,Zip: BURLINGAME, CA 94010

CHINA BASIN TOC "SFS" (Continued) **U001595243**

Tank Num: 001
Container Num: 1
Year Installed: 1984
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Stock Inventor

F39 **CHINA BASIN PROPERTIES** **HIST CORTESE** **S103981370**
WNW **185 BERRY STREET** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107** **SWEEPS UST**
0.126 mi.
664 ft. **Site 10 of 10 in cluster F**

Relative:
Higher

Actual:
9 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0104

LUST:
Region: STATE
Global Id: T0607500095
Latitude: 37.776604
Longitude: -122.392309
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 11/02/1994
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0104
LOC Case Number: 10296
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500095
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500095
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org

CHINA BASIN PROPERTIES (Continued) **S103981370**

Phone Number: Not reported

Status History:
Global Id: T0607500095
Status: Completed - Case Closed
Status Date: 11/02/1994

Global Id: T0607500095
Status: Open - Case Begin Date
Status Date: 09/16/1988

Regulatory Activities:
Global Id: T0607500095
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500095
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

SWEEPS UST:
Status: Not reported
Comp Number: 8800
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008800-000001
Actv Date: Not reported
Capacity: 550
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 3

Status: Not reported
Comp Number: 8800
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008800-000002
Actv Date: Not reported
Capacity: 500
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED

CHINA BASIN PROPERTIES (Continued) **S103981370**

Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	8800
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-008800-000003
Actv Date:	Not reported
Capacity:	500
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	Not reported

---

40 **C C S F PORT OF SF** **RCRA NonGen / NLR** **1000227235**
NNE **PIER 46** **CAD982482226**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.139 mi.
733 ft.

Relative:
Lower

Actual:
0 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/20/2002
Facility name:	C C S F PORT OF SF
Facility address:	PIER 46 SAN FRANCISCO, CA 94107
EPA ID:	CAD982482226
Mailing address:	101 GROVE ST RM 217 SAN FRANCISCO, CA 94102
Contact:	DAVE WELLS
Contact address:	1390 MARKET ST STE 210 SAN FRANCISCO, CA 94102
Contact country:	US
Contact telephone:	(415) 252-3975
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	County
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	CITY AND COUNTY OF SAN FRANCISCO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999

C C S F PORT OF SF (Continued) **1000227235**

Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: C C S F PORT OF SF
Classification: Small Quantity Generator

Date form received by agency: 03/20/1996
Facility name: C C S F PORT OF SF
Site name: CITY & CO. OF SF - PIER 46B
Classification: Large Quantity Generator

Violation Status: No violations found

G41 **ANCHOR ENGINE REBUILDERS INC** **EDR US Hist Auto Stat** **1009002633**
NNW **165 KING ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.148 mi.
779 ft. **Site 1 of 5 in cluster G**

Relative:
Higher

Actual:
15 ft.

EDR Historical Auto Stations:
Name: ANCHOR ENGINE REBUILDERS INC
Year: 1958
Type: AUTOMOBILE REPAIRING

H42 **PIER 50 GEAR ROOM** **HIST UST** **U001595294**
SSE **300 CHINA BASIN** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.157 mi.
830 ft. **Site 1 of 2 in cluster H**

Relative:
Higher

Actual:
5 ft.

HIST UST:

Region:	STATE
Facility ID:	00000036108
Facility Type:	Other
Other Type:	Not reported
Total Tanks:	0001
Contact Name:	J. TUCKER
Telephone:	4152711853
Owner Name:	STEVEDORING SERVICES OF AMERIC
Owner Address:	1195 MARITIME ST.
Owner City,St,Zip:	OAKLAND, CA 94607
Tank Num:	001
Container Num:	0000000001
Year Installed:	1968
Tank Capacity:	00007400
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Stock Inventor

G43 **CONSTRUCTION DEVELOPMENT** **LUST** **S105194747**
NNW **160 KING ST.** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.166 mi.
874 ft. **Site 2 of 5 in cluster G**

Relative:
Higher

Actual:
17 ft.

LUST:

Region:	STATE
Global Id:	T0607591191
Latitude:	37.779252
Longitude:	-122.391369
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/30/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2037
LOC Case Number:	11419
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607591191
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO

CONSTRUCTION DEVELOPMENT (Continued) **S105194747**

Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Global Id: T0607591191
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607591191
Status: Completed - Case Closed
Status Date: 11/30/2000

Global Id: T0607591191
Status: Open - Case Begin Date
Status Date: 08/15/2000

Regulatory Activities:
Global Id: T0607591191
Action Type: ENFORCEMENT
Date: 11/30/2000
Action: Notice of Responsibility

Global Id: T0607591191
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607591191
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2037
Facility Status: Case Closed
Case Number: 11419
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

G44 **ROSENBERG HOOD** **UST** **U004004304**
NNW **160 KING ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.166 mi.
874 ft. **Site 3 of 5 in cluster G**

Relative:
Higher

Actual:
17 ft.

SAN FRANCISCO CO. UST:

Facility ID:	24727
Facility Status:	Not reported
Number Of Tanks:	4
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	255 Shipley Street
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Golden Gate Tank
Application Date:	7/7/2000
Application Name:	Cathy Keller
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	8/17/2000
UST Close ID:	3989
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

ROSENBERG HOOD (Continued) **U004004304**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

G45 **SCCSD EAST CLIFF PUMP STA** **HIST CORTESE** **S104809917**
NNW **160 KING** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.166 mi.
874 ft. **Site 4 of 5 in cluster G**

Relative:
Higher

Actual:
17 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	2689

G46 **CONSTRUCTION** **LUST** **S105627930**
NNW **160 KING ST.** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.166 mi.
874 ft. **Site 5 of 5 in cluster G**

Relative:
Higher

Actual:
17 ft.

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	02-400-019
Facility Status:	Case Closed
Case Number:	11419
Case Type:	Soil only
Release Date:	Not reported

CONSTRUCTION (Continued) **S105627930**

Discovered Date:	8/15/2000
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	11/30/2000
Case Closed:	1/30/2001
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	8/15/2000
Entered Date:	11/30/2000
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Debbie Penney
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	3rd St.
NOR Date:	Not reported
MTBE Current:	Not reported
MTBE Current Date:	8/15/2000
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	8/15/2000
Review Date:	1/30/2001
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	11/30/2000
Basin:	DOWNTOWN
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	8/15/2000
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported

CONSTRUCTION (Continued) **S105627930**

Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	0.067
TPH Date:	8/15/2000
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

I47 **EDR US Hist Cleaners** **1015008155**
WNW **185 BERRY ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.171 mi.
903 ft. **Site 1 of 2 in cluster I**

Relative:
Higher

Actual:
6 ft.

EDR Historical Cleaners:

Name:	DANNYS CLEANERS
Year:	2002
Address:	185 BERRY ST

J48 **ARES COMMERCIAL** **HIST CORTESE** **S103631856**
South **1501 3RD** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.174 mi.
921 ft. **Site 1 of 2 in cluster J**

Relative:
Higher

Actual:
8 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0029

J49 **ARES COMMERCIAL PROPERTIES** **CA FID UST** **S101591879**
South **1501 3RD ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.174 mi.
921 ft. **Site 2 of 2 in cluster J**

Relative:
Higher

Actual:
8 ft.

CA FID UST:

Facility ID:	38000074
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	1501 3RD ST

ARES COMMERCIAL PROPERTIES (Continued) **S101591879**

Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 8512
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 8512
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008512-000001
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 2

Status: Not reported
Comp Number: 8512
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008512-000002
Actv Date: Not reported
Capacity: 1000

ARES COMMERCIAL PROPERTIES (Continued) **S101591879**

Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

H50 **MISSION BAY, PARK P16 MITIGATION PROJECT** **US BROWNFIELDS** **1014949202**
SSE **MISSION BAY BLVD./TERRY FRANCOIS BLVD.** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94158**
0.181 mi.
955 ft. **Site 2 of 2 in cluster H**

Relative:
Higher

Actual:
5 ft.

US BROWNFIELDS:

Recipient name:	California Department of Toxic Substances Control
Grant type:	BCRLF
Property name:	MISSION BAY, PARK P16 MITIGATION PROJECT
Property #:	Not reported
Parcel size:	1.25
Property Description:	Not reported
Latitude:	37.7704166
Longitude:	-122.38638909999997
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	111265
Start date:	15-MAR-10
Completed date:	15-AUG-10
Acres cleaned up:	Not reported
Cleanup funding:	200000
Cleanup funding source:	US EPA - Brownfields RLF Subgrant
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	H
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96987501
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported

MISSION BAY, PARK P16 MITIGATION PROJECT (Continued) **1014949202**

Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
Unknown found:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported

K51 **SOUTHERN PACIFIC** **UST** **U004051285**
WSW **415 CHANNEL ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.182 mi.
960 ft. **Site 1 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

SAN FRANCISCO CO. UST:

Facility ID:	4039
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported

SOUTHERN PACIFIC (Continued) **U004051285**

Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	1/6/1988
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	749
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported

SOUTHERN PACIFIC (Continued) **U004051285**

Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

K52 **SOUTHERN PACIFIC TRANSPORTATIO** **HIST CORTESE** **U001595310**
WSW **415 CHANNEL ST** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107** **HIST UST**
0.182 mi.
960 ft. **Site 2 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0354

LUST:

Region:	STATE
Global Id:	T0607500313
Latitude:	37.7661
Longitude:	-122.3927
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/21/2008
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0354
LOC Case Number:	10591
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500313
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)

SOUTHERN PACIFIC TRANSPORTATIO (Continued) **U001595310**

Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500313
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500313
Status: Completed - Case Closed
Status Date: 10/21/2008

Global Id: T0607500313
Status: Open - Case Begin Date
Status Date: 02/01/1988

Global Id: T0607500313
Status: Open - Site Assessment
Status Date: 02/01/1988

Regulatory Activities:
Global Id: T0607500313
Action Type: ENFORCEMENT
Date: 10/21/2008
Action: Closure/No Further Action Letter

Global Id: T0607500313
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500313
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500313
Action Type: ENFORCEMENT
Date: 10/15/2008
Action: Closure/No Further Action Letter - #10591CCL

LUST REG 2:
Region: 2
Facility Id: 38-0354
Facility Status: Leak being confirmed
Case Number: 10591
How Discovered: Not reported
Leak Cause: Not reported

SOUTHERN PACIFIC TRANSPORTATIO (Continued) **U001595310**

Leak Source: Not reported
Date Leak Confirmed: 2/1/1988
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0354
Facility Status: Leak being confirmed
Case Number: 10591
Case Type: Soil only
Release Date: 2/1/1988
Discovered Date: 1/5/1989
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 2/1/1988
Case Closed: Not reported
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: 1/30/1996
Entered Date: 1/26/1996
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Regional Board
Program: LOP
Responsible Party: CATELLUS DEV. CO.
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: MA
Cross Street: Not reported
NOR Date: 1/26/1996
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal
Interim Remediation: No
Priority: Not reported

SOUTHERN PACIFIC TRANSPORTATIO (Continued) **U001595310**

Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	2/22/1988
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

HIST UST:

Region:	STATE
Facility ID:	00000024508
Facility Type:	Other
Other Type:	RAILYARD
Total Tanks:	0003
Contact Name:	JOSE VARGAS
Telephone:	4155413197
Owner Name:	SOUTHERN PACIFIC TRANSPORTATIO
Owner Address:	ONE MARKET PLAZA
Owner City,St,Zip:	SAN FRANCISCO, CA 94105
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	3/8" inches
Leak Detection:	Pressure Test
Tank Num:	002
Container Num:	2
Year Installed:	Not reported

SOUTHERN PACIFIC TRANSPORTATIO (Continued) **U001595310**

Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 3/8" inches
Leak Detection: Pressure Test

Tank Num: 003
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: Pressure Test

K53 **SOUTHERN PACIFIC TRANSPORT.** **CA FID UST** **S101629569**
WSW **415 CHANNEL ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.182 mi.
960 ft. **Site 3 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

CA FID UST:
Facility ID: 38000393
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 415 CHANNEL ST
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 4039
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-004039-000001
Actv Date: Not reported
Capacity: 5000
Tank Use: M.V. FUEL
Stg: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 3

SOUTHERN PACIFIC TRANSPORT. (Continued) **S101629569**

Status:	Not reported
Comp Number:	4039
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-004039-000002
Actv Date:	Not reported
Capacity:	5000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	LEADED GASOL
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	4039
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-004039-000003
Actv Date:	Not reported
Capacity:	1000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	LEADED GASOL
Number Of Tanks:	Not reported

54
South
1/8-1/4
0.190 mi.
1002 ft.

ARES COMMERCIAL PROPERTIES **LUST** **S111711373**
1501 03RD ST **N/A**
SAN FRANCISCO, CA 94107

Relative:
Higher

Actual:
6 ft.

LUST:

Region:	STATE
Global Id:	T0607500027
Latitude:	37.770404
Longitude:	-122.388189
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/10/1994
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0029
LOC Case Number:	10220
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

ARES COMMERCIAL PROPERTIES (Continued) **S111711373**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500027
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500027
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500027
Status:	Completed - Case Closed
Status Date:	11/10/1994

Global Id:	T0607500027
Status:	Open - Case Begin Date
Status Date:	12/18/1989

Regulatory Activities:

Global Id:	T0607500027
Action Type:	ENFORCEMENT
Date:	02/03/1994
Action:	Notice of Responsibility

Global Id:	T0607500027
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500027
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

I55 WNW 1/8-1/4 0.190 mi. 1005 ft. **AVALON BAY MISSION BAY PROJECT** **RCRA NonGen / NLR** **1004678536**
4TH ST AND BERRY ST **FINDS** **CAR000110270**
SAN FRANCISCO, CA 94107

Site 2 of 2 in cluster I

Relative: Higher

Actual: 6 ft.

RCRA NonGen / NLR:

Date form received by agency:	12/11/2001
Facility name:	AVALON BAY MISSION BAY PROJECT
Facility address:	4TH ST AND BERRY ST SAN FRANCISCO, CA 94107
EPA ID:	CAR000110270
Mailing address:	41 DORMAN ST STE 3 SAN FRANCISCO, CA 94124
Contact:	TED BARRON
Contact address:	41 DORMAN ST STE 3 SAN FRANCISCO, CA 94124
Contact country:	US
Contact telephone:	(415) 716-4877
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DEREK SMITH
Owner/operator address:	41 DORMAN ST STE 3 SAN FRANCISCO, CA 94124
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 282-5160
Legal status:	County
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110012248594

Environmental Interest/Information System

AVALON BAY MISSION BAY PROJECT (Continued) **1004678536**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

K56 **SANTA FE PACIFIC REALTY CORP** **LUST** **S108196102**
WSW **195 CHANNEL ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.191 mi.
1010 ft. **Site 4 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

LUST:

Region:	STATE
Global Id:	T0607500922
Latitude:	37.7745459
Longitude:	-122.3899246
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/13/1998
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	VP
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1029
LOC Case Number:	10498
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500922
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0607500922
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500922
Status:	Completed - Case Closed
Status Date:	07/13/1998

SANTA FE PACIFIC REALTY CORP (Continued) **S108196102**

Global Id: T0607500922
Status: Open - Case Begin Date
Status Date: 06/22/1987

Global Id: T0607500922
Status: Open - Remediation
Status Date: 06/18/1998

Regulatory Activities:
Global Id: T0607500922
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607500922
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500922
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

K57 **CATELLUS** **UST** **U003903197**
WSW **195 CHANNEL ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.191 mi.
1010 ft. **Site 5 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

SAN FRANCISCO CO. UST:
Facility ID: 24335
Facility Status: Not reported
Number Of Tanks: Not reported
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Not reported
Care Of Addr: Not reported
2nd Care Of Add: Not reported
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Permit Number: Not reported
Permit Approved By: Not reported
Permit Expiration Date: Not reported
Applications: Not reported
Application Date: 6/19/1992
Application Name: Not reported
Action Type: Not reported
Yr Spill/Overfill Installed1: Not reported
Yr Spill/Overfill Installed2: Not reported
Yr Spill/Overfill Installed3: Not reported

Tank ID: Not reported
Tank Test: Not reported
Local Tank Id: Not reported
Tank Manufacturer: Not reported

CATELLUS (Continued) **U003903197**

Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	7/27/1992
UST Close ID:	1022
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

L58 **UNKNOWN** **HIST CORTESE** **S100453837**
North **1289 2ND ST** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107** **Notify 65**
0.192 mi.
1012 ft. **Site 1 of 2 in cluster L**

Relative:
Higher

Actual:
11 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0442

LUST:

Region:	STATE
Global Id:	T0607500393
Latitude:	37.7794958
Longitude:	-122.3886775
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/16/1992
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	VP
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0442
LOC Case Number:	38-0442
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500393
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0607500393
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500393
Status:	Completed - Case Closed
Status Date:	10/16/1992

Global Id:	T0607500393
Status:	Open - Case Begin Date
Status Date:	09/01/1992

UNKNOWN (Continued) **S100453837**

Regulatory Activities:

Global Id:	T0607500393
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500393
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607500393
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

LUST REG 2:

Region:	2
Facility Id:	38-0442
Facility Status:	Case Closed
Case Number:	38-0442
How Discovered:	Tank Closure
Leak Cause:	Structure Failure
Leak Source:	Tank
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

Notify 65:

Date Reported:	19921002
Staff Initials:	Not reported
Board File Number:	0LG921239
Facility Type:	Leak Rpt
Discharge Date:	Not reported
Incident Description:	94122-2733

K59 **SANTA FE PACIFIC REALTY C** **HIST CORTESE** **S103947076**
WSW **195 CHANNEL** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.192 mi.
1015 ft. **Site 6 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1029

M60 **MISSION BAY REDEVELOPMENT AREA** **SLIC** **S106162325**
West **MISSION BAY DEVELOPMENT AREA** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94142**
0.199 mi.
1050 ft. **Site 1 of 3 in cluster M**

Relative:
Lower

Actual:
4 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	05/14/2009
Global Id:	T0607591577
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Lead Agency Case Number:	Not reported
Latitude:	37.7750567824051
Longitude:	-122.393445968628
Case Type:	Cleanup Program Site
Case Worker:	RL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38S0044
File Location:	Regional Board
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Lead, Diesel, Gasoline, Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region:	2
Facility ID:	38S0044
Facility Status:	Case Closed
Date Closed:	8/15/2001
Local Case #:	Not reported
How Discovered:	Tank Closure
Leak Cause:	UNK
Leak Source:	UNK
Date Confirmed:	Not reported
Date Prelim Site Assmnt Workplan Submitted:	Not reported
Date Preliminary Site Assessment Began:	Not reported
Date Pollution Characterization Began:	Not reported
Date Remediation Plan Submitted:	Not reported
Date Remedial Action Underway:	5/25/1999
Date Post Remedial Action Monitoring Began:	Not reported

N61 **GOLDEN BRANDS** **UST** **U003903785**
WSW **255 CHANNEL ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.200 mi.
1058 ft. **Site 1 of 3 in cluster N**

Relative:
Higher

Actual:
5 ft.

SAN FRANCISCO CO. UST:

Facility ID:	7980
Facility Status:	Not reported
Number Of Tanks:	2
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported

GOLDEN BRANDS (Continued) **U003903785**

Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	7/22/1994
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	8/4/1994
UST Close ID:	1776
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported

GOLDEN BRANDS (Continued) **U003903785**

Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	10/19/1994
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

N62 **GOLDEN BRANDS BOTTLING CO. INC** **CA FID UST** **S101623225**
WSW **255 CHANNEL ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.200 mi.
1058 ft. **Site 2 of 3 in cluster N**

Relative:
Higher

Actual:
5 ft.

CA FID UST:

Facility ID:	38000206
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4158634669
Mail To:	Not reported
Mailing Address:	255 CHANNEL ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Active
Comp Number:	7980
Number:	1
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-007980-000001
Actv Date:	09-30-92
Capacity:	7500
Tank Use:	UNKNOWN
Stg:	P

GOLDEN BRANDS BOTTLING CO. INC (Continued) **S101623225**

Content:	LEADED GASOL
Number Of Tanks:	2
Status:	Active
Comp Number:	7980
Number:	1
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-007980-000002
Actv Date:	09-30-92
Capacity:	5000
Tank Use:	UNKNOWN
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported

N63 **GOLDEN BRANDS BOTTLING CO., IN** **HIST CORTESE** **U001595262**
WSW **255 CHANNEL ST** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107** **HIST UST**
0.200 mi. **CHMIRS**
1058 ft. **Site 3 of 3 in cluster N**

Relative:
Higher

Actual:
5 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0454

LUST:

Region:	STATE
Global Id:	T0607500404
Latitude:	37.7732
Longitude:	-122.3933
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/09/1995
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0454
LOC Case Number:	10324
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500404
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210

GOLDEN BRANDS BOTTLING CO., IN (Continued) **U001595262**

City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Global Id: T0607500404
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607500404
Status: Completed - Case Closed
Status Date: 03/09/1995

Global Id: T0607500404
Status: Open - Case Begin Date
Status Date: 12/24/1991

Regulatory Activities:
Global Id: T0607500404
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500404
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

LUST REG 2:
Region: 2
Facility Id: 38-0454
Facility Status: Case Closed
Case Number: 10324
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0454
Facility Status: Case Closed

GOLDEN BRANDS BOTTLING CO., IN (Continued) **U001595262**

Case Number:	10324
Case Type:	Other ground water affected
Release Date:	11/25/1991
Discovered Date:	12/24/1991
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	11/25/1991
Case Closed:	3/9/1995
Closed Date:	3/9/1995
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	11/14/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	4TH ST
NOR Date:	11/14/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	3/10/1992
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	3/10/1992
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil

GOLDEN BRANDS BOTTLING CO., IN (Continued) **U001595262**

Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	66
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	11/25/91 [leak

HIST UST:

Region:	STATE
Facility ID:	00000008964
Facility Type:	Other
Other Type:	BEV. DISTRIBUTOR
Total Tanks:	0002
Contact Name:	PAUL MOLAKIDES
Telephone:	4158634669
Owner Name:	GOLDEN BRANDS BOTTLING CO., IN
Owner Address:	255 CHANNEL ST.
Owner City,St,Zip:	SAN FRANCISCO, CA 94107

Tank Num:	001
Container Num:	I
Year Installed:	1975
Tank Capacity:	00007500
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	12 unknown
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	II
Year Installed:	1979
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	12 unknown
Leak Detection:	Stock Inventor

CHMIRS:

OES Incident Number:	009783
OES notification:	Not reported
OES Date:	8/28/1995
OES Time:	06:01:54 PM
Incident Date:	Not reported
Date Completed:	**Not reported**

GOLDEN BRANDS BOTTLING CO., IN (Continued) **U001595262**

Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?:		Not reported
Resp Agncy Personel # Of Decontaminated:		Not reported
Responding Agency Personel # Of Injuries:		Not reported
Responding Agency Personel # Of Fatalities:		Not reported
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	YES	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	pg & e	
Containment:	Not reported	
What Happened:	Not reported	
Type:	CHEMICAL	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	1995	
Agency:	san francisco fire dept.	
Incident Date:	28/1455 Aug 95	
Admin Agency:	Not reported	
Amount:	2 gals.	
Contained:	NO	
Site Type:	OTHER	
E Date:	Not reported	
Substance:	possible pcb’s	
Quantity Released:	Not reported	
BBLS:	Not reported	
Cups:	Not reported	
CUFT:	Not reported	
Gallons:	Not reported	
Grams:	Not reported	
Pounds:	Not reported	

GOLDEN BRANDS BOTTLING CO., IN (Continued) **U001595262**

Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	trailer truck was backing into a loading dock when it knocked into a telephone pole.

O64 **SANTA FE PACIFIC REALTY C** **HIST CORTESE** **S101308436**
SW **1301 6TH** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.202 mi.
1065 ft. **Site 1 of 4 in cluster O**

Relative:
Higher

Actual:
7 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0260

LUST:

Region:	STATE
Global Id:	T0607500225
Latitude:	37.7711188
Longitude:	-122.3963621
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/13/1998
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	VP
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0260
LOC Case Number:	10401
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500225
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0607500225
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL

SANTA FE PACIFIC REALTY C (Continued) **S101308436**

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607500225
Status: Completed - Case Closed
Status Date: 07/13/1998

Global Id: T0607500225
Status: Open - Case Begin Date
Status Date: 12/19/1988

Global Id: T0607500225
Status: Open - Site Assessment
Status Date: 12/19/1988

Regulatory Activities:
Global Id: T0607500225
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500225
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500225
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

LUST REG 2:
Region: 2
Facility Id: 38-0260
Facility Status: Case Closed
Case Number: 10401
How Discovered: Tank Closure
Leak Cause: Structure Failure
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 12/19/1988
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

O65 **ROMEO DRAYAGE & WAREHOUSING CO** **HIST UST** **U001595300**
SW **1301 6TH ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.202 mi.
1065 ft. **Site 2 of 4 in cluster O**

Relative:
Higher

Actual:
7 ft.

HIST UST:

Region:	STATE
Facility ID:	00000030267
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0003
Contact Name:	TOM FAENZI
Telephone:	4158636938
Owner Name:	ROMEO DRAYAGE & WAREHOUSING CO
Owner Address:	1301 6TH ST
Owner City,St,Zip:	SAN FRANCISCO, CA 94107
Tank Num:	001
Container Num:	#1
Year Installed:	Not reported
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	None

O66 **SOUTHERN PACIFIC DEVELOPMENT** **CA FID UST** **S101591984**
SW **1301 6TH ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.202 mi.
1065 ft. **Site 3 of 4 in cluster O**

Relative:
Higher

Actual:
7 ft.

CA FID UST:

Facility ID:	38000301
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	1301 6TH ST

SOUTHERN PACIFIC DEVELOPMENT (Continued) **S101591984**

Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94107
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 8857
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008857-000001
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 3

Status: Not reported
Comp Number: 8857
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008857-000002
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 8857
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008857-000003
Actv Date: Not reported
Capacity: 2000

SOUTHERN PACIFIC DEVELOPMENT (Continued) **S101591984**

Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	Not reported
Status:	Active
Comp Number:	8857
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-10-93
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

P67 **MC DONALD'S CORP** **LUST** **S104889686**
NW **701 03RD ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94103**
0.209 mi.
1104 ft. **Site 1 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

LUST:

Region:	STATE
Global Id:	T0607500733
Latitude:	37.778897
Longitude:	-122.392547
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/19/1996
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	CDM
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0838
LOC Case Number:	10726
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500733
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

MC DONALD'S CORP (Continued) **S104889686**

Global Id: T0607500733
Contact Type: Local Agency Caseworker
Contact Name: CDM
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 101 GROVE STREET
City: SAN FRANCISCO
Email: Not reported
Phone Number: Not reported

Status History:
Global Id: T0607500733
Status: Completed - Case Closed
Status Date: 12/19/1996

Global Id: T0607500733
Status: Open - Case Begin Date
Status Date: 11/07/1996

Regulatory Activities:
Global Id: T0607500733
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500733
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

LUST REG 2:
Region: 2
Facility Id: 38-0838
Facility Status: Case Closed
Case Number: 10726
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0838
Facility Status: Case Closed
Case Number: 10726
Case Type: Other ground water affected
Release Date: 11/7/1996
Discovered Date: 11/7/1996

MC DONALD'S CORP (Continued) **S104889686**

Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Report Date:	11/7/1996
Case Closed:	12/19/1996
Closed Date:	12/19/1996
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	11/7/1996
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	CDM
Cross Street:	TOWNSEND ST
NOR Date:	11/7/1996
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported

MC DONALD'S CORP (Continued) **S104889686**

Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

P68 **PG AND E GAS PLANT SAN FRANCISCO** **EDR MGP** **1008407757**
NW **KING NR 3RD STREET** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.214 mi.
1129 ft. **Site 2 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

Manufactured Gas Plants:
Alternate Name:PACIFIC GAS IMPROVEMENT CO. No additional information available

---

P69 **MCDONALDS CORPORATION** **HIST CORTESE** **S103669647**
NW **701 3RD** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94105**
0.216 mi.
1138 ft. **Site 3 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0838

P70 **BOB S UNION SERVICE STATION** **EDR US Hist Auto Stat** **1009070308**
NW **701 3RD** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.216 mi.
1138 ft. **Site 4 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

EDR Historical Auto Stations:

Name:	BOB S UNION SERVICE STATION
Year:	1962
Type:	GASOLINE STATIONS
Name:	BOB S UNION SERVICE STATION
Year:	1966
Type:	GASOLINE STATIONS

P71 **SITE DEVELOPMENT** **UST** **U004004348**
NW **200 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.216 mi.
1140 ft. **Site 5 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

SAN FRANCISCO CO. UST:

Facility ID:	25904
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	405 Clyde Avenue
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Lowney Associates
Application Date:	3/27/2001
Application Name:	Doug Young
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	5/1/2001
UST Close ID:	4116
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

SITE DEVELOPMENT (Continued) **U004004348**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

P72 **LEE & PAUL** **EDR US Hist Auto Stat** **1009070003**
NW **701 3D** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.217 mi.
1144 ft. **Site 6 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

EDR Historical Auto Stations:

Name:	LEE & PAUL
Year:	1953
Type:	GASOLINE STATIONS
Name:	BOB S UNION SERVICE STATION
Year:	1958
Type:	GASOLINE STATIONS

P73 **PEER LIGHT CO.** **UST** **U003904223**
NW **179 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.219 mi.
1157 ft. **Site 7 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:

Facility ID:	25148
Facility Status:	Not reported
Number Of Tanks:	Not reported

PEER LIGHT CO. (Continued) **U003904223**

Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	11/5/1993
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	11/15/1993
UST Close ID:	1517
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported

PEER LIGHT CO. (Continued) **U003904223**

Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

K74 **WESCAR FREIGHT, INC** **CA FID UST** **S101592087**
WSW **195 CHANNEL ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.219 mi.
1158 ft. **Site 7 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

CA FID UST:

Facility ID:	38000459
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	195 CHANNEL ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	2732
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported

WESCAR FREIGHT, INC (Continued) **S101592087**

Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-002732-000001
Actv Date: Not reported
Capacity: 7500
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 1

Status: Active
Comp Number: 2732
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

K75 **SANTA FE PACIFIC REALTY CORP** **LUST** **S103472561**
WSW **195 CHANNEL ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.219 mi.
1158 ft. **Site 8 of 8 in cluster K**

Relative:
Lower

Actual:
4 ft.

LUST REG 2:
Region: 2
Facility Id: 38-1029
Facility Status: Case Closed
Case Number: 10498
How Discovered: OM
Leak Cause: Other Cause
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: 6/18/1998
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

P76
NW
1/8-1/4
0.220 mi.
1159 ft.

NGOW AUTO CENTER & BODY
177 TOWNSEND ST
SAN FRANCISCO, CA 94107

Site 8 of 23 in cluster P

CA FID UST **S101592471**
SWEEPS UST **N/A**

Relative:
Higher

Actual:
23 ft.

CA FID UST:

Facility ID:	38005296
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	177 TOWNSEND ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	2522
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-002522-000001
Actv Date:	Not reported
Capacity:	10000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	2522
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

P77
NW
1/8-1/4
0.220 mi.
1159 ft.

NGOW AUTO CENTER &
177 TOWNSEND ST
SAN FRANCISCO, CA

Site 9 of 23 in cluster P

UST **U003904105**
N/A

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:

Facility ID:	25147
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	8/5/1987
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	8/17/1987
UST Close ID:	567
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

NGOW AUTO CENTER & (Continued) **U003904105**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

P78 **178 TOWNSEND ST** **UST** **U003995273**
NW **178 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.220 mi.
1159 ft. **Site 10 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:

Facility ID:	29287
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	255 Shipley St
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Golden Gate Tank
Application Date:	4/5/2005
Application Name:	Tracy Wallace
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported

178 TOWNSEND ST (Continued) **U003995273**

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	4/12/2005
UST Close ID:	4683
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported

178 TOWNSEND ST (Continued) **U003995273**

Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

P79 **TOWNSEND** **US BROWNFIELDS** **1014677526**
NW **178 TOWNSEND STREET** **FINDS** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.220 mi.
1159 ft. **Site 11 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

US BROWNFIELDS:

Recipient name:	California Department of Toxic Substances Control
Grant type:	BCRLF
Property name:	TOWNSEND
Property #:	Not reported
Parcel size:	.51
Property Description:	Not reported
Latitude:	37.779473
Longitude:	-122.392183
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	111184
Start date:	01-AUG-08
Completed date:	17-AUG-10
Acres cleaned up:	.51
Cleanup funding:	1238000
Cleanup funding source:	US EPA - Brownfields RLF Loan
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	EPA
Grant type:	H
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96987501
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	No
Photo available:	No
Institutional controls required:	Y
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Y
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Yes
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	17-AUG-10

TOWNSEND (Continued) **1014677526**

Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Y
Surface water cleaned:	Not reported
Unknown found:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported

Recipient name:	California Department of Toxic Substances Control
Grant type:	BCRLF
Property name:	TOWNSEND
Property #:	Not reported
Parcel size:	.51
Property Description:	Not reported
Latitude:	37.779473
Longitude:	-122.392183
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported

TOWNSEND (Continued) **1014677526**

Datum:	Not reported
ACRES property ID:	111184
Start date:	01-AUG-08
Completed date:	17-AUG-10
Acres cleaned up:	.51
Cleanup funding:	12000
Cleanup funding source:	Private/Other Funding
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	178 Townsend Prop
Grant type:	H
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96987501
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	No
Photo available:	No
Institutional controls required:	Y
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Y
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Yes
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	17-AUG-10
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported

TOWNSEND (Continued) **1014677526**

PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Y
Surface water cleaned:	Not reported
Unknown found:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported

FINDS:

Registry ID: 110042110710

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

P80 **WESTWIND AUTOMOTIVE** **LUST** **S100622088**
NW **178 TOWNSEND** **EMI** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.220 mi.
1159 ft. **Site 12 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

LUST:

Region:	STATE
Global Id:	T0607584054
Latitude:	37.77922
Longitude:	-122.392094
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/11/2005
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2348
LOC Case Number:	11687
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

WESTWIND AUTOMOTIVE (Continued) **S100622088**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607584054
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607584054
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET
City:	OAKLAND
Email:	nkatyl@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607584054
Status:	Completed - Case Closed
Status Date:	07/11/2005

Global Id:	T0607584054
Status:	Open - Case Begin Date
Status Date:	04/12/2005

Global Id:	T0607584054
Status:	Open - Site Assessment
Status Date:	04/12/2005

Regulatory Activities:

Global Id:	T0607584054
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation

Global Id:	T0607584054
Action Type:	ENFORCEMENT
Date:	07/08/2005
Action:	Notice of Responsibility

Global Id:	T0607584054
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607584054
Action Type:	ENFORCEMENT
Date:	07/11/2005
Action:	Closure/No Further Action Letter

Global Id:	T0607584054

WESTWIND AUTOMOTIVE (Continued) **S100622088**

Action Type: ENFORCEMENT
Date: 07/11/2005
Action: File review

Global Id: T0607584054
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

EMI:

Year:	1995
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1997
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

WESTWIND AUTOMOTIVE (Continued) **S100622088**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1998
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1999
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	2000
County Code:	38
Air Basin:	SF
Facility ID:	4500
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

P81 **WEST WINDS** **UST** **U003916713**
NW **178 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.220 mi.
1159 ft. **Site 13 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:

Facility ID:	6164
Facility Status:	Not reported
Number Of Tanks:	Not reported
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	2/18/1994
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	3/2/1994
UST Close ID:	1607
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

WEST WINDS (Continued) **U003916713**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	5/3/1994
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

P82 **PETRUCELA & CO** **EDR US Hist Auto Stat** **1009001599**
NW **180 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.220 mi.
1162 ft. **Site 14 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

EDR Historical Auto Stations:

Name:	PETRUCELA & CO
Year:	1962
Type:	AUTOMOBILE REPAIRING
Name:	PETRUCELA & CO
Year:	1966
Type:	AUTOMOBILE REPAIRING
Name:	PETRUCELA & CO
Year:	1971
Type:	AUTOMOBILE REPAIRING
Name:	PETRUCELA & CO
Year:	1977
Type:	AUTOMOBILE REPAIRING
Name:	PETRUCELA & CO
Year:	1977
Type:	AUTOMOBILE REPAIRING

PETRUCELA & CO (Continued) **1009001599**

Name: PETRUCELA & CO
Year: 1982
Type: AUTOMOBILE REPAIRING

Name: PETRUCELA & CO
Year: 1982
Type: AUTOMOBILE REPAIRING

P83 **NOW AUTO CENTER &** **UST** **U003916350**
NW **180 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.220 mi.
1162 ft. **Site 15 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:
Facility ID: 12095
Facility Status: Not reported
Number Of Tanks: 2
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Not reported
Care Of Addr: Not reported
2nd Care Of Add: Not reported
Mailing Address: 1717 Doolittle Dr.
Mailing City,St,Zip: Not reported
Permit Number: Not reported
Permit Approved By: Not reported
Permit Expiration Date: Not reported
Applications: Scott Company of
Application Date: 5/1/1996
Application Name: Paul Ferreira
Action Type: Not reported
Yr Spill/Overfill Installed1: Not reported
Yr Spill/Overfill Installed2: Not reported
Yr Spill/Overfill Installed3: Not reported

Tank ID: Not reported
Tank Test: Not reported
Local Tank Id: Not reported
Tank Manufacturer: Not reported
Compartmentalized Tank: Not reported
Of Tank Compartments: Not reported
Date Tank Installed: Not reported
Tank Capacity: Not reported
Additional Desc: Not reported
Tank Use: Not reported
Petroleum Type: Not reported
Common Name: Not reported
Case Number: Not reported
Type Of Tank: Not reported
Primary Tank Material: Not reported
Secondary Tank Material: Not reported
Tank Interior Lining: Not reported
Date Interior Lining Install: Not reported
Date Closed: 10/25/1996
UST Close ID: 2539
Type Of Spill Protection: Not reported
Date Alarm Overfill Protection Installed: Not reported

NOW AUTO CENTER & (Continued) **U003916350**

Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported

NOW AUTO CENTER & (Continued) **U003916350**

Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	10/25/1996
UST Close ID:	2733
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	3/16/1999
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

P84 **NOW AUTO CENTER AND BODY SHOP** **RCRA-SQG 1000904857**
NW **180 TOWNSEND ST** **HAZNET CA0000138412**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.220 mi.
1162 ft. **Site 16 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

RCRA-SQG:

Date form received by agency:	02/24/1994
Facility name:	NOW AUTO CENTER AND BODY SHOP
Facility address:	180 TOWNSEND ST SAN FRANCISCO, CA 94107
EPA ID:	CA0000138412

NOW AUTO CENTER AND BODY SHOP (Continued) **1000904857**

Mailing address: TOWNSEND ST
SAN FRANCISCO, CA 94107
Contact: LARRY NOW
Contact address: 180 TOWNSEND ST
SAN FRANCISCO, CA 94107
Contact country: US
Contact telephone: (415) 495-7371
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: CLW AUTOMOTIVE INC
Owner/operator address: 180 TOWNSEND
SAN FRANCISCO, CA 94107
Owner/operator country: Not reported
Owner/operator telephone: (415) 495-7371
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

HAZNET:
Year: 1997
Gepaid: CA0000138412
Contact: CLW AUTOMOTIVE INC
Telephone: 4154957371
Mailing Name: Not reported
Mailing Address: 180 TOWNSEND ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941071909
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported

NOW AUTO CENTER AND BODY SHOP (Continued) **1000904857**

Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .0540
Facility County: San Francisco

Year: 1996
Gepaid: CA0000138412
Contact: CLW AUTOMOTIVE INC
Telephone: 4154957371
Mailing Name: Not reported
Mailing Address: 180 TOWNSEND ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941071909
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .1800
Facility County: San Francisco

Year: 1996
Gepaid: CA0000138412
Contact: CLW AUTOMOTIVE INC
Telephone: 4154957371
Mailing Name: Not reported
Mailing Address: 180 TOWNSEND ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941071909
Gen County: Not reported
TSD EPA ID: CAD000242105
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Tons: 3.7530
Facility County: San Francisco

Year: 1996
Gepaid: CA0000138412
Contact: CLW AUTOMOTIVE INC
Telephone: 4154957371
Mailing Name: Not reported
Mailing Address: 180 TOWNSEND ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941071909
Gen County: Not reported
TSD EPA ID: CAT000613950
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .0180
Facility County: San Francisco

Year: 1996
Gepaid: CA0000138412
Contact: CLW AUTOMOTIVE INC
Telephone: 4154957371
Mailing Name: Not reported
Mailing Address: 180 TOWNSEND ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941071909

NOW AUTO CENTER AND BODY SHOP (Continued) **1000904857**

Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: 1.0000
Facility County: San Francisco

Click this hyperlink while viewing on your computer to access
4 additional CA_HAZNET: record(s) in the EDR Site Report.

P85 **LOHMANN WM & CO** **EDR US Hist Auto Stat** **1009067879**
NW **181 TOWNSEND** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.221 mi.
1165 ft. **Site 17 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

EDR Historical Auto Stations:

Name: LOHMANN W M & CO
Year: 1930
Type: AUTOMOBILE GARAGES

Name: LOHMANN WM M & CO
Year: 1935
Type: AUTOMOBILE GARAGES

Name: LOHMANN WM & CO
Year: 1940
Type: AUTOMOBILE GARAGES

P86 **EDR US Hist Auto Stat** **1015275405**
NW **178 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.221 mi.
1166 ft. **Site 18 of 23 in cluster P**

Relative:
Higher

Actual:
23 ft.

EDR Historical Auto Stations:

Name: GARDINER JOHN AUTOMOTIVE INCORPORATED
Year: 1999
Address: 178 TOWNSEND ST

Name: DEPALO AUTOMOTIVE
Year: 2000
Address: 178 TOWNSEND ST

P87 **RESIDENTIAL** **LUST** **S105627934**
NW **360 RITCH** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.222 mi.
1170 ft. **Site 19 of 23 in cluster P**

Relative:
Higher

Actual:
20 ft.

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	02-101-006
Facility Status:	Case Closed
Case Number:	11428
Case Type:	Soil only
Release Date:	Not reported
Discovered Date:	10/24/2000
Substance:	Heater Fuel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	1/26/2001
Case Closed:	6/28/2001
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	10/24/2000
Entered Date:	2/1/2001
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Larry Mathews
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	Townesend
NOR Date:	Not reported
MTBE Current:	Not reported
MTBE Current Date:	10/24/2000
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	10/24/2000
Review Date:	6/28/2001
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	2/1/2001
Basin:	DOWNTOWN
Beneficial Use:	No

RESIDENTIAL (Continued) **S105627934**

Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	10/24/2000
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	ND
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	10/24/2000
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	6/28/01 case

P88 **360 RITCH ST** **UST** **U004003358**
NW **360 RITCH ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.222 mi.
1170 ft. **Site 20 of 23 in cluster P**

Relative:
Higher

Actual:
20 ft.

SAN FRANCISCO CO. UST:

Facility ID:	25396
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	255 Shipley Street
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Golden Gate Tank
Application Date:	9/22/2000
Application Name:	Cathy Keller
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported

360 RITCH ST (Continued) **U004003358**

Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	10/24/2000
UST Close ID:	4030
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported

360 RITCH ST (Continued) **U004003358**

Fill Tube Present: Not reported
Other Tank Leak Detection Present: Not reported

P89 **RESIDENTIAL APARTMENT** **LUST** **S105688819**
NW **360 RITCH** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.222 mi.
1170 ft. **Site 21 of 23 in cluster P**

Relative:
Higher

Actual:
20 ft.

LUST:

Region:	STATE
Global Id:	T0607591860
Latitude:	37.778825
Longitude:	-122.394065
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/26/2001
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2043
LOC Case Number:	11428
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607591860
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607591860
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607591860
Status:	Completed - Case Closed
Status Date:	01/26/2001

Global Id:	T0607591860
Status:	Open - Case Begin Date
Status Date:	10/24/2000

RESIDENTIAL APARTMENT (Continued) **S105688819**

Regulatory Activities:

Global Id:	T0607591860
Action Type:	ENFORCEMENT
Date:	02/01/2001
Action:	Notice of Responsibility
Global Id:	T0607591860
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607591860
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	38-2043
Facility Status:	Case Closed
Case Number:	11428
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

P90 **PETRUCELA & CO** **EDR US Hist Auto Stat** **1009070333**
NW **180 TOWNSEND** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.223 mi.
1175 ft. **Site 22 of 23 in cluster P**

Relative:
Higher

Actual:
24 ft.

EDR Historical Auto Stations:

Name:	PETRUCELA & CO
Year:	1962
Type:	AUTOMOBILE REPAIRING
Name:	PETRUCELA & CO
Year:	1966
Type:	AUTOMOBILE REPAIRING

L91 **PG&E GAS PLANT SAN FRANCISCO 502 1B** **CERC-NFRAP** **1003878901**
North **KING & 2ND STS** **CAD981415417**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.224 mi.
1181 ft. **Site 2 of 2 in cluster L**

Relative:
Higher

Actual:
14 ft.

CERC-NFRAP:
Site ID: 0902365
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 13053405.00000
Person ID: 9271184.00000

Contact Sequence ID: 13289757.00000
Person ID: 13003854.00000

Contact Sequence ID: 13295352.00000
Person ID: 13003858.00000

Contact Sequence ID: 13301210.00000
Person ID: 13004003.00000

CERCLIS-NFRAP Assessment History:
Action: DISCOVERY
Date Started: / /
Date Completed: 06/01/86
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 12/01/87
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 12/01/87
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

---

Q92 **J & T CLEANERS** **EDR US Hist Cleaners** **1009180320**
NW **234 TOWNSEND** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.224 mi.
1181 ft. **Site 1 of 7 in cluster Q**

Relative:
Higher

Actual:
19 ft.

EDR Historical Cleaners:
Name: J & T CLEANERS
Year: 1953
Type: CLEANERS AND DYERS

93
WNW
1/8-1/4
0.225 mi.
1187 ft.

NEXCYCLE
298 KING ST
SAN FRANCISCO, CA 94107

SWRCY **S111347239**
N/A

Relative:
Higher

Actual:
10 ft.

SWRCY:

Reg Id:	146880
Cert Id:	RC146880.001
Mailing Address:	25837 Business Center Dr Ste F
Mailing City:	Redlands
Mailing State:	CA
Mailing Zip Code:	92374
Website:	Not reported
Phone Number:	(909) 796-2210
Grand Father:	N
Rural:	N
Operation Begin Date:	10/28/2011
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	CLOSED
Tuesday Hours Of Operation:	10:00 am - 4:00 pm
Wednesday Hours Of Operation:	10:00 am - 4:00 pm
Thursday Hours Of Operation:	10:00 am - 4:00 pm
Friday Hours Of Operation:	10:00 am - 4:00 pm
Saturday Hours Of Operation:	10:00 am - 4:00 pm
Sunday Hours Of Operation:	CLOSED
Cert Status:	Operational
Organization ID:	18826
Organization Name:	Contain-A-Way Inc
Agency Reg ID:	N/A
Operation End Date:	Not reported

Q94
NW
1/8-1/4
0.226 mi.
1192 ft.

DAVIS G R MRS
230 TOWNSEND ST
SAN FRANCISCO, CA

Site 2 of 7 in cluster Q

EDR US Hist Cleaners **1009128579**
N/A

Relative:
Higher

Actual:
19 ft.

EDR Historical Cleaners:

Name:	DAVIS G R MRS
Year:	1925
Type:	CLEANERS AND DYER

R95
NNW
1/8-1/4
0.226 mi.
1192 ft.

PG & E
UNKNOWN KING & 2ND ST
SAN FRANCISCO, CA

Site 1 of 6 in cluster R

SLIC **S106234984**
N/A

Relative:
Higher

Actual:
16 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Inactive**
Status Date:	01/01/2002
Global Id:	SLT2O267363

PG & E (Continued) **S106234984**

Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Lead Agency Case Number: Not reported
Latitude: 37.779936
Longitude: -122.389673
Case Type: Cleanup Program Site
Case Worker: VP
Local Agency: Not reported
RB Case Number: 38S0010
File Location: Not reported
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:
Region: 2
Facility ID: 38S0010
Facility Status: Leak being confirmed
Date Closed: Not reported
Local Case #: Not reported
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Confirmed: Not reported
Date Prelim Site Assmnt Workplan Submitted: Not reported
Date Preliminary Site Assessment Began: Not reported
Date Pollution Characterization Began: Not reported
Date Remediation Plan Submitted: Not reported
Date Remedial Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

R96 **CCSF/PURCHASING/CENTRAL SHOPS** **UST** **U003173523**
NNW **100 KING ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.226 mi.
1194 ft. **Site 2 of 6 in cluster R**

Relative:
Higher

Actual:
16 ft.

UST:
Facility ID: 9362
Latitude: 37.77981
Longitude: -122.38994

S97 **WEST COAST SHIP CHANDLERS** **HIST UST** **U001595318**
NNW **164 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.227 mi.
1197 ft. **Site 1 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

HIST UST:
Region: STATE
Facility ID: 00000067316
Facility Type: Other
Other Type: SHIP CHANDLERS
Total Tanks: 0001
Contact Name: ALEX MADRIGAL

WEST COAST SHIP CHANDLERS (Continued) **U001595318**

Telephone: 4154955400
Owner Name: VAN MEURS, DIRK
Owner Address: 14 SKYLAND WAY
Owner City,St,Zip: ROSS, CA 94957

Tank Num: 001
Container Num: 0001
Year Installed: 1968
Tank Capacity: 00001000
Tank Used for: WASTE
Type of Fuel: 2
Tank Construction: Unkown inches
Leak Detection: None

S98 **WEST COAST SHIP** **UST** **U003906541**
NNW **164 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.227 mi.
1197 ft. **Site 2 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:
Facility ID: 16221
Facility Status: Not reported
Number Of Tanks: 1
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Not reported
Care Of Addr: Not reported
2nd Care Of Add: Not reported
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Permit Number: Not reported
Permit Approved By: Not reported
Permit Expiration Date: Not reported
Applications: Not reported
Application Date: 7/6/1989
Application Name: Not reported
Action Type: Not reported
Yr Spill/Overfill Installed1: Not reported
Yr Spill/Overfill Installed2: Not reported
Yr Spill/Overfill Installed3: Not reported

Tank ID: Not reported
Tank Test: Not reported
Local Tank Id: Not reported
Tank Manufacturer: Not reported
Compartmentalized Tank: Not reported
Of Tank Compartments: Not reported
Date Tank Installed: Not reported
Tank Capacity: Not reported
Additional Desc: Not reported
Tank Use: Not reported
Petroleum Type: Not reported
Common Name: Not reported
Case Number: Not reported
Type Of Tank: Not reported
Primary Tank Material: Not reported
Secondary Tank Material: Not reported

WEST COAST SHIP (Continued) **U003906541**

Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	1/23/1990
UST Close ID:	233
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

S99 **WEST COAST SHIP CHANDLERS INC.** **CA FID UST** **S101623240**
NNW **164 TOWNSEND ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.227 mi.
1197 ft. **Site 3 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

CA FID UST:

Facility ID:	38000462
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported

WEST COAST SHIP CHANDLERS INC. (Continued) **S101623240**

Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	164 TOWNSEND ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	6609
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-006609-000001
Actv Date:	Not reported
Capacity:	1000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	6609
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

S100 **WEST COAST SHIP CHANDLERS** **HIST CORTESE** **S103634552**
NNW **164 TOWNSEND** **LUST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.227 mi.
1197 ft. **Site 4 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0428

LUST:

Region:	STATE
Global Id:	T0607500379
Latitude:	37.779868
Longitude:	-122.392343
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/23/1994
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0428
LOC Case Number:	10207
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500379
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500379
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500379
Status:	Completed - Case Closed
Status Date:	07/23/1994

Global Id:	T0607500379
Status:	Open - Case Begin Date
Status Date:	05/01/1989

WEST COAST SHIP CHANDLERS (Continued) **S103634552**

Regulatory Activities:

Global Id:	T0607500379
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500379
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

LUST REG 2:

Region:	2
Facility Id:	38-0428
Facility Status:	Case Closed
Case Number:	10207
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0428
Facility Status:	Case Closed
Case Number:	10207
Case Type:	Soil only
Release Date:	9/12/1989
Discovered Date:	5/1/1989
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	9/12/1989
Case Closed:	7/23/1994
Closed Date:	7/23/1994
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	1/14/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported

WEST COAST SHIP CHANDLERS (Continued) **S103634552**

Staff Initial:	VP
Facility Staff:	SC
Cross Street:	CLARENCE ST
NOR Date:	1/14/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	2A
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	1/23/1990
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	9/12/89 [leak

S101 **LINCOLN PROPERTY COMPANY** **CA FID UST** **S101592581**
NNW **155 TOWNSEND ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.228 mi.
1204 ft. **Site 5 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

CA FID UST:

Facility ID:	38005451
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	155 TOWNSEND ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	7997
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-007997-000001
Actv Date:	Not reported
Capacity:	3500
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	7997
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

S102 **LINCOLN PROPERTY** **UST** **U003903985**
NNW **155 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.228 mi.
1204 ft. **Site 6 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

SAN FRANCISCO CO. UST:

Facility ID:	25146
Facility Status:	Not reported
Number Of Tanks:	1
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Not reported
Application Date:	11/19/1986
Application Name:	Not reported
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	585
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

LINCOLN PROPERTY (Continued) **U003903985**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

S103 **SITE K (SEAWALL LOT 333)** **HIST CORTESE** **S105026207**
NNW **159 & 1/2 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.228 mi.
1206 ft. **Site 7 of 7 in cluster S**

Relative:
Higher

Actual:
23 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	CALSI
Reg Id:	38750002

Q104 **EDR US Hist Cleaners** **1015026218**
NW **242 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.230 mi.
1214 ft. **Site 3 of 7 in cluster Q**

Relative:
Higher

Actual:
19 ft.

EDR Historical Cleaners:

Name:	SOMA CLEANERS
Year:	2005
Address:	242 TOWNSEND ST
Name:	SOMA CLEANERS 3
Year:	2007

(Continued) **1015026218**

Address: 242 TOWNSEND ST

Name: SOMA CLEANERS
Year: 2010
Address: 242 TOWNSEND ST

P105 **DAVIS G R MRS** **EDR US Hist Cleaners** **1009178044**
NW **682 3D** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.231 mi.
1221 ft. **Site 23 of 23 in cluster P**

Relative:
Higher

Actual:
22 ft.

EDR Historical Cleaners:
Name: DAVIS G R MRS
Year: 1930
Type: CLOTHES PRESSERS AND CLEANERS

Q106 **SUN CHEMICAL CORPORATION #1** **ENVIROSTOR** **S105754202**
NW **252 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.235 mi.
1240 ft. **Site 4 of 7 in cluster Q**

Relative:
Higher

Actual:
18 ft.

ENVIROSTOR:
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Facility ID: 38280278
Site Code: 200095
Assembly: 17
Senate: 11
Special Program: Not reported
Status: No Further Action
Status Date: 03/26/1982
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 37.77805
Longitude: -122.3938
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: * CONTAMINATED SOIL
Confirmed COC: * CONTAMINATED SOIL, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: A C HORN CO INC
Alias Type: Alternate Name
Alias Name: 200095
Alias Type: Project Code (Site Code)
Alias Name: 38280278
Alias Type: Envirostor ID Number

SUN CHEMICAL CORPORATION #1 (Continued) **S105754202**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	09/28/1981
Comments:	FACILITY IDENTIFIED ID'D FROM 1954 POLK DIRECTORY
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

M107 **COMMERCIAL DEVELOPMENT PROPERTY** **LUST** **S108220475**
West **235 BERRY STREET** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94158**
0.239 mi.
1264 ft. **Site 2 of 3 in cluster M**

Relative:
Higher

Actual:
5 ft.

LUST:

Region:	STATE
Global Id:	T0607519456
Latitude:	37.774959
Longitude:	-122.39439
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/01/2005
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2342
LOC Case Number:	11681
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607519456
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported
Global Id:	T0607519456
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET

COMMERCIAL DEVELOPMENT PROPERTY (Continued) **S108220475**

City: OAKLAND
Email: nkatyl@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607519456
Status: Completed - Case Closed
Status Date: 08/01/2005

Global Id: T0607519456
Status: Open - Case Begin Date
Status Date: 04/24/2005

Global Id: T0607519456
Status: Open - Site Assessment
Status Date: 04/24/2005

Regulatory Activities:
Global Id: T0607519456
Action Type: ENFORCEMENT
Date: 08/01/2005
Action: Closure/No Further Action Letter

Global Id: T0607519456
Action Type: ENFORCEMENT
Date: 06/21/2005
Action: Notice of Responsibility

Global Id: T0607519456
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

Global Id: T0607519456
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607519456
Action Type: ENFORCEMENT
Date: 07/15/2005
Action: File review

Global Id: T0607519456
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

M108 **DEVCON (CONST** **UST** **U003995351**
West **235 BERRY ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.239 mi.
1264 ft. **Site 3 of 3 in cluster M**

Relative:
Higher

Actual:
5 ft.

SAN FRANCISCO CO. UST:

Facility ID:	29301
Facility Status:	Not reported
Number Of Tanks:	3
Owner/Operator Name:	Not reported
Owner/Operator Title:	Not reported
Owner Name:	Not reported
Care Of Addr:	Not reported
2nd Care Of Add:	Not reported
Mailing Address:	255 Shipley St
Mailing City,St,Zip:	Not reported
Permit Number:	Not reported
Permit Approved By:	Not reported
Permit Expiration Date:	Not reported
Applications:	Golden Gate Tank
Application Date:	3/30/2005
Application Name:	Tracy Wallace
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	4/22/2005
UST Close ID:	4680
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported

DEVCON (CONST (Continued) **U003995351**

Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

O109 **A.R.A. SERVICES** **CA FID UST** **S101592218**
SW **1400 6TH ST** **SWEEPS UST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.241 mi.
1270 ft. **Site 4 of 4 in cluster O**

Relative:
Higher

Actual:
7 ft.

CA FID UST:

Facility ID:	38001633
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	1400 6TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

A.R.A. SERVICES (Continued) **S101592218**

Status:	Not reported
Comp Number:	5286
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-005286-000001
Actv Date:	Not reported
Capacity:	1000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Q110 **SAN FRANCISCO IRON FOUNDRY** **ENVIROSTOR** **S100193760**
WNW **260 TOWNSEND** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.241 mi.
1270 ft. **Site 5 of 7 in cluster Q**

Relative:
Higher

Actual:
17 ft.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0.5
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Facility ID:	38330098
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	EPA - PASI
Status:	No Further Action
Status Date:	01/13/2009
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.77814
Longitude:	-122.3944
APN:	3787024
Past Use:	NONE
Potential COC:	NONE SPECIFIED, No Contaminants found
Confirmed COC:	NONE SPECIFIED, No Contaminants found, No Contaminants found
Potential Description:	NMA
Alias Name:	3787024
Alias Type:	APN
Alias Name:	38330098
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

SAN FRANCISCO IRON FOUNDRY (Continued) **S100193760**

Completed Document Type: * Discovery
Completed Date: 09/28/1981
Comments: FACILITY IDENTIFIED ID FROM 1954 POLK DIRECTORY

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Reassessment
Completed Date: 01/12/2009
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Q111 **EDR US Hist Auto Stat** **1015371203**
WNW **260 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.241 mi.
1270 ft. **Site 6 of 7 in cluster Q**

Relative:
Higher

Actual:
17 ft.

EDR Historical Auto Stations:
Name: PHILLIPS 66 CO
Year: 2004
Address: 260 TOWNSEND ST

Name: VALERO ENERGY
Year: 2005
Address: 260 TOWNSEND ST

Q112 **CIRCLE PLAZA** **UST** **U003903306**
WNW **260 TOWNSEND ST** **N/A**
1/8-1/4 **SAN FRANCISCO, CA**
0.241 mi.
1270 ft. **Site 7 of 7 in cluster Q**

Relative:
Higher

Actual:
17 ft.

SAN FRANCISCO CO. UST:
Facility ID: 26384
Facility Status: Not reported
Number Of Tanks: 1
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Not reported
Care Of Addr: Not reported
2nd Care Of Add: Not reported
Mailing Address: 15350 Vickery Dr
Mailing City,St,Zip: Not reported
Permit Number: Not reported
Permit Approved By: Not reported
Permit Expiration Date: Not reported
Applications: Circle

CIRCLE PLAZA (Continued) **U003903306**

Application Date:	12/21/2001
Application Name:	Shawn Helm
Action Type:	Not reported
Yr Spill/Overfill Installed1:	Not reported
Yr Spill/Overfill Installed2:	Not reported
Yr Spill/Overfill Installed3:	Not reported
Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	3/27/2002
UST Close ID:	4216
Type Of Spill Protection:	Not reported
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported

CIRCLE PLAZA (Continued) **U003903306**

Date Certified (Tank Unit):	Not reported
Certified Date:	5/20/2002
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

R113 **PG AND E GAS PLANT SAN FRANCISCO** **EDR MGP** **1008407758**
NNW **KING AND 2ND STREET** **N/A**
1/8-1/4 **SAN FRANCISCO, CA 94107**
0.245 mi.
1295 ft. **Site 3 of 6 in cluster R**

Relative:
Higher

Manufactured Gas Plants:
Alternate Name:SAN FRANCISCO GAS AND ELECTRIC CO. No additional information available

Actual:
17 ft.

R114 **725 2ND STREET** **ENVIROSTOR** **S108407591**
NNW **725 2ND STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.264 mi.
1392 ft. **Site 4 of 6 in cluster R**

Relative:
Higher

Actual:
20 ft.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Berkeley
Facility ID:	60000533
Site Code:	Not reported
Assembly:	13
Senate:	03
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	08/22/1997
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	0
Longitude:	0
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	60000533
Alias Type:	Envirostor ID Number

725 2ND STREET (Continued) **S108407591**

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported
Completed Date:	Not reported
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

R115 **MARINA VISTA PROJECT (SIT** **HIST CORTESE** **S105026213**
NNW **725 2ND 75 & 99 TOWNSEND** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.265 mi.
1400 ft. **Site 5 of 6 in cluster R**

Relative:
Higher

Actual:
20 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	CALSI
Reg Id:	38270353

R116 **MARINA VISTA PROJECT** **DEED** **S101482017**
NNW **725 2ND STREET (75 & 99 TOWNSEND)** **VCP** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **ENVIROSTOR**
0.265 mi.
1400 ft. **Site 6 of 6 in cluster R**

Relative:
Higher

Actual:
20 ft.

DEED:

Area:	PROJECT WIDE
Sub Area:	Not reported
Site Type:	VOLUNTARY CLEANUP
Status:	CERTIFIED / OPERATION & MAINTENANCE
Deed Date(s):	09/28/1998
EDR Link ID:	38270353

VCP:

Facility ID:	38270353
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	REM, ASP, LUC, EX, GW, NDAM, COV
Acres:	1.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Lead Agency Description:	SAN FRANCISCO COUNTY
Project Manager:	Claude Jemison
Supervisor:	Mark Piros

MARINA VISTA PROJECT (Continued) **S101482017**

Division Branch:	Cleanup Berkeley
Site Code:	200947
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified / Operation & Maintenance
Status Date:	09/28/1998
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.78063 / -122.3905
APN:	Block 3793 Lot 001, Block 3793 Lot 002, Block 3793 Lot 003
Past Use:	ILLEGAL DUMPING
Potential COC:	30001, 30013, 30019
Confirmed COC:	30019,30001,30013
Potential Description:	SOIL
Alias Name:	MARINA VISTA
Alias Type:	Alternate Name
Alias Name:	MARINA VISTA PROJECT (SITE L)
Alias Type:	Alternate Name
Alias Name:	ONE EMBARCADERO SOUTH
Alias Type:	Alternate Name
Alias Name:	Block 3793 Lot 001
Alias Type:	APN
Alias Name:	Block 3793 Lot 002
Alias Type:	APN
Alias Name:	Block 3793 Lot 003
Alias Type:	APN
Alias Name:	110033608754
Alias Type:	EPA (FRS #)
Alias Name:	200947
Alias Type:	Project Code (Site Code)
Alias Name:	38270353
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	10/08/2003
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	09/25/1990
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	04/17/2009
Comments:	Upon observing the current site conditions, DTSC concludes that they remain protective on human health and the environment. Impacted soil remains under the concrete surface, which remains undisturbed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report

MARINA VISTA PROJECT (Continued) **S101482017**

Completed Date: 12/28/2005
Comments: Summary of DTSC Cap Inspection conducted on 12/9/05.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/18/1989
Comments: Article 20 Site Study - Phase I: Site History

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/07/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 09/28/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/03/2007
Comments: The building and adjacent sidewalks are in good conditions. There was no evidence of any activities prohibited by the deed restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 09/02/2003
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/10/2008
Comments: The building and adjacent sidewalk appeared in good condition. Additionally, there was no evidence of any activities prohibited by the Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: The building and adjacent sidewalk appeared in good condition. Additionally, there was no evidence of any activities prohibited by the Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/18/1990
Comments: Phase II - Article 20: Soil Sampling & Chemical Analysis

Completed Area Name: PROJECT WIDE

MARINA VISTA PROJECT (Continued) **S101482017**

Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/23/1990
Comments: Phase III Article 20 - Soil Sampling & Analysis

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/06/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 11/03/2008
Comments: Public Notice for Start of 5-Year Review to be published in the SF Chronicle

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/11/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building and adjacent sidewalk appeared in good condition. There was no evidence of any activities prohibited by the Land Use Covenant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/19/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 09/28/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/29/1997
Comments: Not reported

MARINA VISTA PROJECT (Continued) **S101482017**

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Operations and Maintenance Report
Future Due Date: 2015
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: 5 Year Review Reports
Schedule Due Date: 01/14/2014
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 1.5
NPL: NO
Regulatory Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38270353
Site Code: 200947
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Certified / Operation & Maintenance
Status Date: 09/28/1998
Restricted Use: YES
Site Mgmt. Req.: REM, ASP, LUC, EX, GW, NDAM, COV
Funding: Responsible Party
Latitude: 37.78063
Longitude: -122.3905
APN: Block 3793 Lot 001, Block 3793 Lot 002, Block 3793 Lot 003
Past Use: ILLEGAL DUMPING
Potential COC: Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs, Polynuclear aromatic hydrocarbons (PAHs, Arsenic, Lead
Potential Description: SOIL
Alias Name: MARINA VISTA
Alias Type: Alternate Name
Alias Name: MARINA VISTA PROJECT (SITE L)
Alias Type: Alternate Name
Alias Name: ONE EMBARCADERO SOUTH
Alias Type: Alternate Name
Alias Name: Block 3793 Lot 001
Alias Type: APN
Alias Name: Block 3793 Lot 002
Alias Type: APN
Alias Name: Block 3793 Lot 003
Alias Type: APN
Alias Name: 110033608754
Alias Type: EPA (FRS #)
Alias Name: 200947
Alias Type: Project Code (Site Code)
Alias Name: 38270353
Alias Type: Envirostor ID Number

MARINA VISTA PROJECT (Continued) **S101482017**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	10/08/2003
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	09/25/1990
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	04/17/2009
Comments:	Upon observing the current site conditions, DTSC concludes that they remain protective on human health and the environment. Impacted soil remains under the concrete surface, which remains undisturbed.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	12/28/2005
Comments:	Summary of DTSC Cap Inspection conducted on 12/9/05.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	12/18/1989
Comments:	Article 20 Site Study - Phase I: Site History

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	10/07/2010
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	09/28/1998
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	10/03/2007
Comments:	The building and adjacent sidewalks are in good conditions. There was no evidence of any activities prohibited by the deed restriction.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	09/02/2003
Comments:	Not reported

MARINA VISTA PROJECT (Continued) **S101482017**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/10/2008
Comments: The building and adjacent sidewalk appeared in good condition. Additionally, there was no evidence of any activities prohibited by the Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: The building and adjacent sidewalk appeared in good condition. Additionally, there was no evidence of any activities prohibited by the Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/18/1990
Comments: Phase II - Article 20: Soil Sampling & Chemical Analysis

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/23/1990
Comments: Phase III Article 20 - Soil Sampling & Analysis

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/06/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 11/03/2008
Comments: Public Notice for Start of 5-Year Review to be published in the SF Chronicle

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/11/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012

MARINA VISTA PROJECT (Continued) **S101482017**

Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building and adjacent sidewalk appeared in good condition. There was no evidence of any activities prohibited by the Land Use Covenant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/19/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 09/28/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/29/1997
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Operations and Maintenance Report
Future Due Date: 2015
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: 5 Year Review Reports
Schedule Due Date: 01/14/2014
Schedule Revised Date: Not reported

T117 **COMMERCIAL** **LUST** **S105244839**
NNW **101 TOWNSEND STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.275 mi.
1451 ft. **Site 1 of 7 in cluster T**

Relative:
Higher

Actual:
21 ft.

LUST REG 2:
Region: 2
Facility Id: 38-0913
Facility Status: Case Closed
Case Number: 10840
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

COMMERCIAL (Continued) **S105244839**

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0913
Facility Status:	Case Closed
Case Number:	10840
Case Type:	Soil only
Release Date:	5/19/1997
Discovered Date:	5/23/1997
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	5/19/1997
Case Closed:	7/11/1997
Closed Date:	7/11/1997
Leak Source:	Other Source
Leak Cause:	Corrosion
Leak Confirmed:	Not reported
Entered Date:	7/8/1997
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	2ND ST
NOR Date:	7/8/1997
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Not reported
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Remove Free Product - remove floating product from water table
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	5/15/1997
Free Product:	No

COMMERCIAL (Continued) **S105244839**

Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	5/23/97 [leak

T118 **COMMERCIAL** **HIST CORTESE** **S103620260**
NNW **101 TOWNSEND** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.275 mi.
1451 ft. **Site 2 of 7 in cluster T**

Relative:
Higher

Actual:
21 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0913

LUST:

Region:	STATE
Global Id:	T0607500808
Latitude:	37.780365
Longitude:	-122.390635
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/11/1997
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0913
LOC Case Number:	10840
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500808
Contact Type:	Regional Board Caseworker

COMMERCIAL (Continued) **S103620260**

Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500808
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500808
Status: Completed - Case Closed
Status Date: 07/11/1997

Global Id: T0607500808
Status: Open - Case Begin Date
Status Date: 05/23/1997

Regulatory Activities:
Global Id: T0607500808
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500808
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

T119 **SFFD PUMPING STATION** **HIST CORTESE** **S101308416**
NNW **698 2ND** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.277 mi.
1462 ft. **Site 3 of 7 in cluster T**

Relative:
Higher

Actual:
21 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-293

U120 **COMMERCIAL** **LUST** **S103996628**
NW **630 3RD ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.288 mi.
1519 ft. **Site 1 of 5 in cluster U**

Relative:
Higher

Actual:
23 ft.

LUST:

Region:	STATE
Global Id:	T0607592740
Latitude:	37.779379
Longitude:	-122.394056
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/25/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	UNK
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1597
LOC Case Number:	38-1597
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607592740
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0607592740
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607592740
Status:	Completed - Case Closed
Status Date:	05/25/2000

Global Id:	T0607592740
Status:	Open - Case Begin Date
Status Date:	08/24/1998

Regulatory Activities:

Global Id:	T0607592740
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

COMMERCIAL (Continued) **S103996628**

Global Id: T0607592740
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607592740
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Region: STATE
Global Id: T0607591828
Latitude: 37.779379
Longitude: -122.394056
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/20/2000
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: UNK
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-1592
LOC Case Number: 38-1592
File Location: Not reported
Potential Media Affect: Under Investigation
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607591828
Contact Type: Local Agency Caseworker
Contact Name: UNK
Organization Name: SAN FRANCISCO COUNTY LOP
Address: Not reported
City: r2 UNKNOWN
Email: Not reported
Phone Number: Not reported

Global Id: T0607591828
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607591828
Status: Completed - Case Closed
Status Date: 07/20/2000

Global Id: T0607591828
Status: Open - Case Begin Date
Status Date: 05/30/2000

COMMERCIAL (Continued) **S103996628**

Regulatory Activities:
Global Id: T0607591828
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1592
Facility Status: Case Closed
Case Number: 38-1592
How Discovered: Tank Closure
Leak Cause: UNK
Leak Source: UNK
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

U121 **COMMERCIAL PROPERTY** **LUST** **S104732891**
NW **630 3RD ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.288 mi.
1519 ft. **Site 2 of 5 in cluster U**

Relative:
Higher

Actual:
23 ft.

LUST REG 2:
Region: 2
Facility Id: 38-1597
Facility Status: Case Closed
Case Number: 38-1597
How Discovered: Tank Closure
Leak Cause: Corrosion
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

U122 **ZELLERBACH FAMILY FUND** **LUST** **S105806101**
NW **630 03RD ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.288 mi.
1519 ft. **Site 3 of 5 in cluster U**

Relative:
Higher

Actual:
23 ft.

LUST:

Region:	STATE
Global Id:	T0607548688
Latitude:	Not reported
Longitude:	Not reported
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/30/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2158
LOC Case Number:	11368
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607548688
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607548688
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607548688
Status:	Completed - Case Closed
Status Date:	05/30/2000

Global Id:	T0607548688
Status:	Open - Case Begin Date
Status Date:	08/24/1998

Regulatory Activities:

Global Id:	T0607548688
Action Type:	ENFORCEMENT
Date:	05/25/2000
Action:	Notice of Responsibility

ZELLERBACH FAMILY FUND (Continued) **S105806101**

Global Id: T0607548688
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607548688
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2158
Facility Status: Case Closed
Case Number: 11368
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 02-200-013
Facility Status: Case Closed
Case Number: 11368
Case Type: Soil only
Release Date: Not reported
Discovered Date: 8/24/1998
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 9/14/1998
Case Closed: 5/30/2000
Closed Date: 5/30/2000
Leak Source: Tank
Leak Cause: Corrosion
Leak Confirmed: 8/24/1998
Entered Date: 5/25/2000
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: John Zellerbach
Staff Initial: VP

ZELLERBACH FAMILY FUND (Continued) **S105806101**

Facility Staff:	AL
Cross Street:	Brannan
NOR Date:	5/25/2000
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	5/30/2000
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	5/25/2000
Basin:	DOWNTOWN
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	8/24/1998
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	190
TPH Date:	8/25/1998
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

U123 **COMMERCIAL PROPERTY** **LUST** **S106161986**
NW **322-326 RITCH ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.290 mi.
1532 ft. **Site 4 of 5 in cluster U**

Relative:
Higher

Actual:
21 ft.

LUST:

Region:	STATE
Global Id:	T0607513556
Latitude:	37.779082
Longitude:	-122.394386
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/31/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2160
LOC Case Number:	11365
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607513556
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Global Id:	T0607513556
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607513556
Status:	Completed - Case Closed
Status Date:	05/31/2000

Global Id:	T0607513556
Status:	Open - Case Begin Date
Status Date:	05/08/2000

Regulatory Activities:

Global Id:	T0607513556
Action Type:	ENFORCEMENT
Date:	05/19/2000
Action:	Notice of Responsibility

COMMERCIAL PROPERTY (Continued) **S106161986**

Global Id: T0607513556
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607513556
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2160
Facility Status: Case Closed
Case Number: 11365
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 02-200-010
Facility Status: Case Closed
Case Number: 11365
Case Type: Soil only
Release Date: Not reported
Discovered Date: 5/8/2000
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 5/9/2000
Case Closed: 5/31/2000
Closed Date: 5/31/2000
Leak Source: Tank
Leak Cause: Unknown
Leak Confirmed: Not reported
Entered Date: 5/19/2000
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: John Paulsen
Staff Initial: VP

COMMERCIAL PROPERTY (Continued) **S106161986**

Facility Staff:	MA
Cross Street:	Brannan
NOR Date:	5/19/2000
MTBE Current:	Not reported
MTBE Current Date:	5/9/2000
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	5/9/2000
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	5/19/2000
Basin:	Not reported
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	5/8/2000
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	ND
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	5/9/2000
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

T124 **COMMERCIAL PROPERTY** **HIST CORTESE** **S103972843**
NNW **680 2ND** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.294 mi.
1552 ft. **Site 4 of 7 in cluster T**

Relative:
Higher

Actual:
23 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1212

V125 **SOUTHERN PACIFIC TRANSPOR** **HIST CORTESE** **S104025400**
WNW **329 TOWNSEND** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.309 mi.
1632 ft. **Site 1 of 2 in cluster V**

Relative:
Higher

Actual:
9 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0355

LUST:
Region: STATE
Global Id: T0607500314
Latitude: 37.776493
Longitude: -122.394607
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 11/02/1999
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: MA
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0355
LOC Case Number: 10302
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500314
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500314
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO

SOUTHERN PACIFIC TRANSPOR (Continued) **S104025400**

Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500314
Status: Completed - Case Closed
Status Date: 11/02/1999

Global Id: T0607500314
Status: Open - Case Begin Date
Status Date: 06/01/1990

Regulatory Activities:
Global Id: T0607500314
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500314
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

LUST REG 2:
Region: 2
Facility Id: 38-0355
Facility Status: Case Closed
Case Number: 10302
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0355
Facility Status: Case Closed
Case Number: 10302
Case Type: Other ground water affected
Release Date: 10/3/1990
Discovered Date: 6/1/1990
Substance: Diesel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 10/3/1990
Case Closed: 11/2/1999

SOUTHERN PACIFIC TRANSPOR (Continued) **S104025400**

Closed Date:	11/2/1999
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	9/26/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	SOUTHERN PACIFIC
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	4TH ST
NOR Date:	9/26/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	11/2/1999
Workplan Submitted:	7/11/1991
Assessment Underway:	12/2/1996
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site, Remove Free Product - remove floating product from water table
Enforcement Type:	2A
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	10/3/1990
Free Product:	No
Depth to Grnd Wtr:	8’
Gradient:	SW
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	ND
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	20000

SOUTHERN PACIFIC TRANSPOR (Continued) **S104025400**

TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	10/3/90 [leak

W126 **MISSION BAY PARCEL 24** **HIST CORTESE S104241994**
SW **1600 6TH** **LUST N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.318 mi.
1680 ft. **Site 1 of 2 in cluster W**

Relative:
Higher

Actual:
8 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1416

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1584

LUST:

Region:	STATE
Global Id:	T0607501300
Latitude:	37.7689651
Longitude:	-122.3936651
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/19/1999
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	VP
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1416
LOC Case Number:	38-1416
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501300
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

MISSION BAY PARCEL 24 (Continued) **S104241994**

Global Id:	T0607501300
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501300
Status:	Completed - Case Closed
Status Date:	10/19/1999

Global Id:	T0607501300
Status:	Open - Case Begin Date
Status Date:	05/13/1999

Regulatory Activities:

Global Id:	T0607501300
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607501300
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607501300
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	38-1416
Facility Status:	Case Closed
Case Number:	38-1416
How Discovered:	Tank Closure
Leak Cause:	UNK
Leak Source:	UNK
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

X127 **COMMERCIAL** **LUST** **S105627988**
NNW **35 STANFORD ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.321 mi.
1694 ft. **Site 1 of 6 in cluster X**

Relative:
Higher

Actual:
28 ft.

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	02-100-011
Facility Status:	Case Closed
Case Number:	11342
Case Type:	Soil only
Release Date:	Not reported
Discovered Date:	3/2/1994
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	3/22/1994
Case Closed:	11/12/2002
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Unknown
Leak Confirmed:	3/22/1994
Entered Date:	2/1/2000
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Charles Henker
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	Brannan
NOR Date:	2/1/2000
MTBE Current:	Not reported
MTBE Current Date:	3/22/1994
MTBE:	YES
Maximum MTBE Soil:	1910
Maximum MTBE GW:	Not reported
MTBE DATE:	3/22/1994
Review Date:	11/12/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	2/1/2000
Basin:	Downtown Basin
Beneficial Use:	No

COMMERCIAL (Continued) **S105627988**

Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	3/22/1994
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	11/12/02 file

X128 **COMMERCIAL BUILDING** **LUST** **S105688854**
NNW **35 STANFORD ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.321 mi.
1694 ft. **Site 2 of 6 in cluster X**

Relative:
Higher

Actual:
28 ft.

LUST:

Region:	STATE
Global Id:	T0607526461
Latitude:	37.781228
Longitude:	-122.391894
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/12/2002
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2128
LOC Case Number:	11342
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607526461
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE

COMMERCIAL BUILDING (Continued) **S105688854**

Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607526461
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607526461
Status: Completed - Case Closed
Status Date: 11/12/2002

Global Id: T0607526461
Status: Open - Case Begin Date
Status Date: 03/22/1994

Global Id: T0607526461
Status: Open - Site Assessment
Status Date: 03/22/1994

Regulatory Activities:
Global Id: T0607526461
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607526461
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607526461
Action Type: ENFORCEMENT
Date: 02/01/2000
Action: Notice of Responsibility

Global Id: T0607526461
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2128
Facility Status: Case Closed
Case Number: 11342
How Discovered: Tank Closure

COMMERCIAL BUILDING (Continued) **S105688854**

Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: 3/22/1994
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

X129 **GEORGE LITHOGRAPH** **HIST CORTESE** **1001614572**
NNW **650 2ND** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.322 mi.
1700 ft. **Site 3 of 6 in cluster X**

Relative:
Higher

Actual:
25 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0667

T130 **COMMERCIAL** **HIST CORTESE** **S110060635**
NNW **64 72 TOWNSEND** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.322 mi.
1700 ft. **Site 5 of 7 in cluster T**

Relative:
Higher

Actual:
19 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1253

T131 **COMMERCIAL** **LUST** **S106162988**
NNW **64-72 TOWNSEND STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.322 mi.
1700 ft. **Site 6 of 7 in cluster T**

Relative:
Higher

Actual:
19 ft.

LUST REG 2:
Region: 2
Facility Id: 38-1253
Facility Status: Case Closed
Case Number: 11132
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported

COMMERCIAL (Continued) **S106162988**

Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1253
Facility Status:	Case Closed
Case Number:	11132
Case Type:	Soil only
Release Date:	7/23/1998
Discovered Date:	7/23/1998
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	7/23/1998
Case Closed:	2/19/1999
Closed Date:	2/19/1999
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	1/7/1999
Entered Date:	1/7/1999
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Fox Properties
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	2ND ST
NOR Date:	1/7/1999
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported

COMMERCIAL (Continued) **S106162988**

CUFID:	Not reported
Suspended:	No
Stopped Date:	7/23/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	1/27/99 sent to

T132 **COMMERCIAL** **LUST** **S103964885**
NNW **64-72 TOWNSEND STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.322 mi.
1700 ft. **Site 7 of 7 in cluster T**

Relative:
Higher

Actual:
19 ft.

LUST:

Region:	STATE
Global Id:	T0607501138
Latitude:	37.78139
Longitude:	-122.390353
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/19/1999
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1253
LOC Case Number:	11132
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501138
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP

COMMERCIAL (Continued) **S103964885**

Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607501138
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501138
Status: Completed - Case Closed
Status Date: 02/19/1999

Global Id: T0607501138
Status: Open - Case Begin Date
Status Date: 07/23/1998

Regulatory Activities:
Global Id: T0607501138
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501138
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Y133 **SFFD PUMPING STATION** **LUST** **1006101618**
South **698 02ND ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.333 mi.
1760 ft. **Site 1 of 3 in cluster Y**

Relative:
Higher

Actual:
11 ft.

LUST:
Region: STATE
Global Id: T0607500258
Latitude: 37.780802
Longitude: -122.389587
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 08/26/2008
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0293
LOC Case Number: 10163
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline

SFFD PUMPING STATION (Continued) **1006101618**

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500258
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500258
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500258
Status: Completed - Case Closed
Status Date: 08/26/2008

Global Id: T0607500258
Status: Open - Case Begin Date
Status Date: 04/07/1987

Global Id: T0607500258
Status: Open - Site Assessment
Status Date: 04/13/1987

Global Id: T0607500258
Status: Open - Site Assessment
Status Date: 01/30/2008

Regulatory Activities:
Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 07/15/2008
Action: Referral to Regional Board

Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 07/15/2008
Action: LOP Case Closure Summary to RB

Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 08/26/2008
Action: Closure/No Further Action Letter

Global Id: T0607500258

SFFD PUMPING STATION (Continued) **1006101618**

Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 05/30/2003
Action: File review

Global Id: T0607500258
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 07/14/2008
Action: File review

Global Id: T0607500258
Action Type: ENFORCEMENT
Date: 08/26/2008
Action: Closure/No Further Action Letter - #10163CCL

LUST REG 2:
Region: 2
Facility Id: 38-0293
Facility Status: Leak being confirmed
Case Number: 10163
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: 4/13/1987
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0293
Facility Status: Leak being confirmed
Case Number: 10163
Case Type: Soil only
Release Date: 4/13/1987
Discovered Date: 4/7/1987
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 4/13/1987
Case Closed: Not reported

SFFD PUMPING STATION (Continued) **1006101618**

Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	1/23/1996
Entered Date:	8/18/1993
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	SFFD
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	TOWNSEND ST
NOR Date:	8/18/1993
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	Informal Enforcement Actions,including Notices of Violations and Staff Enforcement Letters
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	11/3/1986
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported

SFFD PUMPING STATION (Continued) **1006101618**

Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

V134 **COMMERCIAL PROPERTY** **LUST** **S109117592**
WNW **330 TOWNSEND ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.334 mi.
1764 ft. **Site 2 of 2 in cluster V**

Relative:
Higher

Actual:
9 ft.

LUST:

Region:	STATE
Global Id:	T0607597691
Latitude:	37.776611
Longitude:	-122.395765
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/29/2008
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2498
LOC Case Number:	11837
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Regional Board concurrence 7/23/08

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607597691
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607597691
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET
City:	OAKLAND
Email:	nkatyl@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607597691
Status:	Completed - Case Closed
Status Date:	07/29/2008

COMMERCIAL PROPERTY (Continued) **S109117592**

Global Id: T0607597691
Status: Open - Case Begin Date
Status Date: 11/29/2007

Global Id: T0607597691
Status: Open - Site Assessment
Status Date: 11/29/2007

Regulatory Activities:

Global Id: T0607597691
Action Type: ENFORCEMENT
Date: 07/29/2008
Action: Closure/No Further Action Letter

Global Id: T0607597691
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

Global Id: T0607597691
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

Global Id: T0607597691
Action Type: ENFORCEMENT
Date: 07/21/2008
Action: Referral to Regional Board

Global Id: T0607597691
Action Type: ENFORCEMENT
Date: 07/21/2008
Action: File review

Global Id: T0607597691
Action Type: ENFORCEMENT
Date: 07/29/2008
Action: Closure/No Further Action Letter

Global Id: T0607597691
Action Type: ENFORCEMENT
Date: 06/18/2008
Action: Notice of Responsibility

Global Id: T0607597691
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607597691
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

U135 **PARKING LOT** **HIST CORTESE** **S104228723**
NW **599 3RD ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.336 mi.
1772 ft. **Site 5 of 5 in cluster U**

Relative:
Higher

Actual:
23 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1467

---

136 **RINCON POINT SOUTH BEACH** **SLIC** **S106234990**
North **UNKNOWN UNKNOWN** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.339 mi.
1788 ft.

Relative:
Higher

Actual:
5 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Inactive**
Status Date:	01/01/2002
Global Id:	SLT2O271367
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Lead Agency Case Number:	Not reported
Latitude:	37.7816711247802
Longitude:	-122.387952804565
Case Type:	Cleanup Program Site
Case Worker:	VP
Local Agency:	Not reported
RB Case Number:	38S0041
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region:	2
Facility ID:	38S0041
Facility Status:	Leak being confirmed
Date Closed:	Not reported
Local Case #:	Not reported
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Confirmed:	Not reported
Date Prelim Site Assmnt Workplan Submitted:	Not reported
Date Preliminary Site Assessment Began:	Not reported
Date Pollution Characterization Began:	Not reported
Date Remediation Plan Submitted:	Not reported
Date Remedial Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

137
North
1/4-1/2
0.341 mi.
1800 ft.

SITE K (SEAWALL LOT 333)
1-59&1/2 TOWNSEND STREET
SAN FRANCISCO, CA 94107

HIST Cal-Sites
DEED
RESPONSE
ENVIROSTOR

S101482036
N/A

Relative:
Higher

Actual:
14 ft.

Calsite:

Facility ID:	38750002
Region:	2
Region Name:	BERKELEY
Branch:	NC
Branch Name:	NORTH COAST
File Name:	Not reported
State Senate District:	07182000
Status:	CERTIFIED OPERATION AND MAINTENANCE, ALL PLANNED ACTIVITIES IMPLEMENTED, REMEDIATION CONTINUES
Status Name:	CERTIFIED / OPERATION & MAINTENANCE
Lead Agency:	DTSC
Lead Agency:	DEPT OF TOXIC SUBSTANCES CONTROL
Facility Type:	RP
Type Name:	RESPONSIBLE PARTY
NPL:	Not Listed
SIC Code:	75
SIC Name:	AUTO REPAIR, SERVICES & PARKING
Access:	Not reported
Cortese:	Not reported
Hazardous Ranking Score:	Not reported
Date Site Hazard Ranked:	Not reported
Groundwater Contamination:	Not reported
Staff Member Responsible for Site:	JNAITO
Supervisor Responsible for Site:	Not reported
Region Water Control Board:	SF
Region Water Control Board Name:	SAN FRANCISCO BAY
Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported
State Assembly District Code:	13
State Senate District Code:	03
Facility ID:	38750002
Activity:	SS
Activity Name:	SITE SCREENING
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	09181990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38750002
Activity:	PEA
Activity Name:	PRELIMINARY ENDANGERMENT ASSESSMENT
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	05141991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38750002
Activity:	RA
Activity Name:	REMOVAL ACTION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	04241996
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	246
Action Included Capping:	X
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	N
Activity Comments:	EXCAVATION AND BIOREMEDIATION OF CONTAMINATED SOIL AND PLACEMENTOF A CONCRETE CAP. SOIL CONTAMINATED WITH TOTAL PETROLEUM HYDRO-CARBONS ABOVE 1000 PPM WAS EXCAVATED AND TREATED ON SITE.
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38750002
Activity:	DEED
Activity Name:	DEED RESTRICTIONS

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	07052000
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38750002
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	07182000
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38750002
Activity:	5YEAR
Activity Name:	FIVE-YEAR REVIEW REQUIRED BY CERCLA
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	07312005
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Alternate Address:	1-59&1/2 TOWNSEND STREET
Alternate City,St,Zip:	SAN FRANCISCO, CA 94107
Background Info:	Site K is located at 1 through 59 1/2 Townsend Street in San Francisco, and is owned by the San Francisco Redevelopment Agency. The site was underwater during the 1800's but completely filled with soil and construction debris by 1913. Previous site occupants included a paint warehouse, ship service companies, and a forklift service company.
Comments Date:	04241996
Comments:	Approved RA. The removal activities at the site consisted of
Comments Date:	04241996
Comments:	excavation and bioremediation of soil containing petroleum
Comments Date:	04241996
Comments:	cap. Approximately 246 cubic yards of petroleum hydrocarbon
Comments Date:	04241996
Comments:	contaminated soil were biotreated on an asphalt paved lot and
Comments Date:	04241996
Comments:	subsequently used as backfill. The cap covers all portions of
Comments Date:	04241996
Comments:	the property and consists of a layer of 10 mils Visqueen plastic
Comments Date:	04241996
Comments:	and a 4-inch thick concrete slab. A 3-story residential
Comments Date:	04241996
Comments:	building and 1-story at-grade parking lot has been constructed
Comments Date:	04241996
Comments:	on site.
Comments Date:	05141991
Comments:	Approved PEA. Documented fuel leaks at the site impacted the
Comments Date:	05141991
Comments:	soil and groundwater. DTSC approved a hazardous waste
Comments Date:	05141991
Comments:	management plan on May 6, 1991.
Comments Date:	07052000
Comments:	Recorded Deed Restriction.
Comments Date:	07182000
Comments:	Certified Site.
Comments Date:	09181990
Comments:	Site Screening noted 5 underground tanks removed.
Comments Date:	04241996
Comments:	hydrocarbons above 1,000 mg/kg and the placement of a concrete
ID Name:	CALSTARS CODE
ID Value:	200249
Alternate Name:	SITE K (SEAWALL LOT 333)
Special Programs Code:	Not reported
Special Programs Name:	Not reported

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

DEED:
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: STATE RESPONSE
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Deed Date(s): 07/05/2000
EDR Link ID: 38750002

RESPONSE:
Facility ID: 38750002
Site Type: State Response
Site Type Detail: State Response or NPL
Acres: 1.4
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Site Code: 200249
Site Mgmt. Req.: REM, LUC, EX, NOWN, NDAM
Assembly: 17
Senate: 11
Special Program Status: Not reported
Status: Certified O&M - Land Use Restrictions Only
Status Date: 07/18/2000
Restricted Use: YES
Funding: Responsible Party
Latitude: 37.78175
Longitude: -122.3880
APN: Block 3792 Lot 002
Past Use: SHIPYARD - SHIP BUILDING/REPAIR, TRANSPORTATION - WAREHOUSING
Potential COC: Arsenic, Lead, Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs
Not reported
Confirmed COC: Arsenic, Lead, Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs, Arsenic, Lead, , Arsenic, Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs
Potential Description: SOIL
Alias Name: Site K (Seawall Lot 333)
Alias Type: Alternate Name
Alias Name: Block 3792 Lot 002
Alias Type: APN
Alias Name: 110033609307
Alias Type: EPA (FRS #)
Alias Name: 200249
Alias Type: Project Code (Site Code)
Alias Name: 38750002
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 07/18/2000
Comments: Certified Site.

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 07/05/2000
Comments: Recorded Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/24/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: Upon inspection, it was observed that the building exterior was in good condition and well maintained. The adjacent side walks were also inspected and were in good condition, only showing a few minor (surficial) cracks.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 08/10/2005
Comments: Five-Year Review Report was approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 04/24/1996
Comments: Approved RA. The removal activities at the site consisted of excavation and bioremediation of soil containing petroleum hydrocarbons above 1,000 mg/kg and the placement of a concrete cap. Approximately 246 cubic yards of petroleum hydrocarbon contaminated soil were biotreated on an asphalt paved lot and subsequently used as backfill. The cap covers all portions of the property and consists of a layer of 10 mils Visqueen plastic and a 4-inch thick concrete slab. A 3-story residential building and 1-story at-grade parking lot have been constructed on site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/14/1991
Comments: Documented fuel leaks at the site impacted the soil and groundwater. DTSC approved a hazardous waste management plan on May 6, 1991.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/18/1990
Comments: Site Screening noted 5 underground tanks removed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

Completed Date: 11/23/2010
Comments: No notifications of any activities disturbing or interfering with the integrity of the cap were received in the past year. The building foundation, which serves as the cap, is still present; therefore, DTSC concludes that the cap is still in place, providing an effective barrier for the underlying impacted soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/23/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building foundation serves as the cap. It was observed that the building exterior was in good condition and well maintained. The adjacent side walks were also inspected and were in good condition, only minor cracks were observed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/07/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/01/2007
Comments: The cap is in good condition. No evidence of any activities prohibited by the deed restriction was observed.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2015
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 1.4

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

NPL: NO
Regulatory Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SMBRP
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38750002
Site Code: 200249
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Certified O&M - Land Use Restrictions Only
Status Date: 07/18/2000
Restricted Use: YES
Site Mgmt. Req.: REM, LUC, EX, NOWN, NDAM
Funding: Responsible Party
Latitude: 37.78175
Longitude: -122.3880
APN: Block 3792 Lot 002
Past Use: SHIPYARD - SHIP BUILDING/REPAIR, TRANSPORTATION - WAREHOUSING
Potential COC: Arsenic, Lead, Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs
Not reported
Confirmed COC: Arsenic, Lead, Arsenic, Lead, Polynuclear aromatic hydrocarbons
(PAHs, Arsenic, Lead, , Arsenic, Arsenic, Lead, Polynuclear aromatic
hydrocarbons (PAHs
Potential Description: SOIL
Alias Name: Site K (Seawall Lot 333)
Alias Type: Alternate Name
Alias Name: Block 3792 Lot 002
Alias Type: APN
Alias Name: 110033609307
Alias Type: EPA (FRS #)
Alias Name: 200249
Alias Type: Project Code (Site Code)
Alias Name: 38750002
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 07/18/2000
Comments: Certified Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 07/05/2000
Comments: Recorded Deed Restriction.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/24/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: Upon inspection, it was observed that the building exterior was in good condition and well maintained. The adjacent side walks were also inspected and were in good condition, only showing a few minor (surficial) cracks.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 08/10/2005
Comments: Five-Year Review Report was approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 04/24/1996
Comments: Approved RA. The removal activities at the site consisted of excavation and bioremediation of soil containing petroleum hydrocarbons above 1,000 mg/kg and the placement of a concrete cap. Approximately 246 cubic yards of petroleum hydrocarbon contaminated soil were biotreated on an asphalt paved lot and subsequently used as backfill. The cap covers all portions of the property and consists of a layer of 10 mils Visqueen plastic and a 4-inch thick concrete slab. A 3-story residential building and 1-story at-grade parking lot have been constructed on site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/14/1991
Comments: Documented fuel leaks at the site impacted the soil and groundwater. DTSC approved a hazardous waste management plan on May 6, 1991.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/18/1990
Comments: Site Screening noted 5 underground tanks removed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 11/23/2010
Comments: No notifications of any activities disturbing or interfering with the integrity of the cap were received in the past year. The building foundation, which serves as the cap, is still present; therefore, DTSC concludes that the cap is still in place, providing an effective barrier for the underlying impacted soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/23/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE

SITE K (SEAWALL LOT 333) (Continued) **S101482036**

Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building foundation serves as the cap. It was observed that the building exterior was in good condition and well maintained. The adjacent side walks were also inspected and were in good condition, only minor cracks were observed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/07/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/01/2007
Comments: The cap is in good condition. No evidence of any activities prohibited by the deed restriction was observed.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2015
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Z138 **ROSENMAYER PROPERTY** **LUST** **S103654599**
NNW **350 BRANNAN STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.346 mi.
1828 ft. **Site 1 of 2 in cluster Z**

Relative:
Higher

Actual:
31 ft.

LUST REG 2:
Region: 2
Facility Id: 38-0972
Facility Status: Case Closed
Case Number: 10873
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported

ROSENMAYER PROPERTY (Continued) **S103654599**

Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0972
Facility Status:	Case Closed
Case Number:	10873
Case Type:	Soil only
Release Date:	9/18/1997
Discovered Date:	9/18/1997
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	9/18/1997
Case Closed:	2/18/1998
Closed Date:	2/18/1998
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	Not reported
Entered Date:	9/19/1997
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	FRANK ROSENMAYER
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	JACK LONDON
NOR Date:	9/19/1997
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Remove Free Product - remove floating product from water table, Pump and Treat Ground Water - generally employed to remove dissolved contaminants, Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported

ROSENMAYER PROPERTY (Continued) **S103654599**

Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

Z139 **ROSENMAYER PROPERTY** **HIST CORTESE** **S102955773**
NNW **350 BRANNAN STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.346 mi.
1828 ft. **Site 2 of 2 in cluster Z**

Relative:
Higher

Actual:
31 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0972

LUST:

Region:	STATE
Global Id:	T0607500865
Latitude:	37.780822
Longitude:	-122.393543
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/18/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0972
LOC Case Number:	10873
File Location:	Not reported
Potential Media Affect:	Soil

ROSENMAYER PROPERTY (Continued) **S102955773**

Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500865
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500865
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500865
Status: Completed - Case Closed
Status Date: 02/18/1998

Global Id: T0607500865
Status: Open - Case Begin Date
Status Date: 09/18/1997

Regulatory Activities:
Global Id: T0607500865
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500865
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

X140 **COMMERCIAL PROPERTY** **LUST** **S105688786**
NNW **680 02ND ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.353 mi.
1862 ft. **Site 4 of 6 in cluster X**

Relative:
Higher

Actual:
29 ft.

LUST:
Region: STATE
Global Id: T0607501097
Latitude: 37.781527
Longitude: -122.391882
Case Type: LUST Cleanup Site

COMMERCIAL PROPERTY (Continued) **S105688786**

Status:	Completed - Case Closed
Status Date:	12/08/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1212
LOC Case Number:	11105
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501097
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607501097
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501097
Status:	Completed - Case Closed
Status Date:	12/08/1998

Global Id:	T0607501097
Status:	Open - Case Begin Date
Status Date:	01/08/1998

Regulatory Activities:

Global Id:	T0607501097
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607501097
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2

COMMERCIAL PROPERTY (Continued) **S105688786**

Facility Id: 38-1212
Facility Status: Case Closed
Case Number: 11105
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1212
Facility Status: Case Closed
Case Number: 11105
Case Type: Soil only
Release Date: 1/13/1998
Discovered Date: 1/8/1998
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Repair Tank
Report Date: 1/13/1998
Case Closed: 12/8/1998
Closed Date: 12/8/1998
Leak Source: Tank
Leak Cause: Corrosion
Leak Confirmed: 11/30/1998
Entered Date: 11/30/1998
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Julian & Stanley
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: SC
Cross Street: BRANNAN ST
NOR Date: 11/30/1998
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: ND
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported

COMMERCIAL PROPERTY (Continued) **S105688786**

Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Required - incident is minor, requiring no remedial action
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	1/8/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Fuel Oils Nos. 1 -
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	tain View 94043.

W141 **PACIFIC MOTOR TURCKING CO** **RCRA NonGen / NLR** **1000250560**
SW **1355 6TH STREET** **FINDS** **CAD000083436**
1/4-1/2 **SAN FRANCISCO, CA 94107** **LUST**
0.354 mi. **CA FID UST**
1868 ft. **Site 2 of 2 in cluster W** **HIST UST**
SWEEPS UST

Relative:
Higher

Actual:
9 ft.

RCRA NonGen / NLR:

Date form received by agency:	08/15/1980
Facility name:	PACIFIC MOTOR TURCKING CO
Facility address:	1355 6TH STREET SAN FRANCISCO, CA 94107
EPA ID:	CAD000083436
Mailing address:	SIXTH STREET SAN FRANCISCO, CA 94107
Contact:	ENVIRONMENTAL MANAGER
Contact address:	1355 SIXTH STREET SAN FRANCISCO, CA 94107
Contact country:	US
Contact telephone:	(415) 397-3600

PACIFIC MOTOR TURCKING CO (Continued) **1000250560**

Contact email: Not reported
EPA Region: 09
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PACIFIC MOTOR TRUCKING CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002626436

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PACIFIC MOTOR TURCKING CO (Continued) **1000250560**

LUST REG 2:
Region: 2
Facility Id: 38-0261
Facility Status: Case Closed
Case Number: 10325
How Discovered: Tank Closure
Leak Cause: Structure Failure
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

CA FID UST:
Facility ID: 38000302
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 1355 6TH ST
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94100
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HIST UST:
Region: STATE
Facility ID: 00000019488
Facility Type: Other
Other Type: Not reported
Total Tanks: 0003
Contact Name: Not reported
Telephone: 4156921300
Owner Name: PACIFIC MOTOR TRUCKING COMPANY
Owner Address: Not reported
Owner City,St,Zip: 1766 EL CAMINO REAL, CA 94010

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Stock Inventor, Pressure Test

PACIFIC MOTOR TURCKING CO (Continued) **1000250560**

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: Stock Inventor, Pressure Test

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

SWEEPS UST:
Status: Not reported
Comp Number: 8948
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008948-000001
Actv Date: Not reported
Capacity: 7500
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 2

Status: Not reported
Comp Number: 8948
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-008948-000002
Actv Date: Not reported
Capacity: 5000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Active
Comp Number: 8948
Number: 9
Board Of Equalization: Not reported

PACIFIC MOTOR TURCKING CO (Continued) **1000250560**

Referral Date:	09-10-93
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-008948-000003
Actv Date:	09-30-92
Capacity:	550
Tank Use:	OIL
Stg:	W
Content:	UNSPECIFIED
Number Of Tanks:	1

X142 **JACKSON H E & CO#** **RCRA-SQG** **1000272813**
NNW **334 BRANNAN ST** **FINDS** **CAD009233230**
1/4-1/2 **SAN FRANCISCO, CA** **HIST CORTESE**
0.354 mi. **LUST**
1871 ft. **Site 5 of 6 in cluster X**

Relative: Higher

Actual: 32 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	JACKSON H E & CO#
Facility address:	334 BRANNAN ST SAN FRANCISCO, CA 94107
EPA ID:	CAD009233230
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	HE & DP JACKSON
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator

JACKSON H E & CO# (Continued) **1000272813**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/15/1980
Facility name: JACKSON H E & CO#
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110002636292

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1022

LUST:
Region: STATE
Global Id: T0607500915
Latitude: 37.781415
Longitude: -122.393015
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 10/11/1996
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC

JACKSON H E & CO# (Continued) **1000272813**

Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-1022
LOC Case Number: 10671
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500915
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500915
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500915
Status: Completed - Case Closed
Status Date: 10/11/1996

Global Id: T0607500915
Status: Open - Case Begin Date
Status Date: 03/24/1995

Regulatory Activities:
Global Id: T0607500915
Action Type: ENFORCEMENT
Date: 03/24/1995
Action: Notice of Responsibility

Global Id: T0607500915
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500915
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

X143 **H.E. JACKSON CO.** **LUST** **U003746308**
NNW **334 BRANNAN STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.354 mi.
1871 ft. **Site 6 of 6 in cluster X**

Relative:
Higher

Actual:
32 ft.

LUST REG 2:

Region:	2
Facility Id:	38-1022
Facility Status:	Case Closed
Case Number:	10671
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1022
Facility Status:	Case Closed
Case Number:	10671
Case Type:	Soil only
Release Date:	8/5/1996
Discovered Date:	8/5/1996
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	8/5/1996
Case Closed:	10/11/1996
Closed Date:	10/11/1996
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	Not reported
Entered Date:	8/12/1996
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	2ND ST
NOR Date:	8/12/1996
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported

H.E. JACKSON CO. (Continued) **U003746308**

MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	3/24/1995
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	8/14/1996
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

Y144 **CCSF - PORT OF SAN FRANCISCO** **LUST** **S103472601**
South **333 ILLINOIS STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.363 mi.
1916 ft. **Site 2 of 3 in cluster Y**

Relative:
Higher

Actual:
12 ft.

LUST REG 2:

Region:	2
Facility Id:	38-0312
Facility Status:	Remediation Plan
Case Number:	10320
How Discovered:	Not reported
Leak Cause:	Not reported

CCSF - PORT OF SAN FRANCISCO (Continued) **S103472601**

Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: 9/3/1987
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0312
Facility Status: Not reported
Case Number: 10320
Case Type: Other ground water affected
Release Date: 9/3/1987
Discovered Date: 9/3/1987
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 9/3/1987
Case Closed: Not reported
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: Not reported
Entered Date: 10/4/1994
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: PORT OF S.F.
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: MA
Cross Street: 16TH ST
NOR Date: 10/4/1994
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: 4/27/1989
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal
Interim Remediation: Yes
Priority: Not reported

CCSF - PORT OF SAN FRANCISCO (Continued) **S103472601**

Abatement:	Enhanced Biodegradation - use of any available technology to promote bacterial decomposition of contaminants
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	11/2/1987
Free Product:	No
Depth to Grnd Wtr:	7.5'
Gradient:	NA
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	ND
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

Y145 **CCSF - PORT OF SAN FRANCISCO** **HIST CORTESE** **S101308306**
South **333 ILLINOIS STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.363 mi.
1916 ft. **Site 3 of 3 in cluster Y**

Relative:
Higher

Actual:
12 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0312

LUST:

Region:	STATE
Global Id:	T0607500274
Latitude:	37.7667509
Longitude:	-122.3881306
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/05/2006
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP

CCSF - PORT OF SAN FRANCISCO (Continued) **S101308306**

RB Case Number: 38-0312
LOC Case Number: 10320
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500274
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500274
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500274
Status: Completed - Case Closed
Status Date: 12/05/2006

Global Id: T0607500274
Status: Open - Case Begin Date
Status Date: 09/03/1987

Global Id: T0607500274
Status: Open - Remediation
Status Date: 09/03/1987

Regulatory Activities:
Global Id: T0607500274
Action Type: ENFORCEMENT
Date: 09/30/1994
Action: Notice of Responsibility

Global Id: T0607500274
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500274
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

CCSF - PORT OF SAN FRANCISCO (Continued) **S101308306**

Global Id: T0607500274
Action Type: ENFORCEMENT
Date: 12/05/2006
Action: Closure/No Further Action Letter

146
SW
1/4-1/2
0.365 mi.
1928 ft.

SANTA FE PACIFIC REALTY C **HIST CORTESE** **S101308435**
1201 6TH **LUST** **N/A**
SAN FRANCISCO, CA

Relative:
Higher

Actual:
6 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0259

LUST:
Region: STATE
Global Id: T0607500224
Latitude: 37.7711188
Longitude: -122.3963621
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/13/1998
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker: VP
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0259
LOC Case Number: 10450
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500224
Contact Type: Local Agency Caseworker
Contact Name: UNK
Organization Name: SAN FRANCISCO COUNTY LOP
Address: Not reported
City: r2 UNKNOWN
Email: Not reported
Phone Number: Not reported

Global Id: T0607500224
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

SANTA FE PACIFIC REALTY C (Continued) **S101308435**

Status History:

Global Id:	T0607500224
Status:	Completed - Case Closed
Status Date:	07/13/1998
Global Id:	T0607500224
Status:	Open - Case Begin Date
Status Date:	12/19/1988
Global Id:	T0607500224
Status:	Open - Site Assessment
Status Date:	01/04/1989

Regulatory Activities:

Global Id:	T0607500224
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported
Global Id:	T0607500224
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607500224
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

LUST REG 2:

Region:	2
Facility Id:	38-0259
Facility Status:	Case Closed
Case Number:	10450
How Discovered:	Tank Closure
Leak Cause:	Structure Failure
Leak Source:	Tank
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	1/4/1989
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

AA147 **WELLS FARGO BANK PROPERTY** **HIST CORTESE** **S103472546**
WNW **490 BRANNAN** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.370 mi.
1954 ft. **Site 1 of 5 in cluster AA**

Relative:
Higher

Actual:
12 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1214

LUST:

Region:	STATE
Global Id:	T0607501099
Latitude:	37.7788619
Longitude:	-122.396445
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/24/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1214
LOC Case Number:	11103
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501099
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607501099
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501099
Status:	Completed - Case Closed
Status Date:	08/24/1998

Global Id:	T0607501099
Status:	Open - Case Begin Date
Status Date:	08/13/1998

WELLS FARGO BANK PROPERTY (Continued) **S103472546**

Regulatory Activities:

Global Id:	T0607501099
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607501099
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	38-1214
Facility Status:	Case Closed
Case Number:	11103
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1214
Facility Status:	Case Closed
Case Number:	11103
Case Type:	Soil only
Release Date:	8/24/1998
Discovered Date:	8/13/1998
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	8/24/1998
Case Closed:	4/10/2002
Closed Date:	Not reported
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	12/2/1998
Entered Date:	11/23/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Diane Estrin
RP Address:	Not reported
Operator:	Not reported

WELLS FARGO BANK PROPERTY (Continued) **S103472546**

Staff Initial:	VP
Facility Staff:	AL
Cross Street:	4TH ST
NOR Date:	11/23/1998
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	4/9/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	8/13/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Fuel Oils Nos. 1 -
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Leasee; Jeffery

148
SSW
1/4-1/2
0.372 mi.
1963 ft.

PEARSON EQUIPMENT CO (FORMER)
1400 06TH ST
SAN FRANCISCO, CA 94107

LUST **S105688790**
N/A

Relative:
Higher

Actual:
10 ft.

LUST:

Region:	STATE
Global Id:	T0607501174
Latitude:	37.768573
Longitude:	-122.393414
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/19/1999
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	CDM
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1289
LOC Case Number:	11150
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501174
Contact Type:	Local Agency Caseworker
Contact Name:	CDM
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	101 GROVE STREET
City:	SAN FRANCISCO
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0607501174
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501174
Status:	Completed - Case Closed
Status Date:	03/19/1999

Global Id:	T0607501174
Status:	Open - Case Begin Date
Status Date:	12/03/1985

Regulatory Activities:

Global Id:	T0607501174
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

PEARSON EQUIPMENT CO (FORMER) (Continued) **S105688790**

Global Id: T0607501174
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1289
Facility Status: Case Closed
Case Number: 11150
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1289
Facility Status: Case Closed
Case Number: 11150
Case Type: Soil only
Release Date: 12/3/1985
Discovered Date: 12/3/1985
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Not reported
How Stopped: Not reported
Report Date: 12/3/1985
Case Closed: 3/19/1999
Closed Date: 3/19/1999
Leak Source: Unknown
Leak Cause: Unknown
Leak Confirmed: 2/4/1999
Entered Date: 2/4/1999
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Pearson Equipment
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: CDM
Cross Street: Not reported
NOR Date: 2/4/1999
MTBE Current: Not reported
MTBE Current Date: Not reported

PEARSON EQUIPMENT CO (FORMER) (Continued) **S105688790**

MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AB149 **COMMERCIAL** **WMUDS/SWAT** **S103441326**
West **444 NATOMA ST** **HIST CORTESE** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94103** **LUST**
0.373 mi.
1972 ft. **Site 1 of 3 in cluster AB**

Relative:
Higher

Actual:
7 ft.

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported

COMMERCIAL (Continued) **S103441326**

Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Base Meridian:	Not reported
NPID:	Not reported
Tonnage:	0
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	Not reported
Agency Name:	Not reported
Agency Department:	Not reported
Agency Address:	Not reported
Agency City,St,Zip:	Not reported
Agency Contact:	Not reported
Agency Telephone:	Not reported
Land Owner Name:	Not reported
Land Owner Address:	Not reported
Land Owner City,St,Zip:	CA
Land Owner Contact:	Not reported
Land Owner Phone:	Not reported
Region:	4
Facility Type:	Not reported
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	Not reported
Primary SIC:	Not reported
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	False
Solid Waste Assessment Test Program:	True
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	False
Department of Defence:	False
Solid Waste Assessment Test Program:	Not reported
Threat to Water Quality:	Not reported
Sub Chapter 15:	False
Regional Board Project Officer:	LT
Number of WMUDS at Facility:	1
Section Range:	Not reported
RCRA Facility:	Not reported
Waste Discharge Requirements:	Not reported
Self-Monitoring Rept. Frequency:	Not reported
Waste Discharge System ID:	4 190046NUR
Solid Waste Information ID:	Not reported

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1247

LUST:

Region:	STATE

COMMERCIAL (Continued) **S103441326**

Global Id:	T0607556586
Latitude:	37.776049
Longitude:	-122.396788
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	04/21/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2148
LOC Case Number:	11362
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607556586
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607556586
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607556586
Status:	Completed - Case Closed
Status Date:	04/21/2000

Global Id:	T0607556586
Status:	Open - Case Begin Date
Status Date:	03/08/2000

Regulatory Activities:

Global Id:	T0607556586
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607556586
Action Type:	ENFORCEMENT
Date:	04/20/2000
Action:	Notice of Responsibility

COMMERCIAL (Continued) **S103441326**

Global Id: T0607556586
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Region: STATE
Global Id: T0607501132
Latitude: 37.781106
Longitude: -122.406781
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 05/28/1999
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: AL
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-1247
LOC Case Number: 11126
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607501132
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607501132
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501132
Status: Completed - Case Closed
Status Date: 05/28/1999

Global Id: T0607501132
Status: Open - Case Begin Date
Status Date: 09/08/1998

Regulatory Activities:
Global Id: T0607501132
Action Type: Other
Date: 01/01/1950

COMMERCIAL (Continued) **S103441326**

Action: Leak Discovery

Global Id: T0607501132
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

AB150 **COMMERCIAL** **LUST** **S106229907**
West **370 TOWNSEND ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.374 mi.
1974 ft. **Site 2 of 3 in cluster AB**

Relative:
Higher

Actual:
7 ft.

LUST REG 2:
Region: 2
Facility Id: 38-2148
Facility Status: Case Closed
Case Number: 11362
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 02-200-007
Facility Status: Case Closed
Case Number: 11362
Case Type: Soil only
Release Date: Not reported
Discovered Date: 3/8/2000
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 3/8/2000
Case Closed: 4/21/2000
Closed Date: 4/21/2000
Leak Source: Tank
Leak Cause: Corrosion
Leak Confirmed: 3/8/2000
Entered Date: 4/20/2000
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported

COMMERCIAL (Continued) **S106229907**

Operator:	Sinclair Louie
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	5th St
NOR Date:	4/20/2000
MTBE Current:	Not reported
MTBE Current Date:	3/8/2000
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	3/8/2000
Review Date:	4/20/2000
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	4/20/2000
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	3/8/2000
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Fuel Oils Nos. 1 -
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	ND
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	3/8/2000
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AC151 **PARKING LOT** **LUST** **S104889738**
NW **599 03RD ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.375 mi.
1978 ft. **Site 1 of 6 in cluster AC**

Relative:
Higher

Actual:
23 ft.

LUST:

Region:	STATE
Global Id:	T0607501351
Latitude:	37.780296
Longitude:	-122.394273
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/01/1999
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1467
LOC Case Number:	11318
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501351
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607501351
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501351
Status:	Completed - Case Closed
Status Date:	12/01/1999

Global Id:	T0607501351
Status:	Open - Case Begin Date
Status Date:	09/21/1999

Regulatory Activities:

Global Id:	T0607501351
Action Type:	ENFORCEMENT
Date:	11/17/1999
Action:	Notice of Responsibility

PARKING LOT (Continued) **S104889738**

Global Id: T0607501351
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501351
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1467
Facility Status: Case Closed
Case Number: 11318
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1467
Facility Status: Case Closed
Case Number: 11318
Case Type: Soil only
Release Date: Not reported
Discovered Date: 9/21/1999
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 11/4/1999
Case Closed: 12/1/1999
Closed Date: 12/1/1999
Leak Source: Tank
Leak Cause: Corrosion
Leak Confirmed: 9/21/1999
Entered Date: 11/17/1999
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Paul Chow
Staff Initial: VP

PARKING LOT (Continued) **S104889738**

Facility Staff:	AL
Cross Street:	Brannan
NOR Date:	11/17/1999
MTBE Current:	Not reported
MTBE Current Date:	9/21/1999
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	9/21/1999
Review Date:	11/30/1999
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	11/17/1999
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	9/21/1999
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Fuel Oil Nos. 1-6
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	1500
TPH Date:	9/21/1999
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AA152 **HEUBLEIN INC** **HIST CORTESE** **S102431349**
WNW **601 4TH** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.375 mi.
1979 ft. **Site 2 of 5 in cluster AA**

Relative:
Higher

Actual:
12 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0179

AA153 **HEUBLEIN, INC.** **LUST** **S104889644**
WNW **601 04TH ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.376 mi.
1983 ft. **Site 3 of 5 in cluster AA**

Relative:
Higher

Actual:
12 ft.

LUST:

Region:	STATE
Global Id:	T0607500156
Latitude:	37.778386
Longitude:	-122.39513
Case Type:	LUST Cleanup Site
Status:	Open - Eligible for Closure
Status Date:	07/31/2013
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0179
LOC Case Number:	10239
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	7.7.10: site was redeveloped before LOP obtained site as case. unable to ID appropriate RP since site is redeveloped as condominiums.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500156
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500156
Contact Type:	Regional Board Caseworker
Contact Name:	Cheryl L. Prowell
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 Clay Street, Suite 1400
City:	Oakland
Email:	cprowell@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500156

HEUBLEIN, INC. (Continued) **S104889644**

Status: Open - Case Begin Date
Status Date: 04/11/1988

Global Id: T0607500156
Status: Open - Eligible for Closure
Status Date: 07/31/2013

Global Id: T0607500156
Status: Open - Inactive
Status Date: 04/11/1988

Global Id: T0607500156
Status: Open - Inactive
Status Date: 07/19/2013

Global Id: T0607500156
Status: Open - Site Assessment
Status Date: 04/11/1988

Global Id: T0607500156
Status: Open - Site Assessment
Status Date: 08/12/2010

Global Id: T0607500156
Status: Open - Site Assessment
Status Date: 08/13/2010

Regulatory Activities:
Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 07/19/2013
Action: File review

Global Id: T0607500156
Action Type: Other
Date: 01/01/1950
Action: Leak Began

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 07/19/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 08/13/2010
Action: File review

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 06/03/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 07/31/2013
Action: File Review - Closure

HEUBLEIN, INC. (Continued) **S104889644**

Global Id: T0607500156
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500156
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500156
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 02/08/2007
Action: File review

Global Id: T0607500156
Action Type: ENFORCEMENT
Date: 07/02/2010
Action: File review

LUST REG 2:
Region: 2
Facility Id: 38-0179
Facility Status: Leak being confirmed
Case Number: 10239
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: 4/11/1988
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0179
Facility Status: Leak being confirmed
Case Number: 10239
Case Type: Other ground water affected
Release Date: 4/11/1998
Discovered Date: 4/11/1988
Substance: Diesel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 4/11/1988

HEUBLEIN, INC. (Continued) **S104889644**

Case Closed:	Not reported
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	5/1/1989
Entered Date:	3/9/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	HUBLEIN INC.
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	BRANNAN ST
NOR Date:	3/9/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	6/27/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	4/11/1988
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	4000
TPH Date:	Not reported

HEUBLEIN, INC. (Continued) **S104889644**

Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	6/26-6/27/02 file

AC154 **SHELL BRANDED GASOLINE STATION** **LUST** **S112141916**
NW **551 03RD STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.383 mi.
2020 ft. **Site 2 of 6 in cluster AC**

Relative:
Higher

Actual:
23 ft.

LUST:

Region:	STATE
Global Id:	T10000004261
Latitude:	37.7807214094438
Longitude:	-122.394733428955
Case Type:	LUST Cleanup Site
Status:	Open - Site Assessment
Status Date:	11/06/2012
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	EH
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	11979
File Location:	Local Agency
Potential Media Affect:	Not reported
Potential Contaminants of Concern:	Diesel, Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T10000004261
Contact Type:	Local Agency Caseworker
Contact Name:	ELYSE HEILSHORN
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 Market Street Suite 210
City:	SAN FRANCISCO
Email:	elyse.heilshorn@sfdph.org
Phone Number:	4152523885

Status History:

Global Id:	T10000004261
Status:	Open - Case Begin Date
Status Date:	01/01/1999
Global Id:	T10000004261
Status:	Open - Site Assessment
Status Date:	09/06/2012
Global Id:	T10000004261
Status:	Open - Site Assessment
Status Date:	11/06/2012

SHELL BRANDED GASOLINE STATION (Continued) **S112141916**

Regulatory Activities:

Global Id:	T10000004261
Action Type:	ENFORCEMENT
Date:	01/09/2013
Action:	Staff Letter
Global Id:	T10000004261
Action Type:	Other
Date:	01/01/1950
Action:	Leak Began
Global Id:	T10000004261
Action Type:	ENFORCEMENT
Date:	09/27/2012
Action:	Notice of Responsibility - #11979
Global Id:	T10000004261
Action Type:	ENFORCEMENT
Date:	10/12/2012
Action:	Staff Letter
Global Id:	T10000004261
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped
Global Id:	T10000004261
Action Type:	ENFORCEMENT
Date:	09/05/2012
Action:	Unauthorized Release Form
Global Id:	T10000004261
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T10000004261
Action Type:	ENFORCEMENT
Date:	08/07/2013
Action:	Staff Letter
Global Id:	T10000004261
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

AD155 **GEORGE LITHOGRAPH** **LUST** **1002851800**
NNW **650 02ND ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.385 mi.
2031 ft. **Site 1 of 3 in cluster AD**

Relative:
Higher

Actual:
33 ft.

LUST:

Region:	STATE
Global Id:	T0607500583
Latitude:	37.781235

GEORGE LITHOGRAPH (Continued) **1002851800**

Longitude:	-122.39007
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/02/1996
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0667
LOC Case Number:	10538
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500583
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500583
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500583
Status:	Completed - Case Closed
Status Date:	01/02/1996

Global Id:	T0607500583
Status:	Open - Case Begin Date
Status Date:	05/18/1995

Regulatory Activities:

Global Id:	T0607500583
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500583
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

GEORGE LITHOGRAPH (Continued) **1002851800**

LUST REG 2:

Region:	2
Facility Id:	38-0667
Facility Status:	Case Closed
Case Number:	10538
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0667
Facility Status:	Case Closed
Case Number:	10538
Case Type:	Soil only
Release Date:	6/13/1995
Discovered Date:	5/18/1995
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Report Date:	6/13/1995
Case Closed:	1/2/1996
Closed Date:	1/2/1996
Leak Source:	Not reported
Leak Cause:	Not reported
Leak Confirmed:	Not reported
Entered Date:	10/10/1995
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	Not reported
NOR Date:	10/10/1995
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported

GEORGE LITHOGRAPH (Continued) **1002851800**

Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Not reported
Interim Remediation:	Not reported
Priority:	Not reported
Abatement:	Not reported
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AE156 **SANTA FE PACIFIC REALTY C** **HIST CORTESE** **S101308255**
WSW **205 CHANNEL** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.385 mi.
2035 ft. **Site 1 of 2 in cluster AE**

Relative:
Lower

Actual:
4 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0263

LUST:

Region:	STATE
Global Id:	T0607500228
Latitude:	37.7745393

SANTA FE PACIFIC REALTY C (Continued) **S101308255**

Longitude:	-122.3899934
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/13/1998
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	VP
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0263
LOC Case Number:	10403
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500228
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500228
Contact Type:	Local Agency Caseworker
Contact Name:	UNK
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	Not reported
City:	r2 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

Status History:

Global Id:	T0607500228
Status:	Completed - Case Closed
Status Date:	07/13/1998

Global Id:	T0607500228
Status:	Open - Case Begin Date
Status Date:	12/16/1988

Global Id:	T0607500228
Status:	Open - Site Assessment
Status Date:	12/19/1988

Regulatory Activities:

Global Id:	T0607500228
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500228
Action Type:	Other
Date:	01/01/1950

SANTA FE PACIFIC REALTY C (Continued) **S101308255**

Action: Leak Discovery

Global Id: T0607500228
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

LUST REG 2:
Region: 2
Facility Id: 38-0263
Facility Status: Case Closed
Case Number: 10403
How Discovered: Tank Closure
Leak Cause: Structure Failure
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 12/19/1988
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

AE157 **PEARSON EQUIPMENT COMPANY** **HIST CORTESE** **S103890719**
WSW **1400 6TH** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.387 mi.
2046 ft. **Site 2 of 2 in cluster AE**

Relative:
Lower

Actual:
0 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1289

AA158 **BRANNAN STREET AUTO REPAIR** **LUST** **S105694687**
WNW **518 BRANNAN STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94109**
0.394 mi.
2078 ft. **Site 4 of 5 in cluster AA**

Relative:
Higher

Actual:
10 ft.

LUST:
Region: STATE
Global Id: T0607586221
Latitude: 37.778159
Longitude: -122.39733
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/17/2002
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: AL
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-2192
LOC Case Number: 11531

BRANNAN STREET AUTO REPAIR (Continued) **S105694687**

File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607586221
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607586221
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607586221
Status: Completed - Case Closed
Status Date: 12/17/2002

Global Id: T0607586221
Status: Open - Case Begin Date
Status Date: 07/23/2002

Regulatory Activities:
Global Id: T0607586221
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607586221
Action Type: ENFORCEMENT
Date: 12/11/2002
Action: Notice of Responsibility

Global Id: T0607586221
Action Type: ENFORCEMENT
Date: 12/17/2002
Action: Closure/No Further Action Letter

Global Id: T0607586221
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

Global Id: T0607586221

BRANNAN STREET AUTO REPAIR (Continued) **S105694687**

Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607586221
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2192
Facility Status: Case Closed
Case Number: 11531
How Discovered: Tank Closure
Leak Cause: Corrosion
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

AC159 **THIRD STREET SHELL** **LUST U001595312**
NW **551 03RD ST** **UST N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **HIST UST**
0.395 mi. **SWEEPS UST**
2088 ft. **Site 3 of 6 in cluster AC**

Relative:
Higher

Actual:
21 ft.

LUST:
Region: STATE
Global Id: T10000000355
Latitude: 37.7528341
Longitude: -122.3878342
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/29/2009
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: MA
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 11850
File Location: Not reported
Potential Media Affect: Not reported
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000000355
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP

THIRD STREET SHELL (Continued) **U001595312**

Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T10000000355
Status: Completed - Case Closed
Status Date: 12/29/2009

Global Id: T10000000355
Status: Open - Case Begin Date
Status Date: 09/17/2008

Global Id: T10000000355
Status: Open - Site Assessment
Status Date: 09/17/2008

Regulatory Activities:
Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 12/29/2009
Action: Closure/No Further Action Letter

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 10/30/2009
Action: File Review - Closure

Global Id: T10000000355
Action Type: RESPONSE
Date: 10/20/2009
Action: Correspondence

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 12/29/2009
Action: Closure/No Further Action Letter

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 12/24/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 09/24/2009
Action: File review

Global Id: T10000000355
Action Type: RESPONSE
Date: 09/25/2009
Action: Site Assessment Report

Global Id: T10000000355
Action Type: RESPONSE

THIRD STREET SHELL (Continued) **U001595312**

Date: 09/24/2009
Action: Verbal Communication

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 09/29/2009
Action: File review

Global Id: T10000000355
Action Type: ENFORCEMENT
Date: 10/22/2009
Action: Site Visit / Inspection / Sampling

Global Id: T10000000355
Action Type: RESPONSE
Date: 10/16/2009
Action: Correspondence

UST:
Facility ID: 21327
Latitude: 37.78055
Longitude: -122.39484

SAN FRANCISCO CO. UST:
Facility ID: 29496
Facility Status: Not reported
Number Of Tanks: Not reported
Owner/Operator Name: Not reported
Owner/Operator Title: Not reported
Owner Name: Shell Oil Products
Care Of Addr: Michelle Ponce
2nd Care Of Add: 551-03rd ST
Mailing Address: 20945 S.
Mailing City,St,Zip: Carson, CA 90810
Permit Number: Not reported
Permit Approved By: Not reported
Permit Expiration Date: Not reported
Applications: Not reported
Application Date: Not reported
Application Name: Not reported
Action Type: 1
Yr Spill/Overfill Installed1: Not reported
Yr Spill/Overfill Installed2: Not reported
Yr Spill/Overfill Installed3: Not reported

Tank ID: 1001
Tank Test: Not reported
Local Tank Id: 29496001001
Tank Manufacturer: Owens Corning
Compartmentalized Tank: No
Of Tank Compartments: Not reported
Date Tank Installed: 1/1/1981
Tank Capacity: 10000
Additional Desc: Not reported
Tank Use: 1

THIRD STREET SHELL (Continued) **U001595312**

Petroleum Type:	Regular Unleaded
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Single wall
Primary Tank Material:	Fiberglass/plastic
Secondary Tank Material:	Not reported
Tank Interior Lining:	Unlined
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	spill containment, drop tube, striker plate
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	No
Othr Tnk Corrosive Prtctn:	Fiberglass Reinforced Plastic (FRP)
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	0
Tank Filled With Inert Material:	0
Piping System Type (Underground):	Pressure
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Double Wall
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Fiberglass, Other
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Sump Snsr, Alrm ,Auto Shutoff For Leaks, Failure, & Disconnect
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	12/19/2003
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Continuous Dispenser With Auto Shutoff for Dispenser
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	4/16/2008
2nd Containment Test:	1/21/2008
Spill Containment Present:	Yes
Drop Tube Present:	Yes
Striker Plate Present:	Yes
Alarm Present:	No
Ball Float Present:	No
Fill Tube Present:	Yes
Other Tank Leak Detection Present:	No

Tank ID:	1002
Tank Test:	Not reported
Local Tank Id:	29496001002
Tank Manufacturer:	Owens Corning

THIRD STREET SHELL (Continued) **U001595312**

Compartmentalized Tank:	No
# Of Tank Compartments:	Not reported
Date Tank Installed:	1/1/1981
Tank Capacity:	10000
Additional Desc:	Not reported
Tank Use:	1
Petroleum Type:	Premium Unleaded
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Single wall
Primary Tank Material:	Fiberglass/plastic
Secondary Tank Material:	Not reported
Tank Interior Lining:	Unlined
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	spill containment, drop tube, striker plate
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	No
Othr Tnk Corrosive Prtctn:	Fiberglass Reinforced Plastic (FRP)
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	0
Tank Filled With Inert Material:	0
Piping System Type (Underground):	Pressure
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Double Wall
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Fiberglass
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Sump Snsr, Alrm ,Auto Shutoff For Leaks, Failure, & Disconnect
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	12/13/2003
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Continuous Dispenser With Auto Shutoff for Dispenser
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	4/16/2008
2nd Containment Test:	1/21/2008
Spill Containment Present:	Yes
Drop Tube Present:	Yes
Striker Plate Present:	Yes
Alarm Present:	No
Ball Float Present:	No
Fill Tube Present:	Yes
Other Tank Leak Detection Present:	No

THIRD STREET SHELL (Continued) **U001595312**

Tank ID:	1003
Tank Test:	Not reported
Local Tank Id:	29496001003
Tank Manufacturer:	Owens Corning
Compartmentalized Tank:	No
# Of Tank Compartments:	Not reported
Date Tank Installed:	1/1/1981
Tank Capacity:	10000
Additional Desc:	Not reported
Tank Use:	1
Petroleum Type:	Diesel
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Single wall
Primary Tank Material:	Fiberglass/plastic
Secondary Tank Material:	Not reported
Tank Interior Lining:	Unlined
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	spill containment, drop tube, striker plate
Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	No
Othr Tnk Corrosive Prtctn:	Fiberglass Reinforced Plastic (FRP)
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	0
Tank Filled With Inert Material:	0
Piping System Type (Underground):	Pressure
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Double Wall
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Fiberglass
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Sump Snsr, Alrm ,Auto Shutoff For Leaks, Failure, & Disconnect
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	8/21/2003
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Continuous Dispenser With Auto Shutoff for Dispenser
Date Certified (Tank Unit):	Not reported
Certified Date:	Not reported
Last Annual Monitoring Cert:	4/16/2008
2nd Containment Test:	1/21/2008
Spill Containment Present:	Yes
Drop Tube Present:	Yes
Striker Plate Present:	Yes

THIRD STREET SHELL (Continued) **U001595312**

Alarm Present:	No
Ball Float Present:	No
Fill Tube Present:	Yes
Other Tank Leak Detection Present:	No

Tank ID:	Not reported
Tank Test:	Not reported
Local Tank Id:	Not reported
Tank Manufacturer:	Not reported
Compartmentalized Tank:	Not reported
# Of Tank Compartments:	Not reported
Date Tank Installed:	Not reported
Tank Capacity:	Not reported
Additional Desc:	Not reported
Tank Use:	Not reported
Petroleum Type:	Not reported
Common Name:	Not reported
Case Number:	Not reported
Type Of Tank:	Not reported
Primary Tank Material:	Not reported
Secondary Tank Material:	Not reported
Tank Interior Lining:	Not reported
Date Interior Lining Install:	Not reported
Date Closed:	Not reported
UST Close ID:	Not reported
Type Of Spill Protection:	Not reported

Date Alarm Overfill Protection Installed:	Not reported
Date Ball Float Overfill Protection Installed:	Not reported
Date Fill Tube Shut Overfill Protection Installed:	Not reported
Overfill Protection Exempt:	Not reported
Othr Tnk Corrosive Prtctn:	Not reported
Date Corrosive Prtctn Install:	Not reported
Tank Leak Detection (single walled):	Not reported
Tank Leak Detection (double wall):	Not reported
Estimated Date Last Used:	Not reported
Estimated Qty Of Substance Remaining:	Not reported
Tank Filled With Inert Material:	Not reported
Piping System Type (Underground):	Not reported
Piping System Type (Aboveground):	Not reported
Piping Construction (Underground):	Not reported
Piping Manufacturer (Underground):	Not reported
Piping Construction (Aboveground):	Not reported
Piping Manufacturer (Aboveground):	Not reported
Piping Material & Corrosion Protection (Underground):	Not reported
Piping Material & Corrosion Protection (Aboveground):	Not reported
Piping Leak Detection (Undrgrnd - Single Wall):	Not reported
Piping Leak Detection (2nd Contained):	Not reported
Piping Leak Detection (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Underground:	Not reported
Piping Leak Detection (Aboveground - Single Wall):	Not reported
Piping Leak Detection (Underground - 2nd Contained):	Not reported
Piping Leak Detection Underground (Emrgncy Gnrtrs):	Not reported
Pipe Integrity Test, Aboveground:	Not reported
Date Dispenser Containment Installed:	Not reported
Dispenser Containment Type:	Not reported
Date Certified (Tank Unit):	Not reported

THIRD STREET SHELL (Continued) **U001595312**

Certified Date:	Not reported
Last Annual Monitoring Cert:	Not reported
2nd Containment Test:	Not reported
Spill Containment Present:	Not reported
Drop Tube Present:	Not reported
Striker Plate Present:	Not reported
Alarm Present:	Not reported
Ball Float Present:	Not reported
Fill Tube Present:	Not reported
Other Tank Leak Detection Present:	Not reported

HIST UST:

Region:	STATE
Facility ID:	00000009647
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0003
Contact Name:	JOE *= WU
Telephone:	4155434016
Owner Name:	SHELL OIL COMPANY
Owner Address:	P.O. BOX 4848
Owner City,St,Zip:	ANAHEIM, CA 92803

Tank Num:	001
Container Num:	1
Year Installed:	78
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10

Tank Num:	002
Container Num:	2
Year Installed:	1978
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10

Tank Num:	003
Container Num:	3
Year Installed:	1978
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10

SWEEPS UST:

Status:	Active
Comp Number:	1212
Number:	1
Board Of Equalization:	44-000074
Referral Date:	08-24-93

THIRD STREET SHELL (Continued) **U001595312**

Action Date:	09-10-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	001212001001
Swrcb Tank Id:	38-000-001212-000001
Actv Date:	08-17-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	3

Status:	Active
Comp Number:	1212
Number:	1
Board Of Equalization:	44-000074
Referral Date:	08-24-93
Action Date:	09-10-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	001212001002
Swrcb Tank Id:	38-000-001212-000002
Actv Date:	08-17-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	1212
Number:	1
Board Of Equalization:	44-000074
Referral Date:	08-24-93
Action Date:	09-10-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	001212001003
Swrcb Tank Id:	38-000-001212-000003
Actv Date:	08-17-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	PRM UNLEADED
Number Of Tanks:	Not reported

AC160 **BAYSIDE VILLAGE ASSOCIATES** **HIST CORTESE** **S101592427**
NW **551 1ST ST** **CA FID UST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94105** **SWEEPS UST**
0.395 mi.
2088 ft. **Site 4 of 6 in cluster AC**

Relative:
Higher

Actual:
21 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0040

BAYSIDE VILLAGE ASSOCIATES (Continued) **S101592427**

CA FID UST:
Facility ID: 38005232
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 551 1ST ST
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN FRANCISCO 94105
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Active
Comp Number: 297
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 297
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-000297-000001
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 5

Status: Not reported
Comp Number: 297

BAYSIDE VILLAGE ASSOCIATES (Continued) **S101592427**

Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-000297-000002
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 297
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-000297-000003
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 297
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-000297-000004
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 297
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported

BAYSIDE VILLAGE ASSOCIATES (Continued) **S101592427**

Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-000297-000005
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

AF161 **CHARLES O. JONES, INC.** **LUST** **S105806062**
NW **49 ZOE STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.399 mi.
2105 ft. **Site 1 of 2 in cluster AF**

Relative:
Higher

Actual:
16 ft.

LUST REG 2:
Region: 2
Facility Id: 38-0192
Facility Status: Case Closed
Case Number: 10130
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0192
Facility Status: Case Closed
Case Number: 10130
Case Type: Other ground water affected
Release Date: 6/12/1991
Discovered Date: 6/5/1991
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 6/12/1991
Case Closed: 7/23/1994
Closed Date: 7/23/1994
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: Not reported
Entered Date: 1/28/1993
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported

CHARLES O. JONES, INC. (Continued) **S105806062**

RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	WELSH ST
NOR Date:	1/28/1993
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	8/16/1991
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming), Pump and Treat Ground Water - generally employed to remove dissolved contaminants
Enforcement Type:	2A
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	10/4/1991
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AF162 **CHARLES O JONES INC** **HIST CORTESE** **S104161859**
NW **49 ZOE** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **SWEEPS UST**
0.399 mi.
2105 ft. **Site 2 of 2 in cluster AF**

Relative:
Higher

Actual:
16 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0192

LUST:

Region:	STATE
Global Id:	T0607500164
Latitude:	37.780076
Longitude:	-122.396012
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/23/1994
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0192
LOC Case Number:	10130
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500164
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500164
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500164
Status:	Completed - Case Closed
Status Date:	07/23/1994

Global Id:	T0607500164
Status:	Open - Case Begin Date
Status Date:	06/05/1991

CHARLES O JONES INC (Continued) **S104161859**

Regulatory Activities:

Global Id:	T0607500164
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500164
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

SWEEPS UST:

Status:	Not reported
Comp Number:	8624
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-008624-000001
Actv Date:	Not reported
Capacity:	1000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	1

Status:	Active
Comp Number:	8624
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

163
NNW
1/4-1/2
0.403 mi.
2128 ft.

COMMERCIAL PROPERTY
33-35 SOUTH PARK
SAN FRANCISCO, CA 94107

LUST **S106162697**
N/A

Relative:
Higher

Actual:
37 ft.

LUST:

Region:	STATE
Global Id:	T0607506366
Latitude:	37.781701
Longitude:	-122.393534
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/27/2003
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2203
LOC Case Number:	11542
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607506366
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Global Id:	T0607506366
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607506366
Status:	Completed - Case Closed
Status Date:	02/27/2003

Global Id:	T0607506366
Status:	Open - Case Begin Date
Status Date:	02/06/2003

Global Id:	T0607506366
Status:	Open - Site Assessment
Status Date:	02/06/2003

COMMERCIAL PROPERTY (Continued) **S106162697**

Regulatory Activities:

Global Id:	T0607506366
Action Type:	ENFORCEMENT
Date:	02/25/2003
Action:	Notice of Responsibility

Global Id:	T0607506366
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

Global Id:	T0607506366
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607506366
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation

Global Id:	T0607506366
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	38-2203
Facility Status:	Case Closed
Case Number:	11542
How Discovered:	Tank Closure
Leak Cause:	Corrosion
Leak Source:	Tank
Date Leak Confirmed:	2/6/2003
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

AG164 **RINGROSE CORPORATION** **LUST** **S101592573**
NNW **275 BRANNAN ST** **CA FID UST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **SWEEPS UST**
0.405 mi.
2138 ft. **Site 1 of 3 in cluster AG**

Relative:
Higher

Actual:
31 ft.

LUST:

Region:	STATE
Global Id:	T0607564631
Latitude:	37.782081
Longitude:	-122.39124
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed

RINGROSE CORPORATION (Continued) **S101592573**

Status Date:	07/23/2001
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2102
LOC Case Number:	11475
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607564631
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607564631
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607564631
Status:	Completed - Case Closed
Status Date:	07/23/2001

Global Id:	T0607564631
Status:	Open - Case Begin Date
Status Date:	07/18/2001

Regulatory Activities:

Global Id:	T0607564631
Action Type:	ENFORCEMENT
Date:	09/27/2001
Action:	Notice of Responsibility

Global Id:	T0607564631
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607564631
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

RINGROSE CORPORATION (Continued) **S101592573**

LUST REG 2:

Region:	2
Facility Id:	38-2102
Facility Status:	Case Closed
Case Number:	11475
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	02-301-024
Facility Status:	Case Closed
Case Number:	11475
Case Type:	Soil only
Release Date:	Not reported
Discovered Date:	7/18/2001
Substance:	Heater Fuel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	7/23/2001
Case Closed:	10/1/2001
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	7/18/2001
Entered Date:	9/27/2001
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Thomas Gherin
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	2nd St
NOR Date:	Not reported
MTBE Current:	Not reported
MTBE Current Date:	7/18/2001
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	7/18/2001
Review Date:	9/28/2001
Workplan Submitted:	Not reported

RINGROSE CORPORATION (Continued) **S101592573**

Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	9/27/2001
Basin:	DOWNTOWN
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	7/18/2001
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	6
TPH Date:	7/18/2001
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	10/1/01 case

CA FID UST:

Facility ID:	38005442
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	275 BRANNAN ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported

RINGROSE CORPORATION (Continued) **S101592573**

EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 7671
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-007671-000001
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 1

Status: Active
Comp Number: 7671
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

AC165 **TAYLOR PROPERTY** **HIST CORTESE** **S102438452**
NW **150 PARK** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.405 mi.
2140 ft. **Site 5 of 6 in cluster AC**

Relative:
Higher

Actual:
26 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0365

LUST:
Region: STATE
Global Id: T0607500323
Latitude: 37.7814059
Longitude: -122.394798
Case Type: LUST Cleanup Site

TAYLOR PROPERTY (Continued) **S102438452**

Status:	Completed - Case Closed
Status Date:	01/29/1996
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0365
LOC Case Number:	10587
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500323
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500323
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500323
Status:	Completed - Case Closed
Status Date:	01/29/1996

Global Id:	T0607500323
Status:	Open - Case Begin Date
Status Date:	10/03/1986

Regulatory Activities:

Global Id:	T0607500323
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500323
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

LUST REG 2:

Region:	2

TAYLOR PROPERTY (Continued) **S102438452**

Facility Id: 38-0365
Facility Status: Case Closed
Case Number: 10587
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0365
Facility Status: Case Closed
Case Number: 10587
Case Type: Soil only
Release Date: 10/3/1986
Discovered Date: 10/3/1986
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 10/3/1986
Case Closed: 1/29/1996
Closed Date: 1/29/1996
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: 1/31/1996
Entered Date: 1/19/1996
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: AL
Cross Street: Not reported
NOR Date: 1/19/1996
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported

TAYLOR PROPERTY (Continued) **S102438452**

Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	10/3/1986
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	10/3/86 [leak

---

166 **CATELLUS DEVELOPMENT CORP.** **LUST** **S105688801**
SSW **1600 06TH ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.407 mi.
2151 ft.

Relative:
Higher

Actual:
13 ft.

LUST:

Region:	STATE
Global Id:	T0607501366
Latitude:	37.767388
Longitude:	-122.391895
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/14/2000
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1594
LOC Case Number:	11330
File Location:	Not reported

CATELLUS DEVELOPMENT CORP. (Continued) **S105688801**

Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607501366
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Global Id: T0607501366
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501366
Status: Completed - Case Closed
Status Date: 01/14/2000

Global Id: T0607501366
Status: Open - Case Begin Date
Status Date: 05/27/1999

Regulatory Activities:
Global Id: T0607501366
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501366
Action Type: ENFORCEMENT
Date: 12/22/1999
Action: Notice of Responsibility

Global Id: T0607501366
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1594
Facility Status: Case Closed
Case Number: 11330

CATELLUS DEVELOPMENT CORP. (Continued) **S105688801**

How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1594
Facility Status: Case Closed
Case Number: 11330
Case Type: Other ground water affected
Release Date: Not reported
Discovered Date: 5/27/1999
Substance: Waste Oil
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 12/22/1999
Case Closed: 1/14/2000
Closed Date: 1/14/2000
Leak Source: Tank
Leak Cause: Unknown
Leak Confirmed: 5/27/1999
Entered Date: 12/22/1999
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: James Adams
Staff Initial: VP
Facility Staff: MA
Cross Street: 16th St
NOR Date: 12/22/1999
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: ND
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal

CATELLUS DEVELOPMENT CORP. (Continued) **S105688801**

Interim Remediation:	No
Priority:	Moderate Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	12/22/1999
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	5/27/1999
Free Product:	Not reported
Depth to Grnd Wtr:	11 feet
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	ND
Max TPH GW:	Not reported
Max TPH Soil:	230
TPH Date:	5/21/1999
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AB167 **COMMERCIAL PROPERTY** **LUST** **S108751056**
WNW **77 BLUXOME ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.408 mi.
2155 ft. **Site 3 of 3 in cluster AB**

Relative:
Higher

Actual:
8 ft.

LUST:

Region:	STATE
Global Id:	T0607580091
Latitude:	37.776386
Longitude:	-122.397463
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/24/2007
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2446
LOC Case Number:	11785
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline

COMMERCIAL PROPERTY (Continued) **S108751056**

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607580091
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607580091
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET
City:	OAKLAND
Email:	nkatyl@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607580091
Status:	Completed - Case Closed
Status Date:	01/24/2007

Global Id:	T0607580091
Status:	Open - Case Begin Date
Status Date:	09/01/2006

Global Id:	T0607580091
Status:	Open - Site Assessment
Status Date:	09/01/2006

Regulatory Activities:

Global Id:	T0607580091
Action Type:	ENFORCEMENT
Date:	01/16/2007
Action:	File review

Global Id:	T0607580091
Action Type:	ENFORCEMENT
Date:	01/12/2007
Action:	Notice of Responsibility

Global Id:	T0607580091
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607580091
Action Type:	ENFORCEMENT
Date:	01/24/2007
Action:	Closure/No Further Action Letter

COMMERCIAL PROPERTY (Continued) **S108751056**

Global Id: T0607580091
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607580091
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

168
WSW
1/4-1/2
0.408 mi.
2155 ft.

SOUTHERN PACIFIC MOTOR TRUCKING **HIST CORTESE** **S100849712**
1355 6TH ST **LUST** **N/A**
SAN FRANCISCO, CA 94107

Relative:
Lower

Actual:
4 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0261

LUST:
Region: STATE
Global Id: T0607500226
Latitude: 37.7708621
Longitude: -122.3960372
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 09/25/1998
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker: VP
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0261
LOC Case Number: 10325
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500226
Contact Type: Local Agency Caseworker
Contact Name: UNK
Organization Name: SAN FRANCISCO COUNTY LOP
Address: Not reported
City: r2 UNKNOWN
Email: Not reported
Phone Number: Not reported

Global Id: T0607500226
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400

SOUTHERN PACIFIC MOTOR TRUCKING (Continued) **S100849712**

City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607500226
Status: Completed - Case Closed
Status Date: 09/25/1998

Global Id: T0607500226
Status: Open - Case Begin Date
Status Date: 12/19/1988

Regulatory Activities:
Global Id: T0607500226
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500226
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500226
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

AH169 **3RD STREET LIGHT RAIL PROJECT SEG.B** **LUST** **S110655148**
South **3RD STREET & 16TH STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94103**
0.410 mi.
2164 ft. **Site 1 of 4 in cluster AH**

Relative:
Higher

Actual:
14 ft.

LUST:
Region: STATE
Global Id: T0607573507
Latitude: 37.7670509406117
Longitude: -122.38911151886
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 11/16/2006
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-2438
LOC Case Number: 11777
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

3RD STREET LIGHT RAIL PROJECT SEG.B (Continued) **S110655148**

Global Id: T0607573507
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Global Id: T0607573507
Contact Type: Regional Board Caseworker
Contact Name: NANCY KATYL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET
City: OAKLAND
Email: nkatyl@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607573507
Status: Completed - Case Closed
Status Date: 11/16/2006

Global Id: T0607573507
Status: Open - Case Begin Date
Status Date: 05/07/2003

Global Id: T0607573507
Status: Open - Site Assessment
Status Date: 05/07/2003

Regulatory Activities:
Global Id: T0607573507
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607573507
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607573507
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

AI170 **COMMERCIAL BUILDING** **LUST** **S105194392**
WNW **542 BRANNAN STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.413 mi.
2180 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
10 ft.

LUST REG 2:

Region:	2
Facility Id:	38-1035
Facility Status:	Case Closed
Case Number:	10989
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1035
Facility Status:	Case Closed
Case Number:	10989
Case Type:	Soil only
Release Date:	5/4/1998
Discovered Date:	5/1/1998
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	5/4/1998
Case Closed:	6/30/1998
Closed Date:	6/30/1998
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	Not reported
Entered Date:	6/16/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	4TH ST
NOR Date:	6/16/1998
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported

COMMERCIAL BUILDING (Continued) **S105194392**

MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Remove Free Product - remove floating product from water table, Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	5/1/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AI171 **SAN PACIFIC IMPORTS, INC.** **HIST CORTESE** **S101591988**
WNW **530 BRANNAN ST** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **CA FID UST**
0.413 mi. **SWEEPS UST**
2180 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
10 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0274

SAN PACIFIC IMPORTS, INC. (Continued) **S101591988**

LUST:

Region:	STATE
Global Id:	T0607500239
Latitude:	37.778062
Longitude:	-122.397452
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/22/1996
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0274
LOC Case Number:	10380
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500239
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500239
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500239
Status:	Completed - Case Closed
Status Date:	10/22/1996

Global Id:	T0607500239
Status:	Open - Case Begin Date
Status Date:	09/05/1991

Regulatory Activities:

Global Id:	T0607500239
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500239
Action Type:	Other

SAN PACIFIC IMPORTS, INC. (Continued) **S101591988**

Date: 01/01/1950
Action: Leak Discovery

LUST REG 2:
Region: 2
Facility Id: 38-0274
Facility Status: Case Closed
Case Number: 10380
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0274
Facility Status: Case Closed
Case Number: 10380
Case Type: Other ground water affected
Release Date: 10/24/1991
Discovered Date: 9/5/1991
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 10/24/1991
Case Closed: 10/22/1996
Closed Date: 10/22/1996
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: Not reported
Entered Date: 3/6/1995
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: SC
Cross Street: 4TH ST
NOR Date: 3/6/1995
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported

SAN PACIFIC IMPORTS, INC. (Continued) **S101591988**

Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	7/31/1996
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	12/10/1991
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	6900
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

CA FID UST:

Facility ID:	38000313
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	530 BRANNAN ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107

SAN PACIFIC IMPORTS, INC. (Continued) **S101591988**

Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

SWEEPS UST:
Status: Not reported
Comp Number: 9596
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-009596-000001
Actv Date: Not reported
Capacity: 5000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: 4

Status: Not reported
Comp Number: 9596
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-009596-000002
Actv Date: Not reported
Capacity: 10000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 9596
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-009596-000003
Actv Date: Not reported
Capacity: 550
Tank Use: UNKNOWN
Stg: PRODUCT

SAN PACIFIC IMPORTS, INC. (Continued) **S101591988**

Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 9596
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: 38-000-009596-000004
Actv Date: Not reported
Capacity: 1000
Tank Use: UNKNOWN
Stg: PRODUCT
Content: UNSPECIFIED
Number Of Tanks: Not reported

Status: Active
Comp Number: 9596
Number: 9
Board Of Equalization: Not reported
Referral Date: 09-30-92
Action Date: 12-10-91
Created Date: 01-01-01
Tank Status: Not reported
Owner Tank Id: Not reported
Swrcb Tank Id: Not reported
Actv Date: Not reported
Capacity: Not reported
Tank Use: Not reported
Stg: Not reported
Content: Not reported
Number Of Tanks: Not reported

AC172 **AUTO REPAIR & AUTO PARK** **HIST CORTESE** **S101302419**
NW **529 3RD** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.414 mi.
2186 ft. **Site 6 of 6 in cluster AC**

Relative:
Higher

Actual:
20 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0461

LUST:
Region: STATE
Global Id: T0607500411
Latitude: 37.780986
Longitude: -122.394046
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/26/1990

AUTO REPAIR & AUTO PARK (Continued) **S101302419**

Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0461
LOC Case Number:	10469
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500411
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500411
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500411
Status:	Completed - Case Closed
Status Date:	03/26/1990

Global Id:	T0607500411
Status:	Open - Case Begin Date
Status Date:	03/13/1990

Regulatory Activities:

Global Id:	T0607500411
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500411
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

LUST REG 2:

Region:	2
Facility Id:	38-0461
Facility Status:	Case Closed

AUTO REPAIR & AUTO PARK (Continued) **S101302419**

Case Number: 10469
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0461
Facility Status: Case Closed
Case Number: 10469
Case Type: Other ground water affected
Release Date: 3/26/1990
Discovered Date: 3/13/1990
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 3/26/1990
Case Closed: 1/23/2001
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: 3/15/1993
Entered Date: 7/7/1995
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: TOCK CORP./ELMO
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: MA
Cross Street: BRYANT ST
NOR Date: 7/7/1995
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: ND
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: 1/23/2001
Workplan Submitted: 7/16/1996
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported
Remediation Underway: Not reported
Monitoring Begun: Not reported

AUTO REPAIR & AUTO PARK (Continued) **S101302419**

Funding:	Federal
Interim Remediation:	No
Priority:	Moderate Priority Site
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	3/26/1990
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	S-SW
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	1470
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AH173 **KAISER SAND & GRAVEL** **HIST CORTESE** **S100849496**
South **300 16TH** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.415 mi.
2191 ft. **Site 2 of 4 in cluster AH**

Relative:
Higher

Actual:
14 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0477

LUST:

Region:	STATE
Global Id:	T0607500425
Latitude:	37.7669445
Longitude:	-122.3892065
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/02/1995
Lead Agency:	SAN FRANCISCO COUNTY LOP

KAISER SAND & GRAVEL (Continued) **S100849496**

Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0477
LOC Case Number:	10254
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500425
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500425
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500425
Status:	Completed - Case Closed
Status Date:	02/02/1995

Global Id:	T0607500425
Status:	Open - Case Begin Date
Status Date:	06/10/1993

Regulatory Activities:

Global Id:	T0607500425
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500425
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

LUST REG 2:

Region:	2
Facility Id:	38-0477
Facility Status:	Case Closed
Case Number:	10254

KAISER SAND & GRAVEL (Continued) **S100849496**

How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0477
Facility Status: Case Closed
Case Number: 10254
Case Type: Other ground water affected
Release Date: 6/15/1993
Discovered Date: 6/10/1993
Substance: Diesel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 6/15/1993
Case Closed: 2/2/1995
Closed Date: 2/2/1995
Leak Source: Unknown
Leak Cause: Unknown
Leak Confirmed: Not reported
Entered Date: 4/17/1994
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: SC
Cross Street: 3RD ST
NOR Date: 4/17/1994
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported
MTBE DATE: Not reported
Review Date: Not reported
Workplan Submitted: Not reported
Assessment Underway: 4/29/1993
Pollution Characterization: Not reported
Corrective Action Plan: Not reported
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal

KAISER SAND & GRAVEL (Continued) **S100849496**

Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	2/19/1993
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	400
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AA174 **COMMERCIAL PROPERTY** **HIST CORTESE** **S110060638**
WNW **557 4TH** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.415 mi.
2193 ft. **Site 5 of 5 in cluster AA**

Relative:
Higher

Actual:
12 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1217

AH175 **CARRARO PROPERTY** **HIST CORTESE** **S102426375**
South **1800 03RD ST** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.419 mi.
2211 ft. **Site 3 of 4 in cluster AH**

Relative:
Higher

Actual:
14 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0070

LUST:

Region:	STATE
Global Id:	T0607500062
Latitude:	37.76679
Longitude:	-122.388068
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/03/1993
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0070
LOC Case Number:	10185
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500062
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500062
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500062
Status:	Completed - Case Closed
Status Date:	11/03/1993

Global Id:	T0607500062
Status:	Open - Case Begin Date
Status Date:	12/19/1989

CARRARO PROPERTY (Continued) **S102426375**

Regulatory Activities:

Global Id:	T0607500062
Action Type:	ENFORCEMENT
Date:	09/01/1993
Action:	Notice of Responsibility

Global Id:	T0607500062
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500062
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

LUST REG 2:

Region:	2
Facility Id:	38-0070
Facility Status:	Case Closed
Case Number:	10185
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0070
Facility Status:	Case Closed
Case Number:	10185
Case Type:	Soil only
Release Date:	12/19/1989
Discovered Date:	12/19/1989
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	12/19/1989
Case Closed:	11/3/1993
Closed Date:	11/3/1993
Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	9/1/1993
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000

CARRARO PROPERTY (Continued) **S102426375**

Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	16TH ST
NOR Date:	9/1/1993
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	9/1/1993
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	1/10/1990
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	190
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AH176 **3RD STREET LIGHT RAIL PROJECT SEG.B** **LUST** **S110655157**
South **3RD STREET & 16TH STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94103**
0.419 mi.
2212 ft. **Site 4 of 4 in cluster AH**

Relative:
Higher

Actual:
14 ft.

LUST:

Region:	STATE
Global Id:	T0607586046
Latitude:	37.7669152409077
Longitude:	-122.389197349548
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/16/2006
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2438
LOC Case Number:	11777
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607586046
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607586046
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET
City:	OAKLAND
Email:	nkatyl@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607586046
Status:	Completed - Case Closed
Status Date:	11/16/2006

Global Id:	T0607586046
Status:	Open - Case Begin Date
Status Date:	05/07/2003

Global Id:	T0607586046
Status:	Open - Site Assessment
Status Date:	05/07/2003

3RD STREET LIGHT RAIL PROJECT SEG.B (Continued) **S110655157**

Regulatory Activities:

Global Id:	T0607586046
Action Type:	ENFORCEMENT
Date:	10/27/2006
Action:	Notice of Responsibility
Global Id:	T0607586046
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607586046
Action Type:	ENFORCEMENT
Date:	11/16/2006
Action:	Closure/No Further Action Letter
Global Id:	T0607586046
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported
Global Id:	T0607586046
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation

177
WNW
1/4-1/2
0.427 mi.
2254 ft.

COMMERCIAL PROPERTY **LUST** **S105688787**
557 04TH ST. **N/A**
SAN FRANCISCO, CA 94107

Relative:
Higher

Actual:
12 ft.

LUST:

Region:	STATE
Global Id:	T0607501102
Latitude:	37.779033
Longitude:	-122.397196
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/25/2004
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1217
LOC Case Number:	11102
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501102
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP

COMMERCIAL PROPERTY (Continued) **S105688787**

Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Global Id: T0607501102
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501102
Status: Completed - Case Closed
Status Date: 02/25/2004

Global Id: T0607501102
Status: Open - Case Begin Date
Status Date: 11/13/1998

Global Id: T0607501102
Status: Open - Site Assessment
Status Date: 11/13/1998

Regulatory Activities:
Global Id: T0607501102
Action Type: ENFORCEMENT
Date: 10/02/2003
Action: File review

Global Id: T0607501102
Action Type: ENFORCEMENT
Date: 11/23/1998
Action: Notice of Responsibility

Global Id: T0607501102
Action Type: ENFORCEMENT
Date: 02/25/2004
Action: Closure/No Further Action Letter

Global Id: T0607501102
Action Type: ENFORCEMENT
Date: 02/24/2004
Action: File review

Global Id: T0607501102
Action Type: ENFORCEMENT
Date: 06/02/2003
Action: File review

Global Id: T0607501102
Action Type: Other
Date: 01/01/1950

COMMERCIAL PROPERTY (Continued) **S105688787**

Action: Leak Discovery

Global Id: T0607501102
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1217
Facility Status: Case Closed
Case Number: 11102
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 11/13/1998
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1217
Facility Status: Not reported
Case Number: 11102
Case Type: Other ground water affected
Release Date: 11/13/1998
Discovered Date: 11/13/1998
Substance: Diesel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 11/13/1998
Case Closed: Not reported
Closed Date: Not reported
Leak Source: Unknown
Leak Cause: Unknown
Leak Confirmed: 11/23/1998
Entered Date: 11/23/1998
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Joe Cassidy,
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: SC
Cross Street: WELSH ST
NOR Date: 11/23/1998

COMMERCIAL PROPERTY (Continued) **S105688787**

MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	9/13/2000
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	9/13/2000
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Not reported
Priority:	Low Priority Site
Abatement:	Not reported
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	11/13/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	117 Clement

AD178 **WASHINGTON SPORTSWEAR, INC.** **LUST** **S106163346**
NNW **ONE SOUTH PARK AVE** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.429 mi.
2265 ft. **Site 2 of 3 in cluster AD**

Relative:
Higher

Actual:
40 ft.

LUST:

Region:	STATE
Global Id:	T0607520007
Latitude:	37.782053
Longitude:	-122.392835
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/23/2002
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2180
LOC Case Number:	11519
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607520007
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607520007
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607520007
Status:	Completed - Case Closed
Status Date:	09/23/2002

Global Id:	T0607520007
Status:	Open - Case Begin Date
Status Date:	11/04/1999

Regulatory Activities:

Global Id:	T0607520007
Action Type:	Other
Date:	01/01/1950
Action:	Leak Stopped

WASHINGTON SPORTSWEAR, INC. (Continued) **S106163346**

Global Id: T0607520007
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607520007
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607520007
Action Type: REMEDIATION
Date: 01/01/1950
Action: Excavation

LUST REG 2:
Region: 2
Facility Id: 38-2180
Facility Status: Case Closed
Case Number: 11519
How Discovered: Tank Closure
Leak Cause: Corrosion
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

AD179 **WASHINGTON** **LUST** **S105806119**
NNW **1 SOUTH PARK AVE** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.429 mi.
2265 ft. **Site 3 of 3 in cluster AD**

Relative:
Higher

Actual:
40 ft.

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 02-302-013
Facility Status: Case Closed
Case Number: 11519
Case Type: Soil only
Release Date: Not reported
Discovered Date: 11/4/1999
Substance: Heater Fuel
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 11/8/1999
Case Closed: 9/23/2002
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Corrosion
Leak Confirmed: 11/4/1999

WASHINGTON (Continued) **S105806119**

Entered Date:	9/19/2002
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Peter Tong
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	3rd St
NOR Date:	Not reported
MTBE Current:	Not reported
MTBE Current Date:	11/4/1999
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	11/4/1999
Review Date:	9/23/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	9/19/2002
Basin:	DOWNTOWN
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	11/4/1999
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	ND
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	11/4/1999
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported

WASHINGTON (Continued) **S105806119**

TPH Current Date: Not reported
Grnd Wtr Qualifier: Not reported
Soil Qualifier: Not reported
Comments: Not reported
Summary: file review and

180
North
1/4-1/2
0.432 mi.
2282 ft.

SF RDVLOPMNT AGNCY #K **HIST CORTESE** **S104396890**
1 59.5 TOWNSEND ST **LUST** **N/A**
SAN FRANCISCO, CA 94107

Relative:
Higher

Actual:
6 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0319

LUST:
Region: STATE
Global Id: T0607500279
Latitude: 37.7812824
Longitude: -122.3896648
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 08/26/1993
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker: VP
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0319
LOC Case Number: 38-0319
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500279
Contact Type: Local Agency Caseworker
Contact Name: UNK
Organization Name: SAN FRANCISCO COUNTY LOP
Address: Not reported
City: r2 UNKNOWN
Email: Not reported
Phone Number: Not reported

Global Id: T0607500279
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

SF RDVLOPMNT AGNCY #K (Continued) **S104396890**

Status History:
Global Id: T0607500279
Status: Completed - Case Closed
Status Date: 08/26/1993

Global Id: T0607500279
Status: Open - Case Begin Date
Status Date: 11/30/1988

Global Id: T0607500279
Status: Open - Site Assessment
Status Date: 11/30/1988

Regulatory Activities:
Global Id: T0607500279
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500279
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500279
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

AG181 **LNR-LANNAR BRANNAN, LLC** **HIST CORTESE** **S104889617**
NNW **250 BRANNAN ST** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94110**
0.435 mi.
2299 ft. **Site 2 of 3 in cluster AG**

Relative:
Higher

Actual:
27 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0625

LUST:
Region: STATE
Global Id: T0607500546
Latitude: 37.783226
Longitude: -122.391218
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/04/1996
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-0625
LOC Case Number: 10488
File Location: Not reported

LNR-LANNAR BRANNAN, LLC (Continued) **S104889617**

Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500546
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500546
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500546
Status: Completed - Case Closed
Status Date: 03/04/1996

Global Id: T0607500546
Status: Open - Case Begin Date
Status Date: 07/17/1995

Regulatory Activities:
Global Id: T0607500546
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500546
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Region: STATE
Global Id: T0607591199
Latitude: 37.782905
Longitude: -122.391029
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 02/12/2001
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: AL
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-2048

LNR-LANNAR BRANNAN, LLC (Continued) **S104889617**

LOC Case Number: 11433
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Heating Oil / Fuel Oil
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607591199
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607591199
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607591199
Status: Completed - Case Closed
Status Date: 02/12/2001

Global Id: T0607591199
Status: Open - Case Begin Date
Status Date: 02/12/2001

Regulatory Activities:
Global Id: T0607591199
Action Type: ENFORCEMENT
Date: 02/12/2001
Action: Notice of Responsibility

Global Id: T0607591199
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607591199
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

AG182 **GALLO SALAME** **LUST** **S105159316**
NNW **250 BRANNAN ST** **HIST UST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.435 mi.
2299 ft. **Site 3 of 3 in cluster AG**

Relative:
Higher

Actual:
27 ft.

LUST REG 2:

Region:	2
Facility Id:	38-0625
Facility Status:	Case Closed
Case Number:	10488
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

Region:	2
Facility Id:	38-2048
Facility Status:	Case Closed
Case Number:	11433
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0625
Facility Status:	Case Closed
Case Number:	10488
Case Type:	Soil only
Release Date:	7/19/1995
Discovered Date:	7/17/1995
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Report Date:	7/19/1995
Case Closed:	3/4/1996
Closed Date:	3/4/1996
Leak Source:	Tank
Leak Cause:	Not reported
Leak Confirmed:	1/23/1996
Entered Date:	7/20/1995
Number of Wells:	Not reported

GALLO SALAME (Continued) **S105159316**

Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	1ST ST
NOR Date:	7/20/1995
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Not reported
Interim Remediation:	Not reported
Priority:	Not reported
Abatement:	Not reported
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	730
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported

GALLO SALAME (Continued) **S105159316**

Comments:	Not reported
Summary:	Not reported
Region:	SAN FRANCISCO
Facility ID:	02-101-011
Facility Status:	Case Closed
Case Number:	11433
Case Type:	Soil only
Release Date:	Not reported
Discovered Date:	2/12/2001
Substance:	Heater Fuel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	2/12/2001
Case Closed:	3/6/2001
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	2/12/2001
Entered Date:	2/14/2001
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Chas Allen
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	Delancey St
NOR Date:	Not reported
MTBE Current:	Not reported
MTBE Current Date:	2/12/2001
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	2/12/2001
Review Date:	3/5/2001
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Low Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	2/12/2001
Basin:	DOWNTOWN
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported

GALLO SALAME (Continued) **S105159316**

Suspended:	No
Stopped Date:	2/12/2001
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Not reported
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	35
TPH Date:	2/12/2001
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	3/5/01 review case

HIST UST:

Region:	STATE
Facility ID:	00000018530
Facility Type:	Other
Other Type:	FOOD PROCESSING
Total Tanks:	0003
Contact Name:	I. MAGGAY III
Telephone:	4154956000
Owner Name:	CONSOLIDATED FOODS CORPORATION
Owner Address:	THREE FIRST NATIONAL PLAZA
Owner City,St,Zip:	CHICAGO, IL 60602

Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	None

Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00004107
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor

Tank Num: 003

GALLO SALAME (Continued) **S105159316**

Container Num: 3
Year Installed: Not reported
Tank Capacity: 00004107
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: None

183
SSE
1/4-1/2
0.441 mi.
2326 ft.

PIER 64/MISSION BAY **SLIC** **S106234991**
VICINITY OF PIER 64 **N/A**
SAN FRANCISCO, CA 95110

Relative:
Higher

Actual:
6 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Remediation**
Status Date:	06/01/2005
Global Id:	SL18397817
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Lead Agency Case Number:	Not reported
Latitude:	37.767034
Longitude:	-122.386172
Case Type:	Cleanup Program Site
Case Worker:	VP
Local Agency:	Not reported
RB Case Number:	38S0044
File Location:	Regional Board
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

SLIC REG 2:

Region:	2
Facility ID:	38S0044
Facility Status:	Pollution Characterization
Date Closed:	Not reported
Local Case #:	Not reported
How Discovered:	DVA
Leak Cause:	Not reported
Leak Source:	Not reported
Date Confirmed:	Not reported
Date Prelim Site Assmnt Workplan Submitted:	Not reported
Date Preliminary Site Assessment Began:	Not reported
Date Pollution Characterization Began:	Not reported
Date Remediation Plan Submitted:	Not reported
Date Remedial Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

184
SW
1/4-1/2
0.452 mi.
2389 ft.

MISSION BAY P10
1600 OWENS ST
SAN FRANCISCO, CA 94158

US BROWNFIELDS **1016139482**
N/A

Relative:
Higher

Actual:
12 ft.

US BROWNFIELDS:

Recipient name:	California Department of Toxic Substances Control
Grant type:	BCRLF
Property name:	MISSION BAY P10
Property #:	8709-002 & 8709-003
Parcel size:	2
Property Description:	The property is located on Mission Bay Drive, between Seventh Street, Owens Street and Channel Street. The Mission Bay development, itself, replaces 300 acres of former rail yards and surface parking lots with a new transit oriented urban neighborhood, served by five light rail stops, multiple buses and shuttles, and the terminus of Caltrain. At full build out Mission Bay will be comprised of 6,000 residential units, including 1,800 affordable 30, 4.4M SF of office and lab space, the University of California, San Francisco's UCSF premier 43 acre campus, 2.65M SF Mission Bay campus, and a new 550 bed children s, women s and cancer hospital. The Mission Bay project will increase the City's tax base by an estimated 6 billion and create tens of thousands of construction and permanent jobs.
Latitude:	37.770528
Longitude:	-122.395957
HCM label:	Global Positioning Method-Unspecified Parameters
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	124838
Start date:	31-MAY-11
Completed date:	26-JAN-12
Acres cleaned up:	2
Cleanup funding:	760720
Cleanup funding source:	US EPA - Brownfields RLF Subgrant
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	2121044
Redev. funding source:	Local Funding
Redev. funding entity name:	CCSF Redevelopment
Redevelopment start date:	08-JUN-10
Assessment funding entity:	Not reported
Cleanup funding entity:	EPA
Grant type:	H
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96987501
Ownership entity:	Private
Current owner:	Not reported
Did owner change:	N
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	Y
IC Category proprietary controls:	Y
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Y
IC cat. enforcement permit tools:	Y

MISSION BAY P10 (Continued) **1016139482**

IC in place date:	11-MAY-99
IC in place:	Yes
State/tribal program date:	04-FEB-11
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Y
Petro products found:	Y
Petro products cleaned:	Y
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Y
Surface water cleaned:	Not reported
Unknown found:	Not reported
VOCs found:	Y
VOCs cleaned:	Y
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	410
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	1
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	1
Superfund Fed. landowner flag:	Not reported

AJ185 **COMMERCIAL PROPERTY** **LUST** **S108214593**
NW **501 3RD ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.455 mi.
2400 ft. **Site 1 of 6 in cluster AJ**

Relative:
Higher

Actual:
17 ft.

LUST:

Region:	STATE
Global Id:	T0607537683
Latitude:	37.781315
Longitude:	-122.395443
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/14/2005
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-2316
LOC Case Number:	11655
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607537683
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607537683
Contact Type:	Regional Board Caseworker
Contact Name:	NANCY KATYL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET
City:	OAKLAND
Email:	nkatyl@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607537683
Status:	Completed - Case Closed
Status Date:	03/14/2005

Global Id:	T0607537683
Status:	Open - Case Begin Date
Status Date:	06/17/2004

Global Id:	T0607537683
Status:	Open - Site Assessment
Status Date:	06/17/2004

COMMERCIAL PROPERTY (Continued) **S108214593**

Regulatory Activities:

Global Id:	T0607537683
Action Type:	ENFORCEMENT
Date:	03/09/2005
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607537683
Action Type:	ENFORCEMENT
Date:	01/13/2005
Action:	LOP Case Closure Summary to RB
Global Id:	T0607537683
Action Type:	ENFORCEMENT
Date:	01/10/2005
Action:	Notice of Responsibility
Global Id:	T0607537683
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery
Global Id:	T0607537683
Action Type:	REMEDIATION
Date:	01/01/1950
Action:	Excavation
Global Id:	T0607537683
Action Type:	ENFORCEMENT
Date:	03/14/2005
Action:	Closure/No Further Action Letter
Global Id:	T0607537683
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

AJ186 **COMMERCIAL** **LUST** **S110504455**
NW **500 3RD STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.455 mi.
2400 ft. **Site 2 of 6 in cluster AJ**

Relative:
Higher

Actual:
17 ft.

LUST:

Region:	STATE
Global Id:	T10000002355
Latitude:	37.780991
Longitude:	-122.3955896
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/18/2010
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	11911
File Location:	Not reported

COMMERCIAL (Continued) **S110504455**

Potential Media Affect: Not reported
Potential Contaminants of Concern: Heating Oil / Fuel Oil
Site History: 8.18.2010 site closed

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000002355
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T10000002355
Contact Type: Regional Board Caseworker
Contact Name: NANCY KATYL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET
City: OAKLAND
Email: nkatyl@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T10000002355
Status: Completed - Case Closed
Status Date: 08/18/2010

Global Id: T10000002355
Status: Open - Case Begin Date
Status Date: 06/22/2010

Global Id: T10000002355
Status: Open - Site Assessment
Status Date: 08/06/2010

Regulatory Activities:
Global Id: T10000002355
Action Type: Other
Date: 01/01/1950
Action: Leak Began

Global Id: T10000002355
Action Type: ENFORCEMENT
Date: 08/17/2010
Action: State Water Board Closure Order - #11911

Global Id: T10000002355
Action Type: ENFORCEMENT
Date: 08/06/2010
Action: Clean Up Fund - Letter to RP - #11911

Global Id: T10000002355
Action Type: Other
Date: 01/01/1950

COMMERCIAL (Continued) **S110504455**

Action: Leak Stopped

Global Id: T10000002355
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T10000002355
Action Type: RESPONSE
Date: 08/16/2010
Action: Tank Removal Report / UST Sampling Report

Global Id: T10000002355
Action Type: ENFORCEMENT
Date: 08/16/2010
Action: File Review - Closure

Global Id: T10000002355
Action Type: ENFORCEMENT
Date: 08/18/2010
Action: Closure/No Further Action Letter

Global Id: T10000002355
Action Type: ENFORCEMENT
Date: 08/06/2010
Action: Notice of Responsibility

Global Id: T10000002355
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

AJ187 **PAUL SHEEL METAL WORK** **HIST CORTESE** **S104732803**
NW **474 BRYANT** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.455 mi.
2405 ft. **Site 3 of 6 in cluster AJ**

Relative:
Higher

Actual:
24 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1144

LUST:
Region: STATE
Global Id: T0607501032
Latitude: 37.7817771
Longitude: -122.395293
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/31/2003
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: AL
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-1144

PAUL SHEEL METAL WORK (Continued) **S104732803**

LOC Case Number: 11015
File Location: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607501032
Contact Type: Local Agency Caseworker
Contact Name: ALBERT LEE
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: albert.lee@sfdph.org
Phone Number: Not reported

Global Id: T0607501032
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501032
Status: Completed - Case Closed
Status Date: 07/31/2003

Global Id: T0607501032
Status: Open - Case Begin Date
Status Date: 05/01/1998

Global Id: T0607501032
Status: Open - Site Assessment
Status Date: 05/06/1998

Regulatory Activities:
Global Id: T0607501032
Action Type: ENFORCEMENT
Date: 07/31/2003
Action: Closure/No Further Action Letter

Global Id: T0607501032
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501032
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

AJ188 **PAUL SHEET METAL WORK** **LUST** **S103283982**
NW **474 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.455 mi.
2405 ft. **Site 4 of 6 in cluster AJ**

Relative:
Higher

Actual:
24 ft.

LUST REG 2:

Region:	2
Facility Id:	38-1144
Facility Status:	Case Closed
Case Number:	11015
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	5/6/1998
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1144
Facility Status:	Leak being confirmed
Case Number:	11015
Case Type:	Soil only
Release Date:	5/6/1998
Discovered Date:	5/1/1998
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	5/6/1998
Case Closed:	Not reported
Closed Date:	Not reported
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	8/10/1998
Entered Date:	7/27/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	3RD ST
NOR Date:	7/27/1998
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported

PAUL SHEET METAL WORK (Continued) **S103283982**

MTBE DATE:	Not reported
Review Date:	6/26/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Not reported
Priority:	Low Priority Site
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	5/1/1998
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	6/25/02 file has

AJ189 **MERLE HORN ET AL., PROPERTY** **HIST CORTESE** **S100927317**
NW **510 BRYANT STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.457 mi.
2414 ft. **Site 5 of 6 in cluster AJ**

Relative:
Higher

Actual:
17 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0503

LUST:

MERLE HORN ET AL., PROPERTY (Continued) **S100927317**

Region:	STATE
Global Id:	T0607500449
Latitude:	37.7812089
Longitude:	-122.396376
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	04/22/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0503
LOC Case Number:	10227
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500449
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500449
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500449
Status:	Completed - Case Closed
Status Date:	04/22/1998

Global Id:	T0607500449
Status:	Open - Case Begin Date
Status Date:	06/22/1993

Regulatory Activities:

Global Id:	T0607500449
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500449
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

AJ190 **MERLE HORN ET AL., PROPERTY** **LUST** **S103177161**
NW **510 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.457 mi.
2414 ft. **Site 6 of 6 in cluster AJ**

Relative:
Higher

Actual:
17 ft.

LUST REG 2:

Region:	2
Facility Id:	38-0503
Facility Status:	Case Closed
Case Number:	10227
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0503
Facility Status:	Case Closed
Case Number:	10227
Case Type:	Other ground water affected
Release Date:	11/7/1983
Discovered Date:	6/22/1993
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	11/7/1983
Case Closed:	4/22/1998
Closed Date:	4/22/1998
Leak Source:	Tank
Leak Cause:	Corrosion
Leak Confirmed:	6/9/1994
Entered Date:	2/11/1994
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	REVCA COMMERCIAL
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	3RD & 4TH ST
NOR Date:	2/11/1994
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported

MERLE HORN ET AL., PROPERTY (Continued) **S103177161**

MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	2A
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	6/15/1993
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	290
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	<
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AK191 **COMMERCIAL PROPERTY** **HIST CORTESE** **U003200207**
NW **542 BRANNAN** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.461 mi.
2436 ft. **Site 1 of 3 in cluster AK**

Relative:
Higher

Actual:
16 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1035

COMMERCIAL PROPERTY (Continued) **U003200207**

LUST:

Region:	STATE
Global Id:	T0607500928
Latitude:	37.777916
Longitude:	-122.397636
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/30/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1035
LOC Case Number:	10989
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500928
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500928
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500928
Status:	Completed - Case Closed
Status Date:	06/30/1998

Global Id:	T0607500928
Status:	Open - Case Begin Date
Status Date:	05/01/1998

Regulatory Activities:

Global Id:	T0607500928
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607500928
Action Type:	Other

COMMERCIAL PROPERTY (Continued) **U003200207**

Date: 01/01/1950
Action: Leak Reported

AK192 **COMMERCIAL PROPERTY** **LUST** **S105194409**
NW **535 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.461 mi.
2436 ft. **Site 2 of 3 in cluster AK**

Relative:
Higher

Actual:
16 ft.

LUST REG 2:

Region:	2
Facility Id:	38-1215
Facility Status:	Pollution Characterization
Case Number:	11100
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	11/17/1998
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1215
Facility Status:	Not reported
Case Number:	11100
Case Type:	Other ground water affected
Release Date:	11/17/1998
Discovered Date:	11/17/1998
Substance:	Stoddard Solvent
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	11/17/1998
Case Closed:	Not reported
Closed Date:	Not reported
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	11/23/1998
Entered Date:	11/23/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Trung Bang
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	AL
Cross Street:	ZOE ST

COMMERCIAL PROPERTY (Continued) **S105194409**

NOR Date:	11/23/1998
MTBE Current:	12/27/2001
MTBE Current Date:	Not reported
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	6/20/2002
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	Informal Enforcement Actions,including Notices of Violations and Staff Enforcement Letters
Enforcement Due Date:	10/3/2001
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	9/16/1998
Free Product:	No
Depth to Grnd Wtr:	7 ft
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Stoddard solvent
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	3/28/2002
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	3x2000 cylindrical

AK193 **COMMERCIAL PROPERTY** **HIST CORTESE** **S110060637**
NW **535 BRYANT STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.461 mi.
2436 ft. **Site 3 of 3 in cluster AK**

Relative:
Higher

Actual:
16 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-1215

LUST:

Region:	STATE
Global Id:	T0607501100
Latitude:	37.780406
Longitude:	-122.396802
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/08/2004
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1215
LOC Case Number:	11100
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Stoddard solvent / Mineral Spriits / Distillates
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501100
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Global Id:	T0607501100
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607501100
Status:	Completed - Case Closed
Status Date:	10/08/2004

Global Id:	T0607501100
Status:	Open - Case Begin Date
Status Date:	11/17/1998

COMMERCIAL PROPERTY (Continued) **S110060637**

Global Id: T0607501100
Status: Open - Site Assessment
Status Date: 11/17/1998

Regulatory Activities:
Global Id: T0607501100
Action Type: ENFORCEMENT
Date: 10/03/2001
Action: Staff Letter

Global Id: T0607501100
Action Type: ENFORCEMENT
Date: 05/13/2003
Action: File review

Global Id: T0607501100
Action Type: ENFORCEMENT
Date: 10/08/2004
Action: Closure/No Further Action Letter

Global Id: T0607501100
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501100
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

AL194 **CHROME WORKS** **LUST** **S104810024**
NNW **425 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.470 mi.
2484 ft. **Site 1 of 3 in cluster AL**

Relative:
Higher

Actual:
44 ft.

LUST REG 2:
Region: 2
Facility Id: 38-0900
Facility Status: Case Closed
Case Number: 10743
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0900

CHROME WORKS (Continued) **S104810024**

Facility Status:	Case Closed
Case Number:	10743
Case Type:	Soil only
Release Date:	12/2/1996
Discovered Date:	12/2/1996
Substance:	Diesel
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Remove Contents
Report Date:	12/2/1996
Case Closed:	2/4/1997
Closed Date:	2/4/1997
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	Not reported
Entered Date:	12/3/1996
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	2ND ST
NOR Date:	12/3/1996
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	NT
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Not reported
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Required - incident is minor, requiring no remedial action
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	12/4/1996
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported

CHROME WORKS (Continued) **S104810024**

Primary Substance:	Diesel fuel oil
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AL195 **CHROME WORKS** **HIST CORTESE** **S100870805**
NNW **425 BRYANT STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.470 mi.
2484 ft. **Site 2 of 3 in cluster AL**

Relative:
Higher

Actual:
44 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0900

LUST:

Region:	STATE
Global Id:	T0607500795
Latitude:	37.782446
Longitude:	-122.394016
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/04/1997
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0900
LOC Case Number:	10743
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500795
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400

CHROME WORKS (Continued) **S100870805**

City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Global Id: T0607500795
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500795
Status: Completed - Case Closed
Status Date: 02/04/1997

Global Id: T0607500795
Status: Open - Case Begin Date
Status Date: 12/02/1996

Regulatory Activities:
Global Id: T0607500795
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500795
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

AL196 **415 BRYANT STREET** **ENVIROSTOR** **S108407592**
NNW **415 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.475 mi.
2510 ft. **Site 3 of 3 in cluster AL**

Relative:
Higher

Actual:
48 ft.

ENVIROSTOR:
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Facility ID: 60000536
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: 1248 Local Agency
Status Date: 10/31/2000

415 BRYANT STREET (Continued) **S108407592**

Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.78256
Longitude:	-122.3938
APN:	3775164
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	3775164
Alias Type:	APN
Alias Name:	60000536
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported
Completed Date:	Not reported
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

197
SSW
1/4-1/2
0.479 mi.
2529 ft.

SUPER SHUTTLE
700 16TH ST
SAN FRANCISCO, CA 94107

HIST CORTESE **S101592088**
LUST **N/A**
CA FID UST
SWEEPS UST

Relative:
Higher

Actual:
14 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0426

LUST:

Region:	STATE
Global Id:	T0607500377
Latitude:	37.7667795
Longitude:	-122.3928244
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/09/1987
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0426
LOC Case Number:	10447
File Location:	Not reported

SUPER SHUTTLE (Continued) **S101592088**

Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607500377
Contact Type: Local Agency Caseworker
Contact Name: MAMDOUH AWWAD
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET, #210
City: SAN FRANCISCO
Email: mamdouh.awwad@sfdph.org
Phone Number: Not reported

Global Id: T0607500377
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607500377
Status: Completed - Case Closed
Status Date: 06/09/1987

Global Id: T0607500377
Status: Open - Case Begin Date
Status Date: 06/09/1987

Regulatory Activities:
Global Id: T0607500377
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500377
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

LUST REG 2:
Region: 2
Facility Id: 38-0426
Facility Status: Case Closed
Case Number: 10447
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

SUPER SHUTTLE (Continued) **S101592088**

Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0426
Facility Status: Case Closed
Case Number: 10447
Case Type: Other ground water affected
Release Date: 6/9/1987
Discovered Date: 6/9/1987
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 6/9/1987
Case Closed: 2/14/2001
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: 12/28/1987
Entered Date: 6/14/1995
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Catellus
RP Address: Not reported
Operator: Cattellus Corp.
Staff Initial: VP
Facility Staff: MA
Cross Street: Not reported
NOR Date: 6/14/1995
MTBE Current: Not reported
MTBE Current Date: 11/10/2000
MTBE: YES
Maximum MTBE Soil: 4.5
Maximum MTBE GW: Not reported
MTBE DATE: 11/10/2000
Review Date: 2/14/2001
Workplan Submitted: Not reported
Assessment Underway: Not reported
Pollution Characterization: Not reported
Corrective Action Plan: Not reported
Remediation Underway: Not reported
Monitoring Begun: Not reported
Funding: Federal
Interim Remediation: No
Priority: Moderate Priority Site
Abatement: No Action Taken - no action has as yet been taken at the site
Enforcement Type: Not reported
Enforcement Due Date: Not reported

SUPER SHUTTLE (Continued) **S101592088**

Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	7/17/1987
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	660
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

CA FID UST:

Facility ID:	38000460
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	700 16TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN FRANCISCO 94107
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

SWEEPS UST:

Status:	Not reported
Comp Number:	7813
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported

SUPER SHUTTLE (Continued) **S101592088**

Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-007813-000001
Actv Date:	Not reported
Capacity:	10000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	2

Status:	Not reported
Comp Number:	7813
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-007813-000002
Actv Date:	Not reported
Capacity:	5000
Tank Use:	UNKNOWN
Stg:	PRODUCT
Content:	UNSPECIFIED
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	7813
Number:	9
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	Not reported
Actv Date:	Not reported
Capacity:	Not reported
Tank Use:	Not reported
Stg:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	8704
Number:	1
Board Of Equalization:	Not reported
Referral Date:	09-30-92
Action Date:	12-10-91
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	38-000-008704-000001
Actv Date:	09-30-92
Capacity:	5000

SUPER SHUTTLE (Continued) **S101592088**

Tank Use: UNKNOWN
Stg: P
Content: UNSPECIFIED
Number Of Tanks: 1

AM198 **FERRO & VERNAZZA PROPERTY** **HIST CORTESE** **S102628452**
WNW **601 BRANNAN STREET** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94123**
0.480 mi.
2533 ft. **Site 1 of 3 in cluster AM**

Relative:
Higher

Actual:
9 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-0880

LUST REG 2:
Region: 2
Facility Id: 38-0880
Facility Status: Case Closed
Case Number: 10756
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0880
Facility Status: Case Closed
Case Number: 10756
Case Type: Other ground water affected
Release Date: 8/29/1996
Discovered Date: 10/31/1996
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Remove Contents
Report Date: 8/29/1996
Case Closed: 3/26/1997
Closed Date: 3/26/1997
Leak Source: Tank
Leak Cause: Unknown
Leak Confirmed: Not reported
Entered Date: 12/6/1996
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency

FERRO & VERNAZZA PROPERTY (Continued) **S102628452**

Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	5TH ST
NOR Date:	12/6/1996
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	YES
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	9/3/1996
Monitoring Begun:	Not reported
Funding:	Not reported
Interim Remediation:	Yes
Priority:	Not reported
Abatement:	Remove Free Product - remove floating product from water table, Excavate and Treat - remove contaminated soil and treat (includes spreading or land farming), Pump and Treat Ground Water - generally employed to remove dissolved contaminants
Enforcement Type:	NOR
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	9/6/1996
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	ND
Maximum Soil GW:	ND
Max Soil Concentration:	Not reported
TPH Tested:	Not reported
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported

FERRO & VERNAZZA PROPERTY (Continued) **S102628452**

Comments: Not reported
Summary: Not reported

AM199 **FERRO & VERNAZZA PROPERTY** **LUST** **S103666357**
WNW **601 BRANNAN STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94103**
0.480 mi.
2533 ft. **Site 2 of 3 in cluster AM**

Relative:
Higher

Actual:
9 ft.

LUST:

Region:	STATE
Global Id:	T0607500775
Latitude:	37.775896
Longitude:	-122.398781
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/26/1997
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0880
LOC Case Number:	10756
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500775
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500775
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500775
Status:	Completed - Case Closed
Status Date:	03/26/1997

Global Id:	T0607500775
Status:	Open - Case Begin Date
Status Date:	10/31/1996

FERRO & VERNAZZA PROPERTY (Continued) **S103666357**

Regulatory Activities:

Global Id:	T0607500775
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500775
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

AM200 **SAN FRANCISCO NEWSPAPER AGENCY** **HIST CORTESE** **U001595123**
WNW **590 BRANNAN ST** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107** **HIST UST**
0.483 mi.
2548 ft. **Site 3 of 3 in cluster AM**

Relative:
Higher

Actual:
9 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0321

LUST:

Region:	STATE
Global Id:	T0607500281
Latitude:	37.777056
Longitude:	-122.397178
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	07/24/2012
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0321
LOC Case Number:	10097
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Need to remove Free Product. Letter sent. 7/2012 Remediation ongoing

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500281
Contact Type:	Local Agency Caseworker
Contact Name:	ELYSE HEILSHORN
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 Market Street Suite 210
City:	SAN FRANCISCO
Email:	elyse.heilshorn@sfdph.org
Phone Number:	4152523885

Status History:

Global Id:	T0607500281
Status:	Open - Case Begin Date

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Status Date: 03/23/1990

Global Id: T0607500281
Status: Open - Remediation
Status Date: 07/24/2012

Global Id: T0607500281
Status: Open - Verification Monitoring
Status Date: 03/23/1990

Regulatory Activities:
Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 01/19/2011
Action: Staff Letter

Global Id: T0607500281
Action Type: Other
Date: 01/01/1950
Action: Leak Began

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 09/27/2009
Action: File review

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 03/25/2011
Action: Staff Letter

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 08/17/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 10/26/2011
Action: Staff Letter

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 01/20/2011
Action: File review

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 01/18/2012
Action: Staff Letter

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 02/01/2011
Action: Staff Letter - #10097

Global Id: T0607500281

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500281
Action Type: RESPONSE
Date: 01/18/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607500281
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 06/28/2013
Action: Staff Letter

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 04/25/2010
Action: File review

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 09/11/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 09/12/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500281
Action Type: Other
Date: 01/01/1950
Action: Leak Stopped

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 11/16/1992
Action: Notice of Responsibility

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 11/06/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 03/15/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607500281
Action Type: ENFORCEMENT
Date: 01/28/2011

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Action: Staff Letter

LUST REG 2:
Region: 2
Facility Id: 38-0321
Facility Status: Post remedial action monitoring
Case Number: 10097
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: 3/23/1990

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0321
Facility Status: Post remedial action monitoring
Case Number: 10097
Case Type: Other ground water affected
Release Date: 3/23/1990
Discovered Date: 3/23/1990
Substance: Gasoline
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 3/23/1990
Case Closed: Not reported
Closed Date: Not reported
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: 3/23/1990
Entered Date: 11/16/1992
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: SF NEWS AGENCY
RP Address: Not reported
Operator: SFNA
Staff Initial: VP
Facility Staff: MA
Cross Street: 5TH ST
NOR Date: 11/16/1992
MTBE Current: 3/14/2000
MTBE Current Date: 12/22/1996
MTBE: YES
Maximum MTBE Soil: Not reported
Maximum MTBE GW: Not reported

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

MTBE DATE:	12/22/1996
Review Date:	3/23/2000
Workplan Submitted:	Not reported
Assessment Underway:	10/31/1986
Pollution Characterization:	9/4/1991
Corrective Action Plan:	Not reported
Remediation Underway:	8/30/1995
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	High Priority Site
Abatement:	Remove Free Product - remove floating product from water table, Vent Soil - bore holes in soil to allow volatilization of contaminants
Enforcement Type:	NOR
Enforcement Due Date:	11/16/1992
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	4/18/1991
Free Product:	Yes
Depth to Grnd Wtr:	6' - 9'
Gradient:	S 0.017
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	12/9/1986
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	FP
TPH Current Date:	3/14/2000
Grnd Wtr Qualifier:	<
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Max TPH-D=160,000

HIST UST:

Region:	STATE
Facility ID:	00000020377
Facility Type:	Other
Other Type:	NEWSPAPER
Total Tanks:	0007
Contact Name:	GEORGE PERRY
Telephone:	4157777535
Owner Name:	CHRONICLE PUBLISHING CO.
Owner Address:	925 MISSION STREET
Owner City,St,Zip:	SAN FRANCISCO, CA 94103

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Tank Num: 001
Container Num: SF1
Year Installed: 1973
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: 1/4 inches
Leak Detection: Stock Inventor

Tank Num: 001
Container Num: SUMP #EIGH
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: Visual

Tank Num: 002
Container Num: TANK #SEVE
Year Installed: Not reported
Tank Capacity: 00000250
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 002
Container Num: SF2
Year Installed: 1979
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 003
Container Num: TANK #SIX
Year Installed: 1979
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: None

Tank Num: 003
Container Num: SF-3
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 004
Container Num: TANK #FOUR
Year Installed: 1973

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: None

Tank Num: 004
Container Num: SF-4
Year Installed: 1979
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 005
Container Num: SF-5
Year Installed: 1973
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 005
Container Num: TANK #FIVE
Year Installed: 1973
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Tank Construction: Not reported
Leak Detection: None

Tank Num: 006
Container Num: TANK #ONE
Year Installed: 1973
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Tank Construction: Not reported
Leak Detection: Stock Inventor

Tank Num: 006
Container Num: SF-6
Year Installed: 1973
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 007
Container Num: TANK #TWO
Year Installed: 1979
Tank Capacity: 00004000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED

SAN FRANCISCO NEWSPAPER AGENCY (Continued) **U001595123**

Tank Construction: Not reported
Leak Detection: None

Tank Num: 007
Container Num: SF-7
Year Installed: 1973
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Tank Construction: 1/4 inches
Leak Detection: None

Tank Num: 008
Container Num: TANK #THRE
Year Installed: 1979
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Tank Construction: Not reported
Leak Detection: None

AN201 **CHAVO'S RESTAURANT** **LUST** **S105115823**
WNW **595 BRYANT ST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.483 mi.
2550 ft. **Site 1 of 5 in cluster AN**

Relative:
Higher

Actual:
13 ft.

LUST:
Region: STATE
Global Id: T0607584299
Latitude: 37.779604
Longitude: -122.397728
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 05/23/2000
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-2137
LOC Case Number: 11351
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607584299
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Global Id: T0607584299

CHAVO'S RESTAURANT (Continued) **S105115823**

Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607584299
Status: Completed - Case Closed
Status Date: 05/23/2000

Global Id: T0607584299
Status: Open - Case Begin Date
Status Date: 01/28/2000

Regulatory Activities:
Global Id: T0607584299
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607584299
Action Type: ENFORCEMENT
Date: 03/02/2000
Action: Notice of Responsibility

Global Id: T0607584299
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-2137
Facility Status: Case Closed
Case Number: 11351
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 02-100-020
Facility Status: Case Closed

CHAVO'S RESTAURANT (Continued) **S105115823**

Case Number:	11351
Case Type:	Other ground water affected
Release Date:	Not reported
Discovered Date:	1/28/2000
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	1/28/2000
Case Closed:	5/23/2000
Closed Date:	5/23/2000
Leak Source:	Tank
Leak Cause:	Unknown
Leak Confirmed:	1/28/2000
Entered Date:	3/2/2000
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Not reported
RP Address:	Not reported
Operator:	Ed Rathbun
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	Fourth St
NOR Date:	3/2/2000
MTBE Current:	Not reported
MTBE Current Date:	1/29/2000
MTBE:	YES
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	1/29/2000
Review Date:	3/17/2000
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	3/17/2000
Funding:	Federal
Interim Remediation:	No
Priority:	Moderate Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	NOR
Enforcement Due Date:	3/2/2000
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	1/28/2000
Free Product:	Not reported
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported

CHAVO'S RESTAURANT (Continued) **S105115823**

Primary Substance:	Gasoline
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	ND
Max Soil Concentration:	0,005
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	1/29/2000
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

AN202 **BANK OF AMERICA AUTO REPAIR** **LUST** **S105806080**
WNW **420 04TH ST.** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.484 mi.
2558 ft. **Site 2 of 5 in cluster AN**

Relative:
Higher

Actual:
12 ft.

LUST:

Region:	STATE
Global Id:	T0607501076
Latitude:	37.7794
Longitude:	-122.3981
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/19/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-1189
LOC Case Number:	11028
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607501076
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Global Id:	T0607501076
Contact Type:	Regional Board Caseworker

BANK OF AMERICA AUTO REPAIR (Continued) **S105806080**

Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501076
Status: Completed - Case Closed
Status Date: 08/19/1998

Global Id: T0607501076
Status: Open - Case Begin Date
Status Date: 08/10/1998

Regulatory Activities:
Global Id: T0607501076
Action Type: ENFORCEMENT
Date: 11/30/1999
Action: Staff Letter

Global Id: T0607501076
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607501076
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: 38-1189
Facility Status: Case Closed
Case Number: 11028
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-1189
Facility Status: Case Closed
Case Number: 11028

BANK OF AMERICA AUTO REPAIR (Continued) **S105806080**

Case Type:	Other ground water affected
Release Date:	8/19/1998
Discovered Date:	8/10/1998
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Repair Tank
Report Date:	8/19/1998
Case Closed:	1/22/2002
Closed Date:	Not reported
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	8/20/1998
Entered Date:	8/20/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	BANK OF AMERICA,
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	HARRISON
NOR Date:	8/20/1998
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	1/22/2002
Workplan Submitted:	9/2/1999
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	Yes
Priority:	Moderate Priority Site
Abatement:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Enforcement Type:	Informal Enforcement Actions,including Notices of Violations and Staff Enforcement Letters
Enforcement Due Date:	11/30/1999
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	8/19/1998
Free Product:	no
Depth to Grnd Wtr:	8-11’
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Gasoline

BANK OF AMERICA AUTO REPAIR (Continued) **S105806080**

Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	7000
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	<
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	updated 11/13/98.

AN203 **SHELL STATION #8202** **LUST** **S105194344**
WNW **598 BRYANT STREET** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.488 mi.
2575 ft. **Site 3 of 5 in cluster AN**

Relative:
Higher

Actual:
13 ft.

LUST REG 2:

Region:	2
Facility Id:	38-0345
Facility Status:	Remedial action (cleanup) Underway
Case Number:	10070
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	8/15/1988
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-0345
Facility Status:	Remedial action (cleanup) Underway
Case Number:	10070
Case Type:	Other ground water affected
Release Date:	8/15/1988
Discovered Date:	8/15/1988
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Tank Closure
How Stopped:	Close Tank
Report Date:	8/15/1988
Case Closed:	Not reported
Closed Date:	Not reported

SHELL STATION #8202 (Continued) **S105194344**

Leak Source:	Tank
Leak Cause:	Structure Failure
Leak Confirmed:	Not reported
Entered Date:	5/13/1992
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000
Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Shell Product
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	MA
Cross Street:	4TH ST
NOR Date:	5/13/1992
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	YES
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	3/21/1989
Pollution Characterization:	1/20/1989
Corrective Action Plan:	7/29/1992
Remediation Underway:	Not reported
Monitoring Begun:	6/30/1996
Funding:	Federal
Interim Remediation:	Yes
Priority:	High Priority Site
Abatement:	Remove Free Product - remove floating product from water table
Enforcement Type:	Informal Enforcement Actions,including Notices of Violations and Staff Enforcement Letters
Enforcement Due Date:	Not reported
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	3/15/1990
Free Product:	Yes
Depth to Grnd Wtr:	Not reported
Gradient:	SW
Benzene:	Not reported
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	3000
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported

SHELL STATION #8202 (Continued) **S105194344**

Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	TESTED 7/11/97

AN204 **SIA'S SUPER SHELL #4, SIA BAKHTIARI** **HIST CORTESE** **S101302314**
WNW **598 BRYANT ST** **SWEEPS UST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA 94107**
0.488 mi.
2575 ft. **Site 4 of 5 in cluster AN**

Relative:
Higher

Actual:
13 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0345

SWEEPS UST:

Status:	Active
Comp Number:	4765
Number:	2
Board Of Equalization:	44-000074
Referral Date:	10-21-93
Action Date:	10-21-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	004765001001
Swrcb Tank Id:	38-000-004765-000001
Actv Date:	09-10-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	3

Status:	Active
Comp Number:	4765
Number:	2
Board Of Equalization:	44-000074
Referral Date:	10-21-93
Action Date:	10-21-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	004765001002
Swrcb Tank Id:	38-000-004765-000002
Actv Date:	09-10-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	4765

SIA'S SUPER SHELL #4, SIA BAKHTIARI (Continued) **S101302314**

Number:	2
Board Of Equalization:	44-000074
Referral Date:	10-21-93
Action Date:	10-21-93
Created Date:	01-01-01
Tank Status:	A
Owner Tank Id:	004765001003
Swrcb Tank Id:	38-000-004765-000003
Actv Date:	09-10-93
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	PRM UNLEADED
Number Of Tanks:	Not reported

AN205 **RETAIL SHELL SERVICE STATION** **FINDS** **1007057250**
WNW **598 BRYANT** **LUST** **N/A**
1/4-1/2 **SAN FRANCISCO, CA**
0.488 mi.
2575 ft. **Site 5 of 5 in cluster AN**

Relative: Higher

Actual: 13 ft.

FINDS:

Registry ID: 110015327617

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Region:	STATE
Global Id:	T0607500305
Latitude:	37.779829
Longitude:	-122.396765
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/22/2005
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	MA
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0345
LOC Case Number:	10070
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

RETAIL SHELL SERVICE STATION (Continued) **1007057250**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500305
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500305
Contact Type:	Local Agency Caseworker
Contact Name:	MAMDOUH AWWAD
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	mamdouh.awwad@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500305
Status:	Completed - Case Closed
Status Date:	12/22/2005

Global Id:	T0607500305
Status:	Open - Case Begin Date
Status Date:	08/15/1988

Global Id:	T0607500305
Status:	Open - Remediation
Status Date:	08/15/1988

Regulatory Activities:

Global Id:	T0607500305
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500305
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

206
SW
1/4-1/2
0.490 mi.
2586 ft.

CHEVRON STATION #9-0294
1200 07TH AVE
SAN FRANCISCO, CA 94122

LUST **S105688724**
N/A

Relative:
Higher

Actual:
12 ft.

LUST:

Region:	STATE
Global Id:	T0607500072
Latitude:	37.76834

CHEVRON STATION #9-0294 (Continued) **S105688724**

Longitude:	-122.39628
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/09/1992
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0081
LOC Case Number:	10008
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500072
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500072
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org
Phone Number:	Not reported

Status History:

Global Id:	T0607500072
Status:	Completed - Case Closed
Status Date:	10/09/1992

Global Id:	T0607500072
Status:	Open - Case Begin Date
Status Date:	02/08/1988

Regulatory Activities:

Global Id:	T0607500072
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

Global Id:	T0607500072
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607500072
Action Type:	ENFORCEMENT

CHEVRON STATION #9-0294 (Continued) **S105688724**

Date: 04/22/1992
Action: Notice of Responsibility

LUST REG 2:
Region: 2
Facility Id: 38-0081
Facility Status: Case Closed
Case Number: 10008
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN FRANCISCO CO. LUST:
Region: SAN FRANCISCO
Facility ID: 38-0081
Facility Status: Case Closed
Case Number: 10008
Case Type: Soil only
Release Date: 2/8/1988
Discovered Date: 2/8/1988
Substance: Waste Oil
Substance Qty: Not reported
How Discovered: Tank Closure
How Stopped: Close Tank
Report Date: 2/8/1988
Case Closed: 10/9/1992
Closed Date: 10/9/1992
Leak Source: Tank
Leak Cause: Structure Failure
Leak Confirmed: Not reported
Entered Date: 4/22/1992
Number of Wells: Not reported
Regional Board: San Francisco Bay Region
Local Agency: 38000
Lead Agency: Local Agency
Program: LOP
Responsible Party: Not reported
RP Address: Not reported
Operator: Not reported
Staff Initial: VP
Facility Staff: AL
Cross Street: LINCOLN ST
NOR Date: 4/22/1992
MTBE Current: Not reported
MTBE Current Date: Not reported
MTBE: NT
Maximum MTBE Soil: Not reported

CHEVRON STATION #9-0294 (Continued) **S105688724**

Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	Not reported
Workplan Submitted:	Not reported
Assessment Underway:	Not reported
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	Not reported
Funding:	Federal
Interim Remediation:	No
Priority:	Not reported
Abatement:	No Action Taken - no action has as yet been taken at the site
Enforcement Type:	NOR
Enforcement Due Date:	4/22/1992
Basin:	Westside Basin
Beneficial Use:	Yes
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	2/8/1988
Free Product:	No
Depth to Grnd Wtr:	Not reported
Gradient:	Not reported
Benzene:	Not reported
Primary Substance:	Used oil (waste
Enforcement Type:	Not reported
Amount of Free Produce:	Not reported
Benzene Test:	Not reported
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	960
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	Not reported
TPH Current Date:	Not reported
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Not reported

207
South
1/4-1/2
0.490 mi.
2586 ft.

ESPRIT OUTLET STORE
499 ILLINOIS ST
SAN FRANCISCO, CA 94107

HIST CORTESE **U001595249**
HIST UST **N/A**

Relative:
Higher

Actual:
11 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0141

ESPRIT OUTLET STORE (Continued) **U001595249**

HIST UST:

Region:	STATE
Facility ID:	00000056863
Facility Type:	Other
Other Type:	RETAIL STORE
Total Tanks:	0000
Contact Name:	Not reported
Telephone:	4156486900
Owner Name:	ESPRIT DE CORP.
Owner Address:	900 MINNESOTA ST.
Owner City,St,Zip:	SAN FRANCISCO, CA 94107

Tank Num:	001
Container Num:	1
Year Installed:	1972
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor

Tank Num:	002
Container Num:	2
Year Installed:	1972
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor

Tank Num:	003
Container Num:	3
Year Installed:	1972
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor

Tank Num:	004
Container Num:	4
Year Installed:	1972
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Tank Construction:	Not reported
Leak Detection:	Visual, Stock Inventor

208 NNW 1/2-1 0.518 mi. 2737 ft. — **355 BRYANT STREET SITE**, **355 BRYANT STREET**, **SAN FRANCISCO, CA 94107** — **VCP** **ENVIROSTOR** — **S107027323** **N/A**

Relative: Higher

Actual: 62 ft.

VCP:

Facility ID:	38990009
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	0.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Lead Agency Description:	SAN FRANCISCO COUNTY
Project Manager:	Janet Naito
Supervisor:	Barbara Cook
Division Branch:	Cleanup Berkeley
Site Code:	201008
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: Other Agency
Status Date:	09/30/1997
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.78355 / -122.3924
APN:	3774075
Past Use:	NONE SPECIFIED
Potential COC:	30019
Confirmed COC:	30019
Potential Description:	SOIL
Alias Name:	355 BRYANT STREET SITE
Alias Type:	Alternate Name
Alias Name:	3774075
Alias Type:	APN
Alias Name:	110033612874
Alias Type:	EPA (FRS #)
Alias Name:	201008
Alias Type:	Project Code (Site Code)
Alias Name:	38990009
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	09/30/1997
Comments:	Provided comments regarding the risk assessment evaluations conducted. Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	08/21/1997
Comments:	Signed Agreement with Geomatrix Consultants for review of existing environmental reports to determine if potential unacceptable risks are present given the current site use.

355 BRYANT STREET SITE (Continued) **S107027323**

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 0.5
NPL: NO
Regulatory Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Janet Naito
Supervisor: Barbara Cook
Division Branch: Cleanup Berkeley
Facility ID: 38990009
Site Code: 201008
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Refer: Other Agency
Status Date: 09/30/1997
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.78355
Longitude: -122.3924
APN: 3774075
Past Use: NONE SPECIFIED
Potential COC: Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Polynuclear aromatic hydrocarbons (PAHs, Polynuclear aromatic hydrocarbons (PAHs
Potential Description: SOIL
Alias Name: 355 BRYANT STREET SITE
Alias Type: Alternate Name
Alias Name: 3774075
Alias Type: APN
Alias Name: 110033612874
Alias Type: EPA (FRS #)
Alias Name: 201008
Alias Type: Project Code (Site Code)
Alias Name: 38990009
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 09/30/1997
Comments: Provided comments regarding the risk assessment evaluations conducted. Not reported

355 BRYANT STREET SITE (Continued) **S107027323**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	08/21/1997
Comments:	Signed Agreement with Geomatrix Consultants for review of existing environmental reports to determine if potential unacceptable risks are present given the current site use.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

---

209 West 1/2-1 0.573 mi. 3024 ft. **FLAIR ELECTRO SALES INC.** **HIST CORTESE** **S100233573**
516 TOWNSEND **LUST** **N/A**
SAN FRANCISCO, CA 94103 **Notify 65**

Relative: Higher

Actual: 12 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0152

LUST:

Region:	STATE
Global Id:	T0607500134
Latitude:	37.7808375
Longitude:	-122.3902708
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/07/1999
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0152
LOC Case Number:	10522
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500134
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov

FLAIR ELECTRO SALES INC. (Continued) **S100233573**

Phone Number: Not reported

Global Id: T0607500134
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Status History:
Global Id: T0607500134
Status: Completed - Case Closed
Status Date: 01/07/1999

Global Id: T0607500134
Status: Open - Case Begin Date
Status Date: 07/13/1988

Regulatory Activities:
Global Id: T0607500134
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500134
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Notify 65:
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: 94103

---

210 SSW 1/2-1 0.595 mi. 3144 ft.

Relative: Higher

Actual: 20 ft.

NORTH HALF OF MISSISSIPPI STREET **ENVIROSTOR** **S101482015**
17TH AND MISSISSIPPI STREETS **N/A**
SAN FRANCISCO, CA 94120

ENVIROSTOR:
Site Type: Historical
Site Type Detailed: * Historical
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley

NORTH HALF OF MISSISSIPPI STREET (Continued) **S101482015**

Facility ID:	38170002
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Refer: Other Agency
Status Date:	03/25/1995
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.76527
Longitude:	-122.3944
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	* OIL/WATER SEPARATION SLUDGE, * OTHER STILL BOTTOM WASTE
Confirmed COC:	* OIL/WATER SEPARATION SLUDGE, * OTHER STILL BOTTOM WASTE, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	CITRANS/DATASAFE WAREHOUSE
Alias Type:	Alternate Name
Alias Name:	DEE ENGINEERING COMPANY
Alias Type:	Alternate Name
Alias Name:	VIKING DISTRIBUTION
Alias Type:	Alternate Name
Alias Name:	38170002
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	06/14/1988
Comments:	Site Screening Done: There is unknown waste in the soil and groundwater. Located in an industrial area, companies on the north half of Mississippi include Viking Distribution, Dee Engineering Co, and Citrans/Datasafe Warehouse. PA required.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

---

211 SW 1/2-1 0.607 mi. 3206 ft. **THE GLIDDEN COMPANY** **Notify 65 S100179572**
1000 16TH STREET **EMI N/A**
SAN FRANCISCO, CA 92270

Relative: Higher

Actual: 17 ft.

Notify 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported

THE GLIDDEN COMPANY (Continued) **S100179572**

Discharge Date: Not reported
Incident Description: 92270

EMI:

Year:	1987
County Code:	38
Air Basin:	SF
Facility ID:	1195
Air District Name:	BA
SIC Code:	2851
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	17
Reactive Organic Gases Tons/Yr:	16
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1990
County Code:	38
Air Basin:	SF
Facility ID:	1195
Air District Name:	BA
SIC Code:	2851
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	99
Reactive Organic Gases Tons/Yr:	96
Carbon Monoxide Emissions Tons/Yr:	1
NOX - Oxides of Nitrogen Tons/Yr:	3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1995
County Code:	38
Air Basin:	SF
Facility ID:	1195
Air District Name:	BA
SIC Code:	2851
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Year:	1996
County Code:	38

THE GLIDDEN COMPANY (Continued) **S100179572**

Air Basin:	SF
Facility ID:	1195
Air District Name:	BA
SIC Code:	2851
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

AO212 **C & M PLATING WORKS** **ENVIROSTOR** **S100857136**
West **598 6TH STREET** **HWP** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103**
0.615 mi.
3245 ft. **Site 1 of 2 in cluster AO**

Relative:
Higher

Actual:
12 ft.

ENVIROSTOR:

Site Type:	Corrective Action
Site Type Detailed:	Corrective Action
Acres:	0.25
NPL:	NO
Regulatory Agencies:	HWMP
Lead Agency:	HWMP
Program Manager:	Robert Boggs
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Facility ID:	80001619
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	No Further Action
Status Date:	03/29/2001
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.77485
Longitude:	-122.4010
APN:	NONE SPECIFIED
Past Use:	METAL PLATING - OTHER
Potential COC:	NONE SPECIFIED, No Contaminants found
Confirmed COC:	NONE SPECIFIED, No Contaminants found, No Contaminants found
Potential Description:	NMA
Alias Name:	CAD009204736
Alias Type:	EPA Identification Number
Alias Name:	60000525
Alias Type:	Envirostor ID Number
Alias Name:	80001619
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

C & M PLATING WORKS (Continued) **S100857136**

Completed Document Type: Preliminary Assessment Report
Completed Date: 08/31/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedy Constructed
Completed Date: 04/09/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: RCRA Facility Assessment Report
Completed Date: 03/29/2001
Comments: RCRA Facility Assessment Completed 3/2001

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Other Instrument
Completed Date: 08/15/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Groundwater Migration Controlled
Completed Date: 08/07/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Remedy Selected
Completed Date: 08/30/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Human Exposure Controlled
Completed Date: 08/07/2006
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Not reported

C & M PLATING WORKS (Continued) **S100857136**

Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Facility ID: 60000525
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: 1248 Local Agency
Status Date: 01/27/2000
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.77560
Longitude: -122.4008
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED, No Contaminants found, No Contaminants found, NONE SPECIFIED
Confirmed COC: NONE SPECIFIED, No Contaminants found, No Contaminants found, NONE SPECIFIED, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAD009204736
Alias Type: EPA Identification Number
Alias Name: 60000525
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HWP:
EPA Id: CAD009204736
Cleanup Status: CLOSED
Latitude: 37.77485
Longitude: -122.4010
Facility Type: Historical - Non-Operating
Facility Size: Not reported
Team: Not reported
Supervisor: Not reported
Site Code: Not reported
Assembly District: 17
Senate District: 11
Public Information Officer: Not reported

C & M PLATING WORKS (Continued) **S100857136**

Activities:

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - APPLICATION PART B RECEIVED
Actual Date: 04/21/1983

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - PERMIT TERMINATED - TERMINATION RECEIVED
Actual Date: 12/20/1988

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - APPLICATION PART A RECEIVED
Actual Date: 11/14/1980

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Actual Date: 08/03/1983

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - TECHNICAL COMPLETE LETTER
Actual Date: 07/12/1983

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - PERMIT TERMINATED - TERMINATION APPROVED
Actual Date: 03/02/1989

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: New Operating Permit - FINAL PERMIT
Actual Date: 09/30/1983

Closure:

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure - RECEIVE CLOSURE CERTIFICATION
Actual Date: 07/16/1992

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure Final - ISSUE CLOSURE VERIFICATION
Actual Date: 07/16/1992

C & M PLATING WORKS (Continued) **S100857136**

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure Final - RESPONSE TO 1ST NOD RECEIVED
Actual Date: 02/28/1989

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure - ISSUE CLOSURE VERIFICATION
Actual Date: 07/16/1992

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure Final - CLOSURE PLAN RECEIVED
Actual Date: 04/22/1988

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure Final - CLOSURE PLAN APPROVED
Actual Date: 03/02/1989

EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Unit Names: CONTAIN1, TANKSTR1
Event Description: Closure Final - RECEIVE CLOSURE CERTIFICATION
Actual Date: 05/17/1991

Alias:
EPA Id: CAD009204736
Facility Type: Historical - Non-Operating
Alias Type: Envirostor ID Number
Alias: 60000525

AO213 **C & M PLATING WORKS** **RCRA-TSDF** **1000123000**
West **598 SIXTH ST** **CERC-NFRAP** **CAD009204736**
1/2-1 **SAN FRANCISCO, CA 94103** **CORRACTS**
0.615 mi. **RCRA-SQG**
3245 ft. **Site 2 of 2 in cluster AO** **FINDS**
2020 COR ACTION

Relative:
Higher

RCRA-TSDF:
Date form received by agency: 05/16/1997

Actual:
12 ft.

Facility name: C & M PLATING WORKS
Facility address: 598 SIXTH ST
SAN FRANCISCO, CA 941034708
EPA ID: CAD009204736
Mailing address: 598 SIXTH STREET
SAN FRANCISCO, CA 941034708
Contact: RAY MATTMAN
Contact address: 598 SIXTH ST
SAN FRANCISCO, CA 941034708
Contact country: US
Contact telephone: (415) 861-1556

C & M PLATING WORKS (Continued) **1000123000**

Contact email: Not reported
EPA Region: 09
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste

Owner/Operator Summary:
Owner/operator name: C&M PLATING WORKS
Owner/operator address: 598 SIXTH STREET
SAN FRANCISCO, CA 94103
Owner/operator country: Not reported
Owner/operator telephone: (415) 861-1556
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: C&M PLATING WORKS
Owner/operator address: 598 SIXTH STREET
CITY NOT REPORTED, CA 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 861-1556
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Facility name: C & M PLATING WORKS
Classification: Small Quantity Generator

Date form received by agency: 02/05/1992
Facility name: C & M PLATING WORKS
Classification: Large Quantity Generator

Date form received by agency: 04/03/1990
Facility name: C & M PLATING WORKS

C & M PLATING WORKS (Continued) **1000123000**

Classification: Large Quantity Generator

Corrective Action Summary:

Event date: 08/31/1990
Event: CA074LO

Event date: 08/31/1990
Event: CA029ST

Event date: 08/31/1990
Event: CA Prioritization, Facility or area was assigned a low corrective action priority.

Event date: 08/31/1990
Event: CA049PA

Event date: 03/29/2001
Event: RFA Completed, Assessment was an RFA.

Event date: 08/07/2006
Event: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Event date: 08/07/2006
Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

Event date: 08/15/2006
Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the EI determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

Event date: 08/15/2006
Event: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater

C & M PLATING WORKS (Continued) **1000123000**

remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Event date: 08/30/2006
Event: Date For Remedy Selection (CM Imposed)

Event date: 08/30/2006
Event: Date For Remedy Selection (CM Imposed)

Event date: 04/09/2007
Event: CA550RC

Event date: 04/09/2007
Event: CA550RC

Event date: 09/24/2009
Event: CA800YE

Event date: Not reported
Event: CA03192

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: TSD - Financial Requirements
Date violation determined: 02/05/1992
Date achieved compliance: 01/01/1993
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/27/1991
Date achieved compliance: 03/16/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/09/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date violation determined: 11/27/1991
Date achieved compliance: 03/16/1992
Violation lead agency: State
Enforcement action: Not reported

C & M PLATING WORKS (Continued) **1000123000**

Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General Facility Standards
Date violation determined: 11/27/1991
Date achieved compliance: 03/16/1992
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Preparedness and Prevention
Date violation determined: 11/27/1991
Date achieved compliance: 03/16/1992
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Container Use and Management
Date violation determined: 11/27/1991
Date achieved compliance: 03/16/1992
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 09/21/1989
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/28/1989

C & M PLATING WORKS (Continued) **1000123000**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 09/21/1989
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/28/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Manifest/Records/Reporting
Date violation determined: 09/21/1989
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 12/28/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: LDR - General
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/30/1989
Enf. disposition status: Not reported

C & M PLATING WORKS (Continued) **1000123000**

Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/23/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Manifest/Records/Reporting
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/23/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Manifest/Records/Reporting
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

C & M PLATING WORKS (Continued) **1000123000**

Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - Closure/Post-Closure
Date violation determined: 03/24/1988
Date achieved compliance: 01/24/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/23/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 02/05/1992
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: TSD - Financial Requirements
Date achieved compliance: 01/01/1993
Evaluation lead agency: EPA Contractor/Grantee

Evaluation date: 10/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Contingency Plan and Emergency Procedures
Date achieved compliance: 03/16/1992
Evaluation lead agency: State

Evaluation date: 10/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General Facility Standards
Date achieved compliance: 03/16/1992
Evaluation lead agency: State

Evaluation date: 10/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Container Use and Management
Date achieved compliance: 03/16/1992
Evaluation lead agency: State

Evaluation date: 10/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Preparedness and Prevention
Date achieved compliance: 03/16/1992
Evaluation lead agency: State

Evaluation date: 10/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/16/1992
Evaluation lead agency: State

Evaluation date: 09/21/1989

C & M PLATING WORKS (Continued) **1000123000**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 09/21/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Manifest/Records/Reporting
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 09/21/1989
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 08/11/1989
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/24/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Closure/Post-Closure
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 03/24/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 03/24/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 03/24/1988
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/24/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Manifest/Records/Reporting
Date achieved compliance: 01/24/1990
Evaluation lead agency: State

Evaluation date: 03/22/1988
Evaluation: FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported

C & M PLATING WORKS (Continued) **1000123000**

Evaluation lead agency: State

CERC-NFRAP:
Site ID: 0900362
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: Deferred to RCRA

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 13051240.00000
Person ID: 9271184.00000

Contact Sequence ID: 13289835.00000
Person ID: 13003854.00000

Contact Sequence ID: 13295430.00000
Person ID: 13003858.00000

Contact Sequence ID: 13301288.00000
Person ID: 13004003.00000

Program Priority:
Description: RCRA Deferral Audit

Description: RCRA Deferral - Lead Confirmed

Description: RCRA Deferral - Further Superfund Assessment

CERCLIS-NFRAP Assessment History:
Action: ARCHIVE SITE
Date Started: / /
Date Completed: 01/23/96
Priority Level: Not reported

Action: DISCOVERY
Date Started: / /
Date Completed: 06/12/90
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 09/10/90
Priority Level: Deferred to RCRA (Subtitle C)

CORRACTS:

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20010329
Action: CA050RF - RFA Completed, Assessment was an RFA
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

C & M PLATING WORKS (Continued) **1000123000**

EPA ID: CAD009204736
EPA Region: 09
Area Name: BUILDING 2
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: GROUNDWATER
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: CONTAINER STORAGE AREA
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: 20070409
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: BUILDING 1
Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: DRUM STORAGE AREA

C & M PLATING WORKS (Continued) **1000123000**

Actual Date: 20070409
Action: CA550RC
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20060807
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified
NAICS Code(s): Not reported
Original schedule date: 20060807
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20060807
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified
NAICS Code(s): Not reported
Original schedule date: 20060807
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20060815
Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20060815
Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20060830
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): Not reported
Original schedule date: 20060830
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09

C & M PLATING WORKS (Continued) **1000123000**

Area Name: ENTIRE FACILITY
Actual Date: 20060830
Action: CA400 - Date For Remedy Selection (CM Imposed)
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19900831
Action: CA074LO
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19900831
Action: CA049PA
NAICS Code(s): Not reported
Original schedule date: 19881208
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19900831
Action: CA029ST
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 19900831
Action: CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: 20090924
Action: CA800YE
NAICS Code(s): Not reported
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: CAD009204736
EPA Region: 09
Area Name: ENTIRE FACILITY
Actual Date: Not reported

C & M PLATING WORKS (Continued) **1000123000**

Action: CA03192
NAICS Code(s): Not reported
Original schedule date: 19921001
Schedule end date: Not reported

FINDS:

Registry ID: 110002636130

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

2020 COR ACTION:
EPA ID: CAD009204736
Region: 9
Action: Remedy Constructed

---

214 WNW 1/2-1 0.615 mi. 3248 ft. **FILIPINO EDUCATION CENTER** **SCH S108747299**
824 HARRISON STREET **ENVIROSTOR N/A**
SAN FRANCISCO, CA 94107

Relative: Higher

Actual: 15 ft.

SCH:

Facility ID: 60000627
Site Type: School Cleanup
Site Type Detail: School
Site Mgmt. Req.: NONE SPECIFIED
Acres: 0.85
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Harold (Bud) Duke
Supervisor: Mark Malinowski
Division Branch: Northern California Schools & Santa Susana
Site Code: 204201
Assembly: 17
Senate: 11
Special Program Status: Not reported
Status: Inactive - Action Required
Status Date: 10/05/2007
Restricted Use: NO
Funding: School District
Latitude: 37.78047
Longitude: -122.4004
APN: 3752 012, 3752012
Past Use: LDF, SCHOOL - MIDDLE, UNKNOWN
Potential COC: Methane
Confirmed COC: Methane

FILIPINO EDUCATION CENTER (Continued) **S108747299**

Potential Description: SOIL, SV
Alias Name: 3752 012
Alias Type: APN
Alias Name: 3752012
Alias Type: APN
Alias Name: 110033615363
Alias Type: EPA (FRS #)
Alias Name: 204201
Alias Type: Project Code (Site Code)
Alias Name: 60000627
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 06/15/2007
Comments: DTSC submitted determination letter of PEA required based on review of Millennium's 05/18/07 Phase 1 ESA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 07/16/2007
Comments: DTSC accepted the PEA Workplan as adequate provided certain caveats are implemented, as outlined in the approval letter.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 10/05/2007
Comments: DTSC issued letter concurring with recommendations provided in the PEA Report. Since the District had entered the DTSC program voluntarily, the District chose to opt-out of the program and DTSC did not issue a formal approval of the PEA report. The PEA report recommended a vapor barrier under the building and a venting system to address methane from degrading diesel from the adjacent property.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 06/28/2007
Comments: Mark Malinowski, Bud Duke and Gabriele Windgasse (via teleconference)attended PEA Workplan scoping meeting with District represenatives and District consultant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 12/28/2007
Comments: DTSC issued a CRU Memo to Accounting to close-out the project files.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 07/24/2007
Comments: Sent fully executed agreement to district.

FILIPINO EDUCATION CENTER (Continued) **S108747299**

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: School Cleanup
Site Type Detailed: School
Acres: 0.85
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Harold (Bud) Duke
Supervisor: Mark Malinowski
Division Branch: Northern California Schools & Santa Susana
Facility ID: 60000627
Site Code: 204201
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Inactive - Action Required
Status Date: 10/05/2007
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: School District
Latitude: 37.78047
Longitude: -122.4004
APN: 3752 012, 3752012
Past Use: LDF, SCHOOL - MIDDLE, UNKNOWN
Potential COC: Methane
Confirmed COC: Methane, Methane
Potential Description: SOIL, SV
Alias Name: 3752 012
Alias Type: APN
Alias Name: 3752012
Alias Type: APN
Alias Name: 110033615363
Alias Type: EPA (FRS #)
Alias Name: 204201
Alias Type: Project Code (Site Code)
Alias Name: 60000627
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 06/15/2007
Comments: DTSC submitted determination letter of PEA required based on review of Millennium's 05/18/07 Phase 1 ESA.

Completed Area Name: PROJECT WIDE

FILIPINO EDUCATION CENTER (Continued) **S108747299**

Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 07/16/2007
Comments: DTSC accepted the PEA Workplan as adequate provided certain caveats are implemented, as outlined in the approval letter.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 10/05/2007
Comments: DTSC issued letter concurring with recommendations provided in the PEA Report. Since the District had entered the DTSC program voluntarily, the District chose to opt-out of the program and DTSC did not issue a formal approval of the PEA report. The PEA report recommended a vapor barrier under the building and a venting system to address methane from degrading diesel from the adjacent property.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 06/28/2007
Comments: Mark Malinowski, Bud Duke and Gabriele Windgasse (via teleconference)attended PEA Workplan scoping meeting with District represenatives and District consultant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 12/28/2007
Comments: DTSC issued a CRU Memo to Accounting to close-out the project files.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 07/24/2007
Comments: Sent fully executed agreement to district.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

215 SSW 1/2-1 0.636 mi. 3357 ft. **UNKOWN**
1200 17TH STREET
SAN FRANCISCO, CA 92270

Notify 65 **S100179117**
N/A

Relative: Higher

Actual: 21 ft.

Notify 65:
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported

UNKOWN (Continued) **S100179117**

Discharge Date: Not reported
Incident Description: 92270

AP216 **AUTO SYMPHONY** **HIST CORTESE** **S100453836**
West **800 BRYAN ST.** **LUST** **N/A**
1/2-1 **SAN FRANCISCO, CA** **Notify 65**
0.689 mi.
3638 ft. **Site 1 of 3 in cluster AP**

Relative:
Higher

Actual:
13 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0511

LUST:

Region:	STATE
Global Id:	T0607500457
Latitude:	37.7760455
Longitude:	-122.4025432
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/17/1997
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	SC
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0511
LOC Case Number:	10229
File Location:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500457
Contact Type:	Local Agency Caseworker
Contact Name:	STEPHANIE CUSHING
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET #210
City:	SAN FRANCISCO
Email:	stephanie.cushing@sfdph.org
Phone Number:	Not reported

Global Id:	T0607500457
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Status History:

Global Id:	T0607500457
Status:	Completed - Case Closed

AUTO SYMPHONY (Continued) **S100453836**

Status Date: 11/17/1997

Global Id: T0607500457
Status: Open - Case Begin Date
Status Date: 10/12/1989

Regulatory Activities:
Global Id: T0607500457
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

Global Id: T0607500457
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Notify 65:
Date Reported: 19920930
Staff Initials: Not reported
Board File Number: 0LG921238
Facility Type: Leak Rpt
Discharge Date: Not reported
Incident Description: Not reported

Date Reported: 19920930
Staff Initials: Not reported
Board File Number: 0LG921238
Facility Type: Leak Rpt
Discharge Date: Not reported
Incident Description: Not reported

---

217 South 1/2-1 0.692 mi. 3652 ft.

Relative: Higher

Actual: 29 ft.

RUBER, E. G. & SONS **ENVIROSTOR** **S101482023**
725 18TH **N/A**
SAN FRANCISCO, CA 94107

ENVIROSTOR:
Site Type: Historical
Site Type Detailed: * Historical
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Facility ID: 38330103
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: Other Agency
Status Date: 07/29/1994
Restricted Use: NO

RUBER, E. G. & SONS (Continued) **S101482023**

Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 37.76272
Longitude: -122.3902
APN: 4043013
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CONSUMERS AUTO BUILDER
Alias Type: Alternate Name
Alias Name: 4043013
Alias Type: APN
Alias Name: 38330103
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 09/28/1981
Comments: FACILITY IDENTIFIED ID FROM 1954 POLK DIRECTORY

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

218
WSW
1/2-1
0.696 mi.
3676 ft.

CONSOLIDATED IRON WORKS **HIST Cal-Sites 1000383957**
634 TOWNSEND STREET **ENVIROSTOR N/A**
SAN FRANCISCO, CA 94103

Relative:
Higher

Actual:
15 ft.

Calsite:
Facility ID: 38330010
Region: 2
Region Name: BERKELEY
Branch: NC
Branch Name: NORTH COAST
File Name: Not reported
State Senate District: 01011982
Status: CERTIFIED AS HAVING BEEN REMEDIED SATISFACTORILY UNDER DTSC OVERSIGHT
Status Name: CERTIFIED
Lead Agency: Not reported
Lead Agency: N/A
Facility Type: RP
Type Name: RESPONSIBLE PARTY
NPL: Not reported
SIC Code: 33
SIC Name: MANU - PRIMARY METAL INDUSTRIES
Access: Not reported
Cortese: Not reported

CONSOLIDATED IRON WORKS (Continued) **1000383957**

Hazardous Ranking Score:	Not reported
Date Site Hazard Ranked:	Not reported
Groundwater Contamination:	Not reported
Staff Member Responsible for Site:	KHILF
Supervisor Responsible for Site:	Not reported
Region Water Control Board:	SF
Region Water Control Board Name:	SAN FRANCISCO BAY
Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported
State Assembly District Code:	13
State Senate District Code:	03
Facility ID:	38330010
Activity:	DISC
Activity Name:	DISCOVERY
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	09081981
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38330010
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	01011982
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported

CONSOLIDATED IRON WORKS (Continued) **1000383957**

For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	38330010
Activity:	SS
Activity Name:	SITE SCREENING
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	02181987
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Alternate Address:	7TH AND TOWNSEND ST.
Alternate City,St,Zip:	SAN FRANCISCO, CA 94103
Alternate Address:	634 TOWNSEND STREET
Alternate City,St,Zip:	SAN FRANCISCO, CA 94103
Background Info:	This site is at the corner of 7th Street and Townsend in San Francisco, California. The Site is bounded by 7th Street to the east, Brennan Street and Highway 101 Skyway to the north, 8th Street to the west, and Townsend on the south. Currently, the Concourse Exhibit Hall, the Townsend Center, parking garage, and the Macromedia (SEGA) office building occupy the two-acre site in an industrial/commercial area. The San Francisco Bay is one-quarter mile to the east. Consolidated Iron Works (CIW)(also known as (a.k.a.) Consolidated Iron and Metal) operated a scrap and semiprecious metal recycling and packaging operation from 1950 to 1965. Independent Paper Stock, a paper recycling business, operated at the site from 1965 to 1974. The site was vacant from 1974 to 1982. Bay West Development Company (a.k.a. Showplace Square) acquired it in 1983. The old Western Pacific Railroad Freight Depot, adjacent to CWI was also acquired and added to the site for development. It is part of the Townsend Center and is now known as the Concourse Exhibit Hall. Currently, the site is an office building, parking garage, and exhibit hall with the area covered by buildings or asphalt.
Comments Date:	01011982
Comments:	Certified Site.
Comments Date:	02181987
Comments:	Completed Site Screening. During a Department of Health
Comments Date:	02181987

CONSOLIDATED IRON WORKS (Continued) **1000383957**

Comments:	Services (DHS), predecessor to the Department of Toxic
Comments Date:	02181987
Comments:	Substances Control (DTSC), site inspection in 1982, seven drums
Comments Date:	02181987
Comments:	containing material were discovered on site insite a
Comments Date:	02181987
Comments:	sheetmetal-sided, cement floored factory building. One drum
Comments Date:	02181987
Comments:	contained metals (chromium 495 ug/g, copper 82100 ug/g, nickel
Comments Date:	02181987
Comments:	25400 ug/g, lead 220 ug/g, and zinc 5590 ug/g). Inside one of
Comments Date:	02181987
Comments:	the buildings, surface soil from a crack in the cement, fifteen
Comments Date:	02181987
Comments:	feet from the drums contained 2900 ug/g copper, 109 ug/g lead,
Comments Date:	02181987
Comments:	and 3680 ug/g zinc. The samples were also tested for
Comments Date:	02181987
Comments:	pesticides, which were not detected. The drums were removed and
Comments Date:	02181987
Comments:	properly disposed. The site was re-inspected in 1984 by DHS.
Comments Date:	02181987
Comments:	DHS determined in 1985 that sufficient remedial measures had
Comments Date:	02181987
Comments:	been achieved since the site is located over impermeable bay
Comments Date:	02181987
Comments:	mud, there are no drinking water sources nearby, the source
Comments Date:	02181987
Comments:	(seven drums) were removed, and migration of metals was not an
Comments Date:	02181987
Comments:	issue. The site was removed (delisted) from the State Priority
Comments Date:	02181987
Comments:	Remedial List (SPRL) in 1985. Bay West Development Company then
Comments Date:	02181987
Comments:	started development of the site by demolishing the existing
Comments Date:	02181987
Comments:	buildings and rebuilding the office buildings, exhibit hall, and
Comments Date:	02181987
Comments:	parking garage.
ID Name:	Not reported
ID Value:	Not reported
Alternate Name:	CONSOLIDATED IRON & METALCONSOLIDATED IRON WORKS
Special Programs Code:	Not reported
Special Programs Name:	Not reported

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	2
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Katharine Hilf
Supervisor:	Karen Toth
Division Branch:	Cleanup Berkeley
Facility ID:	38330010
Site Code:	Not reported

CONSOLIDATED IRON WORKS (Continued) **1000383957**

Assembly: 17
Senate: 11
Special Program: Not reported
Status: Certified
Status Date: 01/01/1982
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.77194
Longitude: -122.4023
APN: 378-3-007, 3783007
Past Use: RECYCLING - OTHER, RECYCLING - SCRAP METAL
Potential COC: Lead, Copper and compounds, Nickel, Zinc
Confirmed COC: Lead, Copper and compounds, Nickel, Zinc, NONE SPECIFIED
Potential Description: NMA
Alias Name: CONSOLIDATED IRON & METAL
Alias Type: Alternate Name
Alias Name: Townsend Center
Alias Type: Alternate Name
Alias Name: 378-3-007
Alias Type: APN
Alias Name: 3783007
Alias Type: APN
Alias Name: 38330010
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/22/1985
Comments: Certified Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 09/08/1981
Comments: Solid Waste Information System documentation regarding site

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/18/1987
Comments: Completed Site Screening. During a Department of Health Services (DHS), predecessor to the Department of Toxic Substances Control (DTSC), site inspection in 1982, seven drums containing material were discovered on site insite a sheetmetal-sided, cement floored factory building. One drum contained metals (chromium 495 ug/g, copper 82100 ug/g, nickel 25400 ug/g, lead 220 ug/g, and zinc 5590 ug/g). Inside one of the buildings, surface soil from a crack in the cement, fifteen feet from the drums contained 2900 ug/g copper, 109 ug/g lead, and 3680 ug/g zinc. The samples were also tested for pesticides, which were not detected. The drums were removed and properly disposed. The site was re-inspected in 1984 by DHS. DHS determined in 1985 that sufficient remedial measures had been achieved since the site is located over impermeable bay mud, there are no drinking water sources nearby, the source (seven drums) were removed, and migration of metals was not an issue. The site was

CONSOLIDATED IRON WORKS (Continued) **1000383957**

removed (delisted) from the State Priority Remedial List (SPRL) in 1985. Bay West Development Company then started development of the site by demolishing the existing buildings and rebuilding the office buildings, exhibit hall, and parking garage.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/23/2002
Comments: The site was delisted in 1985, after a 1984 inspection showed the source of metals had been removed. There is no indication any hazardous substances are being used by any of the current occupants.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

AP219 **AUTO SYMPHONY** **Notify 65** **S100453873**
West **800 BRYAN ST.** **N/A**
1/2-1 **SAN FRANCISCO, CA**
0.702 mi.
3706 ft. **Site 2 of 3 in cluster AP**

Relative:
Higher

Actual:
13 ft.

Notify 65:
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: Not reported

AP220 **MCDONALD'S RESTAURANT SITE** **DEED** **S101661373**
West **820 BRYANT ST** **VCP** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103** **ENVIROSTOR**
0.729 mi.
3849 ft. **Site 3 of 3 in cluster AP**

Relative:
Higher

Actual:
14 ft.

DEED:
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Deed Date(s): 02/20/1996
EDR Link ID: 38580001

VCP:
Facility ID: 38580001
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: LUC, NOWN, NDAM, NSUB

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Acres:	1
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Claude Jemison
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	200614
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	03/08/1996
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.77581 / -122.4032
APN:	3759-014, 3759-09, 3759-12, 3759014
Past Use:	ILLEGAL DUMPING
Potential COC:	30013
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL
Alias Name:	3759-014
Alias Type:	APN
Alias Name:	3759-09
Alias Type:	APN
Alias Name:	3759-12
Alias Type:	APN
Alias Name:	3759014
Alias Type:	APN
Alias Name:	110033610224
Alias Type:	EPA (FRS #)
Alias Name:	200614
Alias Type:	Project Code (Site Code)
Alias Name:	38580001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	03/08/1996
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Certification
Completed Date:	03/08/1996
Comments:	Certified Site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	02/20/1996
Comments:	Recorded Deed Restriction limiting the property to commercial uses and included provisions for maintenance of the cap.
Completed Area Name:	PROJECT WIDE

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 10/23/1995
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 09/05/1995
Comments: Voluntary Cleanup Agreement (VCA) entered between DTSC and McDonald's Corporation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 05/16/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. During the inspection, several cracks were observed on the concrete cap. Other than these cracks, the concrete cap appeared to be in good condition, with drainage areas observed to be clear and free of debris, and in good working condition. Cracks greater than 0.25 inches must be repaired with a concrete patch. This is required by the Pavement Monitoring Plan

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/29/2007
Comments: The concrete cap appeared to be in good condition with drainage area observed to be clear and free of debris and in good working condition. Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/19/2010
Comments: DTSC staff visited the Site and observed that the concrete cap appeared to be in good condition, and drainage areas were clear and free of debris and in good working condition.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/01/2001
Comments: Completed Five-Year Review. Selected remedial action remains protective.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Completed Date:	02/08/1996
Comments:	Completed Removal Action. Approximately 350 cubic yards of lead contaminated soil were excavated for the installation of utilities. The upper 0.5-1 foot of soil was removed to achieve the final grade. Approximately 300 cubic yards of crushed rock was imported to raise the grade of the site adjacent to 6th Street. A 5-inch thick reinforced concrete cap was installed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Workplan
Completed Date:	10/23/1995
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	05/18/2004
Comments:	Cap Inspection Report signed off 5/18/04.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	05/02/2005
Comments:	Cap Inspection signed off 5/2/05.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	06/13/2006
Comments:	DTSC completed the 5 year assessment for this project and found that the current remedy, a cap, is still effective.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	04/11/2006
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	05/16/2011
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fact Sheets
Completed Date:	09/15/1995
Comments:	Fact Sheet announces the start of a public comment period and a public meeting on September 28.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Public Notice
Completed Date:	06/24/2011
Comments:	Not reported

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: The concrete cap appeared to be in good condition, with drainage areas observed to be clear and free of debris, and in good working condition.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/28/2008
Comments: The concrete cap appeared to be in good condition.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2016
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 1
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38580001
Site Code: 200614
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Certified O&M - Land Use Restrictions Only
Status Date: 03/08/1996
Restricted Use: YES
Site Mgmt. Req.: LUC, NOWN, NDAM, NSUB
Funding: Responsible Party
Latitude: 37.77581
Longitude: -122.4032
APN: 3759-014, 3759-09, 3759-12, 3759014
Past Use: ILLEGAL DUMPING
Potential COC: Lead
Confirmed COC: Lead, NONE SPECIFIED
Potential Description: SOIL
Alias Name: 3759-014
Alias Type: APN
Alias Name: 3759-09
Alias Type: APN
Alias Name: 3759-12
Alias Type: APN

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Alias Name: 3759014
Alias Type: APN
Alias Name: 110033610224
Alias Type: EPA (FRS #)
Alias Name: 200614
Alias Type: Project Code (Site Code)
Alias Name: 38580001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 03/08/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 03/08/1996
Comments: Certified Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 02/20/1996
Comments: Recorded Deed Restriction limiting the property to commercial uses and included provisions for maintenance of the cap.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 10/23/1995
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 09/05/1995
Comments: Voluntary Cleanup Agreement (VCA) entered between DTSC and McDonald's Corporation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 05/16/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/31/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. During the inspection, several cracks were observed on the concrete cap. Other than these cracks, the concrete cap appeared to be in good condition, with drainage areas observed to be clear and free of debris, and in good working condition. Cracks

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

greater than 0.25 inches must be repaired with a concrete patch.
This is required by the Pavement Monitoring Plan

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/29/2007
Comments: The concrete cap appeared to be in good condition with drainage area observed to be clear and free of debris and in good working condition.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/19/2010
Comments: DTSC staff visited the Site and observed that the concrete cap appeared to be in good condition, and drainage areas were clear and free of debris and in good working condition.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/01/2001
Comments: Completed Five-Year Review. Selected remedial action remains protective.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 02/08/1996
Comments: Completed Removal Action. Approximately 350 cubic yards of lead contaminated soil were excavated for the installation of utilities.
The upper 0.5-1 foot of soil was removed to achieve the final grade.
Approximately 300 cubic yards of crushed rock was imported to raise the grade of the site adjacent to 6th Street. A 5-inch thick reinforced concrete cap was installed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 10/23/1995
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/18/2004
Comments: Cap Inspection Report signed off 5/18/04.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/02/2005
Comments: Cap Inspection signed off 5/2/05.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

MCDONALD'S RESTAURANT SITE (Continued) **S101661373**

Completed Document Type: 5 Year Review Reports
Completed Date: 06/13/2006
Comments: DTSC completed the 5 year assessment for this project and found that the current remedy, a cap, is still effective.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/11/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/16/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 09/15/1995
Comments: Fact Sheet announces the start of a public comment period and a public meeting on September 28.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/24/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/02/2009
Comments: The concrete cap appeared to be in good condition, with drainage areas observed to be clear and free of debris, and in good working condition.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/28/2008
Comments: The concrete cap appeared to be in good condition.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2016
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

221
WNW
1/2-1
0.746 mi.
3939 ft.

ROTOMETALS INC
980-82 HARRISON
SAN FRANCISCO, CA 94107

ENVIROSTOR **S101482022**
N/A

Relative:
Higher

Actual:
13 ft.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0.5
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Facility ID:	38330089
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	EPA - PASI
Status:	No Further Action
Status Date:	01/13/2009
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.77781
Longitude:	-122.4038
APN:	3753-027, 3753027
Past Use:	NONE
Potential COC:	NONE SPECIFIED, No Contaminants found
Confirmed COC:	NONE SPECIFIED, No Contaminants found, 31000-NO
Potential Description:	NMA
Alias Name:	3753-027
Alias Type:	APN
Alias Name:	3753027
Alias Type:	APN
Alias Name:	38330089
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	09/28/1981
Comments:	FACILITY IDENTIFIED ID FROM 1954 POLK DIRECTORY
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	06/01/1988
Comments:	SITE SCREENING DONE NEED MORE INFO
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	PA/SI Reassessment
Completed Date:	01/12/2009
Comments:	Not reported
Future Area Name:	Not reported

ROTOMETALS INC (Continued) **S101482022**

Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

222
WNW
1/2-1
0.747 mi.
3944 ft.

858-860 FOLSOM STREET
858-860 FOLSOM STREET
SAN FRANCISCO, CA 94107

VCP **S102564478**
ENVIROSTOR **N/A**

Relative:
Higher

Actual:
17 ft.

VCP:

Facility ID:	38760001
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	Not reported
National Priorities List:	NO
Cleanup Oversight Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Lead Agency Description:	Not reported
Project Manager:	Not reported
Supervisor:	Barbara Cook
Division Branch:	Cleanup Berkeley
Site Code:	200828
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: 1248 Local Agency
Status Date:	11/30/2003
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.78114 / -122.4026
APN:	3733021
Past Use:	NONE SPECIFIED
Potential COC:	30013, 30024
Confirmed COC:	30024-NO,30013
Potential Description:	SOIL
Alias Name:	858-860 FOLSOM STREET
Alias Type:	Alternate Name
Alias Name:	3733021
Alias Type:	APN
Alias Name:	110033612990
Alias Type:	EPA (FRS #)
Alias Name:	200828
Alias Type:	Project Code (Site Code)
Alias Name:	38760001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	09/23/1996

858-860 FOLSOM STREET (Continued) **S102564478**

Comments: Signed VCA to review documents.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Barbara Cook
Division Branch: Cleanup Berkeley
Facility ID: 38760001
Site Code: 200828
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Refer: 1248 Local Agency
Status Date: 11/30/2003
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.78114
Longitude: -122.4026
APN: 3733021
Past Use: NONE SPECIFIED
Potential COC: Lead, TPH-diesel
Confirmed COC: Lead, TPH-diesel, 30024-NO, Lead
Potential Description: SOIL
Alias Name: 858-860 FOLSOM STREET
Alias Type: Alternate Name
Alias Name: 3733021
Alias Type: APN
Alias Name: 110033612990
Alias Type: EPA (FRS #)
Alias Name: 200828
Alias Type: Project Code (Site Code)
Alias Name: 38760001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 09/23/1996
Comments: Signed VCA to review documents.

858-860 FOLSOM STREET (Continued) **S102564478**

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

223
NNW
1/2-1
0.750 mi.
3960 ft.

ELECTRICAL SHOP **ENVIROSTOR** **S100182554**
528 FOLSOM **N/A**
SAN FRANCISCO, CA 94105

Relative:
Higher

Actual:
46 ft.

ENVIROSTOR:

Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Berkeley
Facility ID:	38360105
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Refer: Other Agency
Status Date:	03/31/1995
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.78698
Longitude:	-122.3955
APN:	3736016
Past Use:	NONE SPECIFIED
Potential COC:	* Metals - Sludge, * ORGANIC LIQUIDS WITH METALS, * CONTAMINATED SOIL, Lead, Cadmium and compounds
Confirmed COC:	* Metals - Sludge, * ORGANIC LIQUIDS WITH METALS, * CONTAMINATED SOIL, Lead, Cadmium and compounds, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	3736016
Alias Type:	APN
Alias Name:	38360105
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	06/12/1987
Comments:	SITE SCREENING DONE RATIONALE FOR PA: NEED MORE INFORMATION.
Completed Area Name:	PROJECT WIDE

ELECTRICAL SHOP (Continued) **S100182554**

Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 09/14/1981
Comments: FACILITY IDENTIFIED ID'D ON DRIVEBY FACILITY DRIVE-BY DRIVEBY-OILY PATCH & DISCOLORED SOIL SAME ADD AS SAN FRANCISCO WELDING & FABRICATING CO #38-76-0012.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

224 South 1/2-1 0.773 mi. 4083 ft.

COLOR III LAB, INC. **ENVIROSTOR** **S100932954**
560 19TH STREET **N/A**
SAN FRANCISCO, CA 94107

Relative: Higher

Actual: 25 ft.

ENVIROSTOR:
Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Not reported
Division Branch: Cleanup Berkeley
Facility ID: 71003404
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Inactive - Needs Evaluation
Status Date: Not reported
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 37.76202
Longitude: -122.3882
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAL920234879
Alias Type: EPA Identification Number
Alias Name: 71003404
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported

COLOR III LAB, INC. (Continued) **S100932954**

Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

225
SW
1/2-1
0.832 mi.
4393 ft.

1717 17TH ST. **ENVIROSTOR** **S108407628**
1717 17TH ST. **N/A**
SAN FRANCISCO, CA 94103

Relative:
Higher

Actual:
23 ft.

ENVIROSTOR:
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Facility ID: 60000549
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: 1248 Local Agency
Status Date: 06/02/2005
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.76451
Longitude: -122.4009
APN: 3980007
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 3980007
Alias Type: APN
Alias Name: 60000549
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

1717 17TH ST. (Continued) **S108407628**

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

226
SW
1/2-1
0.845 mi.
4462 ft.

1601 MARIPOSA STREET **VCP** **S105088004**
1601 MARIPOSA STREET **ENVIROSTOR** **N/A**
SAN FRANCISCO, CA 94107

Relative:
Higher

Actual:
26 ft.

VCP:

Facility ID:	60001763
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	2.31
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Tom Lanphar
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Site Code:	201945
Assembly:	13
Senate:	03
Special Programs Code:	Not reported
Status:	Active
Status Date:	07/01/2012
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.76426 / -122.3898
APN:	NONE SPECIFIED
Past Use:	MANUFACTURING - OTHER, UNDERGROUND STORAGE TANKS
Potential COC:	30003, 30013
Confirmed COC:	30003,30013
Potential Description:	SOIL, SV
Alias Name:	201945
Alias Type:	Project Code (Site Code)
Alias Name:	60001763
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Amendment - Order/Agreement
Completed Date:	03/26/2013
Comments:	This VCA amendment adds three additional Tasks to the Scope of Work (Sampling and Analysis Workplan Implementation, Site Characterization Report, and Remedial Action Scoping)and a revised cost estimate.
Completed Area Name:	PROJECT WIDE

1601 MARIPOSA STREET (Continued) **S105088004**

Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/09/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 07/18/2013
Comments: The Report details the data collection and results of soil, groundwater, and soil gas at properties located at 1601 and 1677 Mariposa Street. Data collection occured at different times between December 2011 and January 2013. The report was completed under DTSC oversight through a Voluntary Cleanup Agreement. The report recomends remediation due to concentrations of soil gas and metals in soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 01/03/2013
Comments: work plan acceptable no modification needed and no comments

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 01/29/2013
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Community Profile
Schedule Due Date: 01/28/2014
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: AB 389 Response Plan
Schedule Due Date: 05/13/2014
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Phase 1
Schedule Due Date: 11/30/2013
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: California Land Reuse and Revitalization Agreement
Schedule Due Date: 12/31/2013
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup

1601 MARIPOSA STREET (Continued) **S105088004**

Acres:	2.31
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Tom Lanphar
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Facility ID:	60001763
Site Code:	201945
Assembly:	13
Senate:	03
Special Program:	Not reported
Status:	Active
Status Date:	07/01/2012
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.76426
Longitude:	-122.3898
APN:	NONE SPECIFIED
Past Use:	MANUFACTURING - OTHER, UNDERGROUND STORAGE TANKS
Potential COC:	Benzene, Lead
Confirmed COC:	Benzene, Lead, Benzene, Lead
Potential Description:	SOIL, SV
Alias Name:	201945
Alias Type:	Project Code (Site Code)
Alias Name:	60001763
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Amendment - Order/Agreement
Completed Date:	03/26/2013
Comments:	This VCA amendment adds three additional Tasks to the Scope of Work (Sampling and Analysis Workplan Implementation, Site Characterization Report, and Remedial Action Scoping)and a revised cost estimate.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	08/09/2012
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Report
Completed Date:	07/18/2013
Comments:	The Report details the data collection and results of soil, groundwater, and soil gas at properties located at 1601 and 1677 Mariposa Street. Data collection occured at different times between December 2011 and January 2013. The report was completed under DTSC oversight through a Voluntary Cleanup Agreement. The report recomends remediation due to concentrations of soil gas and metals in soil.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

1601 MARIPOSA STREET (Continued) **S105088004**

Completed Document Type:	Site Characterization Workplan
Completed Date:	01/03/2013
Comments:	work plan acceptable no modification needed and no comments
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	01/29/2013
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Community Profile
Schedule Due Date:	01/28/2014
Schedule Revised Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	AB 389 Response Plan
Schedule Due Date:	05/13/2014
Schedule Revised Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Phase 1
Schedule Due Date:	11/30/2013
Schedule Revised Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	California Land Reuse and Revitalization Agreement
Schedule Due Date:	12/31/2013
Schedule Revised Date:	Not reported

227
WNW
1/2-1
0.850 mi.
4486 ft.

436-438 CLEMENTINA STREET **ENVIROSTOR** **S108407605**
436-438 CLEMENTINA STREET **N/A**
SAN FRANCISCO, CA 94103

Relative:
Higher

Actual:
19 ft.

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Berkeley
Facility ID:	60000545
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	06/02/2006

436-438 CLEMENTINA STREET (Continued) **S108407605**

Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.78012
Longitude:	-122.4049
APN:	3732062
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	3732062
Alias Type:	APN
Alias Name:	60000545
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported
Completed Date:	Not reported
Comments:	Not reported

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

228
WNW
1/2-1
0.861 mi.
4548 ft.

SAN FRANCISCO GAS LIGHT CO **EDR MGP** **1008407763**
HOWARD, FIFITH AND TEHAMA **N/A**
SAN FRANCISCO, CA 94123

Relative: Higher

Actual: 23 ft.

Manufactured Gas Plants:
Alternate Name:SAB FRANCISCO GAS AND ELECTRIC CO. No additional information available

---

229
NW
1/2-1
0.878 mi.
4637 ft.

PACIFIC BELL **EDR MGP** **1008407751**
140 NEW MONTGOMERY STREET **N/A**
SAN FRANCISCO, CA 94105

Relative: Higher

Actual: 26 ft.

Manufactured Gas Plants:
No additional information available

AQ230 **SKS INVESTMENTS** **HIST CORTESE** **S104025408**
SW **350 RHODE ISLAND STREET** **LUST** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103** **ENVIROSTOR**
0.887 mi.
4682 ft. **Site 1 of 2 in cluster AQ**

Relative:
Higher

Actual:
23 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: LTNKA
Reg Id: 38-1128

LUST:
Region: STATE
Global Id: T0607501017
Latitude: 37.765389
Longitude: -122.403111
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 01/27/1998
Lead Agency: SAN FRANCISCO COUNTY LOP
Case Worker: SC
Local Agency: SAN FRANCISCO COUNTY LOP
RB Case Number: 38-1128
LOC Case Number: 10968
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0607501017
Contact Type: Local Agency Caseworker
Contact Name: STEPHANIE CUSHING
Organization Name: SAN FRANCISCO COUNTY LOP
Address: 1390 MARKET STREET #210
City: SAN FRANCISCO
Email: stephanie.cushing@sfdph.org
Phone Number: Not reported

Global Id: T0607501017
Contact Type: Regional Board Caseworker
Contact Name: VIC PAL
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: vpal@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0607501017
Status: Completed - Case Closed
Status Date: 01/27/1998

Global Id: T0607501017
Status: Open - Case Begin Date
Status Date: 01/27/1998

SKS INVESTMENTS (Continued) **S104025408**

Regulatory Activities:

Global Id:	T0607501017
Action Type:	ENFORCEMENT
Date:	12/16/1999
Action:	Staff Letter

Global Id:	T0607501017
Action Type:	Other
Date:	01/01/1950
Action:	Leak Discovery

Global Id:	T0607501017
Action Type:	Other
Date:	01/01/1950
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	38-1128
Facility Status:	Case Closed
Case Number:	10968
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN FRANCISCO CO. LUST:

Region:	SAN FRANCISCO
Facility ID:	38-1128
Facility Status:	Case Closed
Case Number:	10968
Case Type:	Other ground water affected
Release Date:	1/27/1998
Discovered Date:	1/28/1998
Substance:	Gasoline
Substance Qty:	Not reported
How Discovered:	Not reported
How Stopped:	Not reported
Report Date:	1/27/1998
Case Closed:	5/29/2002
Closed Date:	Not reported
Leak Source:	Unknown
Leak Cause:	Unknown
Leak Confirmed:	5/12/1998
Entered Date:	5/12/1998
Number of Wells:	Not reported
Regional Board:	San Francisco Bay Region
Local Agency:	38000

SKS INVESTMENTS (Continued) **S104025408**

Lead Agency:	Local Agency
Program:	LOP
Responsible Party:	Amy Dictz, Norcal
RP Address:	Not reported
Operator:	Not reported
Staff Initial:	VP
Facility Staff:	SC
Cross Street:	Not reported
NOR Date:	5/12/1998
MTBE Current:	Not reported
MTBE Current Date:	Not reported
MTBE:	ND
Maximum MTBE Soil:	Not reported
Maximum MTBE GW:	Not reported
MTBE DATE:	Not reported
Review Date:	5/29/2002
Workplan Submitted:	Not reported
Assessment Underway:	5/19/1997
Pollution Characterization:	Not reported
Corrective Action Plan:	Not reported
Remediation Underway:	Not reported
Monitoring Begun:	12/19/2001
Funding:	Federal
Interim Remediation:	Not reported
Priority:	Low Priority Site
Abatement:	No Action Required - incident is minor, requiring no remedial action
Enforcement Type:	Informal Enforcement Actions,including Notices of Violations and Staff Enforcement Letters
Enforcement Due Date:	12/16/1999
Basin:	Downtown Basin
Beneficial Use:	No
Lat/Long:	Not reported
CUFID:	Not reported
Suspended:	No
Stopped Date:	Not reported
Free Product:	No
Depth to Grnd Wtr:	10'-12'
Gradient:	Not reported
Benzene:	ND
Primary Substance:	Gasoline
Enforcement Type:	2A
Amount of Free Produce:	Not reported
Benzene Test:	YES
Maximum Soil GW:	Not reported
Max Soil Concentration:	Not reported
TPH Tested:	YES
Max TPH GW:	Not reported
Max TPH Soil:	Not reported
TPH Date:	Not reported
Block:	Not reported
Lot:	Not reported
Notify:	False
TPH Current:	ND
TPH Current Date:	10/26/2001
Grnd Wtr Qualifier:	Not reported
Soil Qualifier:	Not reported
Comments:	Not reported
Summary:	Offsite Source of

SKS INVESTMENTS (Continued) **S104025408**

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Berkeley
Facility ID:	60000529
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Refer: 1248 Local Agency
Status Date:	05/13/1999
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.76515
Longitude:	-122.4031
APN:	3957002
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED, NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	3957002
Alias Type:	APN
Alias Name:	60000529
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported
Completed Date:	Not reported
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

AQ231 **DEHARO/RHODE ISLAND LIVE/WORK** **DEED** **S102564479**
SW **BETWEEN 17TH/DEHARO & 16TH/RHODE ISLAND** **VCP** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103** **ENVIROSTOR**
0.904 mi.
4773 ft. **Site 2 of 2 in cluster AQ**

Relative:
Higher

Actual:
24 ft.

DEED:

Area:	PROJECT WIDE
Sub Area:	Not reported
Site Type:	VOLUNTARY CLEANUP
Status:	CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Deed Date(s):	01/21/2003
EDR Link ID:	38990008

VCP:

Facility ID:	38990008
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	REM, ASP, FOUN, EX, NOWN, NDAM, COV
Acres:	0.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Lead Agency Description:	SAN FRANCISCO COUNTY
Project Manager:	Claude Jemison
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	200773
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	01/31/2003
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.765 / -122.4013
APN:	Block 3956 Lot 10, Block 3956 Lot 9
Past Use:	ILLEGAL DUMPING
Potential COC:	30013
Confirmed COC:	30013
Potential Description:	SOIL
Alias Name:	DEHARO
Alias Type:	Alternate Name
Alias Name:	RHODE ISLAND LIVE
Alias Type:	Alternate Name
Alias Name:	SHOWPLACE SQUARE LOFT ASSOCIATES
Alias Type:	Alternate Name
Alias Name:	WORK
Alias Type:	Alternate Name
Alias Name:	Block 3956 Lot 10
Alias Type:	APN
Alias Name:	Block 3956 Lot 9
Alias Type:	APN
Alias Name:	110033617539
Alias Type:	EPA (FRS #)
Alias Name:	200773
Alias Type:	Project Code (Site Code)
Alias Name:	38990008
Alias Type:	Envirostor ID Number

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Amendment - Order/Agreement
Completed Date:	01/04/1999
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	07/18/1996
Comments:	DTSC entered into a Voluntary Cleanup Agreement with Showplace Square Loft Associates on April 3, 1996 to oversee the site remediation activities required in the City of San Francisco's Negative Declaration adopted September 23, 1993 for the construction of the live/work

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	12/03/1999
Comments:	Soil has been impacted by lead up to 7800 parts per million. The site has been capped.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	10/23/1997
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	05/11/2004
Comments:	Cap Inspection Report signed off 5/11/04.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	08/02/2005
Comments:	Cap Inspection Report signed off 8/2/05.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	04/16/2009
Comments:	No notifications of cap damage or any activities that could disturb the cap were received during the past year. The building foundation and asphalt parking lot which serve as the cap are still present; subsequently, DTSC concludes that the cap is still in place and continues to function as an effective barrier for the impacted soil.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Public Notice
Completed Date:	09/11/2009
Comments:	The Department of Toxic Substances Control (DTSC) has published a

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Public Notice that DTSC has conducted a 5 year review of the remedy in place for the DeHaro/Rhode Island Live/Work site.This five year evaluation has concluded that the current land use controls continued to be protective of human health and environment.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/30/2009
Comments: Upon inspection, the building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/23/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/05/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/24/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/20/2010
Comments: Upon inspection by DTSC, the building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/06/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/03/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting. However, since housing is currently over the Site, the cap and the vapor barriers are inaccessible for inspection; also, it was observed that all Site uses currently comply with the terms of the Land Use Covenant.

Completed Area Name: PROJECT WIDE

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 01/21/2003
Comments: An environmental restriction was placed on the Site to prevent activities which may disturb the Cap and allow DTSC access. units.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 04/03/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/01/2007
Comments: The cap is in good condition. Upon inspection no evidence of any activities prohibited by the deed restriction was observed.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: 5 Year Review Reports
Schedule Due Date: 04/17/2014
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 0.5
NPL: NO
Regulatory Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38990008
Site Code: 200773
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Certified O&M - Land Use Restrictions Only
Status Date: 01/31/2003
Restricted Use: YES
Site Mgmt. Req.: REM, ASP, FOUN, EX, NOWN, NDAM, COV
Funding: Responsible Party
Latitude: 37.765
Longitude: -122.4013
APN: Block 3956 Lot 10, Block 3956 Lot 9
Past Use: ILLEGAL DUMPING
Potential COC: Lead
Confirmed COC: Lead, Lead
Potential Description: SOIL
Alias Name: DEHARO

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Alias Type: Alternate Name
Alias Name: RHODE ISLAND LIVE
Alias Type: Alternate Name
Alias Name: SHOWPLACE SQUARE LOFT ASSOCIATES
Alias Type: Alternate Name
Alias Name: WORK
Alias Type: Alternate Name
Alias Name: Block 3956 Lot 10
Alias Type: APN
Alias Name: Block 3956 Lot 9
Alias Type: APN
Alias Name: 110033617539
Alias Type: EPA (FRS #)
Alias Name: 200773
Alias Type: Project Code (Site Code)
Alias Name: 38990008
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Amendment - Order/Agreement
Completed Date: 01/04/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 07/18/1996
Comments: DTSC entered into a Voluntary Cleanup Agreement with Showplace Square Loft Associates on April 3, 1996 to oversee the site remediation activities required in the City of San Francisco's Negative Declaration adopted September 23, 1993 for the construction of the live/work

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 12/03/1999
Comments: Soil has been impacted by lead up to 7800 parts per million. The site has been capped.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/23/1997
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/11/2004
Comments: Cap Inspection Report signed off 5/11/04.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 08/02/2005

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Comments: Cap Inspection Report signed off 8/2/05.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 04/16/2009
Comments: No notifications of cap damage or any activities that could disturb the cap were received during the past year. The building foundation and asphalt parking lot which serve as the cap are still present; subsequently, DTSC concludes that the cap is still in place and continues to function as an effective barrier for the impacted soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 09/11/2009
Comments: The Department of Toxic Substances Control (DTSC) has published a Public Notice that DTSC has conducted a 5 year review of the remedy in place for the DeHaro/Rhode Island Live/Work site.This five year evaluation has concluded that the current land use controls continued to be protective of human health and environment.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 11/30/2009
Comments: Upon inspection, the building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/23/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/05/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/24/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/20/2010
Comments: Upon inspection by DTSC, the building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit

DEHARO/RHODE ISLAND LIVE/WORK (Continued) **S102564479**

Completed Date: 09/06/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/03/2012
Comments: DTSC conducted its annual site visit to check the condition of the cap and to verify compliance with the restrictions and requirements of the Land Use Covenant. The building exterior and sidewalks appeared to be in good condition, with no visible breaches, cracks or pitting. However, since housing is currently over the Site, the cap and the vapor barriers are inaccessible for inspection; also, it was observed that all Site uses currently comply with the terms of the Land Use Covenant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 01/21/2003
Comments: An environmental restriction was placed on the Site to prevent activities which may disturb the Cap and allow DTSC access. units.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 04/03/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/01/2007
Comments: The cap is in good condition. Upon inspection no evidence of any activities prohibited by the deed restriction was observed.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: 5 Year Review Reports
Schedule Due Date: 04/17/2014
Schedule Revised Date: Not reported

232
NNW
1/2-1
0.914 mi.
4827 ft.

199 FREMONT PROPERTY **VCP** **S103965140**
199 FREMONT STREET **ENVIROSTOR** **N/A**
SAN FRANCISCO, CA 94105

Relative:
Higher

Actual:
16 ft.

VCP:
Facility ID: 38490012
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: Not reported

199 FREMONT PROPERTY (Continued) **S103965140**

National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Lead Agency Description:	SAN FRANCISCO COUNTY
Project Manager:	Not reported
Supervisor:	Barbara Cook
Division Branch:	Cleanup Berkeley
Site Code:	201090
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: Other Agency
Status Date:	12/28/1998
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.78988 / -122.3948
APN:	3719018
Past Use:	ELECTRIC GENERATION/SUBSTATION, FUEL TERMINALS
Potential COC:	10198, 30013
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL
Alias Name:	300 HOWARD STREET PROPERTY
Alias Type:	Alternate Name
Alias Name:	FREMONT INVESTORS
Alias Type:	Alternate Name
Alias Name:	FREMONT INVESTORS PROPERTY
Alias Type:	Alternate Name
Alias Name:	3719018
Alias Type:	APN
Alias Name:	110033621114
Alias Type:	EPA (FRS #)
Alias Name:	201090
Alias Type:	Project Code (Site Code)
Alias Name:	38490012
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	10/14/1998
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	10/14/1998
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	04/21/1998
Comments:	Voluntary Cleanup Agreement No. HSA 97/98-042 signed with Fremont Properties, L.P., the property owner for document review. Comments to be provided to the SF Department of Public Health, the lead agency. Not reported

199 FREMONT PROPERTY (Continued) **S103965140**

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: Not reported
NPL: NO
Regulatory Agencies: SMBRP, SAN FRANCISCO COUNTY
Lead Agency: SAN FRANCISCO COUNTY
Program Manager: Not reported
Supervisor: Barbara Cook
Division Branch: Cleanup Berkeley
Facility ID: 38490012
Site Code: 201090
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Refer: Other Agency
Status Date: 12/28/1998
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.78988
Longitude: -122.3948
APN: 3719018
Past Use: ELECTRIC GENERATION/SUBSTATION, FUEL TERMINALS
Potential COC: * UNSPECIFIED SOLVENT MIXTURES, Lead
Confirmed COC: * UNSPECIFIED SOLVENT MIXTURES, Lead, NONE SPECIFIED
Potential Description: SOIL
Alias Name: 300 HOWARD STREET PROPERTY
Alias Type: Alternate Name
Alias Name: FREMONT INVESTORS
Alias Type: Alternate Name
Alias Name: FREMONT INVESTORS PROPERTY
Alias Type: Alternate Name
Alias Name: 3719018
Alias Type: APN
Alias Name: 110033621114
Alias Type: EPA (FRS #)
Alias Name: 201090
Alias Type: Project Code (Site Code)
Alias Name: 38490012
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 10/14/1998

199 FREMONT PROPERTY (Continued) **S103965140**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 10/14/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 04/21/1998
Comments: Voluntary Cleanup Agreement No. HSA 97/98-042 signed with Fremont Properties, L.P., the property owner for document review. Comments to be provided to the SF Department of Public Health, the lead agency.
Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

233 **241 SIXTH STREET** **HIST CORTESE** **S102008277**
WNW **241 6TH STREET** **DEED** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103** **VCP**
0.927 mi. **ENVIROSTOR**
4892 ft.

Relative:
Higher

Actual:
19 ft.

CORTESE:
Region: CORTESE
Facility County Code: 38
Reg By: CALSI
Reg Id: 38990011

DEED:
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED / OPERATION & MAINTENANCE
Deed Date(s): 06/17/1994
EDR Link ID: 38990011

VCP:
Facility ID: 38990011
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: REM, LUC, NSUB
Acres: 0.18
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program

241 SIXTH STREET (Continued) **S102008277**

Project Manager:	Claude Jemison
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	200322
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified / Operation & Maintenance
Status Date:	01/01/1995
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.77937 / -122.4062
APN:	3732078, Lot 7A - Block 3732
Past Use:	ILLEGAL DUMPING
Potential COC:	30013, 30019
Confirmed COC:	30013,30019
Potential Description:	SOIL
Alias Name:	241 SIXTH ST.
Alias Type:	Alternate Name
Alias Name:	3732078
Alias Type:	APN
Alias Name:	Lot 7A - Block 3732
Alias Type:	APN
Alias Name:	110033612847
Alias Type:	EPA (FRS #)
Alias Name:	200322
Alias Type:	Project Code (Site Code)
Alias Name:	38990011
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	06/15/2010
Comments:	The entire site is covered with an eight-story commercial/residential building and sidewalks, with no exposed soils observed. Upon inspection, the building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	10/29/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	03/29/2004
Comments:	Annual cap inspection report
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	11/03/2008
Comments:	The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or sign of damage.

241 SIXTH STREET (Continued) **S102008277**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 01/11/1995
Comments: Completed VCA. Certified Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 12/28/1994
Comments: Signed Operation and Maintenance Agreement.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 09/15/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/29/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/02/2000
Comments: Completed Five-Year Review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/15/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation Report
Completed Date: 04/30/1994
Comments: Soil and groundwater investigation report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/28/1995
Comments: Groundwater sampling report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation Report
Completed Date: 04/15/1994
Comments: Groundwater well installation and sampling report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report

241 SIXTH STREET (Continued) **S102008277**

Completed Date: 11/15/1991
Comments: Soil sampling and chemical analysis report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 06/20/1991
Comments: Phase I Site Assessment, San Francisco Parcels

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 06/28/1993
Comments: Site Assessment Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/05/2006
Comments: Report noted no problems.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 04/21/2008
Comments: RP submitted the cap inspection report for 2007 after several DTSC followup. Report should be submitted by 12/30 each year.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 04/01/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/23/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/20/1997
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan Amendment
Completed Date: 10/20/1997
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2005
Comments: Completed Second Five-Year Review.

241 SIXTH STREET (Continued) **S102008277**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/14/2011
Comments: The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/23/2012
Comments: DTSC visited the site to verify compliance with the Land Use Covenant restrictions and requirements. The entire Site is covered with an eight-story residential building and sidewalks, with no exposed soils observed. The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/18/2013
Comments: The current owner, GP/TODCO-A, Inc, conducted a site inspection on March 12, 2013 as required by the Operation and Maintenance Agreement dated 1994. The site was found to in compliance with the restrictions and requirements of the Land Use Covenant and there has been no changes to the cap condition. DTSC approved the report documenting the site inspection.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 03/07/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/11/1995
Comments: Certified Site cleanup.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 06/17/1994
Comments: Recorded Deed Restriction. The residential housing begins on the second floor. The propery was deed restricted requiring cap maintenance to ensure its overall integrity.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 01/19/1994
Comments: Signed VCA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit

241 SIXTH STREET (Continued) **S102008277**

Completed Date: 09/18/2007
Comments: No problem was noted during the inspection.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2015
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 0.18
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38990011
Site Code: 200322
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Certified / Operation & Maintenance
Status Date: 01/01/1995
Restricted Use: YES
Site Mgmt. Req.: REM, LUC, NSUB
Funding: Responsible Party
Latitude: 37.77937
Longitude: -122.4062
APN: 3732078, Lot 7A - Block 3732
Past Use: ILLEGAL DUMPING
Potential COC: Lead, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Lead, Polynuclear aromatic hydrocarbons (PAHs, Lead, Polynuclear aromatic hydrocarbons (PAHs
Potential Description: SOIL
Alias Name: 241 SIXTH ST.
Alias Type: Alternate Name
Alias Name: 3732078
Alias Type: APN
Alias Name: Lot 7A - Block 3732
Alias Type: APN
Alias Name: 110033612847
Alias Type: EPA (FRS #)
Alias Name: 200322
Alias Type: Project Code (Site Code)
Alias Name: 38990011
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

241 SIXTH STREET (Continued) **S102008277**

Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	06/15/2010
Comments:	The entire site is covered with an eight-story commercial/residential building and sidewalks, with no exposed soils observed. Upon inspection, the building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	10/29/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	03/29/2004
Comments:	Annual cap inspection report
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	11/03/2008
Comments:	The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or sign of damage.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	01/11/1995
Comments:	Completed VCA. Certified Site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Operation & Maintenance Order/Agreement
Completed Date:	12/28/1994
Comments:	Signed Operation and Maintenance Agreement.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	09/15/2006
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	09/29/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	06/02/2000
Comments:	Completed Five-Year Review.
Completed Area Name:	PROJECT WIDE

241 SIXTH STREET (Continued) **S102008277**

Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/15/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation Report
Completed Date: 04/30/1994
Comments: Soil and groundwater investigation report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/28/1995
Comments: Groundwater sampling report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation Report
Completed Date: 04/15/1994
Comments: Groundwater well installation and sampling report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 11/15/1991
Comments: Soil sampling and chemical analysis report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 06/20/1991
Comments: Phase I Site Assessment, San Francisco Parcels

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 06/28/1993
Comments: Site Assessment Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/05/2006
Comments: Report noted no problems.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 04/21/2008
Comments: RP submitted the cap inspection report for 2007 after several DTSC followup. Report should be submitted by 12/30 each year.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report

241 SIXTH STREET (Continued) **S102008277**

Completed Date: 04/01/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/23/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/20/1997
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan Amendment
Completed Date: 10/20/1997
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2005
Comments: Completed Second Five-Year Review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/14/2011
Comments: The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/23/2012
Comments: DTSC visited the site to verify compliance with the Land Use Covenant restrictions and requirements. The entire Site is covered with an eight-story residential building and sidewalks, with no exposed soils observed. The building and adjacent sidewalks appeared to be in good condition, with no significant cracks or signs of damage.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/18/2013
Comments: The current owner, GP/TODCO-A, Inc, conducted a site inspection on March 12, 2013 as required by the Operation and Maintenance Agreement dated 1994. The site was found to in compliance with the restrictions and requirements of the Land Use Covenant and there has been no changes to the cap condition. DTSC approved the report documenting the site inspection.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

241 SIXTH STREET (Continued) **S102008277**

Completed Document Type:	Correspondence
Completed Date:	03/07/2013
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Certification
Completed Date:	01/11/1995
Comments:	Certified Site cleanup.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	06/17/1994
Comments:	Recorded Deed Restriction. The residential housing begins on the second floor. The propery was deed restricted requiring cap maintenance to ensure its overall integrity.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	01/19/1994
Comments:	Signed VCA.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	09/18/2007
Comments:	No problem was noted during the inspection.
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	5 Year Review Reports
Future Due Date:	2015
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

---

234 SW 1/2-1 0.927 mi. 4894 ft.

PIONEER SOAP CO. INC.
470 CAROLINA ST.
SAN FRANCISCO, CA 94107

ENVIROSTOR **S101482019**
N/A

Relative: Higher

Actual: 33 ft.

ENVIROSTOR:

Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Berkeley
Facility ID:	38280289
Site Code:	Not reported

PIONEER SOAP CO. INC. (Continued) **S101482019**

Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: Other Agency
Status Date: 07/29/1994
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not reported
Latitude: 37.7625
Longitude: -122.4005
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED, NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 38280289
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 03/03/1982
Comments: FACILITY IDENTIFIED ID'D FROM POLKE DIRECTORY

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

235
West
1/2-1
0.930 mi.
4910 ft.

BESSIE CARMICHAEL ELEMENTARY SCHOOL **SCH** **S107735916**
355/375 7TH STREET **ENVIROSTOR** **N/A**
SAN FRANCISCO, CA 94103

Relative:
Higher

Actual:
17 ft.

SCH:

Facility ID: 38420001
Site Type: School Cleanup
Site Type Detail: School
Site Mgmt. Req.: NONE SPECIFIED
Acres: 1.4
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Shahir Haddad
Supervisor: Thomas Cota
Division Branch: Northern California Schools & Santa Susana
Site Code: 204042
Assembly: 17
Senate: 11

BESSIE CARMICHAEL ELEMENTARY SCHOOL (Continued) **S107735916**

Special Program Status:	Not reported
Status:	No Further Action
Status Date:	11/24/2003
Restricted Use:	NO
Funding:	School District
Latitude:	37.77547
Longitude:	-122.4062
APN:	NONE SPECIFIED
Past Use:	TRANSPORTATION - WAREHOUSING
Potential COC:	Copper and compounds, Copper and compounds, Polychlorinated biphenyls (PCBs, Lead, Cadmium and compounds, Arsenic, Zinc, Barium and compounds, Molybdenum, Mercury, Organic (methyl mercury, Antimony and compounds, Arsenic, Asbestos Containing Materials (ACM, Lead, Polynuclear aromatic hydrocarbons (PAHs, Copper and compounds, PCBs (unspeciated mixture, low risk, e.g. Aroclor 1016, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC:	Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs, Polynuclear aromatic hydrocarbons (PAHs, 30156-NO, PCBs (unspeciated mixture, low risk, e.g. Aroclor 1016, Asbestos Containing Materials (ACM
Potential Description:	SOIL, OTH, SOIL, SV
Alias Name:	BESSIE CARMICHAEL SCHOOL SITE
Alias Type:	Alternate Name
Alias Name:	SAN FRANCISCO USD
Alias Type:	Alternate Name
Alias Name:	SAN FRANCISCO USD-BESSIE CARMICHAEL
Alias Type:	Alternate Name
Alias Name:	204042
Alias Type:	Project Code (Site Code)
Alias Name:	38420001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/04/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	11/20/2003
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	11/16/2000
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement
Completed Date:	08/30/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

BESSIE CARMICHAEL ELEMENTARY SCHOOL (Continued) **S107735916**

Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 07/25/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 09/26/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 12/24/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 04/03/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/30/2003
Comments: DTSC determined no further action is required at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/10/2003
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: School Cleanup
Site Type Detailed: School
Acres: 1.4
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Shahir Haddad
Supervisor: Thomas Cota
Division Branch: Northern California Schools & Santa Susana
Facility ID: 38420001
Site Code: 204042
Assembly: 17

BESSIE CARMICHAEL ELEMENTARY SCHOOL (Continued) **S107735916**

Senate: 11
Special Program: Not reported
Status: No Further Action
Status Date: 11/24/2003
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: School District
Latitude: 37.77547
Longitude: -122.4062
APN: NONE SPECIFIED
Past Use: TRANSPORTATION - WAREHOUSING
Potential COC: Copper and compounds, Copper and compounds, Polychlorinated biphenyls (PCBs, Lead, Cadmium and compounds, Arsenic, Zinc, Barium and compounds, Molybdenum, Mercury, Organic (methyl mercury, Antimony and compounds, Arsenic, Asbestos Containing Materials (ACM, Lead, Polynuclear aromatic hydrocarbons (PAHs, Copper and compounds, PCBs (unspeciated mixture, low risk, e.g. Aroclor 1016, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Copper and compounds, Copper and compounds, Polychlorinated biphenyls (PCBs, Lead, Cadmium and compounds, Arsenic, Zinc, Barium and compounds, Molybdenum, Mercury, Organic (methyl mercury, Antimony and compounds, Arsenic, Asbestos Containing Materials (ACM, Lead, Polynuclear aromatic hydrocarbons (PAHs, Copper and compounds, PCBs (unspeciated mixture, low risk, e.g. Aroclor 1016, Polynuclear aromatic hydrocarbons (PAHs, Arsenic, Lead, Polynuclear aromatic hydrocarbons (PAHs, Polynuclear aromatic hydrocarbons (PAHs, 30156-NO, PCBs (unspeciated mixture, low risk, e.g. Aroclor 1016, Asbestos Containing Materials (ACM
Potential Description: SOIL, OTH, SOIL, SV
Alias Name: BESSIE CARMICHAEL SCHOOL SITE
Alias Type: Alternate Name
Alias Name: SAN FRANCISCO USD
Alias Type: Alternate Name
Alias Name: SAN FRANCISCO USD-BESSIE CARMICHAEL
Alias Type: Alternate Name
Alias Name: 204042
Alias Type: Project Code (Site Code)
Alias Name: 38420001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/04/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/20/2003
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 11/16/2000
Comments: Not reported

BESSIE CARMICHAEL ELEMENTARY SCHOOL (Continued) **S107735916**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement
Completed Date: 08/30/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 07/25/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 09/26/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 12/24/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 04/03/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/30/2003
Comments: DTSC determined no further action is required at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/10/2003
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

236
NNW
1/2-1
0.930 mi.
4912 ft.

PG AND E GAS PLANT SAN FRANCISCO — **EDR MGP** — **1008407754**
FIRST, HOWARD,FREMONT, NATOMA — **N/A**
SAN FRANCISCO, CA 94105

Relative:
Higher

Actual:
17 ft.

Manufactured Gas Plants:
No additional information available

237
SW
1/2-1
0.938 mi.
4955 ft.

FORMER S & C FORD — **HIST CORTESE** — **S104165469**
450 RHODE ISLAND STREET — **LUST** — **N/A**
SAN FRANCISCO, CA 94107 — **ENVIROSTOR**

Relative:
Higher

Actual:
44 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	LTNKA
Reg Id:	38-0990

LUST:

Region:	STATE
Global Id:	T0607500883
Latitude:	37.7641321
Longitude:	-122.4025278
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/26/1998
Lead Agency:	SAN FRANCISCO COUNTY LOP
Case Worker:	AL
Local Agency:	SAN FRANCISCO COUNTY LOP
RB Case Number:	38-0990
LOC Case Number:	10915
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0607500883
Contact Type:	Regional Board Caseworker
Contact Name:	VIC PAL
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	vpal@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0607500883
Contact Type:	Local Agency Caseworker
Contact Name:	ALBERT LEE
Organization Name:	SAN FRANCISCO COUNTY LOP
Address:	1390 MARKET STREET, #210
City:	SAN FRANCISCO
Email:	albert.lee@sfdph.org

FORMER S & C FORD (Continued) **S104165469**

Phone Number: Not reported

Status History:
Global Id: T0607500883
Status: Completed - Case Closed
Status Date: 02/26/1998

Global Id: T0607500883
Status: Open - Case Begin Date
Status Date: 12/05/1997

Regulatory Activities:
Global Id: T0607500883
Action Type: Other
Date: 01/01/1950
Action: Leak Discovery

Global Id: T0607500883
Action Type: Other
Date: 01/01/1950
Action: Leak Reported

ENVIROSTOR:
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 1.84
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Ryan Miya
Supervisor: Denise Tsuji
Division Branch: Cleanup Berkeley
Facility ID: 60000290
Site Code: Not reported
Assembly: 17
Senate: 11
Special Program: Not reported
Status: Refer: Other Agency
Status Date: 04/14/2006
Restricted Use: NO
Site Mgmt. Req.: NONE SPECIFIED
Funding: Not Applicable
Latitude: 37.76411
Longitude: -122.4029
APN: 3978-001
Past Use: VEHICLE MAINTENANCE
Potential COC: TPH-diesel, TPH-gas
Confirmed COC: TPH-diesel, TPH-gas, TPH-diesel, TPH-gas
Potential Description: OTH, SOIL
Alias Name: 3978-001
Alias Type: APN
Alias Name: CAL000070729
Alias Type: EPA Identification Number
Alias Name: 60000290
Alias Type: Envirostor ID Number

FORMER S & C FORD (Continued) **S104165469**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	02/16/2004
Comments:	This work was not conducted under any agency's oversight.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	04/11/2006
Comments:	Petroleum hydrocarbons in soil and groundwater onsite exceeds applicable screening levels. The petroleum exclusion (California Health and Safety Code; Chapter 6.8, section 25317) prohibits DTSC oversight at this property. Elevated concentrations of nickel, chromium, and asbestos may in part be due to naturally-occurring serpentine soil onsite. Naturally-occurring materials do not fall under the purview of Chapter 6.8. Therefore, DTSC recommends referral to the Local Oversight Program (San Francisco Department of Public Health) in order to adequately define the extent of petroleum hydrocarbon contamination in soil and groundwater. No further DTSC actions are warranted at this time.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Letter - Notice
Completed Date:	04/14/2006
Comments:	Not reported

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

238
West
1/2-1
0.960 mi.
5069 ft.

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO **DEED** **S106568312**
455 EIGHT STREET **VCP** **N/A**
SAN FRANCISCO, CA 94103 **ENVIROSTOR**

Relative:
Higher

Actual:
21 ft.

DEED:

Area:	PROJECT WIDE
Sub Area:	Not reported
Site Type:	VOLUNTARY CLEANUP
Status:	CERTIFIED / OPERATION & MAINTENANCE
Deed Date(s):	02/16/1996
EDR Link ID:	38920001

VCP:

Facility ID:	38920001
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Site Mgmt. Req.:	REM, ASP, FOUN, DAY, ELD, HOS, LUC, EX, NDAM, NUSE, NDEV, NSUB, SCH, FOOD, COV, RES
Acres:	1.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Claude Jemison
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	200569
Assembly:	17
Senate:	11
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified / Operation & Maintenance
Status Date:	06/18/1996
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.77333 / -122.4072
APN:	3758-126, 3758126
Past Use:	ILLEGAL DUMPING
Potential COC:	30013
Confirmed COC:	30013
Potential Description:	SOIL
Alias Name:	3758-126
Alias Type:	APN
Alias Name:	3758126
Alias Type:	APN
Alias Name:	110033617334
Alias Type:	EPA (FRS #)
Alias Name:	200569
Alias Type:	Project Code (Site Code)
Alias Name:	38920001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	09/30/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	10/01/2007
Comments:	The cap is in good condition. Upon inspection no evidence of any activities prohibited by the deed restriction was observed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction Monitoring Report
Completed Date:	07/17/2006
Comments:	No problems noted during cap inspection. DTSC concludes that final remedy is still appropriate.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/30/2010
Comments: The asphalt was observed to be in good condition and drainage areas were clear and free of debris, with only a few minor cracks observed. The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/17/2003
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/13/2010
Comments: The asphalt was observed to be in good condition and drainage areas were clear and free of debris, with only a few minor cracks observed. The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 01/05/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/04/2001
Comments: Completed Five-Year Review. Remedial actions remain protective. The cap is intact and observed in good condition. The vegetation and landscaping are well maintained.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 05/31/1996
Comments: Completed Removal Action. Area affected with lead was covered with asphalt pavement.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/17/2004
Comments: Cap Inspection Report signed off 5/17/04.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 08/03/2005
Comments: Cap Inspection Report signed off 8/3/05.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Completed Document Type: 5 Year Review Reports
Completed Date: 05/23/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 09/03/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/21/2008
Comments: The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 05/23/2011
Comments: The results of the inspection for the 5 year review will be used also in the annual inspection.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/30/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 12/14/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/05/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 06/18/1996
Comments: Certified Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 02/16/1996
Comments: Recorded Deed Restriction limiting site use to commercial and industrial uses.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Future Document Type: 5 Year Review Reports
Future Due Date: 2016
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 1.5
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Claude Jemison
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Facility ID: 38920001
Site Code: 200569
Assembly: 17
Senate: 11
Special Program: Voluntary Cleanup Program
Status: Certified / Operation & Maintenance
Status Date: 06/18/1996
Restricted Use: YES
Site Mgmt. Req.: REM, ASP, FOUN, DAY, ELD, HOS, LUC, EX, NDAM, NUSE, NDEV, NSUB, SCH, FOOD, COV, RES
Funding: Responsible Party
Latitude: 37.77333
Longitude: -122.4072
APN: 3758-126, 3758126
Past Use: ILLEGAL DUMPING
Potential COC: Lead
Confirmed COC: Lead, Lead
Potential Description: SOIL
Alias Name: 3758-126
Alias Type: APN
Alias Name: 3758126
Alias Type: APN
Alias Name: 110033617334
Alias Type: EPA (FRS #)
Alias Name: 200569
Alias Type: Project Code (Site Code)
Alias Name: 38920001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Completed Date: 10/01/2007
Comments: The cap is in good condition. Upon inspection no evidence of any activities prohibited by the deed restriction was observed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 07/17/2006
Comments: No problems noted during cap inspection. DTSC concludes that final remedy is still appropriate.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/30/2010
Comments: The asphalt was observed to be in good condition and drainage areas were clear and free of debris, with only a few minor cracks observed. The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/17/2003
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/13/2010
Comments: The asphalt was observed to be in good condition and drainage areas were clear and free of debris, with only a few minor cracks observed. The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 01/05/1996
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/04/2001
Comments: Completed Five-Year Review. Remedial actions remain protective. The cap is intact and observed in good condition. The vegetation and landscaping are well maintained.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 05/31/1996
Comments: Completed Removal Action. Area affected with lead was covered with asphalt pavement.

Completed Area Name: PROJECT WIDE

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/17/2004
Comments: Cap Inspection Report signed off 5/17/04.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 08/03/2005
Comments: Cap Inspection Report signed off 8/3/05.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/23/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 09/03/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 10/21/2008
Comments: The cap covering the Site is in good condition and remains protective of human health.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 05/23/2011
Comments: The results of the inspection for the 5 year review will be used also in the annual inspection.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/30/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 12/14/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/05/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CALIFORNIA HIGHWAY PATROL, SAN FRANCISCO (Continued) **S106568312**

Completed Document Type:	Certification
Completed Date:	06/18/1996
Comments:	Certified Site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	02/16/1996
Comments:	Recorded Deed Restriction limiting site use to commercial and industrial uses.
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	5 Year Review Reports
Future Due Date:	2016
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

---

239 **1028 HOWARD STREET** **HIST CORTESE** **S101482041**
WNW **1028 HOWARD** **ENVIROSTOR** **N/A**
1/2-1 **SAN FRANCISCO, CA 94103**
0.993 mi.
5245 ft.

Relative:
Higher

Actual:
22 ft.

CORTESE:

Region:	CORTESE
Facility County Code:	38
Reg By:	CALSI
Reg Id:	38990006

ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SMBRP, SAN FRANCISCO COUNTY
Lead Agency:	SAN FRANCISCO COUNTY
Program Manager:	Janet Naito
Supervisor:	Barbara Cook
Division Branch:	Cleanup Berkeley
Facility ID:	38990006
Site Code:	200323
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Refer: Other Agency
Status Date:	06/30/1993
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.77946
Longitude:	-122.4079
APN:	3726013
Past Use:	NONE SPECIFIED

1028 HOWARD STREET (Continued) **S101482041**

Potential COC: Lead, Polynuclear aromatic hydrocarbons (PAHs
Confirmed COC: Lead, Polynuclear aromatic hydrocarbons (PAHs, Lead, Polynuclear aromatic hydrocarbons (PAHs
Potential Description: SOIL
Alias Name: 1028 HOWARD STREET
Alias Type: Alternate Name
Alias Name: 3726013
Alias Type: APN
Alias Name: 200323
Alias Type: Project Code (Site Code)
Alias Name: 38990006
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 06/30/1993
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 01/04/1993
Comments: Further action pending successful negotiation of an agreement. Metals and PNA's are present in the soil. These contaminants are believed to have been present in fill placed at the site. Soil sampling revealed lead up to 1000 ppm and PNA's up to 1 ppm. A PEA and a risk assessment was submitted for a low income housing project at this site. The proposal includes an apartment building with living space starting on the second story above a concrete slab which covers the entire site. The PEA and associated risk assessment show that direct contact with soil containing metals and PNA's is the pathway which poses a potential health risk. The proposed project minimizes exposure by direct contact with a physical barrier and a site management plan including a deed restriction. The approval by the Departmet is subject to agreement on the terms of the deed restriction and the other conditions enumerated in the letter sent to the Redevelopment Agency.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

AR240 **PORT OF SAN FRANCISCO** **HIST Cal-Sites** **1000592328**
SSE **PIER 70** **RESPONSE** **N/A**
1/2-1 **SAN FRANCISCO, CA 94111** **ENVIROSTOR**
0.999 mi.
5277 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
14 ft.

Calsite:

Facility ID:	38440006
Region:	2
Region Name:	BERKELEY
Branch:	NC
Branch Name:	NORTH COAST
File Name:	Not reported
State Senate District:	01011982
Status:	CERTIFIED AS HAVING BEEN REMEDIED SATISFACTORILY UNDER DTSC OVERSIGHT
Status Name:	CERTIFIED
Lead Agency:	Not reported
Lead Agency:	N/A
Facility Type:	RP
Type Name:	RESPONSIBLE PARTY
NPL:	Not Listed
SIC Code:	44
SIC Name:	WATER TRANSPORTATION
Access:	Not reported
Cortese:	Not reported
Hazardous Ranking Score:	Not reported
Date Site Hazard Ranked:	Not reported
Groundwater Contamination:	Not reported
Staff Member Responsible for Site:	KHILF
Supervisor Responsible for Site:	Not reported
Region Water Control Board:	Not reported
Region Water Control Board Name:	Not reported
Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported
State Assembly District Code:	13
State Senate District Code:	03
Facility ID:	38440006
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	01011982
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0

PORT OF SAN FRANCISCO (Continued) **1000592328**

For Industrial Reuse: 0
For Residential Reuse: 0
Unknown Type: 0
Alternate Address: PIER 70
Alternate City,St,Zip: SAN FRANCISCO, CA 94111
Background Info: The current address for Pier 70 is at the beginning of 20th Street in San Francisco, California. Illinois Street borders the site to the west, 22nd Street and the Potrero Power Plant to the south, China (Central) Basin to the north, and the San Francisco Bay to the east. There are many buildings associated with the Pier. Several of the buildings, 6, 12 (operating area 2 is inside 12), 14 (a storage shed), and 21 (operational area 1 is inside building 21), and a fire damaged area (between Pier 7 and Pier 8) underwent cleanup in 1981, 1984, and 1986 under the oversight of the Department of Toxic Substances Control (DTSC). In 1981, IT Corporation conducted a cleanup of polychlorinated biphenyls (PCBs) at the site. Old leaking transformers containing PCBs were removed from operational areas 1 and 2, and the fire damaged area. Walls, floors, and asphalt driveways were sampled with wipes. PCB (Arochlor 1260) results before cleanup ranged from 17 to 5,888 ug/wipe in operational area 1, from 3 to 229 ug/wipe in operational area 2, and from less than 1 microgram per wipe are (ug/wipe area) to 49,200 ug/wipe area in the fire damaged area. Samples taken from the floor area (asphalt floor) ranged from non-detect to 62 parts per million (ppm). Aroclor 1260 was not detected in samples of mud, water or mussels in the immediate area. After decontamination, confirmation samples were taken in operational area 1 and 2. Samples collected in operational area 1 ranged from 4 to 80 ug/wipe, and from less than 1 ug/wipe 32 ug/wipe for operational area 2. The fire damaged area results ranged from non-detect to 82 ug/wipe. The asphalt confirmation samples were all within residential cleanup levels. The cleanup level for Aroclor 1260 was 220 ug/wipe area for residential and 1,000 ug/wipe area for industrial. Building 6 was used to store some hazardous materials. Surface soil (zero to six inches depth) contained lead up to 3,340 ppm, copper up to 210 ppm, zinc up to 3,040 ppm, and polycyclic aromatic hydrocarbons (PAHs) up to 18.9 ppm. Subsurface soil (20 inches depth) sample results showed lead up to 2,300 ppm, copper up to 4,000 ppm and zinc up to 2,500 ppm. The soil was excavated to a one to two-feet depth in front of the loading dock and approximately ten feet out from the edge of the dock. The area was repaved. No confirmation sample results are available. In 1986, lead and cadmium were found in heavy dust deposits on wall beams and the floor of building 6. Before the 1986 cleanup, composite samples were taken of the floor and wall beam dust. Results showed up to 7,900 milligrams/kilograms (mg/kg) lead, 21,000 mg/kg zinc, 47 mg/kg cadmium, and 1,300 mg/kg copper. Only lead was above the United States Environmental Protection Agency (US EPA) Region 9 residential and industrial PRGs of 400 mg/kg and 750 mg/kg respectively. The dust was removed and the building was decontaminated by high-pressure water scrubbing of the walls, floor, and ceiling by IT Corporation.
Comments Date: 01011982
Comments: Several hundred drums of contaminated waste removed.
Comments Date: 01011982

PORT OF SAN FRANCISCO (Continued) **1000592328**

Comments:	This certification was confirmed by a report prepared by the
Comments Date:	01011982
Comments:	Auditor General. The Auditor General conducted an audit of
Comments Date:	01011982
Comments:	the Department's records to confirm a list of sites where
Comments Date:	01011982
Comments:	the Department was involved in the cleanup and the cleanup
Comments Date:	01011982
Comments:	had been completed. This Auditor General list became the
Comments Date:	01011982
Comments:	basis for our historical certification information. Many of
Comments Date:	01011982
Comments:	the sites on this list were handled by our Surveillance and
Comments Date:	01011982
Comments:	Enforcement Staff. Much of this work was in response to
Comments Date:	01011982
Comments:	complaints from the public or reports from industry and the
Comments Date:	01011982
Comments:	response action may have only addressed the immediate
Comments Date:	01011982
Comments:	problem and not the entire facility.
Comments Date:	01181996
Comments:	Our records do not indicate the actual date this site was
Comments Date:	01181996
Comments:	certified. Our records show 1982 as the certification year.
Comments Date:	01181996
Comments:	We have used 01/01/1982 because this gives us the earliest
Comments Date:	01181996
Comments:	statute of limitations.
Comments Date:	01181996
Comments:	Not reported
ID Name:	Not reported
ID Value:	Not reported
Alternate Name:	PORT OF SAN FRANCISCO
Special Programs Code:	Not reported
Special Programs Name:	Not reported

RESPONSE:

Facility ID:	38440006
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	30
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Katharine Hilf
Supervisor:	Karen Toth
Division Branch:	Cleanup Berkeley
Site Code:	Not reported
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	17
Senate:	11
Special Program Status:	Not reported
Status:	Certified
Status Date:	01/01/1982
Restricted Use:	NO

PORT OF SAN FRANCISCO (Continued) **1000592328**

Funding:	Responsible Party
Latitude:	37.7629
Longitude:	-122.3866
APN:	4046-002, 4046002, 4052-001, 4052001, 9900-060, 9900-070, 9900070
Past Use:	SHIPYARD - SHIP BUILDING/REPAIR, SHIPYARD - TERMINAL
Potential COC:	Lead, Polychlorinated biphenyls (PCBs
Confirmed COC:	Lead, Polychlorinated biphenyls (PCBs, Polychlorinated biphenyls (PCBs, Lead
Potential Description:	SOIL
Alias Name:	4046-002
Alias Type:	APN
Alias Name:	4046002
Alias Type:	APN
Alias Name:	4052-001
Alias Type:	APN
Alias Name:	4052001
Alias Type:	APN
Alias Name:	9900-060
Alias Type:	APN
Alias Name:	9900-070
Alias Type:	APN
Alias Name:	9900070
Alias Type:	APN
Alias Name:	110009546358
Alias Type:	EPA (FRS #)
Alias Name:	38440006
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Certification
Completed Date:	01/01/1982
Comments:	Several hundred drums of contaminated waste removed. This certification was confirmed by a report prepared by the Auditor General. The Auditor General conducted an audit of the Department's records to confirm a list of sites where the Department was involved in the cleanup and the cleanup had been completed. This Auditor General list became the basis for our historical certification information. Many of the sites on this list were handled by our Surveillance and Enforcement Staff. Much of this work was in response to complaints from the public or reports from industry and the response action may have only addressed the immediate problem and not the entire facility.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	04/09/2003
Comments:	This is currently a soil pile on site which requires further action. Hazardous Waste Management Program is coordinating the removal of the pile.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	08/01/1998
Comments:	Additional soil and sediment sampling needed at site.

PORT OF SAN FRANCISCO (Continued) **1000592328**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	03/01/2001
Comments:	Additional soil investigation needed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Workplan
Completed Date:	08/14/2003
Comments:	Proposal for removal of PCBs at Building 50
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

ENVIROSTOR:

Site Type:	State Response
Site Type Detailed:	State Response or NPL
Acres:	30
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Katharine Hilf
Supervisor:	Karen Toth
Division Branch:	Cleanup Berkeley
Facility ID:	38440006
Site Code:	Not reported
Assembly:	17
Senate:	11
Special Program:	Not reported
Status:	Certified
Status Date:	01/01/1982
Restricted Use:	NO
Site Mgmt. Req.:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.7629
Longitude:	-122.3866
APN:	4046-002, 4046002, 4052-001, 4052001, 9900-060, 9900-070, 9900070
Past Use:	SHIPYARD - SHIP BUILDING/REPAIR, SHIPYARD - TERMINAL
Potential COC:	Lead, Polychlorinated biphenyls (PCBs
Confirmed COC:	Lead, Polychlorinated biphenyls (PCBs, Polychlorinated biphenyls (PCBs, Lead
Potential Description:	SOIL
Alias Name:	4046-002
Alias Type:	APN
Alias Name:	4046002
Alias Type:	APN
Alias Name:	4052-001
Alias Type:	APN
Alias Name:	4052001

PORT OF SAN FRANCISCO (Continued) **1000592328**

Alias Type:	APN
Alias Name:	9900-060
Alias Type:	APN
Alias Name:	9900-070
Alias Type:	APN
Alias Name:	9900070
Alias Type:	APN
Alias Name:	110009546358
Alias Type:	EPA (FRS #)
Alias Name:	38440006
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Certification
Completed Date:	01/01/1982
Comments:	Several hundred drums of contaminated waste removed. This certification was confirmed by a report prepared by the Auditor General. The Auditor General conducted an audit of the Department's records to confirm a list of sites where the Department was involved in the cleanup and the cleanup had been completed. This Auditor General list became the basis for our historical certification information. Many of the sites on this list were handled by our Surveillance and Enforcement Staff. Much of this work was in response to complaints from the public or reports from industry and the response action may have only addressed the immediate problem and not the entire facility.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	04/09/2003
Comments:	This is currently a soil pile on site which requires further action. Hazardous Waste Management Program is coordinating the removal of the pile.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	08/01/1998
Comments:	Additional soil and sediment sampling needed at site.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	03/01/2001
Comments:	Additional soil investigation needed.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Workplan
Completed Date:	08/14/2003
Comments:	Proposal for removal of PCBs at Building 50

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported

PORT OF SAN FRANCISCO (Continued) **1000592328**

Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

AR241 **PIER 70** **Notify 65** **S100179568**
SSE **20TH STREET** **N/A**
1/2-1 **SAN FRANCISCO, CA 92270**
0.999 mi.
5277 ft. **Site 2 of 2 in cluster AR**

Relative:
Higher

Actual:
14 ft.

Notify 65:
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Incident Description: 92270

Count: 35 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SAN FRANCISCO	S112926728	CALTRANS DIST 4/CONSTRUCTION	HWY 80 @ PM 4.0-5.9	94107	HAZNET
SAN FRANCISCO	S112928282	CALTRANS DIST 4/CONSTR	HWY 80 PM 4.7-5.9	94103	HAZNET
SAN FRANCISCO	S112948599	CALTRANS DIST 4/CONSTR/EA04-291004	RTE 101 PM R5.1/R5.5	94103	HAZNET
SAN FRANCISCO	S112967225	CIRQUE DU SOLEIL	74 MISSION ROCK ST	94158	HAZNET
SAN FRANCISCO	S112982203	CALTRANS D-4/RELOCATE EXISTING UTI	4TH ST BETWEEN HARRISON ST & B	94103	HAZNET
SAN FRANCISCO	S112998268	CIRQUE DU SOLEIL	74 MISSION ROCK ST	94158	HAZNET
SAN FRANCISCO	S113018134	CCSF-DPW EMBARCADERO ROADWAY	KING ST BETW 6TH AND 4TH ST	94107	HAZNET
SAN FRANCISCO	S113068022	CALTRANS	I-280 FROM ROUTE 1 TO MISSION	94105	HAZNET
SAN FRANCISCO	S113075286	CALTRANS	ROUTE 280 BETWEEN 6TH AND 25TH	94103	HAZNET
SAN FRANCISCO	S113086486	CALTRANS DISTRICT 4	4TH ST -16TH ST ON I80	94103	HAZNET
SAN FRANCISCO	S113086765	STUART-DEAN INC	1501 3RD ST	94107	HAZNET
SAN FRANCISCO	S113128607	CALTRANS DIST 4/CONSTR/04-435V4	RTE 80 PM 4.9-5.9(FROM 5TH ST	94105	HAZNET
SAN FRANCISCO	S113133195	AUTO RETURN - PIER 70	END OF 22ND ST PIER 70	94107	HAZNET
SAN FRANCISCO	S113134234	CITY & COUNTY OF SAN FRANCISCO/DPH	900 BLOCK OF 4TH ST	94107	HAZNET
SAN FRANCISCO	S113162817	B & J SEWING	3450 3RD STREET, STE 1B	94103	HAZNET
SAN FRANCISCO	S113171327	MANHOLE 5276	INTERSECTION OF 3RD AND BERRY	94107	HAZNET
SAN FRANCISCO	S113173377	CALTRANS/KING ST RAMPS	KING ST BTWN 4TH AND 7TH ST	94107	HAZNET
SAN FRANCISCO	S113174402	CALTRANS DISTRICT 4	I80/4TH ST TO 16TH ST	94103	HAZNET
SAN FRANCISCO	S113174538	CITY AND CO OF S F 3RD ST BRIDGE	3RD ST BRIDGE AT MISSION CHANN	94107	HAZNET
SAN FRANCISCO	S113174591	CALTRANS DIST 4/CONSTR	HWY 80 SAN FRAN/OAKLAND BAY BR	94105	HAZNET
SAN FRANCISCO	S113174713	CCSF-MUNI 3RD ST LIGHT RAIL	3RD ST CORRIDOR	94103	HAZNET
SAN FRANCISCO	S113177461	CALTRANS WEST APPROACH TO THE SFOB	ROUTE 80 FROM 5TH ST	94105	HAZNET
SAN FRANCISCO	S113179014	NEKTAR THERAPEUTICS	455 MISSION BAY SOUTH BLVD BLD	94158	HAZNET
SAN FRANCISCO	S113458188	CIRQUE DU SOLEIL - OVO	74 MISSION ROCK ST	94158	HAZNET
SAN FRANCISCO	S113458754	CITY & COUNTY OF SAN FRANCISCO	CORNER OF MISSION RD & 3RD ST	94158	HAZNET
SAN FRANCISCO	S113467622	CALTRANS D-4/CONSTR/EA-163734	RTE 101 PM 9.2-9.8 & RTE 1	94105	HAZNET
SAN FRANCISCO	S113747813	MISSION PLACE, LLC	250 KING & 260 KING ST	94107	EMI
SAN FRANCISCO	S113782066	URBAN HOUSING MB III LLC	1155 4TH ST	94158	HAZNET
SAN FRANCISCO	S113783392	CALTRANS D-4/EA04-2A1404	RTE 80 WB PM 0.0 TO 5.0	94103	HAZNET
SAN FRANCISCO	S113798762	US INNOVATION CTR USIC, BAYER HEAL	455 MISSION BAY BLVD SOUTH STE	94158	HAZNET
SAN FRANCISCO	S113800209	INNOVA DYNAMICS	455 MISSION BAY BLVD SOUTH STE	94158	HAZNET
GUALALA	U001595290	PACIFIC BELL (TD-043)	HIGHWAY ONE	94107	HIST UST
SAN FRANCISCO	U003906400	MISSION	1501 03RD ST		UST
SAN FRANCISCO	U003916313	MISSION BAY	1500 03RD ST		UST
SAN FRANCISCO	U004124296	UCSF/MISSION BAY	1550 04TH ST.		UST

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 10/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 10/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/09/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 62

Source: EPA
Telephone: N/A
Last EDR Contact: 10/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/29/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 72

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 10/09/2012
Date Made Active in Reports: 12/20/2012
Number of Days to Update: 72

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/11/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 05/29/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 72

Source: EPA
Telephone: 703-412-9810
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 06/17/2013
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 104

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 06/17/2013
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 104

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/15/2013
Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/17/2013
Date Made Active in Reports: 02/15/2013
Number of Days to Update: 29

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 09/05/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 35

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 09/05/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 35

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 08/19/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 50

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 08/19/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST: Geotracker's Leaking Underground Fuel Tank Report
Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 29

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Varies

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC: Statewide SLIC Cases
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Semi-Annually

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 08/27/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 07/30/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 94

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013
Date Data Arrived at EDR: 03/01/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 42

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012
Date Data Arrived at EDR: 08/28/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 49

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011
Number of Days to Update: 59

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 184
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/01/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

State and tribal registered storage tank lists

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 29
Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities
A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 08/01/2009
Date Data Arrived at EDR: 09/10/2009
Date Made Active in Reports: 10/01/2009
Number of Days to Update: 21
Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013
Date Data Arrived at EDR: 02/06/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 65
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 45
Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 07/29/2013
Date Data Arrived at EDR: 08/01/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 92

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 02/28/2013
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 43

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011
Date Data Arrived at EDR: 05/11/2011
Date Made Active in Reports: 06/14/2011
Number of Days to Update: 34

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 70

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 11/07/2012
Date Made Active in Reports: 04/12/2013
Number of Days to Update: 156

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/01/2014
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Properties
Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 09/05/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 35

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012
Date Data Arrived at EDR: 10/02/2012
Date Made Active in Reports: 10/16/2012
Number of Days to Update: 14

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/24/2013
Date Data Arrived at EDR: 06/25/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39
Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137
Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: No Update Planned

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30
Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/19/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 28
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 04/26/2013
Date Made Active in Reports: 05/16/2013
Number of Days to Update: 20
Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 08/06/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 22

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 09/04/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Quarterly

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 09/05/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 35

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 09/03/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 37

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007
Date Data Arrived at EDR: 11/19/2008
Date Made Active in Reports: 03/30/2009
Number of Days to Update: 131

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 09/23/2009
Date Data Arrived at EDR: 09/23/2009
Date Made Active in Reports: 10/01/2009
Number of Days to Update: 8

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013
Date Data Arrived at EDR: 04/25/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/01/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 06/14/2013
Date Data Arrived at EDR: 06/17/2013
Date Made Active in Reports: 08/21/2013
Number of Days to Update: 65

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 09/11/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 33

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 09/11/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 55

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 03/12/2013
Date Data Arrived at EDR: 05/01/2013
Date Made Active in Reports: 06/25/2013
Number of Days to Update: 55

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 10/30/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

LDS: Land Disposal Sites Listing

The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 29

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing

The State Water Resources Control Board and nine Regional Water Quality Control Boards partner with the Department of Defense (DoD) through the Defense and State Memorandum of Agreement (DSMOA) to oversee the investigation and remediation of water quality issues at military facilities.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 29

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 10/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 07/11/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 10/02/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 11/06/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 03/13/2013
Number of Days to Update: 15

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/07/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/26/2013
Date Data Arrived at EDR: 06/11/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 143

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 09/13/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/28/2013
Next Scheduled EDR Contact: 09/09/2013
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 28

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 09/05/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/31/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 44

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/30/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006
Date Data Arrived at EDR: 09/29/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 64

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011
Date Data Arrived at EDR: 11/10/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 10/09/2014
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2013
Date Data Arrived at EDR: 07/17/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 107

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 91

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 09/30/2013
Date Data Arrived at EDR: 10/09/2013
Date Made Active in Reports: 11/01/2013
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/08/2013
Date Data Arrived at EDR: 03/21/2013
Date Made Active in Reports: 07/10/2013
Number of Days to Update: 111

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 09/11/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012
Date Data Arrived at EDR: 05/25/2012
Date Made Active in Reports: 07/10/2012
Number of Days to Update: 46

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013
Number of Days to Update: 52

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 08/26/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Biennially

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NPDES: NPDES Permits Listing

A listing of NPDES permits, including stormwater.

Date of Government Version: 08/19/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 50

Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 08/19/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Quarterly

UIC: UIC Listing
A listing of underground control injection wells.

Date of Government Version: 08/21/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 30
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 09/17/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Varies

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 07/05/2013
Date Data Arrived at EDR: 07/05/2013
Date Made Active in Reports: 08/26/2013
Number of Days to Update: 52
Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 10/01/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List
The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 10/21/1993
Date Data Arrived at EDR: 11/01/1993
Date Made Active in Reports: 11/19/1993
Number of Days to Update: 18
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: No Update Planned

DRYCLEANERS: Cleaner Facilities
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 09/10/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 35
Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/24/2012
Data Release Frequency: Annually

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 08/09/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 56

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 07/16/2013
Date Made Active in Reports: 08/26/2013
Number of Days to Update: 41

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 10/15/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2010
Date Data Arrived at EDR: 06/25/2013
Date Made Active in Reports: 08/22/2013
Number of Days to Update: 58

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 09/27/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013
Date Data Arrived at EDR: 03/15/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 56

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/27/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Quarterly

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/01/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/19/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 28
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 08/29/2013
Date Data Arrived at EDR: 09/13/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 31
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 09/11/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 10/15/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010
Date Data Arrived at EDR: 01/03/2011
Date Made Active in Reports: 03/21/2011
Number of Days to Update: 77
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 09/13/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

HWT: Registered Hazardous Waste Transporter Database
A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 07/15/2013
Date Data Arrived at EDR: 07/16/2013
Date Made Active in Reports: 08/12/2013
Number of Days to Update: 27
Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 10/15/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Quarterly

HWP: EnviroStor Permitted Facilities Listing
Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 08/28/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 44

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 08/27/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/12/2013
Date Data Arrived at EDR: 08/20/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 49

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 08/15/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/08/2013
Date Made Active in Reports: 08/27/2013
Number of Days to Update: 19

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 10/25/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013
Date Data Arrived at EDR: 02/14/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 09/24/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011
Date Data Arrived at EDR: 05/18/2012
Date Made Active in Reports: 05/25/2012
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/16/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: N/A

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 04/15/2013
Date Data Arrived at EDR: 07/03/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 72

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/04/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/30/2013
Date Made Active in Reports: 05/10/2013
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-5962
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Annually

EPA WATCH LIST: EPA WATCH LIST
EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 09/13/2013
Number of Days to Update: 31

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 08/07/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 07/25/2013
Date Data Arrived at EDR: 07/26/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 14

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Semi-Annually

Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 07/25/2013
Date Data Arrived at EDR: 07/26/2013
Date Made Active in Reports: 08/20/2013
Number of Days to Update: 25

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA Facility List

Cupa Facility List

Date of Government Version: 06/20/2013
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 08/21/2013
Number of Days to Update: 61

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA Facility Listing

Cupa facility list.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/02/2013
Date Made Active in Reports: 08/22/2013
Number of Days to Update: 20

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 07/24/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 16

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 06/20/2013
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 08/09/2013
Number of Days to Update: 39

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 10/04/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Varies

CONTRA COSTA COUNTY:

Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 46

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA Facility List
Cupa Facility list

Date of Government Version: 01/09/2013
Date Data Arrived at EDR: 01/10/2013
Date Made Active in Reports: 02/25/2013
Number of Days to Update: 46

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 08/20/2013
Date Data Arrived at EDR: 08/23/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 46

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA Resources List

Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 06/30/2013
Date Data Arrived at EDR: 07/16/2013
Date Made Active in Reports: 07/24/2013
Number of Days to Update: 8

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

HUMBOLDT COUNTY:

CUPA Facility List

CUPA facility list.

Date of Government Version: 08/09/2013
Date Data Arrived at EDR: 08/09/2013
Date Made Active in Reports: 08/22/2013
Number of Days to Update: 13

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 08/09/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

IMPERIAL COUNTY:

CUPA Facility List

Cupa facility list.

Date of Government Version: 07/26/2013
Date Data Arrived at EDR: 08/09/2013
Date Made Active in Reports: 08/22/2013
Number of Days to Update: 13

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

INYO COUNTY:

CUPA Facility List

Cupa facility list.

Date of Government Version: 09/10/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 33

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

KERN COUNTY:

Underground Storage Tank Sites & Tank Listing

Kern County Sites and Tanks Listing.

Date of Government Version: 08/31/2010
Date Data Arrived at EDR: 09/01/2010
Date Made Active in Reports: 09/30/2010
Number of Days to Update: 29

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 08/07/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA Facility List

A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/22/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 42

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

LAKE COUNTY:

CUPA Facility List

Cupa facility list

Date of Government Version: 01/23/2013
Date Data Arrived at EDR: 01/25/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 33

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Varies

LOS ANGELES COUNTY:

San Gabriel Valley Areas of Concern

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: EPA Region 9
Telephone: 415-972-3178
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: No Update Planned

HMS: Street Number List

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 03/28/2013
Date Data Arrived at EDR: 06/17/2013
Date Made Active in Reports: 08/21/2013
Number of Days to Update: 65

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

List of Solid Waste Facilities

Solid Waste Facilities in Los Angeles County.

Date of Government Version: 07/22/2013
Date Data Arrived at EDR: 07/22/2013
Date Made Active in Reports: 08/26/2013
Number of Days to Update: 35

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 10/22/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Varies

City of Los Angeles Landfills

Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 03/05/2009
Date Data Arrived at EDR: 03/10/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 29

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 07/17/2013
Next Scheduled EDR Contact: 11/04/2013
Data Release Frequency: Varies

Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 01/30/2013
Date Data Arrived at EDR: 02/21/2013
Date Made Active in Reports: 03/25/2013
Number of Days to Update: 32
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Annually

City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 07/31/2013
Date Data Arrived at EDR: 08/01/2013
Date Made Active in Reports: 08/27/2013
Number of Days to Update: 26
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Semi-Annually

City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/28/2003
Date Data Arrived at EDR: 10/23/2003
Date Made Active in Reports: 11/26/2003
Number of Days to Update: 34
Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Annually

City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 07/15/2013
Date Data Arrived at EDR: 07/18/2013
Date Made Active in Reports: 08/20/2013
Number of Days to Update: 33
Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 10/09/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 09/20/2013
Date Data Arrived at EDR: 09/24/2013
Date Made Active in Reports: 10/18/2013
Number of Days to Update: 24
Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

MARIN COUNTY:

Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 11/26/2012
Date Data Arrived at EDR: 11/28/2012
Date Made Active in Reports: 01/21/2013
Number of Days to Update: 54
Source: Public Works Department Waste Management
Telephone: 415-499-6647
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 08/23/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 42

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

MONO COUNTY:

CUPA Facility List
CUPA Facility List

Date of Government Version: 09/04/2013
Date Data Arrived at EDR: 09/05/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 39

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 09/11/2013
Date Data Arrived at EDR: 09/12/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 32

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

NAPA COUNTY:

Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 12/05/2011
Date Data Arrived at EDR: 12/06/2011
Date Made Active in Reports: 02/07/2012
Number of Days to Update: 63

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: No Update Planned

Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/16/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 23

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 05/29/2013
Date Data Arrived at EDR: 05/30/2013
Date Made Active in Reports: 07/15/2013
Number of Days to Update: 46

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

ORANGE COUNTY:

List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 56

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Annually

List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 56

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Quarterly

List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/13/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 56

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Quarterly

PLACER COUNTY:

Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 08/22/2013
Date Data Arrived at EDR: 08/22/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 49

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 08/20/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Semi-Annually

RIVERSIDE COUNTY:

Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 07/18/2013
Date Data Arrived at EDR: 07/18/2013
Date Made Active in Reports: 07/24/2013
Number of Days to Update: 6

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Quarterly

Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 07/18/2013
Date Data Arrived at EDR: 07/18/2013
Date Made Active in Reports: 08/20/2013
Number of Days to Update: 33
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 05/03/2013
Date Data Arrived at EDR: 07/08/2013
Date Made Active in Reports: 07/24/2013
Number of Days to Update: 16
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 05/03/2013
Date Data Arrived at EDR: 07/08/2013
Date Made Active in Reports: 08/23/2013
Number of Days to Update: 46
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

SAN BERNARDINO COUNTY:

Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 09/03/2013
Date Data Arrived at EDR: 09/03/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 37
Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 08/08/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

Hazardous Materials Management Division Database
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 09/23/2013
Date Data Arrived at EDR: 09/24/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 23
Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Quarterly

Solid Waste Facilities
San Diego County Solid Waste Facilities.

Date of Government Version: 10/31/2012
Date Data Arrived at EDR: 11/06/2012
Date Made Active in Reports: 11/30/2012
Number of Days to Update: 24
Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

Environmental Case Listing
The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24
Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10
Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Quarterly

Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/29/2010
Date Data Arrived at EDR: 03/10/2011
Date Made Active in Reports: 03/15/2011
Number of Days to Update: 5
Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 11/08/2013
Next Scheduled EDR Contact: 02/24/2014
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 09/25/2013
Date Data Arrived at EDR: 09/27/2013
Date Made Active in Reports: 10/18/2013
Number of Days to Update: 21
Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 08/26/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 44
Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

SAN MATEO COUNTY:

Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 07/02/2013
Date Data Arrived at EDR: 07/05/2013
Date Made Active in Reports: 08/23/2013
Number of Days to Update: 49
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/13/2013
Next Scheduled EDR Contact: 09/30/2013
Data Release Frequency: Annually

Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 09/16/2013
Date Data Arrived at EDR: 09/17/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 29
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28
Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

SANTA CLARA COUNTY:

Cupa Facility List
Cupa facility list

Date of Government Version: 09/03/2013
Date Data Arrived at EDR: 09/04/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 36
Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Varies

HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22
Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 09/03/2013
Date Data Arrived at EDR: 09/06/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 38
Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 09/03/2013
Next Scheduled EDR Contact: 12/16/2013
Data Release Frequency: Annually

Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 08/14/2013
Date Data Arrived at EDR: 08/16/2013
Date Made Active in Reports: 10/08/2013
Number of Days to Update: 53

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 08/08/2013
Next Scheduled EDR Contact: 11/25/2013
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA Facility List
CUPA facility listing.

Date of Government Version: 08/22/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 44

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 09/09/2013
Date Data Arrived at EDR: 09/10/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 34

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 08/22/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Varies

SOLANO COUNTY:

Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 09/18/2013
Date Data Arrived at EDR: 09/20/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 27

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 09/18/2013
Date Data Arrived at EDR: 09/24/2013
Date Made Active in Reports: 10/18/2013
Number of Days to Update: 24

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

SONOMA COUNTY:

Cupa Facility List
Cupa Facility list

Date of Government Version: 07/05/2013
Date Data Arrived at EDR: 07/05/2013
Date Made Active in Reports: 08/21/2013
Number of Days to Update: 47

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Varies

Leaking Underground Storage Tank Sites

A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 07/02/2013
Date Data Arrived at EDR: 07/05/2013
Date Made Active in Reports: 08/12/2013
Number of Days to Update: 38

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 09/30/2013
Next Scheduled EDR Contact: 01/13/2014
Data Release Frequency: Quarterly

SUTTER COUNTY:

Underground Storage Tanks

Underground storage tank sites located in Sutter county.

Date of Government Version: 09/10/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 33

Source: Sutter County Department of Agriculture
Telephone: 530-822-7500
Last EDR Contact: 09/10/2013
Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Semi-Annually

TUOLUMNE COUNTY:

CUPA Facility List

Cupa facility list

Date of Government Version: 01/14/2013
Date Data Arrived at EDR: 01/16/2013
Date Made Active in Reports: 02/27/2013
Number of Days to Update: 42

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Varies

VENTURA COUNTY:

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 08/19/2013
Date Data Arrived at EDR: 08/27/2013
Date Made Active in Reports: 10/10/2013
Number of Days to Update: 44

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 08/19/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Quarterly

Inventory of Illegal Abandoned and Inactive Sites

Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 10/07/2013
Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Annually

Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 08/19/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Quarterly

Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 05/28/2013
Date Data Arrived at EDR: 06/24/2013
Date Made Active in Reports: 08/12/2013
Number of Days to Update: 49
Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 10/28/2013
Next Scheduled EDR Contact: 02/11/2014
Data Release Frequency: Quarterly

Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 08/29/2013
Date Data Arrived at EDR: 09/18/2013
Date Made Active in Reports: 10/16/2013
Number of Days to Update: 28
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Quarterly

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 06/24/2013
Date Data Arrived at EDR: 06/26/2013
Date Made Active in Reports: 08/20/2013
Number of Days to Update: 55
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 09/23/2013
Next Scheduled EDR Contact: 01/08/2014
Data Release Frequency: Annually

YUBA COUNTY:

CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/05/2013
Date Made Active in Reports: 08/22/2013
Number of Days to Update: 17
Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 11/04/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/19/2013
Next Scheduled EDR Contact: 12/02/2013
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 07/19/2012
Date Made Active in Reports: 08/28/2012
Number of Days to Update: 40

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/18/2013
Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/07/2013
Date Made Active in Reports: 09/10/2013
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 11/07/2013
Next Scheduled EDR Contact: 02/17/2014
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 07/24/2013
Date Made Active in Reports: 08/19/2013
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/21/2013
Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 06/21/2013
Date Made Active in Reports: 08/05/2013
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/23/2013
Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 08/09/2013
Date Made Active in Reports: 09/27/2013
Number of Days to Update: 49

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/16/2013
Next Scheduled EDR Contact: 12/30/2013
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: Rextag Strategies Corp.
Telephone: (281) 769-2247
U.S. Electric Transmission and Power Plants Systems Digital GIS Data

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

MISSION ROCK
PIER 48
SAN FRANCISCO, CA 94158

TARGET PROPERTY COORDINATES

Latitude (North):	37.7748 - 37° 46' 29.28''
Longitude (West):	122.3883 - 122° 23' 17.88''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	553871.1
UTM Y (Meters):	4180800.0
Elevation:	5 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	37122-G4 SAN FRANCISCO NORTH, CA
Most Recent Revision:	1999
East Map:	37122-G3 OAKLAND WEST, CA
Most Recent Revision:	1980

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 5 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
SAN FRANCISCO, CA	Not Available

Flood Plain Panel at Target Property: Not Reported

Additional Panels in search area: Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
SAN FRANCISCO NORTH	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
A1	0 - 1/8 Mile North	NE, E
A2	0 - 1/8 Mile NNW	NE
B4	1/8 - 1/4 Mile West	NE
5	1/4 - 1/2 Mile WNW	Not Reported
6	1/4 - 1/2 Mile NNE	NE
C7	1/4 - 1/2 Mile NW	SW
C8	1/4 - 1/2 Mile NW	SW
9	1/4 - 1/2 Mile WNW	SW
D10	1/4 - 1/2 Mile NNW	SW

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
D11	1/4 - 1/2 Mile NNW	Varies
D12	1/4 - 1/2 Mile NNW	Not Reported
13	1/4 - 1/2 Mile SW	NE
14	1/4 - 1/2 Mile NNW	Varies
15	1/2 - 1 Mile WNW	SE
16	1/2 - 1 Mile North	SE
E17	1/2 - 1 Mile NW	SW
E18	1/2 - 1 Mile NW	SW
19	1/2 - 1 Mile South	E
F20	1/2 - 1 Mile NW	Varies
G21	1/2 - 1 Mile WNW	SW
G22	1/2 - 1 Mile WNW	SW
G23	1/2 - 1 Mile West	Varies
G24	1/2 - 1 Mile West	NE
F25	1/2 - 1 Mile NW	NE
F26	1/2 - 1 Mile NW	NE
H27	1/2 - 1 Mile WNW	S
H28	1/2 - 1 Mile WNW	S
I29	1/2 - 1 Mile SSW	SW
I30	1/2 - 1 Mile SSW	SW
31	1/2 - 1 Mile NNW	Varies
J32	1/2 - 1 Mile West	Varies
J33	1/2 - 1 Mile West	Varies
J34	1/2 - 1 Mile West	NNE
J35	1/2 - 1 Mile West	NNE
K36	1/2 - 1 Mile South	SE
K37	1/2 - 1 Mile South	SE
L38	1/2 - 1 Mile West	ESE
L39	1/2 - 1 Mile West	ESE
40	1/2 - 1 Mile North	N,NE
M41	1/2 - 1 Mile WSW	E
M42	1/2 - 1 Mile WSW	E
43	1/2 - 1 Mile North	Varies
N44	1/2 - 1 Mile WNW	SE
N45	1/2 - 1 Mile WNW	SW
N46	1/2 - 1 Mile WNW	SW
O47	1/2 - 1 Mile South	E
P48	1/2 - 1 Mile WSW	SW
P49	1/2 - 1 Mile WSW	SW
L50	1/2 - 1 Mile West	SW
Q51	1/2 - 1 Mile NW	SE
Q52	1/2 - 1 Mile NW	NW
N53	1/2 - 1 Mile NW	SE
N54	1/2 - 1 Mile NW	SE
R55	1/2 - 1 Mile SW	N
R56	1/2 - 1 Mile SW	N
O57	1/2 - 1 Mile South	E
S58	1/2 - 1 Mile WNW	NE, SE, NW
S59	1/2 - 1 Mile WNW	SE
T60	1/2 - 1 Mile West	NE
T61	1/2 - 1 Mile West	NE
T62	1/2 - 1 Mile West	SW
T63	1/2 - 1 Mile West	SW
S64	1/2 - 1 Mile WNW	SE
S65	1/2 - 1 Mile WNW	SE
U66	1/2 - 1 Mile WSW	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
U67	1/2 - 1 Mile WSW	Not Reported
V68	1/2 - 1 Mile SSW	NNE
V69	1/2 - 1 Mile SSW	NNE
70	1/2 - 1 Mile NW	SE
71	1/2 - 1 Mile West	SW
Q72	1/2 - 1 Mile NW	SE
T74	1/2 - 1 Mile West	S
T75	1/2 - 1 Mile West	S
76	1/2 - 1 Mile SW	Varies
W77	1/2 - 1 Mile WNW	Varies
W78	1/2 - 1 Mile WNW	Varies
W79	1/2 - 1 Mile WNW	SW
X80	1/2 - 1 Mile South	Varies
X81	1/2 - 1 Mile South	Varies
W82	1/2 - 1 Mile WNW	W
83	1/2 - 1 Mile SSW	E
Y84	1/2 - 1 Mile NNW	NE
Z85	1/2 - 1 Mile West	S
Z86	1/2 - 1 Mile West	S
X87	1/2 - 1 Mile South	NE
X88	1/2 - 1 Mile South	NE
AA89	1/2 - 1 Mile WNW	W
Y90	1/2 - 1 Mile NNW	NE
91	1/2 - 1 Mile NW	NE
AB92	1/2 - 1 Mile SW	NE
AB93	1/2 - 1 Mile SW	NE
AA94	1/2 - 1 Mile West	E
AC95	1/2 - 1 Mile WNW	SE
AC96	1/2 - 1 Mile WNW	SE
AC97	1/2 - 1 Mile WNW	SE
AC98	1/2 - 1 Mile WNW	E, W
AC99	1/2 - 1 Mile WNW	E, W
AD100	1/2 - 1 Mile North	Not Reported
101	1/2 - 1 Mile South	SE
AC102	1/2 - 1 Mile WNW	E
AE103	1/2 - 1 Mile WSW	E
AF104	1/2 - 1 Mile WNW	SW
AF105	1/2 - 1 Mile WNW	E, SW
AG106	1/2 - 1 Mile WNW	W
AD107	1/2 - 1 Mile North	E
AH108	1/2 - 1 Mile NNW	NW
AI109	1/2 - 1 Mile WSW	Varies
AI110	1/2 - 1 Mile WSW	Varies
111	1/2 - 1 Mile SW	NW
AJ112	1/2 - 1 Mile NW	Varies
AJ113	1/2 - 1 Mile NW	SW
AJ114	1/2 - 1 Mile NW	SW
AE115	1/2 - 1 Mile WSW	E
AK116	1/2 - 1 Mile West	S
AG117	1/2 - 1 Mile WNW	W
AH118	1/2 - 1 Mile NNW	N
AK119	1/2 - 1 Mile West	S
AK120	1/2 - 1 Mile West	S

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Mesozoic
System:	Cretaceous
Series:	Upper Mesozoic
Code:	uMze*(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Eugeosynclinal Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 3781208.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Mission Rock	CLIENT:	Baseline Environmental Cons.
ADDRESS:	Pier 48	CONTACT:	Patrick Sutton
	San Francisco CA 94158	INQUIRY #:	3781208.2s
LAT/LONG:	37.7748 / 122.3883	DATE:	November 08, 2013 4:31 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches		Not reported	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 2

Soil Component Name: Water

Soil Surface Texture:
Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

PHYSICAL SETTING SOURCE MAP - 3781208.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Mission Rock	CLIENT:	Baseline Environmental Cons.
ADDRESS:	Pier 48	CONTACT:	Patrick Sutton
	San Francisco CA 94158	INQUIRY #:	3781208.2s
LAT/LONG:	37.7748 / 122.3883	DATE:	November 08, 2013 4:31 pm

Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
A1 **North** **0 - 1/8 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0311 NE, E 60.5 89.5 Not Reported 03/20/1992	**AQUIFLOW**	**69166**
A2 **NNW** **0 - 1/8 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0310 NE Not Reported Not Reported Not Reported Not Reported	**AQUIFLOW**	**66822**
B3 **West** **1/8 - 1/4 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10403 Not Reported Not Reported Not Reported 5 ft 12/16/1988	**AQUIFLOW**	**66938**
B4 **West** **1/8 - 1/4 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10498 NE Not Reported Not Reported 1 10/23/1992	**AQUIFLOW**	**51254**
5 **WNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0104 Not Reported Not Reported Not Reported 7.5 09/29/1994	**AQUIFLOW**	**69128**
6 **NNE** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10312 NE Not Reported Not Reported Not Reported Not Reported	**AQUIFLOW**	**66993**
C7 **NW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0838 SW 4.0 10.20 Not Reported 12/06/1996	**AQUIFLOW**	**69932**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
C8 **NW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0838 SW Not Reported Not Reported Not Reported 12/20/1989	**AQUIFLOW**	**69931**
9 **WNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0355 SW 7 8 Not Reported 11/11/1996	**AQUIFLOW**	**52710**
D10 **NNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0293 SW 25.0 29.5 Not Reported 08/06/1996	**AQUIFLOW**	**69926**
D11 **NNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0913 Varies 13.5 14.0 Not Reported 07/11/1997	**AQUIFLOW**	**70689**
D12 **NNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0667 Not Reported Not Reported Not Reported 7.5 05/02/1995	**AQUIFLOW**	**69979**
13 **SW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0259 NE Not Reported Not Reported 7.8 01/05/1989	**AQUIFLOW**	**70728**
14 **NNW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0972 Varies 11.0 11.5 Not Reported 10/08/1997	**AQUIFLOW**	**54640**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
15 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0274 SE Not Reported Not Reported 2.0 09/18/1991	**AQUIFLOW**	**54179**
16 **North** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0319 SE 9.25 11.62 Not Reported 04/05/1991	**AQUIFLOW**	**70645**
E17 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0192 SW 01.5 11.0 Not Reported 10/04/1991	**AQUIFLOW**	**54756**
E18 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0192 SW 7.0 15.0 Not Reported 06/21/1994	**AQUIFLOW**	**54757**
19 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0477 E 8 9 Not Reported 10/07/1994	**AQUIFLOW**	**52732**
F20 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0461 Varies 10.5 16.5 Not Reported 02/10/1999	**AQUIFLOW**	**54178**
G21 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0321 SW 6.0 11.0 Not Reported 03/06/1987	**AQUIFLOW**	**69866**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
G22 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0321 SW 8.0 15.0 Not Reported 09/26/1994	**AQUIFLOW**	**69867**
G23 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0880 Varies 8.0 15.0 Not Reported 09/06/1996	**AQUIFLOW**	**69740**
G24 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0880 NE 8.5 10.2 Not Reported 03/26/1997	**AQUIFLOW**	**69741**
F25 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0503 NE 10.0 12.08 Not Reported 08/14/1997	**AQUIFLOW**	**54194**
F26 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0503 NE Not Reported Not Reported 15 11/10/1995	**AQUIFLOW**	**54193**
H27 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0345 S 8.0 16.0 Not Reported 04/03/1995	**AQUIFLOW**	**69732**
H28 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0345 S 8.0 9.0 Not Reported 01/06/1989	**AQUIFLOW**	**69733**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
I29 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0426 SW 7.5 8.0 Not Reported 06/18/1987	**AQUIFLOW**	**69929**
I30 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0426 SW Not Reported Not Reported Not Reported 06/14/1995	**AQUIFLOW**	**69930**
31 **NNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0900 Varies Not Reported Not Reported 12.5 02/04/1997	**AQUIFLOW**	**54796**
J32 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0651 Varies Not Reported Not Reported 8.10 06/10/1996	**AQUIFLOW**	**54192**
J33 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0651 Varies 10.0 10.0 Not Reported 07/20/1995	**AQUIFLOW**	**54191**
J34 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0152 NNE 4.0 6.5 Not Reported 04/26/1996	**AQUIFLOW**	**54167**
J35 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0152 NNE Not Reported Not Reported 6.5 10/30/1998	**AQUIFLOW**	**54168**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
K36 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0314 SE 5.5 6.5 Not Reported 10/15/1987	**AQUIFLOW**	**69902**
K37 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0314 SE 6.5 10.0 Not Reported 05/10/1996	**AQUIFLOW**	**69903**
L38 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10961 ESE 10.5 11.0 Not Reported 05/08/1997	**AQUIFLOW**	**69950**
L39 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10961 ESE Not Reported Not Reported 10.5 10/06/1999	**AQUIFLOW**	**69951**
40 **North** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0040 N,NE 10 Not Reported Not Reported 07/24/1995	**AQUIFLOW**	**69967**
M41 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10988 E 8.5 10.5 Not Reported 08/25/1997	**AQUIFLOW**	**69964**
M42 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10988 E Not Reported Not Reported 15.0 05/28/1998	**AQUIFLOW**	**69965**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
43 **North** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0587 Varies 8 UNK Not Reported 07/24/1995	**AQUIFLOW**	**51267**
N44 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11028 SE 12.0 30.0 Not Reported 09/02/1999	**AQUIFLOW**	**54800**
N45 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10737 SW 10.0 10.0 Not Reported 09/29/1998	**AQUIFLOW**	**54632**
N46 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10737 SW 3.0 17.0 Not Reported 07/26/1996	**AQUIFLOW**	**54806**
O47 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10103 E Not Reported Not Reported 10 ft 05/05/1993	**AQUIFLOW**	**51194**
P48 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0354 SW Not Reported Not Reported 8 10/13/1988	**AQUIFLOW**	**54655**
P49 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0354 SW 10.0 20.0 Not Reported 01/26/1996	**AQUIFLOW**	**54656**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
L50 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11009 SW Not Reported Not Reported 18 01/02/1999	**AQUIFLOW**	**70071**
Q51 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0740 SE 8.5 14.5 Not Reported 01/02/1997	**AQUIFLOW**	**69917**
Q52 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0851 NW 10.0 10.5 Not Reported 10/21/1997	**AQUIFLOW**	**69874**
N53 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0202 SE Not Reported Not Reported 21 09/19/1985	**AQUIFLOW**	**70159**
N54 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0202 SE Not Reported Not Reported 36 03/08/1988	**AQUIFLOW**	**70161**
R55 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0371 N 5.0 14.0 Not Reported 10/16/1990	**AQUIFLOW**	**70696**
R56 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0371 N 8.3 9.45 Not Reported 05/31/1997	**AQUIFLOW**	**70697**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
O57 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10103 E Not Reported Not Reported 10 ft 05/05/1993	**AQUIFLOW**	**51192**
S58 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0158 NE, SE, NW 150 180 Not Reported 11/13/1998	**AQUIFLOW**	**69889**
S59 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0795 SE 72 120 Not Reported 07/15/1996	**AQUIFLOW**	**69893**
T60 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0321 NE 6.0 8.0 Not Reported 11/10/1994	**AQUIFLOW**	**70177**
T61 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0321 NE 7.8 8.91 Not Reported 08/28/1996	**AQUIFLOW**	**70178**
T62 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0386 SW 6.48 10.65 Not Reported 09/23/1993	**AQUIFLOW**	**69871**
T63 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0386 SW 7.50 10.0 Not Reported 09/11/1996	**AQUIFLOW**	**69872**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
S64 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11109 SE 6.0 10.0 Not Reported 12/31/1998	**AQUIFLOW**	**69907**
S65 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11109 SE 6.0 8.5 Not Reported 05/05/1999	**AQUIFLOW**	**69908**
U66 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0036 Not Reported Not Reported Not Reported 9.0 02/19/1990	**AQUIFLOW**	**70130**
U67 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0036 Not Reported Not Reported Not Reported 16.5 06/26/1995	**AQUIFLOW**	**70131**
V68 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0061 NNE 3.0 8.0 Not Reported 08/29/1988	**AQUIFLOW**	**70711**
V69 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0061 NNE 7.0 13.5 Not Reported 02/21/1995	**AQUIFLOW**	**70712**
70 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0202 SE Not Reported Not Reported 22 02/21/1986	**AQUIFLOW**	**70160**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
71 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0511 SW 6.52 8.21 Not Reported 05/30/1997	**AQUIFLOW**	**70077**
Q72 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10015 SE 15.5 18.5 Not Reported 07/20/1988	**AQUIFLOW**	**53386**
O73 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10761 Not Reported Not Reported Not Reported 10 ft 12/06/1996	**AQUIFLOW**	**66953**
T74 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0060 S 10.0 12.0 Not Reported 06/23/1993	**AQUIFLOW**	**69883**
T75 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0060 S Not Reported Not Reported 38 06/15/1995	**AQUIFLOW**	**69884**
76 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0506 Varies 3.56 8.53 Not Reported 10/06/1998	**AQUIFLOW**	**54775**
W77 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0023 Varies 5.91 7.05 Not Reported 09/11/1989	**AQUIFLOW**	**53926**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
W78 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0023 Varies Not Reported Not Reported 7.5 10/18/1993	**AQUIFLOW**	**53927**
W79 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10954 SW 7.0 7.0 Not Reported 08/20/1998	**AQUIFLOW**	**69784**
X80 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0419 Varies Not Reported Not Reported 16 11/10/1992	**AQUIFLOW**	**69738**
X81 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0419 Varies 5.0 8.3 Not Reported 05/21/1993	**AQUIFLOW**	**69739**
W82 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0415 W Not Reported Not Reported 13 10/06/1994	**AQUIFLOW**	**69822**
83 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0011 E 9.0 10.3 Not Reported 02/08/1995	**AQUIFLOW**	**69971**
Y84 **NNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0389 NE Not Reported Not Reported 20.40 10/13/1992	**AQUIFLOW**	**53432**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
Z85 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10843 S 36.21 38.72 Not Reported 10/07/1988	**AQUIFLOW**	**69896**
Z86 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10843 S Not Reported Not Reported Not Reported 10/25/1999	**AQUIFLOW**	**69897**
X87 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0485 NE 5.0 10.0 Not Reported 12/01/1993	**AQUIFLOW**	**70007**
X88 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0485 NE Not Reported Not Reported 15 02/14/1994	**AQUIFLOW**	**70008**
AA89 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0997 W Not Reported Not Reported 6.6 06/17/1998	**AQUIFLOW**	**69780**
Y90 **NNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0635 NE 8.0 12.0 Not Reported 12/21/1994	**AQUIFLOW**	**54666**
91 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0513 NE 10.38 14.53 Not Reported 06/30/1998	**AQUIFLOW**	**70079**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
AB92 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0780 NE Not Reported Not Reported 12.5 02/29/1994	**AQUIFLOW**	**70173**
AB93 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0780 NE Not Reported Not Reported 8.5 05/14/1996	**AQUIFLOW**	**70174**
AA94 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11016 E 21.5 23.5 Not Reported 06/14/1999	**AQUIFLOW**	**70627**
AC95 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0052 SE 5.6 6.3 Not Reported 07/08/1993	**AQUIFLOW**	**69912**
AC96 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0052 SE 5.6 10.88 Not Reported 01/05/1995	**AQUIFLOW**	**69913**
AC97 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0052 SE Not Reported Not Reported Not Reported 04/03/1992	**AQUIFLOW**	**69911**
AC98 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0817 E, W 8.6 11.0 Not Reported 07/19/1996	**AQUIFLOW**	**69810**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
AC99 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0817 E, W 10.0 15.0 Not Reported 10/20/1998	**AQUIFLOW**	**69811**
AD100 **North** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10712 Not Reported 10.0 12.0 Not Reported 11/19/1996	**AQUIFLOW**	**70793**
101 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0156 SE Not Reported Not Reported 6 10/08/1986	**AQUIFLOW**	**67409**
AC102 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0336 E 7.56 10.02 Not Reported 09/12/1994	**AQUIFLOW**	**52731**
AE103 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0435 E 7.0 9.0 Not Reported 09/15/1997	**AQUIFLOW**	**69922**
AF104 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10708 SW 9.0 12.0 Not Reported 11/26/1996	**AQUIFLOW**	**69787**
AF105 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10708 E, SW 9.5 10.5 Not Reported 07/22/1999	**AQUIFLOW**	**69788**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
AG106 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0679 W Not Reported Not Reported 7.5 05/11/1993	**AQUIFLOW**	**53947**
AD107 **North** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-10822 E Not Reported Not Reported Not Reported 04/21/1989	**AQUIFLOW**	**53437**
AH108 **NNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	10752 NW 6 ft. 11 ft Not Reported 05/23/1996	**AQUIFLOW**	**51831**
AI109 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11120 Varies Not Reported Not Reported 11 10/14/1998	**AQUIFLOW**	**70682**
AI110 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-11120 Varies 9.0 11.5 Not Reported 01/19/1999	**AQUIFLOW**	**70683**
111 **SW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0564 NW 7.03 11.14 Not Reported 07/16/1998	**AQUIFLOW**	**51619**
AJ112 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0219 Varies Not Reported Not Reported 32 10/08/1995	**AQUIFLOW**	**70168**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
AJ113 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0734 SW 2.50 3.00 Not Reported 05/10/1989	**AQUIFLOW**	**70146**
AJ114 **NW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0734 SW 8.5 11.5 Not Reported 08/13/1996	**AQUIFLOW**	**70147**
AE115 **WSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0435 E 7.3 7.5 Not Reported 10/29/1988	**AQUIFLOW**	**69921**
AK116 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0126 S Not Reported Not Reported 12.2 06/18/1988	**AQUIFLOW**	**69826**
AG117 **WNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0679 W Not Reported Not Reported 6 11/15/1995	**AQUIFLOW**	**53948**
AH118 **NNW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0127 N Not Reported Not Reported 10 02/21/1995	**AQUIFLOW**	**69969**
AK119 **West** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	38-0171 S Not Reported Not Reported 3.50 02/17/1989	**AQUIFLOW**	**69766**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
AK120 **West** **1/2 - 1 Mile** **Higher**	Site ID:	38-0171	**AQUIFLOW**	**69767**
	Groundwater Flow:	S		
	Shallow Water Depth:	2.5		
	Deep Water Depth:	15.5		
	Average Water Depth:	Not Reported		
	Date:	05/28/1997		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for SAN FRANCISCO County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SAN FRANCISCO COUNTY, CA

Number of sites tested: 14

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.636 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.500 pCi/L	100%	0%	0%
Basement	0.360 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)
Source: United States Geologic Survey
A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Health Services
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

OTHER STATE DATABASE INFORMATION

California Oil and Gas Well Locations
Source: Department of Conservation
Telephone: 916-323-1779
Oil and Gas well locations in the state.

RADON

State Database: CA Radon
Source: Department of Health Services
Telephone: 916-324-2208
Radon Database for California

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APENDIX C

LAND USE RESTRICTIONS

RECORDING REQUESTED BY:
The Port of San Francisco
Ferry Building
San Francisco, California 94111

WHEN RECORDED, MAIL TO:

Department of Toxic Substances Control
700 Heinz Avenue, Suite 300
Berkeley, California 94710
Attention: Mohinder S. Sandhu, P.E., Chief
Standardized Permits and Corrective
Action Branch

San Francisco Assessor-Recorder
Doris M. Ward, Assessor-Recorder
DOC- 2000-G723986-00
Acct 25-NO CHARGE DOCUMENT
Thursday, JAN 27, 2000 10:47:55
FRE $0.00
Ttl Pd $0.00 Nbr-0001346614
REEL H561 IMAGE 0199 oed/ER/1-16

N/C
16

SPACE ABOVE THIS LINE RESERVED FOR RECORDER'S USE

COVENANT TO RESTRICT USE OF PROPERTY

ENVIRONMENTAL RESTRICTION

(Re: H&H Site located at Seawall Lot 337, City and County of San Francisco)

This Covenant and Agreement ("Covenant") is made by and between COVENANT TO RESTRICT USE OF PROPERTY

ENVIRONMENTAL RESTRICTION

Re: H&H Site located at Seawall Lot 337, City and County of San Francisco

This Covenant and Agreement ("Covenant") is made by and between the City and County of San Francisco, a charter city and county in trust (the "Covenantor"), the current owner, of certain property situated in the City and County of San Francisco, State of California, described in Exhibit "A", attached hereto and incorporated herein by this reference (the "Property"), and the Department of Toxic Substances Control (the

"Department"). Pursuant to Civil Code section 1471(c), the Department has determined that this Covenant is reasonably necessary to protect present or future human health or safety or the environment as a result of the presence on the land of hazardous materials as defined in Health and Safety Code ("H&SC") section 25260. The Covenantor and the Department, collectively referred to as the "Parties", therefore intend that the use of the Property be restricted as set forth in this Covenant, in order to protect human health, safety and the environment.

ARTICLE I
STATEMENT OF FACTS

1.01. The Property, totaling approximately 14 acres, is more particularly described in Exhibit "A" and depicted in Exhibit "A-1", attached hereto and incorporated herein by this reference. The Property is located in the area now generally bounded by Terry Francois Boulevard on the North and East, in the City and County of San Francisco, California.

1.02. The site was created by filling marshlands and shallow tidal flats bordering San Francisco Bay between 1877 and 1913. Sources of fill are unknown, but likely included construction/demolition debris and rubble, and rock and dirt cut from nearby hills. Historical uses of the Site include railroad tracks and related support structures, parking and shipping by truck, and truck maintenance. From 1950 to 1996 H&H Ship Service operated a hazardous waste treatment facility, including a tank cleaning area and drum storage unit, and used portions of the Property for vehicle parking and offices.

In 1978 several of the wastes managed at the H&H Ship Service facility were determined to be hazardous wastes subject to federal and state hazardous waste management regulations. Since that time, the Department of Toxic Substances Control (or its predecessor in interest, the Department of Health Services) authorized H&H Ship Service's operations pursuant to an interim status document. Under this authorization the property was a hazardous waste facility (Facility), regulated by the Department, subject to the requirements of the California Hazardous Waste Control Law ("HWCL"), at Health and Safety Code ("H&S Code") section 25100 et seq., and the federal Resource Conservation and Recovery Act ("RCRA"), at 42 U.S.C. section 6901 et seq.

The Department is requiring this Covenant pursuant to the closure requirements of the HWCL, including H&S Code section 25246 and post-closure notices provisions of Title 22 California Code of Regulations [section 66265.119(b) for interim status hazardous waste facilities], as part of the facility closure. The Department circulated a closure plan, dated August 30, 1996 and a draft Categorical Exemption pursuant to the California Environmental Quality Act, Public Resources Code section 21000 et seq for

public review and comment from December 23, 1999 to January 24, 2000. The Department approved the closure plan, closure certification report titled, *RCRA Closure Certification Report, Former H&H Ship Service Facility, San Francisco, California, dated February 4, 1999*, containing a health risk assessment, and the Categorical Exemption on January 26, 2000. Hazardous wastes, which are also hazardous materials as defined in Health and Safety Code sections 25117 and 25260, including petroleum hydrocarbons, polynuclear aromatic hydrocarbons, metals and arsenic, remain in the soil and groundwater at the Site at concentrations below those which would pose a significant human health risk under proposed reuse scenarios. The health risk assessment did not evaluate an unrestricted land use scenario, recreational use involving direct contact with soil, or potential impacts from use of groundwater. Therefore a deed restriction to limit use of the property to those exposure scenarios evaluated and found to be below acceptable risk limits is required as part of the facility closure.

1.03. As detailed in the health risk assessment within the *RCRA Closure Certification Report*, as approved by the Department on January 26, 2000, portions of the surface and subsurface soils on the Site contain hazardous wastes and hazardous materials, as defined in H&S Code section 25117 and 25260, including the following contaminants of concern: arsenic (up to 92 mg/kg) and benzo(a)pyrene (up to 2.5 mg/kg). Groundwater beneath the Property is found within 10 to 20 feet below ground surface. Dissolved arsenic was found in groundwater at up to 812 ug/l. California drinking water standards are arsenic at 50 ug/l. Because the health risk assessment did not evaluate an unrestricted land use scenario, recreational use involving direct contact with soil, or potential impacts from use of groundwater, the Department concluded that use of the Property as a residence, hospital, school for persons under the age of 21, day care center, or recreational use involving direct contact with soil would entail an unacceptable potential human health risk. The Department further concluded that the Property, subject to the restrictions of this Covenant, does not present an unacceptable threat to human safety or the environment.

ARTICLE II
DEFINITIONS

2.01. Department. "Department" shall mean the California Department of Toxic Substances Control and shall include its successor agencies, if any.

2.02. Owner. "Owner" shall mean the Covenantor, its successors in interest, and their successors in interest, including heirs and assigns, who at any time hold title to all or any portion of the Property.

2.03. Occupant. "Occupant" shall mean Owners and any person or entity entitled by ownership, leasehold, or other legal relationship to the right to occupy any portion of the Property.

ARTICLE III
GENERAL PROVISIONS

3.01. Restrictions to Run With the Land. This Covenant sets forth protective provisions, covenants, restrictions, and conditions (collectively referred to as "Restrictions"), upon and subject to which the Property and every portion thereof shall be improved, held, used, occupied, leased, sold, hypothecated, encumbered, and/or conveyed. Each and every one of the Restrictions: (a) shall run with the land pursuant to H&SC sections 25202.5, and 25202.6 and Civil Code section 1471; (b) shall inure to the benefit of and pass with each and every portion of the Property, (c) shall apply to and bind the respective successors in interest to the Property, (d) are for the benefit of, and shall be enforceable by the Department, and (e) are imposed upon the entire Property unless expressly stated as applicable only to a specific portion thereof.

3.02. Binding Upon Owners/Occupants. Pursuant to Health and Safety Code section 25202.5(b), this Covenant shall be binding upon all of the owners of the land, their heirs, successors, and assignees, and the agents, employees, and lessees of the owners, heirs, successors, and assignees. Pursuant to Civil Code section 1471(b), all successive owners of the Property are expressly bound hereby for the benefit of the covenantee(s) herein. "Owner" shall include "Covenantor".

3.04. Written Notice of Hazardous Substance Release. The Owner shall, prior to the sale, lease, or rental of the Property, give written notice that a release of hazardous substances has come to be located on or beneath the Property, pursuant to Health and Safety Code section 25359.7. Such written notice shall include a copy of this Covenant.

ARTICLE IV
RESTRICTIONS

4.01. Prohibited Uses. The Property shall not be used for any of the following purposes:

(a) A residence, including any mobile home or factory built housing, constructed or installed for use as residential human habitation;

(b) A hospital for humans;

(c) A public or private school for persons under 21 years of age;

(d) A day care center for children; or

(e) Recreational use involving direct contact with soil.

4.02. Soil Management

(a) Any contaminated soils brought to the surface by grading, excavation, trenching or backfilling shall be managed in accordance with all applicable provisions of state and federal law.

(b) If more than 50 cubic yards of any surface or subsurface soil will be disturbed, including excavation and grading, then the soil shall be evaluated for potential human health risks in compliance with Article 20 of the SF Municipal Code ("the Maher Ordinance"), and managed accordingly.

4.03. Prohibited Activities. The following activities shall not be conducted at the Property:

(a) No raising of food (e.g., cattle, food crops, cotton, etc.) shall be permitted on the property.

(b) No groundwater shall be extracted on the Property for purposes other than site remediation or construction dewatering without prior written approval by the Department.

4.04. Access for Department. Covenantor agrees that the Department shall have reasonable right of entry and access to the Property for inspection, monitoring, and other activities consistent with the purposes of this Covenant as deemed necessary by the Department in order to protect the public health and safety.

ARTICLE V
ENFORCEMENT

5.01. Enforcement. Failure of the Covenantor and/or Owner to comply with any of the Restrictions specifically applicable to it shall be grounds for the Department, by reason of this Covenant, to require that the Covenantor and/or Owner modify or remove any improvements ("Improvements" herein shall mean all buildings, roads, driveways, and paved parking areas, constructed or placed upon any portion of the Property constructed in violation of the Restrictions.) Violation of this Covenant shall be grounds for the Department to file civil and/or criminal actions against the Covenantor and/or Owner as provided by law.

ARTICLE VI
VARIANCE, TERMINATION, AND TERM

6.01. Variance. Any Owner or, with the Owner's written consent, any Occupant of the Property or any portion thereof may apply to the Department for a written variance from the provisions of this Covenant. Such application shall be made in accordance with H&S Code section 25202.6.

6.02. Termination. Any Owner, and/or, with the Owner's written consent, any Occupant of the Property, or any portion thereof, may apply to the Department for a termination of the Restrictions or other terms of this Covenant as they apply to all or any portion of the Property. Such application shall be made in accordance with H&S Code section 25202.6.

6.03. Term. Unless ended in accordance with the Termination Paragraph above, by law, or by the Department in the exercise of its discretion, this Covenant shall continue in effect in perpetuity.

ARTICLE VII
MISCELLANEOUS

7.01. No Dedication Intended. Nothing set forth in this Covenant shall be construed to be a gift or dedication, or offer of a gift or dedication, of the Property, or any portion thereof to the general public or anyone else for any purpose whatsoever.

7.02. Department References. All references to the Department include successor agencies/departments or other successor entity.

7.03. Recordation. The Covenantor shall record this Covenant, with all referenced Exhibits, in the County of San Francisco within ten (10) days of the Covenantor's receipt of a fully executed original.

7.04. Notices. Whenever any person gives or serves any notice ("Notice" as used herein includes any demand or other communication with respect to this Covenant), each such Notice shall be in writing and shall be deemed effective: (1) when delivered, if personally delivered to the person being served or to an officer of a corporate party being served, or (2) three (3) business days after deposit in the mail, if mailed by United States mail, postage paid, certified, return receipt requested:

To Owner:

G723986

On or Before 12/31/00:

Port of San Francisco
3100 Ferry Building
San Francisco, CA 94111
Attention: Carol Bach,

With a copy to

Noreen Ambrose
Port General Counsel
Port of San Francisco
3100 Ferry Building
San Francisco, CA 94111.

After 12/31/00:

Port of San Francisco
Pier 1
San Francisco, CA 94111
Attention: Carol Bach,

With a copy to:
Noreen Ambrose
Port General Counsel
Port of San Francisco
Pier 1
San Francisco, CA 94111.

To Department:

California Environmental Protection Agency
Department of Toxic Substances Control
700 Heinz Avenue, Suite 300
Berkeley, CA 94710-2737
Attention: Branch Chief
Standardized Permits and Corrective Action Branch

Any party may change its address or the individual to whose attention a notice is to be sent by giving written notice in compliance with this paragraph.

7.05. Partial Invalidity. If any portion of the Restrictions or other term set forth herein is determined by a court of competent jurisdiction to be invalid for any reason, the surviving portions of this Covenant shall remain in full force and effect as if such portion found invalid had not been included herein.

G723986

IN WITNESS WHEREOF, the Parties execute this Covenant.

"Covenantor" City & County of San Francisco

Date: 1/26/2000

By: _____
DOUGLAS F. WONG
Its: Executive Director
Port of San Francisco

"Department" Department of Toxic Substances Control

Date: 1/26/00

By: _____
MOHINDER S. SANDHU
Its: Chief, Standardized Permits and Corrective Action Branch

G723986

CALIFORNIA ALL-PURPOSE ACKNOWLEDGMENT

State of California

County of San Francisco } ss.

On January 26, 2000, before me, Virna C. Wu, "Notary Public",
Date Name and Title of Officer (e.g., "Jane Doe, Notary Public")

personally appeared Douglas Farrell Wong,
Name(s) of Signer(s)

☒ personally known to me
☐ ~~proved to me on the basis of satisfactory~~ evidence

to be the person(~~s~~) whose name(~~s~~) is/~~are~~ subscribed to the within instrument and acknowledged to me that he/~~she/they~~ executed the same in his/~~her/their~~ authorized capacity(~~ies~~), and that by his/~~her/their~~ signature(~~s~~) on the instrument the person(~~s~~), or the entity upon behalf of which the person(~~s~~) acted, executed the instrument.

WITNESS my hand and official seal.

Signature of Notary Public

VIRNA CHERN WU
Commission # 1203557
Notary Public - California
San Francisco County
My Comm. Expires Dec 3, 2002

Place Notary Seal Above

OPTIONAL

Though the information below is not required by law, it may prove valuable to persons relying on the document and could prevent fraudulent removal and reattachment of this form to another document.

Description of Attached Document

Title or Type of Document: Environmental Restriction

Document Date: 1/26/2000 Number of Pages: 8 + 6 (Parcel B, C, D)

Signer(s) Other Than Named Above: None

Capacity(ies) Claimed by Signer

Signer's Name: Douglas Farrell Wong

☐ Individual
☐ Corporate Officer — Title(s): _____
☐ Partner — ☐ Limited ☐ General
☐ Attorney in Fact
☐ Trustee
☐ Guardian or Conservator
☐ Other: Port Executive Director

Signer Is Representing: Port of San Francisco

RIGHT THUMBPRINT OF SIGNER
Top of thumb here

© 1997 National Notary Association • 9350 De Soto Ave., P.O. Box 2402 • Chatsworth, CA 91313-2402 Prod. No. 5907 Reorder: Call Toll-Free 1-800-876-6827

G723986

CALIFORNIA ALL-PURPOSE ACKNOWLEDGMENT

State of California

County of San Francisco } ss.

On January 26, 2000 (Date), before me, Virna C. Wu, "Notary Public" (Name and Title of Officer (e.g., "Jane Doe, Notary Public")),

personally appeared Mohinder Singh Sandhu (Name(s) of Signer(s)),

~~☐ personally known to me~~

☒ proved to me on the basis of satisfactory evidence

to be the person~~(s)~~ whose name~~(s)~~ is/~~are~~ subscribed to the within instrument and acknowledged to me that he/~~she/they~~ executed the same in his/~~her/their~~ authorized capacity~~(ies)~~, and that by his/her/their signature~~(s)~~ on the instrument the person~~(s)~~, or the entity upon behalf of which the person~~(s)~~ acted, executed the instrument.

WITNESS my hand and official seal.

Virna C. Wu
Signature of Notary Public

VIRNA CHERN WU
Commission # 1203557
Notary Public - California
San Francisco County
My Comm. Expires Dec 3, 2002

Place Notary Seal Above

OPTIONAL

Though the information below is not required by law, it may prove valuable to persons relying on the document and could prevent fraudulent removal and reattachment of this form to another document.

Description of Attached Document

Title or Type of Document: Environmental Restriction

Document Date: 01/26/2000 Number of Pages: 8+6(Parcel A, C & D)

Signer(s) Other Than Named Above: None

Capacity(ies) Claimed by Signer

Signer's Name: Mohinder Singh Sandhu

☐ Individual
☐ Corporate Officer — Title(s): _____
☐ Partner — ☐ Limited ☐ General
☐ Attorney in Fact
☐ Trustee
☐ Guardian or Conservator
☒ Other: Chief, Standardized Permits & Corrective Action Branch

Signer Is Representing: Dept. of Toxic Substances Control

RIGHT THUMBPRINT OF SIGNER
Top of thumb here

© 1997 National Notary Association • 9350 De Soto Ave., P.O. Box 2402 • Chatsworth, CA 91313-2402 Prod. No. 5907 Reorder: Call Toll-Free 1-800-876-6827

G723986

SEAWALL LOT 337

PARCEL A

ALL THAT CERTAIN REAL PROPERTY SITUATED AT THE CITY AND COUNTY OF SAN FRANCISCO, BEING A PORTION OF SEAWALL LOT 337 OF THE SAN FRANCISCO PORT AUTHORITY, DESCRIBED AS FOLLOWS; COMMENCING AT THE SOUTHWEST CORNER OF THE INTERSECTION OF TOWNSEND STREET AND DELANCEY STREET (FORMERLY FIRST STREET), SAID CORNER BEING INNER 14 OF THE INNER WATERFRONT LINE AS DESCRIBED IN THE RECORDS ON FILE AT THE OFFICE OF ENGINEERING OF THE SAN FRANCISCO PORT AUTHORITY; RUNNING THENCE ALONG SAID INNER WATERFRONT LINE AT S 3DEG 02'27" E A DISTANCE OF 2,217.59 FEET TO THE TRUE POINT OF BEGINNING; THENCE CONTINUING ALONG THE LAST AFOREMENTIONED COURSE A DISTANCE OF 149.77 FEET; THENCE AT S 86DEG 57'33" W A DISTANCE OF 38.12 FEET; THENCE AT S 3DEG 14'22" E A DISTANCE OF 31.51 FEET; THENCE AT N 86DEG 45'38" E A DISTANCE OF 55.69 FEET; THENCE AT S 3DEG 02'27" E A DISTANCE OF 120.00 FEET; THENCE AT S 86DEG 45'38" W A DISTANCE OF 55.27 FEET; THENCE AT N 3DEG 14'22" W A DISTANCE OF 120.00 FEET; THENCE AT S 86DEG 45'38" W A DISTANCE OF 40.17 FEET; THENCE AT S 3DEG 14'22" E A DISTANCE OF 120.00 FEET; THENCE AT N 86DEG 45'38" E A DISTANCE OF 40.17 FEET; THENCE AT S 3DEG 14'22" E A DISTANCE OF 48.20 FEET; THENCE AT S 86DEG 57'33" W A DISTANCE OF 142.25 FEET; THENCE AT

G723986

S 86DEG 50'57" W A DISTANCE OF 111.99 FEET; THENCE AT
N 3DEG 10'55" W A DISTANCE OF 200.00 FEET; THENCE AT
N 86DEG 57'33" E A DISTANCE OF 171.00 FEET; THENCE AT
N 3DEG 02'27" W A DISTANCE OF 149.48 FEET; THENCE AT
N 86DEG 49'20" E A DISTANCE OF 121.29 FEET TO THE TRUE POINT OF BEGINNING, CONTAINING AN AREA OF 70,765.20 SQUARE FEET, MORE OR LESS.



G723986

SEAWALL LOT 337

PARCEL C

BEING A PORTION OF SEAWALL LOT 337 OF THE SAN FRANCISCO PORT AUTHORITY ,CITY AND COUNTY OF SAN FRANCISCO, BRIEFLY DESCRIBED AS FOLLOWS; COMMENCING AT THE SOUTHWEST CORNER OF THE INTERSECTION OF TOWNSEND STREET AND DELANCEY STREET (FORMERLY FIRST STREET), SAID CORNER BEING INNER 14 OF THE INNER WATERFRONT LINE AS DESCRIBED IN THE RECORDS ON FILE AT THE OFFICE OF ENGINEERING OF THE SAN FRANCISCO PORT AUTHORITY; RUNNING THENCE ALONG THE AFORESAID INNER WATERFRONT LINE AT S 3DEG 02'27" E A DISTANCE OF 2,367.36 FEET TO THE TRUE POINT OF BEGINNING; THENCE AT S 48DEG 02'27" E A DISTANCE OF 25.00 FEET; THENCE AT S 3DEG 02'27" E A DISTANCE OF 13.64 FEET; THENCE AT S 86DEG 45'38" W A DISTANCE OF 55.69 FEET; THENCE AT N 3DEG 14'22" W A DISTANCE OF 31.51 FEET; THENCE AT N 86DEG 57'33" E A DISTANCE OF 38.12 FEET TO THE TRUE POINT OF BEGINNING, CONTAINING AN AREA OF 1,594.90 SQUARE FEET, MORE OR LESS.



G723986

ALSO INCLUDED IN THIS PARCEL IS A PORTION OF SEAWALL LOT 337 BRIEFLY DESCRIBED AS FOLLOWS;

COMMENCING AT THE SOUTHWEST CORNER OF THE INTERSECTION OF TOWNSEND STREET AND DELANCEY STREET (FORMERLY FIRST STREET) SAID POINT BEING INNER 14 OF THE INNER WATERFRONT LINE AS DESCRIBED IN THE RECORDS ON FILE AT THE OFFICE OF ENGINEERING OF THE SAN FRANCISCO PORT AUTHORITY; RUNNING THENCE ALONG THE AFORESAID INNER WATERFRONT LINE A DISTANCE OF 2,518.74 FEET; THENCE AT N 86DEG 45'38" E A DISTANCE OF 17.66 FEET TO THE TRUE POINT OF BEGINNING; THENCE AT S 3DEG 02'27" E DISTANCE OF 30.72 FEET; THENCE AT S 41DEG 57'33" W A DISTANCE OF 25.00 FEET; THENCE S 86DEG 57'33" W A DISTANCE OF 37.43 FEET; THENCE AT N 3DEG 14'22" W A DISTANCE OF 48.20 FEET; THENCE AT N 86DEG 45'38" E DISTANCE OF 55.27 FEET TO THE TRUE POINT OF BEGINNING, CONTAINING AN AREA OF 2,509.60 SQUARE FEET, MORE OR LESS.



G723986

SEAWALL LOT 337

PARCEL D

PARCEL D IS A TWO-STORY WAREHOUSE AND OFFICE BUILDING LOCATED AT CHINA BASIN STREET WHOSE FOOTPRINT IS BRIEFLY DESCRIBED AS FOLLOWS;
COMMENCING AT THE SOUTHWEST CORNER OF THE INTERSECTION OF TOWNSEND STREET AND DELANCEY STREET (FORMERLY FIRST STREET), SAID POINT BEING INNER 14 OF THE INNER WATERFRONT LINE AS DESCRIBED IN THE RECORDS ON FILE AT THE OFFICE OF ENGINEERING OF THE SAN FRANCISCO PORT AUTHORITY; RUNNING THENCE SOUTHERLY ALONG THE AFORESAID INNER WATERFRONT LINE AT S 3DEG 02'27" E A DISTANCE OF 2,398.74 FEET; THENCE AT N 86DEG 45'38" E A DISTANCE OF 38.02 FEET TO THE TRUE POINT OF BEGINNING; THENCE AT S 3DEG 14'22" E A DISTANCE OF 120.00 FEET; THENCE AT S 86DEG 45'38" W A DISTANCE OF 40.17 FEET; THENCE AT N 3DEG 14'22" W A DISTANCE OF 120.00 FEET; THENCE AT N 86DEG 45'38" E A DISTANCE OF 40.17 FEET TO THE TRUE POINT OF BEGINNING, CONTAINING AN AREA OF 4,820.00 SQUARE FEET, MORE OR LESS.

ALSO INCLUDED IN THIS PARCEL IS THE SECOND FLOOR OFFICE SPACE OF THE AFOREMENTIONED TWO- STORY BUILDING WITH AN AREA OF 2,414.00 SQUARE FEET, MORE OR LESS.

G723986



PARCEL A	91,844 SF
PARCEL B	14,071 SF
SUB TOTAL	105,915SF
PARCEL C	4,105SF
PARCEL D	
WAREHOUSE	4,820 SF
OFFICE	2,414 SF
TOTAL	117,254 SF

Contract No.

APPROVED BY
SAN FRANCISCO PORT COMMISSION
DATE Jan 21 1992
CHIEF ENGINEER

NO.	DATE	DESCRIPTION

REVISIONS

PORT OF SAN FRANCISCO
SAN FRANCISCO PORT COMMISSION
DEPARTMENT OF ENGINEERING

EXHIBIT A-1
H & H SHIP SERVICE CO.
LEASE NO. L-11679

DRAWN BY E.C.C.	CHECKED BY
DESIGNED BY	DATE 4-27-92
SECTION HEAD	SCALE
DRAWING NO.	SHEET NO. OF SHEETS

APENDIX D

QUALIFICATIONS OF PREPARERS

Yane Nordhav, P.G.

Principal
Professional Geologist

M.S., Geology, Cal State Hayward, 1988
B.A., Geology, U.C. Berkeley, 1976
40-hour HAZWOPER training
Professional Geologist No. 4009, 1985
35 years of experience

Recent Projects

- Sacramento Trapshoot Club, investigation, remediation, agency negotiations, Project Manager, 2004-2010
- New Crystal Springs Bypass Tunnel EIR, San Francisco Public Utilities Commission, Project Manager, 2006-2008.
- Bayview Transportation Improvements Project EIR/EIS, Technical lead for Hazardous Materials and Water Quality Technical Studies, 2004-present.
- Port of Oakland, Berths 25 and 26, investigation, remediation, agency negotiations, 2002-present.
- Technical litigation support for sites along the Bay margin, 1998-present.
- Port of Oakland, Development of soil reuse criteria for Port capital projects, 2010-2012.

Yane Nordhav is a principal of BASELINE. She is a principal-in-charge for BASELINE projects related to hazardous materials management, development of remedial actions, site characterizations, and CEQA/NEPA documentation. She performs QA/QC functions for all projects at BASELINE.

As principal investigator, she has managed and conducted groundwater investigations and remediation on major Superfund sites and local brownfields sites in California, including media contaminated with petroleum hydrocarbons, solvents, metals and manufactured gas plant wastes.

Through her work, she has developed an extensive working knowledge of regulatory requirements and established working relationships with regulatory agency staff on the state and local levels. She routinely works with the Regional Water Quality Control Board, Department of Toxic Substances Control, and local agency staff to arrive at appropriate goals for risk-based cleanup of soil and groundwater resources.

She has managed major environmental audits and developed environmental programs for cities, ports, and industrial clients; her work has included development of strategies for waste management and minimization, soil reuse protocols for large municipal clients, and UST compliance programs.

She also routinely provides technical litigation support and expert witness services to clients on sites that have been affected by historic land uses and require cleanup prior to future productive uses.

In addition, Ms. Nordhav has been the project manager for the preparation of major environmental documents in California, including EIRs for controversial projects, ranging from open pit mines, hazardous waste disposal facilities, water supply infrastructure projects, and new towns. Some of the EIRs she has managed has received awards from the Association of Environmental Professionals as the Document of the Year.

As technical reviewer for hazardous materials and CEQA projects, she provides quality control for reports prior to submittal to clients. She routinely reviews Phase I and Phase II reports, as well as remedial investigations, removal action workplans, remedial action plans, and remedial design and implementation plans for compliance with CERCLA.

Patrick Sutton

Environmental Engineer

M.S., Civil and Environmental Engineering, University of California – Davis

B.S., Environmental Science, Dickinson College

40-hour OSHA training

9 years of experience

Recent Projects

- I-680 Northbound HOV/Express Lane Project, Manager for the Caltrans Initial Site Assessment and Preliminary Geological Assessment.
- Richmond Central Project, Technical Lead on Air Quality, Climate Change, Geology, and Hazardous Materials sections of a CEQA Initial Study.
- Mountain View General Plan, Technical Lead on Hazardous Materials section of a CEQA EIR.
- New Irvington Tunnel Project, Manager of a Phase I Environmental Site Assessment, Technical Lead on Hazards Materials section of a CEQA EIR, and Water Resource Database Manager for over 40 domestic water supply wells.
- I-880 High Occupancy Vehicle Lane Widening Project, Manager for the Initial Site Assessment and Preliminary Site Investigation.

Patrick Sutton is an environmental engineer. He has worked as a field technician for hazardous waste sites, and managed state-funded and privately-financed soil and groundwater remediation projects. Remediation projects have included residential properties, service stations, landfills, drycleaners, railroads, and other commercial properties impacted with lead, asbestos, petroleum hydrocarbons, chlorinated solvents, polychlorinated biphenyls, and heavy metals.

Mr. Sutton has prepared impact evaluations for air quality, climate change, geology, hazardous materials, and water quality sections of CEQA documents for residential, commercial, and industrial projects, as well as community colleges, community parks, and highway improvements projects. He has performed numerous Phase I environmental site assessments, and he has also prepared Initial Site Assessments and Preliminary Site Investigations in accordance with Caltrans requirements for major transportation projects. His proficiency in a wide range of technical software (Microsoft Access, GIS, air quality and groundwater models, and graphics design) allow him to thoroughly and efficiently assess and mitigate environmental concerns.

In 2013, Mr. Sutton designed and modeled a solar powered in-well vapor stripping system to remove chlorinated solvents from groundwater, and to provide an affordable alternative to conventional remediation technologies. In cooperation with the Central Valley Regional Water Quality Control Board, a successful pilot test of the technology was implemented at a dry cleaner site in Sonora. Mr. Sutton has also supervised the installation and maintenance of a variety of remediation systems, such as air sparge and soil vapor extraction, enhanced bioremediation, permanganate injection, and groundwater extraction. Through his work associated with assessing, investigating, and remediating hazardous materials in the subsurface, he had developed an excellent perspective on how to satisfy both regulatory and technical requirements to properly manage hazardous material concerns.